

**TurboMaster**

GARRETT TURBOS OFFICIAL DISTRIBUTOR FOR SPAIN

**Trucks** Catalog**APPLICATIONS**

Andoria	Asia	Astra
Daewoo	Daf	Hyundai
I.H. - Navistar	Isuzu	Iveco
Jianghuai	Mack	Mercedes
Mitsubishi	Nissan	Pegaso
Raba	Renault	Scania
Unimog	Volvo	White

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

**TurboMaster**

GARRETT TURBOS OFFICIAL DISTRIBUTOR FOR SPAIN

**Trucks** Catalog**APPLICATIONS**

SUITABLE FOR:

**Andoria**

Model	Motor	CC	Nº of Cylinders	CV	Year	Model	Part Number	O.E.M Part Number
	4CT90-1	2400	4L		1994	TB2561	<b>454102-0002</b>	2.52.030
	6CT107	6540	6L		1999	GT3271S	<b>705100-0001</b>	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

# TurboMaster

GARRETT TURBOS OFFICIAL DISTRIBUTOR FOR SPAIN



## Trucks Catalog

### APPLICATIONS

SUITABLE FOR:

**Asia**

Model	Motor	CC	Nº of Cylinders	CV	Year	Model	Part Number	O.E.M Part Number
	CA4113Z	5000	4L	140		TB2820	<u>711380-0010</u>	1118010-1 4BKZ

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: [turbomaster@turbomaster.info](mailto:turbomaster@turbomaster.info).

# TurboMaster

GARRETT TURBOS OFFICIAL DISTRIBUTOR FOR SPAIN



## Trucks Catalog

### APPLICATIONS

SUITABLE FOR:

**Astra**

Model	Motor	CC	Nº of Cylinders	CV	Year	Model	Part Number	O.E.M Part Number
<b>BUS</b>	8210.42K.351	13798	6L	370		TA5126	<b>454003-0005</b>	99439019

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

**TurboMaster**

GARRETT TURBOS OFFICIAL DISTRIBUTOR FOR SPAIN

**Trucks Catalog****APPLICATIONS**

SUITABLE FOR:

**Daewoo**

Model	Motor	CC	Nº of Cylinders	CV	Year	Model	Part Number	O.E.M Part Number
	D2366T			293		TA4538	<b>466617-0001</b>	
	D2366T			293		TA4538	<b>466617-0002</b>	
	B3			333		TBP4503	<b>466789-0001</b>	65.09100-7024
	B3			333		TBP4503	<b>466789-0002</b>	65.09100-7037
	D1146TI	8000	6L	203	1998	TO4E55	<b>466721-0012</b>	
	DE12TIB	11000	6L	345	1999	GT4594	<b>713119-0003</b>	
	DV15T	14600	8V	333	1994	TO4E55	<b>466721-0001</b>	65.09100-7088
	DV15T	14600	8V	333	1994	TO4E55	<b>466721-0002</b>	65.09100-7087

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: [turbomaster@turbomaster.info](mailto:turbomaster@turbomaster.info).



## APPLICATIONS

SUITABLE FOR:

**Daf**

Model	Motor	CC	Nº of Cylinders	CV	Year	Model	Part Number	O.E.M Part Number
	NS177M	6200	6L			TBP4	<u>452316-0001</u>	1345172
	RG170 CNG	8600	6L			GT4082	<u>452207-0004</u>	1326680
	RG170 LPG	8600	6L			GT4082	<u>452207-0004</u>	1326680
	GC170LPG	8600	6L		2000	GT3776	<u>709347-0001</u>	
	RS245M	8660	6L	332		TA4510	<u>466502-0006</u>	1303636
	GS245M	8660	6L	332	1994	TA4510	<u>466502-0006</u>	1303636
	PE235C	9200	6L		2000	GT4088	<u>703457-0001</u>	
	XF315C	12600	6L	375	1999	GT4294S	<u>452281-0007</u>	
	XF315M	12600	6L	375	1999	GT4294S	<u>452281-0007</u>	
<b>1000</b>	6BTA	5900	6L			H1C	<b>3525648</b>	492130
<b>1100</b>	DT615	6170	6L	150	1986	TA3501	<u>465186-0001</u>	636949
<b>1100</b>	DNT620	6240	6L	177		TO4E11	<u>466780-0001</u>	284555
<b>1100</b>	DNTD620	6240	6L	177		TO4E11	<u>466780-0001</u>	284555
<b>1300</b>	DNTD620	6240	6L	177		TO4E11	<u>466780-0001</u>	284555
<b>1300</b>	DNT620	6240	6L	177		TO4E11	<u>466780-0001</u>	284555
<b>1300</b>	DNT620	6240	6L	177	1986	TO4E11	<u>466780-0002</u>	394778
<b>1500</b>	DS575	6170	6L			3-275	<b>12050</b>	236292
<b>1500</b>	DS575	6170	6L			3LD9	<b>54674</b>	167206
<b>1500</b>	DT615	6170	6L	150	1986	TA3501	<u>465186-0001</u>	636949
<b>1600</b>	DT615	6170	6L			3A-275	<b>53510</b>	252447
<b>1600</b>	DT615	6170	6L		1973	3LD9	<b>54097</b>	166102
<b>1600</b>	DT615	6170	6L	150	1986	TA3501	<u>465186-0001</u>	636949
<b>1700</b>	DNT620	6240	6L	177		TO4E11	<u>466780-0001</u>	284555
<b>1700</b>	DNT620	6240	6L	177	1986	TO4E11	<u>466780-0002</u>	394778
<b>1800</b>	DT615	6170	6L			3LD9	<b>54097</b>	166102
<b>1800</b>	DHT825	8270	6L	218		TA4503	<u>465942-0013</u>	370871
<b>1900</b>	DT615	6170	6L	150	1986	TA3501	<u>465186-0001</u>	636949
<b>1900</b>	DNT620	6240	6L	177	1986	TO4E11	<u>466780-0001</u>	284555
<b>1900</b>	DNS620	6240	6L	177	1986	TO4E11	<u>466780-0003</u>	538994
<b>1900</b>	DNS620	6240	6L	202	1986	TO4E11	<u>466780-0004</u>	090617
<b>2000</b>	DU825					4LEV	<b>53865</b>	252262
<b>2100</b>	DHT825	8270	6L			TA4510	<u>466502-0011</u>	298515

2100	DHTD825	8270	6L	204		TA4503	<u>465942-0005</u>	674022
2100	DHTD825	8270	6L	204		TA4503	<u>465942-0015</u>	674022
2100	DHT825	8270	6L	218		TA4503	<u>465942-0003</u>	656331
2100	DHT825	8270	6L	218		TA4503	<u>465942-0013</u>	370871
2200	DU825				1972	4LEV	<u>53865</u>	252262
2300	DHT825	8270	6L			TA4510	<u>466502-0011</u>	298515
2300	DHU825	8270			1979	3LKZ	<u>5223-988-3281</u>	631276
2300	DHT825	8270	6L	218		TA4503	<u>465942-0003</u>	656331
2300	DHT825	8270	6L	218		TA4503	<u>465942-0013</u>	370871
2500	DHS825	8270	6L	250		TA4503	<u>465942-0001</u>	655012
2500	DHS825	8270	6L	250		TA4503	<u>465942-0002</u>	370870
2500	DHS825	8270	6L	250		TA4503	<u>465942-0011</u>	370870
2500	DHS825	8270	6L	250		TA4503	<u>465942-0012</u>	657196
2800	DKS1160	11600	6L			4LG	<u>5232-988-2201</u>	504129
2800	DKT1160	11600	6L			4LG	<u>5232-988-3208</u>	629749
2800	DKS1160	11600	6L			4LG	<u>5232-988-3208</u>	629749
2800	DKSE1160	11600	6L			4LG	<u>5232-988-3209</u>	629748
2800	DKS11600	11600	6L	220	1982	4LG	<u>5232-988-3205</u>	662115
2800	DKT1160	11600	6L	251	1989	K29	<u>5329-988-7002</u>	72238
2800	DKS1160	11600	6L	260	1979	4LG	<u>5232-988-3202</u>	641229
2800	DKZE1160	11600	6L	300	1984	K361	<u>5336-988-6449</u>	292152
2800	DKS1160	11600	6L	300	1981	K361	<u>5336-988-6450</u>	641229
3300	DKX1160	11600	6L	310	1985	K361	<u>5336-988-6455</u>	292520
3300	DKX1160	11600	6L	330	1981	K361	<u>5336-988-6450</u>	664576
3300	DKX1160	11600	6L	330	1983	K361	<u>5336-988-6454</u>	274593
3600	DKZE1160	11600	6L	300	1984	K361	<u>5336-988-6449</u>	292152
3600	DKS1160	11600	6L	310	1981	K361	<u>5336-988-6451</u>	663516
400	XD3S	2500	4L			TAO302	<u>465318-0003</u>	192148
45	6BTA	5900	6L			H1C	<u>3525648</u>	492130
55	6BTA	5900	6L			H1C	<u>3531696</u>	3531456
55	6BTA	5900	6L			WH1C	<u>3536368</u>	3536421
55	6BTA	5900	6L			WH1C	<u>3536725</u>	3536726
55	6BT	5900	6L			HX35W	<u>3538626</u>	3538627
65CF.240	NS177M	6200	6L	240	1996	GT3776	<u>452197-0001</u>	1303582
75.240	RS180L	8660	6L	244	1994	TA4510	<u>466502-0001</u>	1249182
75.240	RS180L	8680	6L	240	1994	TA4510	<u>466502-0002</u>	1232972
75.270	RS200L	8660	6L	268	1994	TA4510	<u>466502-0001</u>	1249182
75.270	R200L	8660	6L	268	1994	TA4510	<u>466502-0002</u>	1232972
75.300	RS222L	8660	6L	268		TA4510	<u>466502-0002</u>	1232972

<b>75.300</b>	RS222L	8660	6L	301		TA4510	<u>466502-0001</u>	1249182
<b>75.300</b>	RS200L	8660	6L	301		TA4510	<u>466502-0003</u>	1259758
<b>75.300</b>	RS222L	8660	6L	301		TA4510	<u>466502-0004</u>	1271325
<b>85.300</b>	WS222L	11600	6L	300	1988	K33	<u>5333-988-6407</u>	079257
<b>85.300</b>	WS222L	11630	6L	300	1987	TA5130	<u>452070-0003</u>	1250750
<b>85.300</b>	WS222L	11630	6L	300		TA5130	<u>452070-0004</u>	1250884
<b>85.330</b>	WS242L	11600	6L	330	1987	TA5130	<u>452070-0003</u>	1250750
<b>85.330</b>	WS242L	11600	6L	330		TA5130	<u>452070-0004</u>	1250884
<b>85.330</b>	WS242L	11600	6L	330	1988	K33	<u>5333-988-6407</u>	079257
<b>85.360</b>	WS268L	11600	6L	360	1987	TA5130	<u>452070-0001</u>	1250650
<b>85.360</b>	WS268L	11600	6L	360		TA5130	<u>452070-0002</u>	1250882
<b>85.360</b>	WS268L	11600	6L	360	1988	K33	<u>5333-988-6407</u>	079257
<b>85.360</b>	WS268L	11600	6L	360	1989	K33	<u>5333-988-6410</u>	089878
<b>85.400</b>	WS295L	11600	6L	350	1989	K33	<u>5333-988-6410</u>	089878
<b>95.310</b>	WS315M	11600	6L	310	1987	TA5130	<u>452070-0007</u>	1284020
<b>95.310</b>	WS225	11600	6L	310	1987	K33	<u>5333-988-6406</u>	389901
<b>95.330</b>	WS242L	11600	6L	330	1987	TA5130	<u>452070-0003</u>	1250750
<b>95.330</b>	WS242L	11600	6L	330	1988	K33	<u>5333-988-6407</u>	079257
<b>95.350</b>	WS259	11600	6L	350	1987	K33	<u>5333-988-6406</u>	389901
<b>95.360</b>	WS268L	11600	6L	360	1988	K33	<u>5333-988-6407</u>	079257
<b>95.360</b>	WS268L	11600	6L	360	1989	K33	<u>5333-988-6410</u>	089878
<b>95.380</b>	WS282	11600	6L	380	1987	K33	<u>5333-988-6406</u>	389901
<b>95.400</b>	WS295	11600	6L	350	1989	K33	<u>5333-988-6410</u>	089878
<b>95.400</b>	WS295L	11600	6L	360	1991	K33	<u>5333-988-6415</u>	1239197
<b>95.400</b>	WS295L	11600	6L	400	1993	K33	<u>5333-988-6715</u>	1279827
<b>95.430</b>	WS315L	11600	6L	430	1991	K33	<u>5333-988-6711</u>	1262534
<b>95.430</b>	WS315L	11600	6L	430	1991	K33	<u>5333-988-6713</u>	1229626
<b>95XF</b>	XE390C	12600	6L		1999	GT4294S	<u>452281-0008</u>	1377426
<b>95XF</b>	XF280M	12600	6L		2000	GT4294S	<u>452281-0008</u>	1377426
<b>95XF.380</b>	XF315M	12600	6L	375	1999	GT4294S	<u>706844-0005</u>	1377427
<b>95XF.380</b>	XF280M	12600	6L	380	1997	GT4294S	<u>452229-0002</u>	1319283
<b>95XF.380</b>	XF280M	12600	6L	380	1997	GT4294	<u>452235-0003</u>	1319285
<b>95XF.420</b>	XF355M	12600	6L	420	1999	GT4294S	<u>452281-0006</u>	1377400
<b>95XF.425</b>	XE315C2	12600	6L	422	2001	GT4294S	<u>452281-0010</u>	1453883
<b>95XF.425</b>	XE315C0	12600	6L	426	2002	GT4294S	<u>706844-0006</u>	1609989
<b>95XF.430</b>	XE315	12580	6L	428	2001	K31	<u>5331-988-7124</u>	1398521
<b>95XF.430</b>	XE280	12580	6L	430	2001	K31	<u>5331-988-7124</u>	1398521
<b>95XF.430</b>	XF315M	12600	6L	430	1997	GT4294S	<u>452229-0001</u>	1319282
<b>95XF.430</b>	XF315M	12600	6L	430	1997	GT4294	<u>452235-0002</u>	1319284
<b>95XF.430</b>	XF280M	12600	6L	430	1997	GT4294	<u>706844-0001</u>	1362357



<b>95XF.430</b>	XF280M	12600	6L	430	1997	GT4294	<b>706844-0002</b>	1362358
<b>95XF.430</b>	XE315C	12600	6L	430	1999	GT4294S	<b>706844-0003</b>	1357830
<b>95XF.430</b>	XF315M	12600	6L	430	1999	GT4294	<b>706844-0004</b>	1377402
<b>95XF.475</b>	XE355C	12600	6L	475	2000	GT4294S	<b>452281-0008</b>	1377426
<b>95XF.475</b>	XF355M	12600	6L	475	2002	GT4294S	<b>452281-0013</b>	1609987
<b>95XF.475</b>	XE355C	12600	6L	475	2002	GT4594S	<b>721644-0002</b>	1448806
<b>95XF.480</b>	XE355	12580	6L	480	2001	K31	<b>5331-988-7124</b>	1398521
<b>95XF.480</b>	XF355M	12600	6L	480	1997	GT4294	<b>452235-0001</b>	1319281
<b>95XF.480</b>	XE390C	12600	6L	480	2002	GT4594S	<b>721644-0001</b>	1443766
<b>95XF.520</b>	XE390C	12600	6L	523	2000	GT4294S	<b>452281-0009</b>	1397101
<b>95XF.520</b>	XE390C0	12600	6L	523	2000	GT4294S	<b>452281-0014</b>	1609988
<b>95XF.530</b>	N14			530		BHT3E	<b>3536095</b>	3804308
<b>95XF.530</b>	XF355M	12600	6L	530	1999	GT4294	<b>452281-0008</b>	1337404
<b>BUS</b>	GG170 CNG	8600	6L			GT4082	<b>452207-0003</b>	1320059
<b>BUS</b>	GG170 LPG	8600	6L			GT4082	<b>452207-0003</b>	1320059
<b>BUS</b>	RG170	8600	6L		2000	GT3776	<b>709347-0002</b>	
<b>BUS</b>	RG170	8600	6L		2000	GT3776	<b>709347-0003</b>	
<b>BUS</b>	RT170L	8600	6L	227		TA45	<b>452188-0001</b>	1300737
<b>BUS</b>	GG170 LPG	8600	6L	231		GT4082	<b>452207-0001</b>	1320059
<b>BUS</b>	RG170 LPG	8600	6L	231		GT4082	<b>452207-0002</b>	1326680
<b>BUS</b>	GG170LPG	8600	6L	235	2000	GT4082	<b>452207-0006</b>	1387954
<b>BUS</b>	RG170	8600	6L	235	2000	GT4082	<b>452207-0007</b>	1387955
<b>BUS</b>	GS200L	8660	6L	271	1994	TA4510	<b>466502-0005</b>	1284658
<b>BUS</b>	NTG1160	11600	6L	285	1986	K33	<b>5333-988-6402</b>	389902
<b>BUS</b>	DKS1160	11600	6L	329	1987	K361	<b>5336-988-6460</b>	387964
<b>BUS</b>	DKS11600	11600	6L	380	1990	K361	<b>5336-988-6468</b>	95130
<b>CF65.310</b>	PE235C	9200	6L	308	2000	GT4088	<b>703457-0002</b>	1382393
<b>CF75.280</b>	PF205M	9200	6L	279	1997	GT4088	<b>452231-0002</b>	1314933
<b>CF75.300</b>	PE228C	9200	6L	305	2001	GT4088	<b>716703-0001</b>	1377662
<b>CF75.315</b>	PF235M	9200	6L	313	1997	GT4088	<b>452231-0001</b>	1311280
<b>CF75.355</b>	PE265C	9200	6L	355		GT4088	<b>452257-0005</b>	1398886
<b>CF85.340</b>	XF250M	12580	6L	340	1999	K31	<b>5331-988-7118</b>	1358390
<b>CF85.350</b>	XF280M	12600	6L	350	1999	GT4294S	<b>452281-0003</b>	1337406
<b>CF85.380</b>	XF280M	12600	6L	380	1997	GT4294	<b>452235-0003</b>	1319285
<b>CF85.430</b>	XF315M	12600	6L	430	1997	GT4294	<b>452235-0002</b>	1319284
<b>CF85.430</b>	XE315C2	12600	6L	430	2001	GT4294	<b>452281-0010</b>	1453883
<b>CF85.430</b>	XF315M	12600	6L	430	1999	GT4294	<b>706844-0004</b>	1377402
<b>CF85.475</b>	XE355C	12600	6L	475	2002	GT4594S	<b>721644-0002</b>	1448806
<b>F60</b>	NS133AG		6L		1993	TO4E11	<b>466780-0003</b>	538994

<b>F60</b>	NS133AG		6L		1993	TO4E11	<b>466780-0004</b>	638994
<b>F65.210</b>	NS156L	6200	6L	210	1993	TO4E11	<b>466780-0008</b>	1261575
<b>F85.430</b>	XF315M	12600	6L	430	1999	GT4294S	<b>452281-0002</b>	1337405
<b>F85.430</b>	XF250M	12600	6L	430	1999	GT4294	<b>706844-0004</b>	1377402
<b>F95.420</b>	XF355M	12600	6L	423	1999	GT4294S	<b>452281-0001</b>	1337404
<b>F95.430</b>	XF280M	12600	6L	430	1999	GT4294	<b>706844-0004</b>	1377402
<b>FA65.180</b>	NS156L	6200	6L	180	1990	TO4E11	<b>466780-0005</b>	1261575
<b>FA65.210</b>	NS156M	6200	6L	210	1993	TO4E11	<b>466780-0006</b>	1284626
<b>FA65.240</b>	NS177M	6200	6L	240	1996	GT3776	<b>452197-0001</b>	1303582
<b>FA95.360</b>	WS268L	11630	6L	359		TA5130	<b>452070-0001</b>	1250650
<b>FA95.360</b>	WS268L	11630	6L	360	1989	TA5130	<b>452070-0002</b>	1250882
<b>FA95.400</b>	WS295L	11630	6L	395		TA5130	<b>452070-0003</b>	1250750
<b>FA95.400</b>	WS295L	11630	6L	395		TA5130	<b>452070-0004</b>	1250884
<b>FA95.430</b>	WS315L	11630	6L	430	1987	TA5130	<b>452070-0001</b>	1250650
<b>FA95.430</b>	WS315L	11630	6L	430		TA5130	<b>452070-0002</b>	1250882
<b>FT95.330</b>	WS242L	11630	6L	324		TA5130	<b>452070-0003</b>	1250750
<b>FT95.330</b>	WS242L	11630	6L	324		TA5130	<b>452070-0004</b>	1250884
<b>SB220</b>	LT160L	11630	6L			TA5130	<b>452070-0005</b>	1270190
<b>SB220</b>	LT160L	11630	6L	217		TA5130	<b>452070-0009</b>	1298656
<b>SB2300</b>	DHS825	8270	6L	250		TA4503	<b>465942-0002</b>	657196
<b>SB2300</b>	DHS825	8270	6L	250		TA4503	<b>465942-0012</b>	657196
<b>TB2100</b>	DHT825	8270	6L			TA4503	<b>465942-0006</b>	679024
<b>TB2100</b>	DHT825	8270	6L			TA4503	<b>465942-0016</b>	
<b>TB2100</b>	DHT825	8270	6L			TA4510	<b>466502-0011</b>	298515
<b>TB2100</b>	DHT825	8270	6L	218		TA4503	<b>465942-0003</b>	656331
<b>TB2100</b>	DHT825	8270	6L	218		TA4503	<b>465942-0013</b>	370871

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

## APPLICATIONS

SUITABLE FOR:

## Hyundai

Model	Motor	CC	Nº of Cylinders	CV	Year	Model	Part Number	O.E.M Part Number
CHRORUS BUS	D4AE	3300	4L	100	1994	GT1749	<u>466501-0002</u>	28230-41401
CHRORUS BUS	D4AE	3300	4L	100	1995	GT1749	<u>466501-0003</u>	28230-41402
CHRORUS BUS	D4AE	3300	4L	100	1996	GT1749	<u>466501-0004</u>	28230-41411
CHRORUS BUS	D4AE	3300	4L	100	1998	GT1749	<u>466501-0005</u>	28230-41412
CHRORUS BUS	D4AE	3300	4L	100	1995	GT1749	<u>471037-0001</u>	28230-41421
CHRORUS BUS	D4AE	3300	4L	100	1998	GT1749	<u>471037-0002</u>	28230-41422
CHRORUS BUS	D4AL	3300	4L	100	1998	GT1749	<u>700917-0001</u>	28230-41650
CHRORUS BUS	D4AL	3300	4L	116	1999	GT1749	<u>708337-0001</u>	28230-41720
CHRORUS BUS	D4AL	3300	4L	120	1997	GT1749	<u>471189-0001</u>	28230-41601
CHRORUS BUS	D4AL	3300	4L	120	1999	GT1749	<u>708337-0002</u>	28230-41730
H350	D4AE	3298	4L	100	1998	GT1749LS	<u>466501-0005</u>	28230-41412
H350	D4AE	3298	4L	100	1995	GT1749LS	<u>471037-0001</u>	28230-41421
H350		3298	4L	100		GT2052S	<u>702213-0001</u>	28230-41710
H350	D4AL	3298	4L	100		GT1749	<u>708337-0001</u>	28230-41720
HD72	D4AL	3298	4L	115		GT20	<u>703389-0002</u>	28230-41431

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

## APPLICATIONS

SUITABLE FOR:

### Navistar

Model	Motor	CC	Nº of Cylinders	CV	Year	Model	Part Number	O.E.M Part Number
BUS	DT360			165		TO4E17	465225-0001	1810017C91
BUS	DTA360			180		TO4E17	465225-0002	1810018C91
BUS	DTA360			185	1991	TO4E17	465225-0011	1817529C91
BUS	DT466	7600	6L			TO4E17	465225-0004	1815677C91
BUS	DT466	7600	6L		1991	TO4E17	465225-0008	1817313C91
BUS	DT466	7600	6L			TO4E13	466772-0007	1817006C91
BUS	DT466	7600	6L	185	1991	TO4E17	465225-0014	1817796C91
BUS	DT466E	7600	6L	195	1991	TO4E17	465225-0008	1817313C91
BUS	DT466E	7600	6L	210	1991	TO4E17	<u>465225-0013</u>	1817531C91
BUS	DT466	7600	6L	210		TO4E17	<u>465225-0013</u>	1817531C91
CARGOSTAR	DT466	7600	6L			TO4B25	409770-0002	684335C91
CARGOSTAR	DT466	7600	6L			TO4B25	409770-0003	
CARGOSTAR	DT466B	7600	6L			TO4B25	409770-0003	
CARGOSTAR	DT466	7600	6L			TO4B25	<u>409770-0011</u>	684698C91
CARGOSTAR	DT466B	7600	6L			TO4B25	<u>409770-0011</u>	684698C91
CARGOSTAR	DT466B	7600	6L			TO4B25	<u>409770-0019</u>	1806078C91
CARGOSTAR	DT466	7600	6L			TO4B25	<u>409770-0019</u>	1806078C91

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.



## APPLICATIONS

SUITABLE FOR:

**Isuzu**

Model	Motor	CC	Nº of Cylinders	CV	Year	Model	Part Number	O.E.M Part Number
	4DB2	3856	4L	140	1994	TB2568	<u>466409-0002</u>	8-9710-561-80
<b>NQR SERIES</b>	4HE1XS	4750	4L	165	1998	TB28	<u>700716-0003</u>	8-9718-945-20
<b>NQR SERIES</b>	4HE1XS	4750	4L	165	1998	TB28	<u>700716-0004</u>	
<b>NQR SERIES</b>	4HE1XS	4750	4L	165	1998	TB28	<u>700716-0005</u>	8-9720-896-61
<b>NQR SERIES</b>	4HE1XS	4750	4L	165	2000	TB28	<u>700716-0006</u>	
<b>NQR SERIES</b>	4HE1XS	4750	4L	165	2001	TB28	<u>700716-0007</u>	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: [turbomaster@turbomaster.info](mailto:turbomaster@turbomaster.info).



## APPLICATIONS

SUITABLE FOR:

**Iveco**

Model	Motor	CC	Nº of Cylinders	CV	Year	Model	Part Number	O.E.M Part Number
	8140.27.215	2500	4L			TAO302	<u>465318-0009</u>	4843377
	8040.45.281	3910	4L	110		TAO318	<u>465379-0001</u>	483056
	8040.45.271	3910	4L	110		TAO318	<u>465379-0001</u>	483056
	8040.45.261	3910	4L	110		TAO318	<u>465379-0001</u>	483056
	8042.25.4980	3910	4L	115		TAO303	<u>465632-0007</u>	98444659
	8040.45.4000	3910	4L	180		TAO318	<u>465379-0004</u>	98412430
	8060.24.661	5500	6L	120		TO4B49	<u>465640-0008</u>	4769384
	8060.24.661	5500	6L	130		TO4B49	<u>465640-0021</u>	4769384
	8060.24.642	5500	6L	140		TO4B49	<u>465640-0012</u>	4797662
	8060.24.642	5500	6L	140		TO4B49	<u>465640-0026</u>	4797662
	8060.24.678	5500	6L	165		TO4B49	<u>465640-0025</u>	4774710
	8060.25.4740	5861	6L			TBP408	<u>465425-0003</u>	98465811
	8060.25.621	5861	6L	135		TO4B49	<u>465640-0014</u>	4810501
	8060.25.620	5861	6L	140		TO4B49	<u>465640-0014</u>	4810501
	8060.25.673	5861	6L	150		TO4B49	<u>465640-0014</u>	4810501
	8060.25.221	5861	6L	170		TO4E49	<u>465443-0001</u>	4840419
	8060.25.261	5861	6L	170		TO4E49	<u>465443-0001</u>	4840419
	8060.45.4100	5861	6L	204		TO4E46	<u>465413-0003</u>	4848629
	8062.45.685	5861	6L	220		TO4B49	<u>465640-0019</u>	4837822
	8062.45.668B	5861	6L	220		TO4B49	<u>465640-0019</u>	4837822
	8060.45.6000	5861	6L	224		TO4E46	<u>465413-0002</u>	4848508
	8365.26.512	8100	6L	202		TO4E28	<u>465523-0001</u>	
	8465.41.601	9498	6L	261		TA4511	<u>466652-0003</u>	61319205
	8210.42.3250	13798	6L			TA5126	<u>454003-0006</u>	99461011
	8210.42.300	13798	6L	360		TA5126	<u>454003-0007</u>	99481116
	8210.42K.351	13798	6L	370		TA5126	<u>454003-0005</u>	99439019
	8210.42	13798	6L	380		TBP4802	<u>465481-0002</u>	
	8210.42.3250	13798	6L	382		TA5126	<u>454003-0006</u>	99461011
	8210.42.380	13798	6L	400		TA5126	<u>454003-0003</u>	98429361
<b>110.17</b>	8060.25.600	5861	6L	176		TO4B49	<u>465640-0013</u>	4810230
<b>110.21</b>	8060.45.5100	5861	6L	277		TBP409	<u>465427-0005</u>	99467664
<b>110.21</b>	8060.45.5100	5861	6L	277		TBP409	<u>465427-0007</u>	500326409

115.17	8060.25.600	5861	6L	176		TO4B49	<u>465640-0013</u>	4810230
120.17	8060.25.600	5861	6L	176		TO4B49	<u>465640-0013</u>	4810230
120E23	8060.45.6000	5861	6L	225		TBP409	<u>465427-0002</u>	9841188
135.17	8060.25.600	5861	6L	176		TO4B49	<u>465640-0013</u>	4810230
145.17	8060.25.4700	5861	6L	174		TBP408	<u>465425-0001</u>	98467056
145.17	8060.25.4000	5861	6L	174		TBP408	<u>465425-0001</u>	98467056
150E27	8360.46	7680		265	1989	K27	<u>5327-988-7014</u>	4846402
165.24	8220.22	9700		231	1982	K28	<u>5328-988-7004</u>	61690016
165.24	8220.22	9700		240	1986	H2C	<b>3520546</b>	61690083
165.24	8220.21	9700		240	1985	H2C	<b>3521809</b>	61690054
165.24	8220.21	9700		240	1986	H2C	<b>3523134</b>	61690085
170.30	8210.22	13798	6L	300		4LGK	<b>55548</b>	4729471
170E18	8060.25.420	5861	6L	141		TO4E47	<u>465403-0004</u>	4848507
170E18	8060.25.400	5861	6L	174		TBP408	<u>465425-0001</u>	98467056
170E18	8060.45.410	5861	6L	204		TBP409	<u>465427-0001</u>	98440516
170F30	8210	13798	6L	304		4LGK	<b>3501756</b>	4729471
175.17	8060.25.4000	5861	6L	174		TBP408	<u>465425-0001</u>	98467056
175.17	8060.25.4700	5861	6L	174		TBP408	<u>465425-0001</u>	98467056
175.20	8060.45.4100	5861	6L	204		TBP409	<u>465427-0001</u>	98440516
175.20	8060.45.4300	5861	6L	204		TBP409	<u>465427-0001</u>	98440516
175.20	8060.45.4400	5861	6L	204		TBP409	<u>465427-0001</u>	98440516
175.24	8460.21.260	9498	6L	240		TA4511	<u>466652-0001</u>	61318301
175.24	8460.21	9500		240	1984	H2C	<u>3523022</u>	61317004
175.24	8460.21	9700		240	1986	H2C	<b>3523134</b>	61316026
180.22	8460.45.460	5500	6L	228		TBP409	<u>465427-0003</u>	98465538
180.24	8460.21	9700		240	1986	H2C	<b>3523134</b>	61315103
180E38	8460.41					HX50W	<u>3534355</u>	61320961
190.24	8460.21.200	9498	6L	240		TA4511	<u>466652-0001</u>	61318301
190.26	8460.21.102	9498	6L	261		TA4511	<u>466652-0001</u>	61318301
190.26	8460.21.601	9500		260	1984	H2C	<u>3523022</u>	61318577
190.30	8210.22.241	13798	6L	304	1984	4LGZ	<b>5232-988-3267</b>	4843781
190.30	8210.22.373	13798	6L	304	1981	4LGZ	<b>5232-988-3285</b>	4765164
190.30	8210.22.069	13798	6L	304	1984	4LGZ	<b>5232-988-3287</b>	4806062
190.32	8460.41.350	9498	6L	318		TA4510	<u>465563-0001</u>	61318777
190.32	8460.41.102	9498	6L	318		TA4510	<u>465563-0001</u>	61318777
190.32	8460.41.721	9498	6L	318		TA4510	<u>465563-0001</u>	61318777
190.32	8460.41.102	9500		320	1988	H2C	<b>3527457</b>	61319421
190.33	8210.22.101	13798	6L	330	1984	4LGK	<b>3523055</b>	4802316
190.33	8210.22	13798	6L	331	1984	4LGZ	<b>5232-988-3265</b>	4802317

<b>190.36</b>	8210.22.800	13798	6L	304		TA5126	<b><u>454003-0004</u></b>	
<b>190.36</b>	8210.42.103	13798	6L	360	1986	4LGK	<b>3525178</b>	98414561
<b>190.36</b>	8210.42K.351	13798	6L	360	1999	TA5126	<b>454003-0009</b>	50037231
<b>190.36</b>	8215.42.985	13798	6L	360	1999	TA5126	<b>454003-0011</b>	50037233
<b>190.36</b>	8210.22.170	13798	6L	370		H2D	<b><u>3530980</u></b>	98462946
<b>190.36</b>	8210.42.400	13798	6L	370		TA5126	<b><u>454003-0002</u></b>	4854264
<b>190.36</b>	8210.42.400	13798	6L	370	1999	TA5126	<b><u>454003-0008</u></b>	50037230
<b>190.38</b>	8220.22.000	17173	8V	380		TO4B05	<b>465468-0002</b>	8220.22.000
<b>190.38</b>	8280.22.009	17173	8V	380		TO4B05	<b>465468-0009</b>	8280.22.009
<b>190.38</b>	8280.22.009	17173	8V	380		TO4B05	<b>465468-0010</b>	8280.22.009
<b>190.38</b>	8220.22.000	17173	8V	380		TO4B05	<b>465468-0011</b>	4786457
<b>190.38</b>	8220.22.000	17173	8V	380		TO4B09	<b>465468-0012</b>	4786456
<b>190.38</b>	8280.22.000	17173	8V	380		TO4B05	<b>465468-0012</b>	4805335
<b>190.42</b>	8210.42.400	13798	6L	400		TA5126	<b><u>454003-0002</u></b>	4854264
<b>190.42</b>	8210.22.800	13798	6L	400		TA5126	<b><u>454003-0004</u></b>	
<b>190.42</b>	8210.42.400	13798	6L	400	1999	TA5126	<b><u>454003-0008</u></b>	50037230
<b>190.42</b>	8210.42K.351	13798	6L	420	1999	TA5126	<b>454003-0009</b>	50037231
<b>190.42</b>	8215.42.985	13798	6L	420	1999	TA5126	<b>454003-0011</b>	50037233
<b>190.42</b>	8280.22.205	17173	8V	420		TO4B05	<b><u>465468-0013</u></b>	4819794
<b>190.42</b>	8280.22.205	17173	8V	420		TO4B05	<b><u>465468-0014</u></b>	4819795
<b>190.42</b>	8280.22.205	17173	8V	420		TO4B05	<b><u>465468-0023</u></b>	4835337
<b>190.42</b>	8280.22	17173	8V	420	1985	K27	<b>5327-988-6038</b>	4787336
<b>190.42</b>	8280.22	17173	8V	420	1985	K27	<b>5327-988-6039</b>	4787337
<b>190.45T</b>	8280.42.300	17173	8V	450		TO4B05	<b><u>465468-0021</u></b>	4819893
<b>190.45T</b>	8280.42.300	17173	8V	450		TO4B05	<b><u>465468-0022</u></b>	4819892
<b>190.48</b>	8280.42	17173	8V	448	1988	K27	<b>5327-988-7009</b>	98471193
<b>190.48</b>	8280.42.300	17173	8V	476		TO4B05	<b><u>465468-0024</u></b>	4825119
<b>190.48</b>	8280.42.301	17173	8V	476		TO4B05	<b><u>465468-0025</u></b>	4825118
<b>190.48</b>	8280.42.001	17173	8V	480		TO4B05	<b><u>465468-0021</u></b>	4819893
<b>190.48</b>	8280.42.001	17173	8V	480		TO4B05	<b><u>465468-0022</u></b>	4819892
<b>190.48</b>	8280.42.050	17173	8V	512	1995	TO4E47	<b><u>454007-0003</u></b>	98435387
<b>190.48</b>	8280.42.050	17173	8V	512	1995	TO4E47	<b><u>454007-0004</u></b>	98435386
<b>190.52</b>	8280.42	17173	8V	512	1995	TO4E31	<b><u>454007-0005</u></b>	99465731
<b>190.52</b>	8280.42	17173	8V	512	1995	TO4E31	<b><u>454007-0006</u></b>	99465732
<b>190E15</b>	8060.45.4200	5861	6L	141		TO4E46	<b><u>465413-0004</u></b>	98474932
<b>190E15</b>	8060.25.400	5861	6L	143		TO4E47	<b><u>465403-0003</u></b>	98411632
<b>190E18</b>	8060.25.4700	5861	6L	174		TBP408	<b><u>465425-0001</u></b>	98467056
<b>190E18</b>	8060.25.4000	5861	6L	174		TBP408	<b><u>465425-0001</u></b>	98467056
<b>190E23</b>	8060.45.6280	5861	6L	225		TBP409	<b><u>465427-0002</u></b>	98441188



<b>190E23</b>	8060.45.6200	5861	6L	225		TBP409	<b><u>465427-0002</u></b>	98441188
<b>190E23</b>	8060.45.6000	5861	6L	225		TBP409	<b><u>465427-0002</u></b>	98441188
<b>190E23</b>	8060.45.6090	5861	6L	225		TBP409	<b><u>465427-0002</u></b>	98441188
<b>190E24</b>	8060.45.6280	5861	6L	225		TBP409	<b><u>465427-0002</u></b>	98441188
<b>190E24</b>	8060.45.6090	5861	6L	225		TBP409	<b><u>465427-0002</u></b>	98441188
<b>190E24</b>	8060.45.6200	5861	6L	225		TBP409	<b><u>465427-0002</u></b>	98441188
<b>190E24</b>	8060.45.6000	5861	6L	225		TBP409	<b><u>465427-0002</u></b>	98441188
<b>190E30</b>	8460.41			300		H2D	<b>3530536</b>	61318802
<b>190E42</b>	8210.42SPR	13798	6L	420		H3B	<b>3530555</b>	4863360
<b>190E47</b>	8210.45.5000	13798	6L	380		TO4B05	<b>465468-0001</b>	4732533
<b>190E48</b>	8210.42.5000	13798	6L	476		TBP4802	<b>465481-0001</b>	98429358
<b>190E52</b>	8280.42.320	17173	8V	512	1995	TO4E47	<b><u>454007-0001</u></b>	98439643
<b>190E52</b>	8280.42.350	17173	8V	512	1995	TO4E47	<b><u>454007-0002</u></b>	98439642
<b>240.26</b>	8460.21.106	9498	6L	261		TA4511	<b><u>466652-0001</u></b>	61318301
<b>240.36</b>	8210.22.101	13798	6L	360		TA5126	<b><u>454003-0001</u></b>	
<b>260.36</b>	8210.22.101	13798	6L	360		TA5126	<b><u>454003-0001</u></b>	
<b>280.36</b>	8210.22.101	13798	6L	360		TA5126	<b><u>454003-0001</u></b>	
<b>315.17</b>	8060.25.4600	5861	6L	177		TBP408	<b><u>465425-0002</u></b>	98421466
<b>330.26</b>	8460.21.202	9498	6L	261		TA4511	<b><u>466652-0001</u></b>	61318301
<b>330.33</b>	8210.22.101	13798	6L	330	1984	4LGK	<b>3523055</b>	4802316
<b>330.36</b>	8210.22.101	13798	6L	360		TA5126	<b><u>454003-0001</u></b>	
<b>330.36</b>	8210.42.269	13798	6L	370		H2D	<b><u>3530980</u></b>	98488950
<b>330.36</b>	8210.22.511	13798	6L	370		H2D	<b><u>3530980</u></b>	98462947
<b>370</b>	8460.41.406					WH2D	<b>3531856</b>	61320348
<b>370.24</b>	8460.21.709	9498	6L	240		TA4511	<b><u>466652-0001</u></b>	61318301
<b>370.24</b>	8460.21	9700		240	1986	H2C	<b>3523134</b>	61315102
<b>370.30</b>	8210.22.101	13798	6L	300	1984	4LGK	<b>3522460</b>	4797404
<b>370.30</b>	8210.22.406	13798	6L	304	1984	4LGK	<b>3501756</b>	4804154
<b>370E30</b>	8210.22.419	13798	6L	370		H2D	<b>3531669</b>	98462935
<b>370S24</b>	8460.21	9500		240		H2C	<b><u>3523022</u></b>	61315684
<b>400E34</b>	8460.41.406			340		WH2D	<b>3527078</b>	61318799
<b>400E38</b>				380		WH2D	<b>3527078</b>	61320348
<b>440E44</b>	8210.42.400	13798	6L	400		TA5126	<b><u>454003-0002</u></b>	4854264
<b>440E52</b>	8280.42.350	17173	8V	512	1995	TO4E31	<b><u>454007-0002</u></b>	98435387
<b>480.21</b>	8460.21.611	9498	6L	210		TO4E18	<b><u>465283-0001</u></b>	61217634
<b>480.21</b>	8460.21.615	9498	6L	217		TO4E18	<b><u>465283-0002</u></b>	61320425
<b>480.21</b>	8460.21.611	9498	6L	217		TO4E18	<b><u>465283-0003</u></b>	61320978
<b>490</b>	8360.46	7680		272	1994	K27	<b>5327-988-7017</b>	98499754
<b>490</b>	490	7680		272	1994	K27	<b>5327-988-7019</b>	99442005

<b>60E14</b>	8040.45.400	3910	4L	134	1991	TAO318	<b><u>465379-0003</u></b>	4848601
<b>65.12</b>	8040.25.220	3910	4L	102		TAO302	<b><u>465318-0007</u></b>	4810558
<b>65.12</b>	8040.25.230	3910	4L	115		TAO302	<b><u>465318-0008</u></b>	4810558
<b>65E10</b>	8040.45.4250	3900		115	1994	K24	<b>5324-988-6406</b>	99446020
<b>65E12</b>	8040.25.400	3910	4L	115		TAO303	<b><u>465632-0005</u></b>	4848509
<b>680.26</b>	8460.21.601	9498	6L	261		TA4511	<b><u>466652-0002</u></b>	61319193
<b>680.26</b>	8460.41.603	9498	6L	264		TBP4501	<b>454070-0001</b>	61320218
<b>75E14</b>	8040.45.4300	3900		136	1992	K24	<b>5324-988-6405</b>	99446021
<b>75E14</b>	8040.45.400	3910	4L	134	1991	TAO318	<b><u>465379-0003</u></b>	4848601
<b>75E15</b>	8460.41.406			350	1994	WH2D	<b><u>3532816</u></b>	92901386
<b>80.17</b>	8062.25.670	5861	6L	170		TO4B49	<b><u>465640-0015</u></b>	4812547
<b>BUS</b>	8460.21				1987	H1E	<b>3526031</b>	61317578
<b>BUS</b>	8060.24.678	5500	6L	165		TO4B49	<b>465640-0010</b>	4774710
<b>BUS</b>	8460.21	9500		220	1992	K28	<b>5328-988-6426</b>	8010923
<b>BUS</b>	8460	9500		220	1995	K28	<b>5328-988-6431</b>	8019187
<b>BUS</b>	8210.22.869	13798	6L		1986	4LGK	<b>3525692</b>	4824498
<b>BUS</b>	8210.22	13798	6L	310	1988	4LGK	<b>3526955</b>	98429819
<b>CURSOR</b>	F3A	0		440		HY55W	<b>3594875</b>	504003367
<b>E17</b>		3920	4L	162	2000	GT2259S	<b><u>702989-0003</u></b>	4891639
<b>EuroCargo</b>	8060TC	5861	6L	177	1995	K27	<b>5327-988-6451</b>	99446019
<b>EuroCargo</b>	8060.45.4400	5861	6L	204	1994	K27	<b>5327-988-6715</b>	99446017
<b>EuroStar</b>	8280.42	17173	8V	510	1995	K27	<b>5327-988-6707</b>	98435386
<b>TurboStar</b>	8280.22	17173	8V	380	1982	K27	<b>5327-988-6402</b>	4765151

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: [turbomaster@turbomaster.info](mailto:turbomaster@turbomaster.info).

**TurboMaster**

GARRETT TURBOS OFFICIAL DISTRIBUTOR FOR SPAIN

**Trucks** Catalog**APPLICATIONS**

SUITABLE FOR:

**Jianghuai**

Model	Motor	CC	Nº of Cylinders	CV	Year	Model	Part Number	O.E.M Part Number
	CYD	3860	4L	120	2001	TB2818	<b><u>702365-0009</u></b>	CY4102BZQ

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: [turbomaster@turbomaster.info](mailto:turbomaster@turbomaster.info).

## APPLICATIONS

SUITABLE FOR:

## Mack

Model	Motor	CC	Nº of Cylinders	CV	Year	Model	Part Number	O.E.M Part Number
	E9-700					TV8505	<b>466537-0002</b>	
	E4-210			210		TO4B88	<b>465744-0002</b>	355969
	EC6-250-2VH			250		TV7701	<b>465498-0015</b>	631GC5106-P15
	EMC6-250L			250		TB4501	<b>466398-0005</b>	631GC5117-P3
	EMC6-275L			275		TB4501	<b>466398-0005</b>	631GC5117-P3
	EME6-300L			300		TB4501	<b>466398-0018</b>	631GC5117-P14
	EME6-300L			300		TB4501	<b>466398-0019</b>	631GC5117-P15
	E6-335-4VH			335		TB4501	<b>466398-0013</b>	631GC5117-P13
	EE6-350			350		TB4501	<b>466398-0018</b>	631GC5117-P14
	EE6-350			350		TB4501	<b>466398-0019</b>	631GC5117-P15
	E9-450			450	1989	TV7124	<b>465779-0002</b>	631GC5101-P3
	E9-500			500	1989	TV7124	<b>465779-0002</b>	631GC5101-P3
	MIDR-060226	6180	6L	205		TO4E16	<b>466970-0002</b>	5.000.667.853
	MIDR-062045	9840	6L	230		TO4E23	<b>465569-0001</b>	5.000.670.900
	ENDT675	11010				TEO648	<b>406090-0005</b>	631GC439
	ENDT675	11010				TEO648	<b>406090-0010</b>	631GC439A
	ENDT675	11010				TEO648	<b>406090-0020</b>	631GC487-P1
	ENDT675	11010				TEO648	<b>406090-0021</b>	631GC487-P2
	ENDT675	11010				TEO648	<b>406090-0023</b>	631GC487-P4
	ENDT673	11010				TEO688	<b>406890-0001</b>	631GC436
	ENDT673	11010				TEO688	<b>406890-0002</b>	631GC436A
	ENDT673	11010				TEO688	<b>406890-0003</b>	631GC465
	ENDT673	11010				TEO688	<b>406890-0004</b>	631GC471
	ENDT673	11010				TEO688	<b>406890-0005</b>	631GC465A-P1
	ENDT711	11650				TEO688	<b>406890-0001</b>	631GC436
	ENDT711	11650				TEO688	<b>406890-0002</b>	631GC436A
	ENDT711	11650				TEO688	<b>406890-0003</b>	631GC465
	ENDT711	11650				TEO688	<b>406890-0004</b>	631GC471
	ENDT711	11650				TEO688	<b>406890-0005</b>	631GC465A-P1
	EE9-450	16400	8V	450	1989	TV7124	<b>465779-0004</b>	631GC5101-P5
	EE9-500	16400	8V	500	1989	TV7124	<b>465779-0004</b>	631GC5101-P5
	E9-530	16400	V8	530		BTV7502	<b>466449-0001</b>	631GC5136

E9-550

16400

V8

550

BTV7502

466449-0003

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: [turbomaster@turbomaster.info](mailto:turbomaster@turbomaster.info).



## APPLICATIONS

SUITABLE FOR:

## Mercedes Benz

Model	Motor	CC	Nº of Cylinders	CV	Year	Model	Part Number	O.E.M Part Number
	OM355A					TV6155	<a href="#"><u>465784-0001</u></a>	001 096 8999
	OM314A	3800	4L			TA3114	<a href="#"><u>465722-0004</u></a>	314 096 0499
	OM314A	3800	4L			TA3114	<a href="#"><u>465722-0005</u></a>	314 096 0599
	OM364A	4000	4L			TA3164	<a href="#"><u>466192-0005</u></a>	364 096 1299
	OM364LA	4000	4L			TA3164	<a href="#"><u>466192-0007</u></a>	364 096 1499
	OM364A	4000	4L			TA3164	<a href="#"><u>466192-0008</u></a>	364 096 1799
	OM364A	4000	4L			TA3164	<a href="#"><u>466192-0009</u></a>	364 096 1899
	OM364A	4000	4L	115		TA3164	<a href="#"><u>466192-0013</u></a>	
	OM364LA	4000	4L	135		TA3164	<a href="#"><u>466192-0014</u></a>	374 096 0099
	OM352A	5700	6L			TO4B27	<a href="#"><u>409300-0014</u></a>	352 096 7199
	OM352A	5700	6L			TO4B27	<a href="#"><u>409300-0015</u></a>	352 096 7299
	OM352A	5700	6L	150		TO4B27	<a href="#"><u>409300-0009</u></a>	352 096 3599
	OM352A	5700	6L	150		TO4B27	<a href="#"><u>409300-0012</u></a>	352 096 3699
	OM352A	5700	6L	168		TO4B27	<a href="#"><u>409300-0002</u></a>	352 096 1699
	OM352A	5700	6L	168		TO4B27	<a href="#"><u>409300-0007</u></a>	352 096 3399
	OM352A	5700	6L	168		TO4B27	<a href="#"><u>409300-0008</u></a>	352 096 3499
	OM352A	5700	6L	168		TO4B27	<a href="#"><u>409300-0013</u></a>	352 096 3799
	OM352A	5700	6L	168		TO4B27	<a href="#"><u>409300-0016</u></a>	352 096 4499
	OM352A	5700	6L	168		TO4B27	<a href="#"><u>409300-0017</u></a>	352 096 4599
	OM362A	5700	6L	192		TO4B81	<a href="#"><u>465366-0008</u></a>	362 096 6699
	OM362A	5700	6L	192		TO4B81	<a href="#"><u>465366-0009</u></a>	362 096 6799
	OM362A	5700	6L	192		TO4B81	<a href="#"><u>465366-0014</u></a>	362 096 1299
	OM366LA	6000	6L			TBP418	<a href="#"><u>452085-0001</u></a>	390 096 0099
	OM366LA	6000	6L			TBP418	<a href="#"><u>452085-0002</u></a>	366 096 6399
	OM366LA	6000	6L			TBP418	<a href="#"><u>452085-0003</u></a>	390 096 6499
	OM366LA	6000	6L			TO4B81	<a href="#"><u>465366-0018</u></a>	366 096 0799
	OM366LA	6000	6L			TO4B81	<a href="#"><u>465366-0023</u></a>	376 096 0099
	OM366LA	6000	6L			TO4B81	<a href="#"><u>465366-0024</u></a>	376 095 0399
	OM366LA	6000	6L			TO4E66	<a href="#"><u>466646-0003</u></a>	376 096 0199
	OM366LA	6000	6L			TO4E66	<a href="#"><u>466646-0004</u></a>	376 096 0299
	OM366LA	6000	6L			TO4E66	<a href="#"><u>466646-0007</u></a>	366 096 2599
	OM366LA	6000	6L			TO4E66	<a href="#"><u>466646-0009</u></a>	376 096 0599

	OM366LA	6000	6L			TO4E66	<b>466646-0010</b>	366 096 2399
	OM366LA	6000	6L			TO4E66	<b>466646-0011</b>	366 096 2499
	OM366LA	6000	6L			TO4E66	<b>466646-0013</b>	366 096 2999
	OM366LA	6000	6L			TO4E66	<b>466646-0015</b>	366 096 3199
	OM366LA	6000	6L			TO4E66	<b>466646-0016</b>	366 096 3299
	OM366LA	6000	6L		1991	TO4E66	<b>466646-0021</b>	376 096 0799
	OM366LA	6000	6L		1991	TO4E66	<b>466646-0022</b>	376 096 0899
	OM366LA	6000	6L			TO4E66	<b>466646-0029</b>	366 096 6799
	OM366LA	6000	6L			TO4E66	<b>466646-0030</b>	376 096 7099
	OM366LA	6000	6L			TO4E66	<b>466646-0031</b>	366 096 6899
	OM366A	6000	6L			TO4E66	<b>466646-0033</b>	375 096 7199
	OM366LA	6000	6L			TO4E66	<b>466646-0037</b>	
	OM366LA	6000	6L			TBP4	<b>466679-0001</b>	
	OM366A	6000	6L	167		TO4E66	<b>466646-0003</b>	376 096 0199
	OM366A	6000	6L	167		TO4E66	<b>466646-0004</b>	376 096 0299
	OM366A	6000	6L	167		TO4E66	<b>466646-0007</b>	366 096 2599
	OM366A	6000	6L	167		TO4E66	<b>466646-0009</b>	376 096 0599
	OM366A	6000	6L	167		TO4E66	<b>466646-0016</b>	366 096 3299
	OM449LA	10000	5L			GT4594	<b>465817-0001</b>	475 096 7999
	OM449LA	10000	5L			TA4521	<b>466618-0005</b>	
	OM449LA	10000	5L			TA4521	<b>466618-0007</b>	
	OM449LA	10000	5L	297		TA4521	<b>466618-0022</b>	004 096 3499
	OM441LA	11000	6V			TB4122	<b>466214-0036</b>	005 096 2399
	OM441LA	11000	6V			TB4122	<b>466214-0037</b>	005 096 2499
	OM441LA	11000	6V			TB4122	<b>466214-0038</b>	005 096 2599
	OM441LA	11000	6V			TB4122	<b>466214-0039</b>	005 096 2699
	OM447LA	12000	6L			TA5127	<b>466154-0012</b>	002 096 9999
	OM447LA	12000	6L			TA5127	<b>466154-0016</b>	004 096 1599
	OM447LA	12000	6L			TA5127	<b>466154-0018</b>	003 096 7299
	OM447LA	12000	6L			TA5127	<b>466154-0019</b>	004 096 2499
	OM447LA	12000	6L			TA5127	<b>466154-0021</b>	004 096 6999
	OM447HLA	12000	6L			TA5127	<b>466154-0024</b>	004 096 8299
	OM447LA	12000	6L			TA5127	<b>466154-0025</b>	004 096 8499
	OM447LA	12000	6L			TA5127	<b>466154-0026</b>	004 096 8699
	OM447LA	12000	6L	358		GT4594	<b>465823-0001</b>	476 096 7699
	OM447LA	12000	6L	358		GT4594	<b>465823-0002</b>	476 096 7899
	OM402LA	12700	8V			TB4122	<b>466214-0024</b>	004 096 4099
	OM402LA	12700	8V			TB4122	<b>466214-0025</b>	004 096 4199
	OM402LA	12700	8V			TB4122	<b>466214-0026</b>	004 096 4299

	OM402LA	12700	8V			TB4122	<a href="#">466214-0027</a>	004 096 4399
	OM402LA	12700	8V			TB4122	<a href="#">466214-0033</a>	004 096 5799
	OM402LA	12700	8V			TB4122	<a href="#">466214-0034</a>	004 096 7699
	OM422LA	14700	8V			TB4122	<a href="#">466214-0002</a>	002 096 4699
	OM422LA	14700	8V			TB4122	<a href="#">466214-0006</a>	003 096 2399
	OM422LA	14700	8V			TB4122	<a href="#">466214-0007</a>	003 096 2499
	OM422LA	14700	8V			TB4122	<a href="#">466214-0011</a>	003 096 7899
	OM422LA	14700	8V			TB4122	<a href="#">466214-0012</a>	003 096 7999
	OM422LA	14700	8V			TB4122	<a href="#">466214-0013</a>	003 096 9099
	OM422LA	14700	8V			TB4122	<a href="#">466214-0022</a>	004 096 2899
	OM422LA	14700	8V			TB4122	<a href="#">466214-0023</a>	004 096 2999
	OM422A	14700	8V			TB4122	<a href="#">466214-0028</a>	004 096 5299
	OM422LA	14700	8V			TB4122	<a href="#">466214-0028</a>	004 096 5299
	OM422A	14700	8V			TB4122	<a href="#">466214-0029</a>	004 096 5399
	OM422LA	14700	8V			TB4122	<a href="#">466214-0030</a>	004 096 5599
	OM422LA	14700	8V			TB4122	<a href="#">466214-0031</a>	004 096 5499
	OM422LA	14700	8V			TB4122	<a href="#">466214-0040</a>	005 096 3299
	OM422LA	14700	8V			TB4122	<a href="#">466214-0041</a>	005 096 3399
	OM442LA	14700	8V	500		TO4E42	<a href="#">465357-0001</a>	003 096 6899
	OM442LA	14700	8V	500		TO4E42	<a href="#">465357-0002</a>	003 096 6999
<b>1117</b>	OM366A	6000		165	1991	K27	<a href="#">5327-988-6444</a>	366 096 5299
<b>1117</b>	OM366A	6000		172	1988	K27	<a href="#">5327-988-6440</a>	366 096 0899
<b>1117</b>	OM366A	6000	6L	204	1992	K27	<a href="#">5327-988-6441</a>	366 096 1699
<b>1317</b>	OM366A	6000	6L	172	1988	K27	<a href="#">5327-988-6440</a>	366 096 1499
<b>1320</b>	OM366LA	6000	6L	204	1992	K27	<a href="#">5327-988-6446</a>	366 096 6599
<b>1324</b>	OM366LA	6000	6L	240	1991	K27	<a href="#">5327-988-6710</a>	366 096 5399
<b>1520</b>	OM366A	6000	6L	204	1985	K27	<a href="#">5327-988-6441</a>	376 096 0699
<b>1617</b>	OM352A	5700	6L	168		TO4B27	<a href="#">409300-0001</a>	352 096 1599
<b>1617</b>	OM352A	5700	6L	168		TO4B27	<a href="#">409300-0004</a>	352 096 2899
<b>1617</b>	OM352A	5700	6L	168		TO4B27	<a href="#">409300-0010</a>	352 096 3299
<b>1617</b>	OM352A	5700	6L	168	1975	TO4B27	<a href="#">409300-0011</a>	352 096 1599
<b>1617</b>	OM352A	5700	6L	168		TO4B27	<a href="#">409300-0023</a>	352 096 6099
<b>1617</b>	OM352A	5700	6L	168		TO4B27	<a href="#">409300-0024</a>	352 096 7599
<b>1617</b>	OM352A	5700	6L	168	1981	TO4B81	<a href="#">465366-0001</a>	352 096 4299
<b>1617</b>	OM352A	5700	6L	168	1984	TO4B81	<a href="#">465366-0007</a>	352 096 6399
<b>1617</b>	OM352A	5700	6L	168	1984	TO4B81	<a href="#">465366-0013</a>	352 096 4299
<b>1617</b>	OM352A	5700		168	1975	3LKS	<a href="#">5223-988-2870</a>	352 096 2999
<b>1617</b>	OM352A	5700		168	1973	3LKS	<a href="#">5223-988-2871</a>	352 096 2599
<b>1617</b>	OM352A	5700	6L	168	1980	K27	<a href="#">5327-988-6070</a>	352 096 4399



1617	OM352A	5700		170	1973	3LKY	5223-988-2500	352 096 1899
1617	OM352A	5700		170	1978	3LKS	5223-988-2872	352 096 5699
1617	OM352A	5700		170	1973	3LKS	5223-988-6000	352 096 5699
1617	OM352A	5700		170	1973	3LKS	5223-988-6001	352 096 7199
1617	OM352A	5700	6L	170	1982	K27	5327-988-6072	352 096 8299
1617	OM366A	6000	6L	168	1991	TO4E66	466646-0025	366 096 5299
1630	OM449LA	10000	5L	297		TA4521	466618-0006	
1633	OM422A	14600	8V	330	1984	K27	5327-988-6011	001 096 8199
1633	OM422A	14600	8V	330	1984	K27	5327-988-6016	002 096 5199
1633	OM422LA	14600	8V	330	1987	K27	5327-988-6201	002 096 6599
1633	OM422A	14600	8V	330	1987	K27	5327-988-6203	003 096 2099
1633	OM422A	14600	8V	330	1991	K27	5327-988-6206	003 096 5399
1633	OM422LA	14700	8V	330		TB4122	466214-0003	002 096 6799
1633	OM422LA	14700	8V	330		TB4122	466214-0004	002 096 8699
1633	OM422LA	14700	8V	330		TB4122	466214-0005	002 096 9199
1633	OM422A	14700	8V	330	1987	TB4122	466214-0008	003 096 2599
1633	OM422A	14700	8V	330	1980	TB4122	466214-0009	003 096 2699
1633	OM422A	14700	8V	330	1980	TB4122	466214-0010	003 096 2799
1633	OM422LA	14700	8V	330	1989	TB4122	466214-0014	004 096 0999
1633	OM422LA	14700	8V	330	1989	TB4122	466214-0015	004 096 1099
1633	OM422LA	14700	8V	330		TB4122	466214-0016	004 096 1899
1633	OM422LA	14700	8V	330	1989	TB4122	466214-0017	004 096 1999
1635	OM422LA	14600	8V	350	1987	K27	5327-988-6201	002 096 6699
1635	OM422LA	14600	8V	350	1987	K27	5327-988-6203	003 096 2199
1635	OM422LA	14600	8V	350	1991	K27	5327-988-6206	003 096 5499
1635	OM422LA	14700	8V	350	1987	TB4122	466214-0008	003 096 2599
1635	OM422LA	14700	8V	350	1980	TB4122	466214-0010	003 096 2799
1635	OM422LA	14700	8V	350		TB4122	466214-0018	004 096 1999
1635	OM422LA	14700	8V	350		TB4122	466214-0019	004 096 1999
1638	OM402LA	12700	8V	380		TB4122	466214-0032	004 096 5699
1720	OM366A	6000	6L		1984	H1E	3526590	352 096 5299
1733	OM441LA	11000	6V	330		TA4521	466618-0003	003 096 9699
1734	OM441LA	11000	6V	340		TA4521	466618-0003	003 096 9699
1734	OM441LA	11000	6V	340		TA4521	466618-0009	004 096 3499
1738	OM402LA	12700	8V	380		TB4122	466214-0032	004 096 5699
1820	OM366LA	6000	6L	177	1991	K27	5327-988-6710	366 096 4499
1827	OM401LA	9600	6V	270		TA4521	466618-0010	004 096 3499
1833	OM441LA	11000	6V	330		TA4521	466618-0003	003 096 9699
1833	OM441LA	11000	6V	330		TA4521	466618-0009	004 096 3499
1834	OM441LA	11000	6V	325	1987	K29	5329-988-7001	004 096 3599

<b>1834</b>	OM441LA	11000	6V	340		TA4521	<b><u>466618-0003</u></b>	003 096 9699
<b>1834</b>	OM441LA	11000	6V	340		TA4521	<b><u>466618-0009</u></b>	004 096 3499
<b>1935</b>	OM447LA	12000	6L	350		TA5127	<b><u>466154-0031</u></b>	476 096 7499
<b>1941</b>	OM447LA	12000	6L	410		TA5127	<b><u>466154-0015</u></b>	003 096 7399
<b>1941</b>	OM447LA	12000	6L	410		TA5127	<b><u>466154-0031</u></b>	476 096 7499
<b>1944</b>	OM442LA	14600	8V	440	1987	K27	<b><u>5327-988-6424</u></b>	003 096 0099
<b>1944</b>	OM442LA	14600	8V	440	1991	K27	<b><u>5327-988-6425</u></b>	003 096 0899
<b>1948</b>	OM442LA	14600	8V	440	1987	K27	<b><u>5327-988-6424</u></b>	003 096 0199
<b>1948</b>	OM442LA	14600	8V	440	1991	K27	<b><u>5327-988-6425</u></b>	003 096 7699
<b>1948</b>	OM442LA	14700	8V	480	1991	K27	<b><u>5327-988-6606</u></b>	004 096 0799
<b>1950</b>	OM442LA	14700	8V	503	1990	K27	<b><u>5327-988-6502</u></b>	004 096 6099
<b>2433</b>	OM441LA	11000	6V	330		TA4521	<b><u>466618-0003</u></b>	003 096 9699
<b>2433</b>	OM441LA	11000	6V	330		TA4521	<b><u>466618-0009</u></b>	004 096 3499
<b>2434</b>	OM441LA	11000	6V	340		TA4521	<b><u>466618-0003</u></b>	003 096 9699
<b>2434</b>	OM441LA	11000	6V	340		TA4521	<b><u>466618-0009</u></b>	004 096 3499
<b>2527</b>	OM401LA	9600	6V	270		TA4521	<b><u>466618-0010</u></b>	004 096 3499
<b>2533</b>	OM441LA	11000	6V	330		TA4521	<b><u>466618-0003</u></b>	003 096 9699
<b>2533</b>	OM441LA	11000	6V	330		TA4521	<b><u>466618-0009</u></b>	004 096 3499
<b>2534</b>	OM441LA	11000	6V	340		TA4521	<b><u>466618-0003</u></b>	003 096 9699
<b>2534</b>	OM441LA	11000	6V	340		TA4521	<b><u>466618-0009</u></b>	004 096 3499
<b>3850</b>	OM423LA	18300		500	1984	K28	<b><u>5328-988-6420</u></b>	002 096 5999
<b>711D</b>	OM364LA	4000	4L	104	1994	K16	<b><u>5316-988-6401</u></b>	364 096 4999
<b>711D</b>	OM364LA	4000	4L	104	1994	K16	<b><u>5316-988-6402</u></b>	364 096 5099
<b>711D</b>	OM364LA	4000	4L	104	1994	K16	<b><u>5316-988-6734</u></b>	374 096 0299
<b>711D</b>	OM364A	4000	4L	107	1991	K24	<b><u>5324-988-6404</u></b>	364 096 3199
<b>711D</b>	OM364A	4000	4L	107	1993	K24	<b><u>5324-988-6410</u></b>	364 096 4699
<b>711D</b>	OM364LA	4000	4L	136	1987	K24	<b><u>5324-988-6703</u></b>	364 096 0499
<b>711D</b>	OM364LA	4000	4L	138	1992	K24	<b><u>5324-988-6705</u></b>	364 096 3299
<b>712 ATEGO</b>	OM904LA	4250	4L	121	1996	GT2259	<b><u>452214-0003</u></b>	904 096 0799
<b>811</b>	OM364A	4000	4L	116	1992	K24	<b><u>5324-988-6010</u></b>	364 096 0399
<b>814D</b>	OM364LA	4000	4L	104	1994	K16	<b><u>5316-988-6401</u></b>	364 096 4999
<b>814D</b>	OM364LA	4000	4L	104	1994	K16	<b><u>5316-988-6402</u></b>	364 096 5099
<b>814D</b>	OM364LA	4000	4L	104	1994	K16	<b><u>5316-988-6734</u></b>	374 096 0299
<b>814D</b>	OM364LA	4000	4L	136	1987	K24	<b><u>5324-988-6703</u></b>	364 096 0999
<b>814D</b>	OM364LA	4000	4L	138	1991	K24	<b><u>5324-988-6705</u></b>	364 096 2399
<b>815 ATEGO</b>	OM904LA	4250	4L	135	1996	GT2259	<b><u>452214-0003</u></b>	904 096 0799
<b>ACTROS</b>	OM501LA	11950		428	2002	K31	<b><u>5331-988-7104</u></b>	008 096 0799
<b>ACTROS</b>	OM501LA	11950		428		K31	<b><u>5331-988-7127</u></b>	008 096 5999
<b>ACTROS</b>	OM501LA	11950		456	2001	K31	<b><u>5331-988-7106</u></b>	008 096 2199
<b>ACTROS</b>	OM501LA	11950		456	2002	K31	<b><u>5331-988-7128</u></b>	008 096 6099

<b>ATEGO</b>	OM906LA			275	2001	K27	<b>5327-988-7120</b>	906 096 4699
<b>AXOR</b>	OM457LA	11970			2001	S410	<b>318932</b>	008 096 5099
<b>AXOR</b>	OM457LA	11970			2001	S410	<b>318960</b>	008 096 2699
<b>BUS</b>	M906LAG			228	2002	K27	<b>5327-988-7122</b>	906 096 4499
<b>BUS</b>	OM906LA			280	2001	K27	<b>5327-988-7136</b>	906 096 5899
<b>BUS</b>	OM926LA			322	2001	K27	<b>5327-988-7116</b>	926 096 0699
<b>BUS</b>	OM360A	8700		210	1978	K28	<b>5328-988-7083</b>	001 096 7899
<b>BUS</b>	OM360A	8700		210	1980	K28	<b>5328-988-7085</b>	001 096 9799
<b>BUS</b>	OM447HLA	12000	6L	299	1994	K31	<b><u>5331-988-6800</u></b>	005 096 3599
<b>CITARO</b>	OM906HLA			275	2001	K27	<b>5327-988-7129</b>	906 096 5299
<b>CITARO</b>	OM906LA			275	2001	K27	<b><u>5327-988-7130</u></b>	906 096 5399
<b>CITARO</b>	OM906HLA			275	2001	K27	<b>5327-988-7137</b>	906 096 6099
<b>CITY BUS</b>	OM906LAG			228	2002	K27	<b>5327-988-7128</b>	906 096 6599
<b>CITY BUS</b>	OM906LA			275	2000	K27	<b><u>5327-988-7115</u></b>	906 096 4199
<b>CITY BUS</b>	OM904LA			275	2001	K27	<b>5327-988-7138</b>	906 096 6499
<b>CITY BUS</b>	OM906LAG			275	2003	K27	<b>5327-988-7156</b>	906 096 6599
<b>O404</b>	OM441LA	11000	6V			TA4521	<b><u>466618-0015</u></b>	004 096 5999
<b>O404</b>	OM441LA	11000	6V			TA4521	<b><u>466618-0027</u></b>	004 096 6799
<b>O405</b>	OM447HA	12000	6L	250	1991	K28	<b>5328-988-6800</b>	004 096 7099

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

## APPLICATIONS

SUITABLE FOR:

### Mitsubishi

Model	Motor	CC	Nº of Cylinders	CV	Year	Model	Part Number	O.E.M Part Number
	6D16-T			218		TO4E58	<b>479008-0001</b>	
	6D16-T			220		TO4E61	<b>479011-0001</b>	
	6D16-T			242		TBP422	<b>479004-0001</b>	
CANTER						TFO35	<b>49135-03300</b>	MD202879
CANTER						TFO35	<b>49135-03610</b>	
CANTER						TDO5	<b>49178-02115</b>	ME013458
CANTER						TDO5	<b>49178-02300</b>	
CANTER						TDO5	<b>49178-02385</b>	ME014881
CANTER	4D31T					TDO6	<b>49179-00200</b>	ME013717
CANTER	4D31T					TDO6	<b>49179-00210</b>	ME013714
CANTER	6D31					TDO6	<b>49179-00240</b>	ME083527
CANTER						TDO6H	<b>49179-00251</b>	ME083572

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: [turbomaster@turbomaster.info](mailto:turbomaster@turbomaster.info).

## APPLICATIONS

SUITABLE FOR:

## Nissan

Model	Motor	CC	Nº of Cylinders	CV	Year	Model	Part Number	O.E.M Part Number
	TD27Ti	2700	4L	115	1999	GT1544	<b>705668-0001</b>	
	D620X	13070		435		GT4594	<b>703654-0003</b>	
	GE13	13070		435		GT4594	<b>703654-0007</b>	
	GE13	13070		435		GT4594	<b>703654-0008</b>	
	GE13	13070		435		GT4594	<b>703654-0009</b>	
	GE13	13070		435		GT4594	<b>703654-0010</b>	
	GE13	13070		435		GT4594	<b>703654-0011</b>	
	GE13	13070		435		GT4594	<b>703654-0013</b>	
<b>L35</b>	BD-30 Ti	3000	4L	115	2002	GT2252S	<b>709693-0001</b>	14411-69T60
<b>L60</b>	B4-40 Ti	3000	4L		1996	TB25	<b>452129-0001</b>	14411-D8701
<b>L60</b>	B4-40 Ti	3000	4L		2000	TB25	<b>452129-0002</b>	14411-D8702
<b>L60</b>	B4-40 Ti	3000	4L		2001	TB25	<b>452129-0003</b>	14411-D8703
<b>L70</b>	B4-40 Ti	3000	4L		1996	TB25	<b>452129-0001</b>	14411-D8701
<b>L70</b>	B4-40 Ti	3000	4L		2000	TB25	<b>452129-0002</b>	14411-D8702
<b>L70</b>	B4-40 Ti	3000	4L		2001	TB25	<b>452129-0003</b>	14411-D8703
<b>L80</b>	B4-40 Ti	3000	4L		1996	TB25	<b>452129-0001</b>	14411-D8701
<b>L80</b>	B4-40 Ti	3000	4L		2000	TB25	<b>452129-0002</b>	14411-D8702
<b>L80</b>	B4-40 Ti	3000	4L		2001	TB25	<b>452129-0003</b>	14411-D8703
<b>M100</b>	BD-30 Ti	3000	4L	108	1996	GT2252	<b>452187-0001</b>	14411-59T00
<b>M100</b>	BD-30 Ti	3000	4L	108	1997	GT2252	<b>452187-0006</b>	14411-69T00
<b>M110</b>	MT-36 Ti	5985	6L	209		GT3271S	<b>452203-0002</b>	14411-D8802
<b>M115</b>	MT-36 Ti	5985	6L	209		GT3271S	<b>452203-0001</b>	14411-D8801
<b>M130</b>	MT-36 Ti	5985	6L	209		GT3271S	<b>452203-0001</b>	14411-D8801
<b>M130</b>	MT-36 Ti	5985	6L	209		GT3271S	<b>452203-0002</b>	14411-D8802
<b>M150</b>	MT-36 Ti	5985	6L	209		GT3271S	<b>452203-0001</b>	14411-D8801
<b>M210</b>	B6-60 Ti	5985	6L			GT3267	<b>706705-0001</b>	
<b>TL18</b>	TD27T	2700	4L	90	2001	GT2052S	<b>715645-0002</b>	14411-G2408
<b>TL18</b>	TD27T	2700	4L	95	2001	TB2580	<b>703605-0001</b>	14411-G2405
<b>TL18</b>	TD27T	2700	4L	95	2001	TB2580	<b>703605-0002</b>	14411-G2402
<b>TL18</b>	TD27T	2700	4L	95	2001	TB2580	<b>703605-0003</b>	14411-G2407

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

## APPLICATIONS

SUITABLE FOR:

## Pegaso

Model	Motor	CC	Nº of Cylinders	CV	Year	Model	Part Number	O.E.M Part Number
	9135					TO4B49	<u>465640-0002</u>	635742
	9135					TO4B49	<u>465640-0003</u>	740503
	9135					TO4B49	<u>465640-0018</u>	
	9220	6550	6L			TO4B34	<u>465070-0005</u>	647933
	9220	6550	6L			TO4B34	<u>465070-0010</u>	771443
	9222	10518	6L			TA4502	<u>465922-0014</u>	
	9156	11945	6L			TV6121	<u>465196-0001</u>	646954
	86T1DX	11945	6L			TA5101	<u>466074-0013</u>	772803
	96TIDY	11945	6L	347		TA5101	<u>466074-0014</u>	772008
	9180	11945	6L	347		TA5101	<u>466074-0014</u>	772008
	96R1BZ	11945	6L	360		TA5101	<u>466074-0016</u>	772820
<b>1217</b>	94T1BX	6550	6L	170		TO4B34	<u>465070-0010</u>	771443
<b>1226</b>	95R1AX	10518	6L	258		TA4533	<u>465145-0001</u>	
<b>1234</b>	96R1AX	11945	6L	340		TA5101	<u>466074-0014</u>	772008
<b>1236</b>	96R1EX	11945	6L	360		TA5101	<u>466074-0017</u>	
<b>1237</b>	96R1EX	11946	6L	367		TA5101	<u>466074-0021</u>	
<b>1326</b>	95R1AX	10518	6L	258		TA4533	<u>465145-0001</u>	
<b>1334</b>	96R1AX	11945	6L	340		TA5101	<u>466074-0014</u>	772008
<b>1336</b>	96R1EX	11945	6L	360		TA5101	<u>466074-0017</u>	
<b>1337</b>	96R1EX	11946	6L	367		TA5101	<u>466074-0021</u>	
<b>1436</b>	96R1BX	11945	6L	360		TA5101	<u>466074-0017</u>	
<b>1436</b>	96R1EX	11945	6L	360		TA5101	<u>466074-0017</u>	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

**TurboMaster**

GARRETT TURBOS OFFICIAL DISTRIBUTOR FOR SPAIN

**Trucks** Catalog**APPLICATIONS**

SUITABLE FOR:

**Raba**

Model	Motor	CC	Nº of Cylinders	CV	Year	Model	Part Number	O.E.M Part Number
TLL206	D10	10350		276		TA4544	<b>452169-0001</b>	645554
TLL235	D10	10350		315		TA4544	<b>452169-0001</b>	645554
UTLL206	D10	10350		276		TA4544	<b>452169-0001</b>	645554
UTSLL	D10UTS	10390		255		TO4E38	<b><u>452092-0002</u></b>	637182

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: [turbomaster@turbomaster.info](mailto:turbomaster@turbomaster.info).





## APPLICATIONS

SUITABLE FOR:

**Renault**

Model	Motor	CC	Nº of Cylinders	CV	Year	Model	Part Number	O.E.M Part Number
	MIDR-081008			300		TA4515	<b>466866-0001</b>	
	MIDR-060226	6180	6L	193		TO4E16	<b>466970-0007</b>	5.000.683.535
	MIDR-060226	6180	6L	197		TO4E16	<b>466970-0006</b>	5.000.676.961
	MIDR-060226	6180	6L	204		TO4E16	<b>466970-0001</b>	5.000.667.718
	MIDR-060226	6180	6L	247		TO4E27	<b>454018-0001</b>	5.000.138.961
	MIDR-060226	6180	6L	247		TO4E16	<b>466970-0008</b>	5.000.138.559
	MIDR-062030	8820	6L	219		TO4E50	<b>465463-0001</b>	5.000.679.290
	MIDR-062030	8820	6L	250		TO4E50	<b>465463-0001</b>	5.000.679.290
	MIDS-062030	8820	6L	250		TO4E06	<b>466616-0006</b>	5.000.679.290
	MIDR-062045	9840	6L			TBP440	<b>454090-0003</b>	
	MIDR-062045	9840	6L	272		TO4E10	<b>466742-0007</b>	5.000.670.900
<b>AE380</b>	MIDR-063540	12000	6L	352	1988	S3A	<b>311614</b>	5.000.678.530
<b>AE380</b>	MIDR-063540	12000	6L	352	1988	S3A	<b>311825</b>	5.000.678.436
<b>AE380</b>	MIDR-063540	12000	6L	380	1990	S3A	<b>312227</b>	5.000.678.568
<b>AE380</b>	MIDR-063540	12000	6L	380	1990	S3A	<b>312295</b>	5.000.678.568
<b>AE380</b>	MIDR-063540	12000	6L	380	1990	S3A	<b>312296</b>	5.000.289.500
<b>AE380</b>	MIDR-063540	12000	6L	380	1990	S3A	<b>312297</b>	5.000.678.570
<b>AE380</b>	MIDR-063540	12000	6L	380	1990	S3A	<b>312298</b>	5.000.289.500
<b>AE385</b>	MIDR-063540	12000	6L	380	1992	S3B	<b>313427</b>	5.001.821.926
<b>AE385</b>	MIDR-063540	12000		380		S3B	<b>313443</b>	5.001.821.926
<b>AE385TI</b>	MIDR-062045	9840	6L	327	1992	S2C	<b>313229</b>	5.000.694.051
<b>AE385TI</b>	MIDR-062045	9840	6L	327	1992	S2C	<b>313526</b>	5.000.694.051
<b>AE385TI</b>	MIDR-063540	12000	6L		1992	S3B	<b>313216</b>	5.000.693.083
<b>AE385TI</b>	MIDR-063540	12000	6L	420	1992	S3B	<b>313217</b>	5.000.693.084
<b>AE385TI</b>	MIDR-063540	12000	6L	420	1992	S3B	<b>313418</b>	5.000.693.083
<b>AE420</b>	MIDR-063540	12000	6L		1990	S3B	<b>312671</b>	5.000.678.663
<b>AE420</b>	MIDR-063540	12000	6L	420	1990	S3B	<b>312432</b>	5.000.676.663
<b>AE420TI</b>	MIDR-062045	9840	6L	327	1992	S2C	<b>313229</b>	5.000.649.051
<b>AE420TI</b>	MIDR-062045	9840	6L	327	1992	S2C	<b>313526</b>	5.000.694.051
<b>AE420TI</b>	MIDR-063540	12000	6L	420		S3B	<b>313216</b>	5.001.824.439
<b>AE420TI</b>	MIDR-063540	12000	6L	420	1992	S3B	<b>313217</b>	5.001.824.439
<b>AE420TI</b>	MIDR-063540	12000	6L	420	1992	S3B	<b>313418</b>	5.001.824.439
<b>AE500</b>	EE9-502	16400	8V	500		TV7124	<b>465779-0003</b>	5.000.293.295

<b>AE520</b>	EE9-530	16400	8V	530		BTV7502	<b><u>466449-0001</u></b>	5.001.822.936
<b>C200</b>	MIDR-060212	5490	6L			TO4B47	<b><u>465610-0009</u></b>	5.000.790.573
<b>C290</b>	MIDR-062045	9840	6L	320	1986	H2C	<b>3524695</b>	5.000.249.763
<b>CBH320</b>	MIDR-063540	12000	6L	319	1992	S3B	<b>313214</b>	5.000.693.081
<b>CBH320</b>	MIDR-063540	12000	6L	319	1992	S3B	<b>313215</b>	5.000.693.082
<b>CBH320</b>	MIDR-063540	12000	6L	319	1992	S3B	<b>313417</b>	5.000.693.082
<b>CM400</b>	MIDR-062045	9840	6L	230		TO4E23	<b><u>465569-0001</u></b>	5.000.670.900
<b>CS200P</b>	MIDR-060212	5490	6L	177		TO4B47	<b><u>465610-0005</u></b>	5.000.790.848
<b>CS200P</b>	MIDR-060212	5490	6L	177		TO4B47	<b><u>465610-0005</u></b>	5.000.790.848
<b>CS250</b>	MIDR-060212	5490	6L			TO4B47	<b><u>465610-0009</u></b>	5.000.790.573
<b>CS300T</b>	MIDR-062030	8820	6L	215		TO4B39	<b><u>409200-0014</u></b>	5.000.790.860
<b>CS400</b>	MIDR-060212	5490	6L	175		TO4B47	<b><u>465610-0011</u></b>	5.000.790.848
<b>DG260</b>	MIDS-062045	9840	6L	265		TA4505	<b><u>466200-0021</u></b>	5.000.681.435
<b>DG260</b>	MIDR-062045	9840	6L	285		TA4505	<b><u>466200-0004</u></b>	5.000.790.606
<b>DG290</b>	MIDR-062045	9840	6L	285		TA4505	<b><u>466200-0015</u></b>	5.000.670.512
<b>DG320</b>	MIDR-062045	9840	6L	319	1989	S3A	<b><u>312250</u></b>	5.000.681.665
<b>G200</b>	MIDR-060226	6180	6L		1989	S2B	<b>311014</b>	5.000.667.854
<b>G200</b>	MIDR-060226	6180	6L			S2B	<b>312246</b>	5.000.249.827
<b>G200</b>	MIDR-060226	6180	6L	205		TO4E16	<b><u>466970-0002</u></b>	5.000.667.853
<b>G210</b>	MIDR-060212	5490	6L			TO4B39	<b>409200-0013</b>	5.000.249.657
<b>G230</b>	MIDR-060212	5490	6L			TO4B39	<b>409200-0001</b>	28173053
<b>G230</b>	MIDR-060212	5490	6L			TO4B39	<b>409200-0004</b>	28173062
<b>G230</b>	MIDR-060212	5490	6L			TO4B39	<b>409200-0005</b>	28173063
<b>G230</b>	MIDR-060212	5490	6L			TO4B39	<b>409200-0006</b>	5.000.783.680
<b>G230</b>	MIDR-060212	5490	6L			TO4B39	<b>409200-0013</b>	5.000.790.859
<b>G230</b>	MIDR-060212	5490	6L	215		TO4B39	<b><u>409200-0007</u></b>	5.000.785.927
<b>G230TI</b>	MIDR-060226	6180	6L			S2B	<b>311014</b>	5.000.249.829
<b>G230TI</b>	MIDR-060226	6180	6L			S2B	<b>312246</b>	5.000.667.854
<b>G260</b>	MIDR-062045	9840	6L			TA4505	<b>466200-0018</b>	5.000.681.116
<b>G260</b>	MIDR-062045	9840	6L	265		TA4505	<b><u>466200-0001</u></b>	5.000.789.400
<b>G260</b>	MIDS-062045	9840	6L	265		TA4505	<b><u>466200-0011</u></b>	5.000.789.400
<b>G260</b>	MIDR-062045	9840	6L	285		TA4505	<b><u>466200-0003</u></b>	5.000.790.607
<b>G270</b>	MIDR-062045	9840	6L			H1E	<b>3530811</b>	5.000.686.900
<b>G280</b>	MIDR-062045	9840	6L			TA4505	<b>466200-0018</b>	5.000.681.116
<b>G280</b>	MIDR-062045	9840	6L	285	1978	K28	<b>5328-988-6602</b>	5.000.787.416
<b>G280</b>	MIDS-062045	9840	6L	285	1980	K28	<b>5328-988-6702</b>	5.000.786.041
<b>G290</b>	MIDR-062045	9840	6L	280		TA4505	<b><u>466200-0001</u></b>	5.000.789.400
<b>G290</b>	MIDR-062045	9840	6L	280		TA4505	<b><u>466200-0002</u></b>	5.000.789.763
<b>G290</b>	MIDR-062045	9840	6L	280		TA4505	<b><u>466200-0011</u></b>	5.000.789.400
<b>G290</b>	MIDR-062045	9840	6L	280		TA4505	<b><u>466200-0012</u></b>	5.000.789.673

<b>G290</b>	MIDR-062045	9840	6L	280		TA4505	<b><u>466200-0013</u></b>	5.000.790.607
<b>G290</b>	MIDR-062045	9840	6L	280		TA4505	<b><u>466200-0014</u></b>	5.000.790.606
<b>G290</b>	MIDR-062045	9840	6L	284		TA4505	<b><u>466200-0016</u></b>	5.000.670.627
<b>G290</b>	MIDR-062045	9840	6L	285		TA4505	<b><u>466200-0003</u></b>	5.000.790.607
<b>G290</b>	MIDR-062045	9840	6L	285		TA4505	<b><u>466200-0004</u></b>	5.000.790.606
<b>G290</b>	MIDR-062045	9840	6L	285		TA4505	<b><u>466200-0017</u></b>	5.000.670.720
<b>G290</b>	MIDR-062045	9840	6L	285	1980	K28	<b>5328-988-6602</b>	5.000.786.741
<b>G290</b>	MIDS-062045	9840	6L	285	1978	K28	<b>5328-988-6602</b>	5.000.787.415
<b>G300</b>	MIDR-062045	9840	6L			H1E	<b>3530812</b>	5.000.686.741
<b>G320</b>	MIDR-062045	9840	6L	319	1989	S3A	<b><u>312250</u></b>	5.000.681.664
<b>G340TI</b>	MIDR-062045	9840	6L	319	1992	S2C	<b>313090</b>	5.000.694.050
<b>G340TI</b>	MIDR-062045	9840	6L	319	1992	S2C	<b>313529</b>	5.000.694.050
<b>GS400</b>	MIDR-062045	9840	6L	273		TA4505	<b><u>466200-0020</u></b>	5.000.681.082
<b>M160</b>	MIDS-060212					TO4B47	<b>465610-0012</b>	5.000.138.387
<b>M160</b>	MIDR-060212	5500			1986	TO4B47	<b>465610-0006</b>	5.000.134.530
<b>M160</b>	MIDR-060212	5500	6L			TO4B47	<b><u>465610-0009</u></b>	5.000.790.573
<b>M160</b>	MIDR-060212	5500	6L			TO4B47	<b>465610-0010</b>	5.000.790.027
<b>M160</b>	MIDR-060212	5500	6L	175		TO4B47	<b>465610-0011</b>	5.000.790.848
<b>M160</b>	MIDR-060212	5500	6L	177		TO4B47	<b><u>465610-0005</u></b>	5.000.785.366
<b>M200</b>	MIDR-060226	6200			1988	S2B	<b>312248</b>	5.000.679.702
<b>M200</b>	MIDR-060226	6200				S2B	<b>312248</b>	5.000.679.702
<b>M200</b>	MIDR-060226	6200		225	1987	S2B	<b>311602</b>	5.000.676.451
<b>M200</b>	MIDR-060226	6200		225	1987	S2B	<b>311602</b>	5.000.676.451
<b>M200</b>	MIDR-060226	6200		225	1987	S2B	<b>312247</b>	5.000.289.022
<b>M230</b>	MIDR-060226	6200		225	1987	S2B	<b>311602</b>	5.000.289.022
<b>M230</b>	MIDR-060226	6200		225	1987	S2B	<b>312247</b>	5.000.676.451
<b>MS300</b>	MIDS-062030	8820	6L	215		TO4B39	<b><u>409200-0007</u></b>	5.000.785.927
<b>MS300</b>	MIDS-062030	8820	6L	215		TO4B39	<b><u>409200-0010</u></b>	5.000.788.227
<b>MS300</b>	MIDS-062030	8820	6L	215		TO4B39	<b><u>409200-0014</u></b>	5.000.790.860
<b>MS400</b>	MIDR-060212	5490	6L	175		TO4B47	<b><u>465610-0011</u></b>	5.000.790.848
<b>PR100</b>	BSR16				1985	K27	<b>5327-988-7000</b>	5.430.013.017
<b>R132</b>	MIDS-62045					TO4B39	<b>409200-0012</b>	5.000.789.826
<b>R132</b>	MIDS-062045	9840	6L			TO4B39	<b><u>409200-0011</u></b>	5.000.789.825
<b>R240</b>	MIVR-083530	15000	8V			S4D	<b>312619</b>	5.000.666.729
<b>R300</b>	MIDR-062045	9840	6L	320	1988	H2C	<b>3524695</b>	5.000.681.178
<b>R310</b>	MIDR-063540	12000	6L		1982	4LGZ	<b>182296</b>	5.000.249.489
<b>R310</b>	MIDR-063540	12000	6L		1982	4LGZ	<b>186716</b>	5.000.787.889
<b>R330</b>	MIDR-062045	9840	6L	319	1989	S3A	<b><u>312250</u></b>	5.000.681.269
<b>R330</b>	MIDR-062045	9840	6L	320		H2C	<b>3524695</b>	5.000.686.372
<b>R340</b>	MIDR-063540			340		TA5105	<b>466592-0001</b>	5.000.790.446

<b>R340</b>	MIDR-063540	12000	6L		1987	4LGZ	<b>310928</b>	5.000.249.718
<b>R340</b>	MIDR-063540	12000	6L		1988	4LGZ	<b>311936</b>	5.000.678.471
<b>R340</b>	MIDR-063540	12000	6L	336	1986	4LGZ	<b>310929</b>	5.000.666.816
<b>R340</b>	MIDR-063540	12000	6L	336	1986	4LGZ	<b>310929</b>	5.000.249.718
<b>R340</b>	MIDR-063540	12000	6L	336	1988	4LGZ	<b>311170</b>	5.000.249.718
<b>R340</b>	MIDR-063540	12000	6L	340		TA5105	<b><u>465592-0002</u></b>	5.000.678.300
<b>R340</b>	MIDR-063540	12000	6L	340		TA5105	<b><u>466592-0011</u></b>	5.000.790.466
<b>R340</b>	MIDR-063540	12000	6L	340		TA5105	<b><u>466592-0012</u></b>	5.000.791.462
<b>R340</b>	MIDR-063540	12000	6L	340		TA5105	<b><u>466592-0013</u></b>	5.000.815.822
<b>R340</b>	MIDR-063540	12000	6L	352	1988	S3A	<b>312227</b>	5.000.678.436
<b>R340</b>	MIDR-063540	12000	6L	374	1987	4LGZ	<b>311651</b>	5.000.249.718
<b>R340TI</b>	MIDR-062045	9840	6L		1989	S3A	<b>312294</b>	5.001.014.266
<b>R340TI</b>	MIDR-062045	9840	6L	319	1989	S3A	<b>311785</b>	5.000.681.269
<b>R340TI</b>	MIDR-062045	9840	6L	319	1989	S3A	<b>312232</b>	5.000.681.664
<b>R340TI</b>	MIDR-062045	9840	6L	319	1989	S3A	<b>312233</b>	5.000.681.665
<b>R340TI</b>	MIDR-062045	9840	6L	319		S2C	<b>313090</b>	5.001.825.515
<b>R340TI</b>	MIDR-062045	9840	6L	319	1992	S2C	<b>313529</b>	5.001.825.515
<b>R340TI</b>	MIDR-062045	9840	6L	340	1989	S3A	<b>312250</b>	5.000.670.721
<b>R340TI</b>	MIDR-062045	9840	6L	340	1991	S3A	<b>312250</b>	5.000.686.373
<b>R340TI</b>	MIDR-062045	9840	6L	340	1991	S3A	<b>312583</b>	5.001.014.266
<b>R360</b>	V835-S			349	1977	4LGZ	<b>5232-988-7400</b>	5.000.841.227
<b>R360</b>	MIVR-083530	15000	8V	379	1984	K36	<b>5336-988-7010</b>	5.000.790.468
<b>R360</b>	MIVR-083530	15000	8V	379	1984	K36	<b>5336-988-7011</b>	5.000.790.483
<b>R365</b>	MIDR-063540	12000	6L		1987	4LGZ	<b>310928</b>	5.000.678.214
<b>R365</b>	MIDR-063540	12000	6L	0	1988	4LGZ	<b>311936</b>	5.000.249.718
<b>R365</b>	MIDR-063540	12000	6L	336	1988	4LGZ	<b>311170</b>	5.000.666.816
<b>R365</b>	MIDR-063540	12000	6L	340		TA5105	<b>466592-0001</b>	5.000.790.446
<b>R365</b>	MIDR-063540	12000	6L	340		TA5105	<b>466592-0011</b>	5.000.790.446
<b>R365</b>	MIDR-063540	12000	6L	340		TA5105	<b><u>466592-0012</u></b>	5.000.791.462
<b>R365</b>	MIDR-063540	12000	6L	340		TA5105	<b><u>466592-0013</u></b>	5.000.815.822
<b>R365</b>	MIDR-063540	12000	6L	352	1988	S3A	<b>312227</b>	5.000.678.436
<b>R365</b>	MIDR-063540	12000	6L	365		TA5105	<b><u>466592-0002</u></b>	5.000.678.300
<b>R365</b>	MIDR-063540	12000	6L	374	1987	4LGZ	<b>311651</b>	5.000.678.301
<b>R385</b>	MIDR-063540	12000		380	1992	S3B	<b>313427</b>	5.000.693.134
<b>R385</b>	MIDR-063540	12000		380	1992	S3B	<b>313443</b>	5.000.693.134
<b>R390</b>	MIVR-083530	15000				S4D	<b>310844</b>	5.000.249.717
<b>R390</b>	MIVR-083530	15000	8V		1989	S4A	<b>310845</b>	5.000.666.775
<b>R390</b>	MIVR-083530	15000			1989	S4D	<b>312179</b>	5.000.666.775
<b>R390</b>	MIVR-083530	15000				S4D	<b>312619</b>	5.000.249.717
<b>R390</b>	MIVR-083530	15000	8V			S4D	<b>312619</b>	5.000.666.729

<b>R390</b>	MIVR-083530	15000	8V	380	1989	S4D	<b>312178</b>	5.000.666.729
<b>S150</b>	798				1987	3LE1	<b>54376</b>	5.000.249.336
<b>S170</b>	MIDS-060212					TO4B47	<b>465610-0012</b>	5.000.138.387
<b>S170</b>	MIDR-060212	5500			1986	TO4B47	<b>465610-0006</b>	5.000.134.530
<b>S170</b>	MIDR-060212	5500	6L			TO4B47	<b>465610-0009</b>	5.000.790.573
<b>S170</b>	MIDR-060212	5500	6L			TO4B47	<b>465610-0010</b>	5.000.790.027
<b>S170</b>	MIDR-060212	5500		164	1986	TO4B47	<b>465610-0007</b>	5.000.136.963
<b>S170</b>	MIDR-060212	5500	6L	175		TO4B47	<b>465610-0011</b>	5.000.249.388
<b>S170</b>	MIDR-060212	5500	6L	177		TO4B47	<b>465610-0005</b>	5.000.785.366
<b>S220</b>	MIDR-060226	6180	6L	216		TO4E16	<b>466970-0004</b>	5.000.676.450
<b>TRM340</b>	BSR-36D	12000		353	1985	K33	<b>5333-988-6720</b>	5.430.001.728

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

## APPLICATIONS

SUITABLE FOR:

### Scania

Model	Motor	CC	Nº of Cylinders	CV	Year	Model	Part Number	O.E.M Part Number
	DSC9-13	9000	6L		1997	GT4082	<u>452163-0003</u>	1372848
	DSC9-11	9000	6L			GT4082	<u>452232-0009</u>	1405655
	DSC9	9000	6L			GT4082	<u>452232-0011</u>	1423027
	DSC9-11	9000	6L			GT4082	<u>452286-0001</u>	1400414
	DSC9	9000	6L			GT4082	<u>452286-0002</u>	1400414
	DSC9-11	9000	6L			GT4082	<u>452308-0003</u>	
	DSC9-12	9000	6L		1998	GT4082SN	<u>452309-0004</u>	
	DSC9-12	9000	6L		1998	GT4082SN	<u>452309-0005</u>	
	DC9-02	9000	6L		1999	GT3782	<u>452311-0001</u>	1412940
	DC9-03	9000	6L		1999	GT3782	<u>452311-0002</u>	
	DC9-02	9000	6L		1999	GT3782	<u>452311-0002</u>	
	DSC9	9000	6L			TA4501	<u>465878-0002</u>	323759
	DSC9 Euro III	9000	6L			GT3782	<u>703012-0002</u>	1412938
	DSC9 Euro III	9000	6L			GT3782	<u>703012-0003</u>	1412937
	DSC9 Euro III	9000	6L			GT3782	<u>703012-0004</u>	1412938
	DSC9 Euro III	9000	6L			GT3782	<u>703013-0006</u>	1501657
	DSC9-11	9000	6L	215		GT4082	<u>452232-0005</u>	1386402
	DSC9	9000	6L	215		GT4082	<u>452232-0010</u>	1423026
	DS109	9000	6L	225		GT4082S	<u>452304-0001</u>	
	DS109	9000	6L	225		GT4082S	<u>452304-0002</u>	
	DS9	9000	6L	225		TO4E06	<u>466616-0005</u>	378528
	DC11-07	10640	6L	322	1999	GT4288	<u>709574-0001</u>	
	DC11-07	10640	6L	322	1999	GT4288	<u>709574-0002</u>	
	DC11-03	10640	6L	330	2000	GT4288	<u>709574-0004</u>	1449890
	DS11	11020	6L			TV6114	<u>465990-0007</u>	532530
	DS11	11020	6L			TV6114	<u>465990-0008</u>	537069
	DS11	11020	6L			TV6114	<u>465990-0009</u>	537408
	DS11	11020	6L			TV6114	<u>465990-0011</u>	520320
	DS11	11020	6L			TV6114	<u>465990-0012</u>	543063
	DS11	11020	6L			TA4504	<u>466104-0001</u>	330962
	DS11	11020	6L			TA4504	<u>466104-0011</u>	330962
	DS11-36	11020	6L	191		TA4536	<u>465213-0001</u>	

	DS11-34	11020	6L	191		TA4536	<u>465213-0001</u>	
	DS11-36	11020	6L	230		TA4536	<u>465213-0001</u>	
	DS11-34	11020	6L	230		TA4536	<u>465213-0001</u>	
	DSC11	11020	6L	362		TA4516	<u>466950-0001</u>	1111068
	DSC12	11700	6L			GT4288N	<u>703072-0003</u>	1412299
	OSC12	12000	8V	340	2001	GT4082	<u>721329-0001</u>	1454727
	DS14	14020	8V			TV7704	<u>466120-0004</u>	520294
	DC16	15600	8V	450	2001	UTV7514	<u>722094-0001</u>	
	DC16	15600	8V	512	2001	GT4702	<u>715735-0001</u>	
<b>110</b>	DS11	11020	6L			4LE	<b>53450</b>	189975
<b>110</b>	DS11	11020	6L			4LEK	<b>53994</b>	223620
<b>110</b>	DS11	11020	6L			4LGK	<b>54937</b>	318040
<b>110S</b>	DS11	11000				4LEK	<b>181766</b>	
<b>110S</b>	DS1	11000				4LE	<b>181799</b>	189975
<b>111</b>	DS11	11020	6L	304	1977	4LGZ	<b>5232-988-3276</b>	301250
<b>111</b>	DS11	11020	6L	304	1977	4LGZ	<b>5232-988-3276</b>	301250
<b>111</b>	DS11	11020	6L	310	1977	4LGK	<b>3500403</b>	279135
<b>111</b>	DS11	11020	6L	310	1974	4LGZ	<b>5232-988-3274</b>	301249
<b>111</b>	DS11	11020	6L	310	1974	4LGZ	<b>5232-988-3275</b>	257747
<b>112</b>	DSC11	11020	6L		1987	4LGZ	<b>311425</b>	
<b>112</b>	DSC11	11020	6L			4LGZ	<b>311522</b>	
<b>112</b>	DS11	11020	6L			4LGZ	<b>312043</b>	375500
<b>112</b>	DSC11	11020	6L			4LGK	<b>3504412</b>	322668
<b>112</b>	DSC11-22	11020	6L			HX50	<b>3537639</b>	1378567
<b>112</b>	DS11	11020	6L		1979	4LE	<b>5232-988-5601</b>	207303
<b>112</b>	DS11	11020	6L	304	1980	4LGZ	<b>5232-988-3284</b>	307371
<b>112</b>	DS11	11020	6L	304	1980	4LGZ	<b>5232-988-3286</b>	307372
<b>112</b>	DS11	11020	6L	310	1980	4LGZ	<b>182296</b>	310582
<b>112</b>	DS11	11020	6L	315	1982	4LGZ	<b>310005</b>	332349
<b>112</b>	DS11	11020	6L	319	1982	4LGZ	<b>186586</b>	318041
<b>112</b>	DSJ11	11020	6L	360		4LGK	<b>3503327</b>	305762
<b>113</b>	DS11	11020			1979	4LGZ	<b>310957</b>	375500
<b>113</b>	DS11	11020			1987	4LGZ	<b>311634</b>	1105169
<b>113</b>	DS11	11020			1987	4LGZ	<b>311704</b>	1107067
<b>113</b>	DSC11	11020			1988	4LGZ	<b>311705</b>	1107068
<b>113</b>	DS11	11020			1988	4LGZ	<b>311990</b>	1107067
<b>113</b>	DSC11	11020	6L		1988	4LGZ	<b>311991</b>	1107068
<b>113</b>	DS11-36	11020	6L			S3A	<b>312283</b>	1115749
<b>113</b>	DSC11-18	11020				S3A	<b>313970</b>	115752
<b>113</b>	DSC11-17	11020				H2D	<b>3528016</b>	1116196
<b>113</b>	DSC11-79	11020				HX50	<b>3537564</b>	1375587

113	DS11-78	11020	6L			TA4536	465213-0004	1677955
113	DSC11-17	11020	6L		1989	TA4516	466950-0002	1115752
113	DSC11-22	11020					HX50	3537639
113	DS11-34	11020		310		S3A	198623	1114891
113	DSC11-30	11020		310		S3A	313969	
113	DS11	11020	6L	312	1989	S3A	311023	1115567
113	DSC11	11020	6L	320	1991	S3A	312267	1319894
113	DSC11	11020	6L	320	1991	S3A	312823	1324420
113	DSC11	11020	6L	320	1991	S3A	312824	1324421
113	DSC11	11020	6L	320	1991	S3A	312825	1324422
113	DS11	11020		350	1983	4LGK	3504412	397664
113	DSJ11	11020	6L	350		4LGK	3504412	366801
113	DSJ11	11020	6L	360		4LGK	3503327	305762
113	DSC11-18	11020		360		H2D	3525517	1116193
113	DSC11-21	11020	6L	380	1991	S3A	313063	1319894
113	DSC11	11020		380		H2D	3528650	1322999
113	DSC11	11020		380		H2D	3528941	1319359
113	DSC11	11020		380		H2D	3533616	1350752
113	DTC11	11020		400		H2S	3528525	1332210
113	DTC11	11020		400		H2S	3536258	1368734
124	DSC11-75	11020	6L	355	1995	GT4288	452109-0003	1388059
124	DSC11-80	11020	6L	360	1995	GT4288	452109-0001	1388059
124	DSC12	11700	6L			HX50	3536749	
124	DSC12-05	11700	6L		1995	GT4288N	703072-0001	1412299
124	DSC12-05	11700	6L		1995	GT4288N	703072-0002	1412300
124	DSC12	11700	6L	360	1995	GT4288	452109-0006	1423038
124	DSI12-01	11700	6L	420		HX50	3590810	1409517
124	DSC12-03	11700	6L	420	1995	GT4288N	703072-0001	1412299
124	DSC12-01	11700	6L	420	1995	GT4288N	703072-0001	1412299
124	DSC12-01	11700	6L	420	1995	GT4288N	703072-0002	1412300
124	DSC12-03	11700	6L	420	1995	GT4288N	703072-0002	1412300
124	DSC12-02	11700	6L	470	1995	GT4288N	703072-0001	1412299
124	DSC12-02	11700	6L	470	1995	GT4288N	703072-0002	1412300
124	DSC12-01	11700	6L	535		HX50	3538495	1384333
124	DSC12-01	11700	6L	535		HX50	3591777	1423036
124GB-360	DSC12	11700	6L	360		GT4288	452109-0006	1423038
124LB-360	DSC12	11700	6L	360		GT4288	452109-0006	1423038
133	DS11	11020	6L		1987	4LGZ	311990	1105169
140	DS14	14020	8V			4HD	53499	170795
141	DS14	14000				4HD	53499	170795
141	DS14	14020	8V			4LGK	55277	261228



141	DS14	14020	8V	375	1978	4LGZ	<b>5232-988-7410</b>	292070
141	DSC14-03	14020	8V	450	1983	4LGK	<b>3518687</b>	1104009
142	DS8	8000				3LD1	<b>181793</b>	202665
142	DS14	14000				TV6114	<b>465990-0001</b>	261274
142	DS14	14000				TV6114	<b>465990-0002</b>	
142	DS14	14000				TV6114	<b>465990-0004</b>	532531
142	DS14	14000				4HD	<b>53499</b>	170795
142	DS14	14000				4HD	<b>54458</b>	
142	DS14	14000				4HD	<b>54459</b>	
142	DS14	14000				4HD	<b>54681</b>	245580
142	DS14	14000				4HD	<b>54682</b>	245582
142	DS14	14000				4LGK	<b>54735</b>	
142	DS14	14000				4LGK	<b>54801</b>	
142	DS14	14000				4HD	<b>54889</b>	253978
142	DS14-16	14020	8V			TV7704	<b><u>466120-0001</u></b>	330963
142	DS14	14020	8V			TV7704	<b><u>466120-0002</u></b>	520263
142	DSC14-03	14020	8V	420	1980	4LGK	<b>3503044</b>	519518
142	DSC14-03	14020	8V	450	1983	4LGK	<b>3518687</b>	328579
142	DSC14	14020	8V	470	1988	4LGK	<b><u>3527192</u></b>	1115430
143	DSC14-10	14020	8V			H3B	<b>3528588</b>	1303809
143	DSC14	14020	8V			H3B	<b>3530548</b>	1318460
143	DSC14A	14020	8V			H3B	<b>3533210</b>	1340416
143	DSC14	14020	8V			H3B	<b>3533212</b>	1342985
143	DSC14-03	14020	8V	420	1980	4LGK	<b>3503044</b>	329949
143	DSC14	14020	8V	450		H3B	<b>3533988</b>	1356694
143	DSC14-13	14020	8V	528		HX60	<b>3533023</b>	1384862
143	DSC14-13	14020	8V	528		HX60	<b>3533973</b>	1384862
144	DSC14	14020	8V		1995	HX60	<b>3591830</b>	1423020
144	DSC14-15	14020	8V	465		TV7514	<b><u>452165-0001</u></b>	1383416
144	DSC14-15	14020	8V	465		TV7514	<b><u>452165-0002</u></b>	1411414
144	DSC14-15	14020	8V	465		TV7514	<b><u>452165-0003</u></b>	1383416
164	DC16-01	15600	8V	580	2000	HX60W	<b>3594549</b>	1446732
164	DT16-02	16000	8V	480	2000	HX60	<b>3597488</b>	1489615
80	DS8	8000				TO4B20	<b>408850-0001</b>	230323
80	DS8	8000				3LD1	<b>53368</b>	202665
81	DS8-1	8000				TO4B55	<b>465820-0001</b>	257232
81	DS8-1	8000				TO4B55	<b>465820-0002</b>	257232
82	DS8	8000				3LD	<b>181786</b>	
82	DS8	8000				TO4B20	<b>408850-0002</b>	243084
82	DS8	8000				TO4B20	<b>408850-0003</b>	346230
82	DS18	8000				TO4B88	<b><u>465744-0004</u></b>	355969

82	DS8	8000				3LD	50935	
82	DS8	8000				3LD1	54456	202665
82	DS8-1	8000		227		TO4B55	465820-0001	257232
82	DS8-1	8000		227		TO4B55	465820-0002	257232
820	DC11-03	10640	6L	330	2000	GT4288	709574-0003	
85	DS8	8000			1982	TO4B88	465744-0001	309511
85	DS8	8000			1982	TO4B88	465744-0002	310072
85	DS8	8000			1982	TO4B88	465744-0003	312081
85	DS8-1	8000				TO4B55	465820-0001	257232
85	DS8-1	8000				TO4B55	465820-0002	257232
86	DS8	8000			1982	TO4B88	465744-0001	309511
86	DS8	8000			1982	TO4B88	465744-0002	310072
86	DS8	8000			1982	TO4B88	465744-0003	312081
92	DSC9	9000			1987	H1E	3528621	1341985
92	DSC9	9000			1990	TO4E06	466616-0010	1317655
92	DSC9	9000			1990	TO4E06	466616-0011	571590
92	DSC9	9000	6L			TO4E06	466616-0012	1317654
92	DSC9	9000	6L			TO4E06	466616-0013	1317660
92	DSC9	9000				TO4E06	466616-0015	1351127
92	DS9-40	9000	6L	190		TO4E06	466616-0004	370090
92	DS9-02	9000	6L	221	1987	TO4E06	466616-0003	370090
92	DSC9-01	9000		230		S81	310306	349272
92	DS9	9000		230	1987	TO4E06	466616-0007	393457
92	DS9	9000	6L	275	1987	TO4E06	466616-0001	358501
92	DSC9	9000	6L	275	1987	TO4E06	466616-0001	358501
92	DSC9	9000	6L	275	1987	TO4E06	466616-0002	370091
93	DSC9	9000			1984	S81	310461	349272
93	DSC9	9000			1988	S81	310794	1100371
93	DSC9	9000			1988	S81	311632	1100371
93	466616-0007	9000			1987	TO4E06	466616-0007	393457
93	DSC9	9000			1990	TO4E06	466616-0010	1317655
93	DSC9	9000			1990	TO4E06	466616-0011	
93	DSC9	9000				TO4E06	466616-0012	1317654
93	DSC9	9000				TO4E06	466616-0013	1317660
93	DSC9	9000				TO4E06	466616-0015	1351127
93	DS9-40	9000		190		TO4E06	466616-0004	370090
94	DSC9-12	9000	6L		1995	GT4082	452163-0005	1380097
94	DSC9-13	9000	6L		1999	GT4082	452285-0001	1400412
94	DSC9-13	9000	6L			GT4082	452285-0002	1401481

94	DSC9-13	9000	6L			GT4082	<u>452308-0001</u>	1405666
94	DSC9-13	9000	6L			GT4082	<u>452308-0002</u>	1405667
94	DSC9-12	9000	6L			GT4082	<u>452308-0004</u>	1405667
94	DSC9-13	9000	6L		1998	GT4082	<u>452308-0005</u>	1405667
94	DSC9-13	9000	6L			GT4082SN	<u>452309-0001</u>	1405669
94	DSC9-13	9000	6L			GT4082SN	<u>452309-0002</u>	1405671
94	DSC9-13	9000	6L			GT4082SN	<u>452309-0003</u>	1405670
94	DC9 Euro III	9000	6L		1999	GT3782	<u>452311-0001</u>	1412940
94	DSC9 Euro III	9000	6L		1999	GT3782	<b>703013-0003</b>	1412937
94	DSC9 Euro III	9000	6L		1999	GT3782	<b>703013-0004</b>	1412938
94	DSC9 Euro III	9000	6L		1999	GT3782	<b>703013-0005</b>	1501656
94	DSC9-01	9000	6L	230	1999	GT3782	<b>703013-0002</b>	1412938
<b>94DB-310</b>	DSC9	9000	6L	310		GT4082	<u>452163-0001</u>	1372846
<b>94GA-310</b>	DSC9	9000	6L	310		GT4082	<u>452163-0001</u>	1372846
<b>94GB-310</b>	DSC9	9000	6L	310		GT4082	<u>452163-0001</u>	1372846
<b>BUS</b>	DSC9-11	9000	6L		1997	GT4082	<u>452232-0007</u>	1386404
<b>BUS</b>	DSC9-11	9000	6L	215	1997	GT4082	<u>452232-0008</u>	1386405
<b>BUS</b>	DSC9-11	9000		280	1997	S2B	<b>314413</b>	1362027
<b>BUS</b>	DS11-36	11000			1989	S3A	<b>312283</b>	1114892
<b>BUS</b>	DSC11	11000				WH2D	<b>3534100</b>	1341286
<b>BUS</b>	DSC11-72	11000			0	HX50W	<b>3534857</b>	1362047
<b>BUS</b>	DSC11	11000		320	1991	S3A	<b>312822</b>	1319896
<b>BUS</b>	DS11	11000		323	1989	S3A	<b>312159</b>	1115749
<b>BUS</b>	DSC11-21	11000		380	1991	S3A	<b>313063</b>	1319896
<b>BUS</b>	DSC11-26	11000		380		H2D	<b>3533616</b>	1351631

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

**TurboMaster**

GARRETT TURBOS OFFICIAL DISTRIBUTOR FOR SPAIN

**Trucks** Catalog**APPLICATIONS**

SUITABLE FOR:

**Unimog**

Model	Motor	CC	Nº of Cylinders	CV	Year	Model	Part Number	O.E.M Part Number
1300	OM352A	5700	6L			TO4B27	<b>409300-0003</b>	352 096 2199
1300	OM352A	5700	6L			TO4B27	<b>409300-0009</b>	352 096 3599
1300	OM352A	5700	6L	150		TO4B27	<b>409300-0006</b>	352 096 2399
1300	OM366A	6000	6L			TO4B81	<b><u>465366-0015</u></b>	366 096 0399
1500	OM366A	6000	6L			TO4B81	<b><u>465366-0015</u></b>	366 096 0399
1700	OM366A	6000	6L			TO4B81	<b><u>465366-0015</u></b>	366 096 0399
1700L	OM366LA	6000	6L			TO4B81	<b><u>465366-0016</u></b>	366 096 0499

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: [turbomaster@turbomaster.info](mailto:turbomaster@turbomaster.info).

## APPLICATIONS

SUITABLE FOR:

## Volvo

Model	Motor	CC	Nº of Cylinders	CV	Year	Model	Part Number	O.E.M Part Number
	TD121K					4LGK	<b>3528321</b>	4881245
	TG103					TBP4	<b>452157-0001</b>	298000
	TG103					TBP4	<b>452157-0002</b>	298000
	GH10A					TBP4	<b>452240-0001</b>	8194710
	TD50					3LD	<b>53485</b>	784303
						4LE	<b>54087</b>	
	TD50					3LD	<b>54777</b>	4773573
	TD60B	5480	6L			TO4B46	<b>465600-0008</b>	4880772
	TD60	5480	6L	139		TO4B46	<b>465600-0007</b>	4880771
	TD60	5480	6L	139		TO4B46	<b>465600-0008</b>	4880772
	TD63ES	5480	6L	209		TO4E04	<b>466588-0012</b>	8192070
	TD70D	6720	6L	206		TO4B44	<b>465570-0001</b>	466508
	TD71	6720	6L	206		TO4E04	<b>466588-0005</b>	471627
	TD73ES	7000	6L			H1E	<b>3533595</b>	477834
	TD73ES	7000	6L			WH1E	<b>3533741</b>	477889
	TD73ES	7000	6L			WH1E	<b>3533741</b>	477889
	D7A	7000				WH1E	<b>3534617</b>	477889
	TD102F	9600			1987	H2D	<b>3526059</b>	479116
	TD100	9600				4LEK	<b>3528325</b>	4775211
	TD100C	9600				4LGK	<b>3528327</b>	
	D10A	9600				HX40W	<b>3536545</b>	425830
	D10B	9600	6L		1996	GT4288	<b>452174-0007</b>	8194549
	D10B	9600	6L		2001	GT4082SN	<b>714987-0001</b>	
	D10B	9600	6L		2001	GT4082SN	<b>714987-0002</b>	
	D10B	9600	6L		2001	GT4082SN	<b>714987-0003</b>	
	TD101F	9600	6L	315		TA4530	<b>466666-0001</b>	470977
	TD122FS	11950	6L			TA5102	<b>466076-0016</b>	
	TD122FS	11950	6L			TA5102	<b>466076-0018</b>	6888576
	TD121F	11950	6L			TA4530	<b>466666-0001</b>	470977
	TD121K	12000			1983	4LGK	<b>3521743</b>	4881245
	TD120B	12000				4LGK	<b>3528318</b>	468390
	TD120AG	12000				4LGK	<b>55321</b>	468390
	DH12C	12140	6L		2002	GT4594L	<b>709197-0002</b>	1549451

	D12C	12140	6L		2000	GT4594	<u>712922-0001</u>	3169592
	D12C	12140	6L		2000	GT4594	<u>712922-0006</u>	
<b>B10B</b>	THD102KD	9600			1988	H2D	<b>3526465</b>	424778
<b>B10B</b>	THD100DD	9600	6L			4LEK	<b>3528323</b>	469458
<b>B10B</b>	THD102KE	9600				H2D	<b>3529558</b>	425081
<b>B10B</b>	THD102KA	9600		285	1989	H2D	<b>3526967</b>	424819
<b>B10B</b>	THD100DD	9600	6L	310	1974	4LGK	<b>54797</b>	469458
<b>B10M</b>	THD102KE	9600				H2D	<b>3529558</b>	425081
<b>B10M</b>	THD100DB	9600	6L	250	1980	4LEK	<u>54334</u>	467369
<b>B10M</b>	THD100E	9600	6L	275	1981	H2C	<u>3518613</u>	1545097
<b>B10M</b>	THD100DD	9600	6L	310		4LEK	<b>3528323</b>	469548
<b>B10M</b>	THD100DD	9600	6L	310	1974	4LGK	<b>54797</b>	467272
<b>B10M</b>	THD100DD	9600	6L	310	1974	4LGK	<b>54797</b>	469458
<b>B10R</b>	THD102KF	9600		285	1989	H2D	<b>3526967</b>	424819
<b>B12</b>	TD122FH	11950	6L	360	1984	H2D	<b>3526008</b>	470931
<b>B12</b>	TD122FH	11950	6L	361	1990	S3B	<b>312862</b>	470931
<b>B12</b>	TD122FK	11950	6L	382	1988	TA5102	<u>466076-0015</u>	470943
<b>B12</b>	TD123E	12000				H2D	<b>3525408</b>	470931
<b>B12</b>	TD123ES	12000				TA5102	<u>466076-0019</u>	478794
<b>B12</b>	TD123E	12000		400	1984	H2D	<b>3526008</b>	478522
<b>B12</b>	D12A	12130	6L	385	1995	GT4288	<u>452101-0003</u>	425721
<b>B12</b>	DH12C	12140	6L	415	1999	GT4594L	<u>709197-0001</u>	1549450
<b>B12</b>	DH12D	12140	6L	422	1999	GT4594L	<u>709197-0003</u>	20440364
<b>B54</b>	TD50				1970	3LD9	<b>54089</b>	466182
<b>B55</b>	TD70H	6720	6L			TO4B29	<u>409840-0005</u>	466877
<b>B55</b>	TD70H	6720	6L			TO4B29	<u>409840-0005</u>	466730
<b>B55</b>	TD70H	6720	6L			TO4B29	<u>409840-0005</u>	466730
<b>B57</b>	TD70C				1968	3LD	<b>53468</b>	420412
<b>B57</b>	TD70A				1970	3LD9	<b>54089</b>	466182
<b>B57</b>	TD70G	6720	6L			TO4B29	<u>409840-0005</u>	466730
<b>B57</b>	TD70G	6720	6L			TO4B29	<u>409840-0006</u>	466730
<b>B57</b>	TD70G	6720	6L			TO4B29	<u>409840-0007</u>	466730
<b>B57</b>	TD70E	6720	6L	206		TO4B29	<u>409840-0003</u>	466466
<b>B57</b>	TD70E	6720	6L	206		TO4B29	<u>409840-0004</u>	466466
<b>B58</b>	THD100DB	9600	6L	250	1980	4LEK	<u>54334</u>	469106
<b>B59</b>	THD100A	9600	6L	250	1980	4LEK	<u>54334</u>	467369
<b>B6</b>	TD60B	5480	6L			TO4B46	<b>465600-0010</b>	465254
<b>B6</b>	TD60C	5480	6L	178		TO4B46	<u>465600-0001</u>	465255
<b>B6</b>	TD60B	5480	6L	178		TO4B46	<u>465600-0002</u>	465254

<b>B6</b>	D6A	5480	6L	187	1995	GT3271	<u><b>452176-0003</b></u>	425833
<b>B6</b>	TD63ES	5480	6L	209		TO4E04	<u><b>466588-0013</b></u>	425768
<b>B6</b>	TD63ES	6700	6L			TO4E04	<u><b>466588-0011</b></u>	425548
<b>B6</b>	TD63ES	6720	6L			TO4E04	<u><b>466588-0010</b></u>	425362
<b>B7</b>	TD73ES	7000	6L			H1E	<b>3533595</b>	477868
<b>B9M</b>	THD100E	9600	6L	275	1981	H2C	<u><b>3518613</b></u>	1545097
<b>BM12</b>	DH12D	12140	6L		2001	GT4594L	<u><b>709197-0003</b></u>	20440364
<b>BM12M</b>	DH12C	12140	6L		1999	GT4594L	<u><b>709197-0001</b></u>	1549450
<b>BUS</b>	D12A				1993	GT4594	<b>452164-0003</b>	425777
<b>BUS</b>	TD100G	9600	6L			TA4502	<b>465922-0003</b>	6886157
<b>BUS</b>	TD100G	9600	6L			TA4502	<b>465922-0013</b>	6886157
<b>C10M</b>	THD100KD	9600	6L	275	1981	H2C	<u><b>3518613</b></u>	1545097
<b>F10</b>	TD100D	9600	6L			TA4502	<u><b>465922-0012</b></u>	1545098
<b>F10</b>	TD101F	9600	6L		1985	TA4513	<u><b>466818-0003</b></u>	422938
<b>F10</b>	TD100A	9600	6L	250	1980	4LEK	<u><b>54334</b></u>	467603
<b>F10</b>	TD100G	9600	6L	261	1981	S3A	<b>312540</b>	154097
<b>F10</b>	TD100G	9600	6L	275	1981	H2C	<u><b>3518613</b></u>	1545097
<b>F10</b>	TD102F	9600	6L	297	1985	TA4513	<u><b>466818-0003</b></u>	422938
<b>F10</b>	TD103ES	9600	6L	297	1985	TA4513	<u><b>466818-0003</b></u>	422938
<b>F10</b>	TD101F	9600		310	1983	H2C	<b>3518911</b>	1545281
<b>F10</b>	TD100B	9600	6L	310		4LGK	<b>3528323</b>	467602
<b>F10</b>	TD100B	9600		310		4LGK	<b>3528323</b>	467272
<b>F10</b>	TD100B	9600	6L	310	1974	4LGK	<b>54797</b>	467602
<b>F10</b>	TD100B	9600		310	1974	4LGK	<b>54797</b>	467272
<b>F10</b>	TD100B	9600		310	1974	4LGK	<b>54797</b>	467272
<b>F10</b>	TD101F	10000		361	1990	S3A	<b>312682</b>	1545281
<b>F12</b>	TD120C	11950	6L			4LGK	<b>3528320</b>	468932
<b>F12</b>	TD120F	11950	6L			4LGK	<b>3528326</b>	468882
<b>F12</b>	TD120GA	11950	6L			TA5101	<u><b>466074-0011</b></u>	470387
<b>F12</b>	TD120G	11950	6L			TA5102	<u><b>466076-0001</b></u>	470371
<b>F12</b>	3043	11950	6L			TA5102	<u><b>466076-0002</b></u>	470509
<b>F12</b>	TD123ES	11950	6L			TA5102	<b>466076-0020</b>	478795
<b>F12</b>	TD120G	11950	6L			4LGZ	<b>5232-988-6400</b>	468996
<b>F12</b>	TD120G	11950	6L	329		TA5102	<u><b>466076-0002</b></u>	470509
<b>F12</b>	TD121G	11950	6L	329	1984	TA5102	<u><b>466076-0012</b></u>	470509
<b>F12</b>	TD121G	11950	6L	329	1984	TA5102	<u><b>466076-0012</b></u>	470509
<b>F12</b>	TD121F	11950	6L	382		TA5102	<u><b>466076-0014</b></u>	6886506
<b>F12</b>	TD122FS	11950	6L	382	1988	TA5102	<b>466076-0015</b>	470943
<b>F12</b>	TD122FS	11950	6L	382	1984	TA5102	<u><b>466076-0015</b></u>	470943

F12	TD120F	11950	6L	385	1979	4LGK	<b>3503623</b>	470109
F12	TD120B	11950	6L	385	1985	4LGK	<b>3521971</b>	470779
F12	TD122F	11950	6L	400	1984	H2D	<b>3526008</b>	478673
F12	TD120F	12000			1979	4LFK	<b>3502430</b>	468882
F12	TD123ES	12000				TA5102	<b>466076-0019</b>	478794
F12	TD120C	12000				4LGZ	<b>5232-988-3283</b>	468962
F12	TD120D	12000		350	1977	4LGK	<b>3502594</b>	468931
F12	TD123E	12000		360	1984	H2D	<b>3526008</b>	470931
F12	TD122F	12000		361	1990	S3B	<b>312862</b>	470931
F16	TID162	16000			1984	H3B	<b>3524789</b>	1543496
F16	TD162F	16000			1988	H3B	<b>3526170</b>	1543371
F16	TD163ES	16000				H3B	<b>3530641</b>	1556163
F4	TD40A				1983	H1C	<b>3522715</b>	1545644
F4	TD40A				1983	H1C	<b>3522715</b>	1545862
F4	TD40				1977	H1B	<b>63405</b>	1542190
F4	TD40			120		H1B	<b>3500014</b>	1542190
F6	TD60C	5480	6L			TO4B46	<b>465600-0006</b>	465562
F6	TD60A	5480	6L			TO4B46	<b>465600-0010</b>	465254
F6	TD60	5480	6L	178		TO4B46	<b>465600-0001</b>	465255
F6	TD60A	5480	6L	178		TO4B46	<b>465600-0002</b>	465254
F6	TD60C	5480	6L	178		TO4B46	<b>465600-0002</b>	465254
F6	TD60C	5480	6L	178		TO4B46	<b>465600-0003</b>	465253
F6	TD60A	5480	6L	178		TO4B46	<b>465600-0006</b>	465562
F6S	TD60B	5480	6L			TO4B46	<b>465600-0002</b>	465254
F6S	TD60C	5480	6L			TO4B46	<b>465600-0010</b>	465254
F6S	TD60A	5480	6L	178		TO4B46	<b>465600-0001</b>	465255
F6S	TD60B	5480	6L	178		TO4B46	<b>465600-0002</b>	465254
F6S	TD60	5480		178		TO4B46	<b>465600-0003</b>	465253
F6S	TD60B	5480	6L	178		TO4B46	<b>465600-0006</b>	465562
F7	TD70G	6720	6L	206		TO4B29	<b>409840-0005</b>	466730
F7	TD70G	6720	6L	206		TO4B29	<b>409840-0006</b>	466876
F7	TD70G	6720	6L	206		TO4B29	<b>409840-0007</b>	466877
F7	TD70F	6720	6L	230	1977	TO4B45	<b>465590-0005</b>	466731
F7	TD70FS	6720	6L	230	1977	TO4B45	<b>465590-0005</b>	466731
F85	TD50A				1968	3LD	<b>53468</b>	466173
F85	TD50			180	1970	3LD	<b>54089</b>	466181
F85	TD60	5480	6L	178		TO4B46	<b>465600-0003</b>	465253
F85	TD60B	5480	6L	178		TO4B46	<b>465600-0006</b>	465562
F86	TD70A				1968	3LD	<b>53468</b>	465134
F86	TD70B			180	1970	3LD	<b>54089</b>	466182



F86	TD70C			180	1972	3FD	55407	466632
F86	TD70E	6720	6L	206		TO4B29	<u>409840-0002</u>	466730
F86	TD70E	6720	6L	206		TO4B29	<u>409840-0003</u>	466395
F88	TD100A				1969	4LE	53483	422582
F88	TD96	9600			1969	4-450	10488	517315
F88	TD100A	9600			1969	4-450	10488	424217
F88	TD100A	9600	6L	250	1980	4LEK	54334	467369
F88H	TD100B	9600		310		4LGK	3528323	467272
F88H	TD100B	9600		310	1974	4LGK	54797	467272
F89	TD120A	11950	6L			4LFK	3528317	425037
F89	TD120A	12000				4LGZ	5232-988-3280	468620
F89	TD120A	12000			1970	4LF	53876	468063
F89	TD120A	12000		330	1972	4LFK	54196	468231
FE6	TD61G	6000			1985	H2A	3523296	420521
FE6	TD61G	6000			1986	H2A	3524560	420597
FE6	TD61G	6000			1986	H2A	3524560	420597
FE6	TD61F	6700		206	1985	TO4E04	466588-0003	465881
FE7	TD71F	6700		206		TO4E04	466588-0005	471627
FE7	TD71F	6720	6L	206	1985	TO4E04	<u>466588-0001</u>	471740
FE7	TD71FA	6720	6L	206	1985	TO4E04	<u>466588-0001</u>	471897
FE7	TD71FA	6720	6L	206		TO4E04	<u>466588-0002</u>	471897
FE7	TD71F	6720	6L	206	1985	TO4E04	<u>466588-0002</u>	471740
FE7	TD71FC	6720	6L	206		TO4E04	<u>466588-0004</u>	421474
FE7	TD71FCQ	6720	6L	206	1985	TO4E04	<u>466588-0006</u>	477148
FE7	TD71FCQ	6720	6L	206	1985	TOE04	466588-0007	420804
FE7	TD73ES	7000	6L		1991	H1E	3530669	849680
FH12	D12C	11950			1999	HX55	3591077	9113407
FH12	D12A	12000				HX55	3531858	1677098
FH12	D12A	12000				HX55	3532692	1676089
FH12	D12A	12000				HX55	3533546	1677726
FH12	D12A	12000		420	0	HX55	3537840	1677725
FH12	D12A	12130	6L			GT4594	<u>452164-0002</u>	8148731
FH12	D12A	12130	6L			GT4594	<u>452164-0005</u>	
FH12	D12A	12130	6L	412		GT4288	<u>452101-0001</u>	1677008
FH12	D12A	12130	6L	412	1993	GT4288	<u>452101-0002</u>	1547957
FH12	D12B	12130	6L	420		GT4594	<u>452164-0004</u>	3964637
FH16	D16A	16000				HX60	3532927	1556571
FH16	D16A	16000				HX60W	3532929	1556570
FH16	D16A	16000				HX60W	3533974	1556570
FH16	D16A	16000				HX60	3533975	1556571

<b>FH16</b>	D16A	16000				HX60W	<b>3534181</b>	1556646
<b>FH16</b>	D16A	16000				HX60	<b>3575080</b>	1556645
<b>FH16</b>	D16A	16000				HX60W	<b>3575313</b>	1556645
<b>FH16</b>	D16A	16000		520		HX60W	<b>3590058</b>	1556919
<b>FL10</b>	TD101FA	9600			1983	H2C	<b>3518911</b>	1545281
<b>FL10</b>	TD102F	9600			1986	H2D	<b>3525994</b>	422934
<b>FL10</b>	D10A	9600	6L		1995	GT4288	<b><u>452174-0002</u></b>	425677
<b>FL10</b>	D10A	9600	6L			GT4288	<b><u>452174-0003</u></b>	11033937
<b>FL10</b>	D10A	9600				GT4288	<b><u>452174-0005</u></b>	8128168
<b>FL10</b>	D10A	9600	6L			GT4288	<b><u>452174-0007</u></b>	8194549
<b>FL10</b>	TD101F	9600	6L	297	1983	TA4513	<b><u>466818-0001</u></b>	1545820
<b>FL10</b>	TD101F	9600	6L	297		TA4513	<b><u>466818-0002</u></b>	422809
<b>FL10</b>	TD102F	9600	6L	297	1986	TA4513	<b><u>466818-0003</u></b>	422856
<b>FL10</b>	TD103EA	9600	6L	297	1985	TA4513	<b><u>466818-0009</u></b>	479920
<b>FL10</b>	D10A	9600	6L	360	1995	GT4288	<b><u>452174-0001</u></b>	8194432
<b>FL10</b>	TD101G	9600	6L	361	1990	S3A	<b>312682</b>	1545281
<b>FL12</b>	TD122	11950	6L			TA5102	<b><u>466076-0019</u></b>	478795
<b>FL12</b>	TD121	11950	6L			TA5102	<b><u>466076-0019</u></b>	478794
<b>FL12</b>	TD122	11950	6L			TA5102	<b><u>466076-0020</u></b>	478795
<b>FL12</b>	TD121	11950	6L			TA5102	<b><u>466076-0020</u></b>	478794
<b>FL12</b>	TD121	11950	6L			TA5102	<b><u>466076-0021</u></b>	478794
<b>FL12</b>	TD122	11950	6L			TA5102	<b><u>466076-0021</u></b>	478795
<b>FL12</b>	TD121	11950	6L			TA5102	<b><u>466076-0024</u></b>	478794
<b>FL12</b>	TD122	11950	6L			TA5102	<b><u>466076-0024</u></b>	478795
<b>FL12</b>	D12A	12130	6L		1995	GT4594	<b><u>452164-0001</u></b>	8148873
<b>FL4</b>	TD41G				1986	H1C	<b>3524709</b>	422704
<b>FL6</b>	D6A	5480	6L	187	1995	GT3271	<b><u>452123-0001</u></b>	8192030
<b>FL6</b>	D6A	5480	6L	187	1995	GT3271	<b><u>452176-0001</u></b>	8192083
<b>FL6</b>	D6A	5480	6L	187	1995	GT3271	<b><u>452176-0002</u></b>	8192140
<b>FL6</b>	D6A	5480	6L	250	1995	GT3271	<b><u>452221-0001</u></b>	8192250
<b>FL6</b>	D6A	5480	6L	250	1995	GT3271	<b><u>452221-0002</u></b>	8192250
<b>FL6</b>	TD61G	6000			1985	H2A	<b>3523296</b>	420521
<b>FL6</b>	TD61G	6000			1986	H2A	<b>3524560</b>	420597
<b>FL6</b>	TD61F	6700		206	1985	TO4E04	<b><u>466588-0003</u></b>	465881
<b>FL6</b>	TD63ES	6700	6L	206		TO4E04	<b><u>466588-0008</u></b>	420835
<b>FL6</b>	TD63ES	6700	6L	206		TO4E04	<b><u>466588-0009</u></b>	420879
<b>FL6</b>	TD63ES	6700	6L	210		TO4E04	<b><u>466588-0011</u></b>	425548
<b>FL6</b>	TD61FB	6720	6L	206	1985	TO4E04	<b><u>466588-0003</u></b>	465881
<b>FL6</b>	TD63ES	6720	6L	206		TO4E04	<b><u>466588-0010</u></b>	425362

FL7	TD71F	6700		206		TO4E04	<b>466588-0005</b>	471627
FL7	TD71K	6720	6L			TO4E10	<b>466742-0002</b>	847858
FL7	TD71F	6720	6L	206	1985	TO4E04	<b>466588-0001</b>	471740
FL7	TD71FA	6720	6L	206	1985	TO4E04	<b>466588-0001</b>	471897
FL7	TD71F	6720	6L	206		TO4E04	<b>466588-0002</b>	471740
FL7	TD71FA	6720	6L	206		TO4E04	<b>466588-0002</b>	471897
FL7	TD71	6720	6L	206		TO4E04	<b>466588-0004</b>	421474
FL7	TD71FCQ	6720	6L	206	1985	TO4E04	<b>466588-0006</b>	420804
FL7	TD71FCQ	6720	6L	206	1985	TO4E04	<b>466588-0007</b>	420804
FL7	TD73ES	7000	6L		1991	H1E	<b>3530669</b>	477653
FL7	D7A	7000				WH1E	<b>3535970</b>	8192566
FM12	D12C	11950			1999	HX55	<b>3591077</b>	8113407
FM12	D12C	11950			1999	HX55	<b>3591077</b>	8113407
FM7	D7C	7000			1999	HX40W	<b>3592587</b>	8113604
FM9	D9	9400		340	2001	K29	<b>5329-988-6902</b>	8148173
FM9	D9	9400		340	2001	K29	<b>5329-988-6902</b>	8148173
FM9	D9	9400		340	2002	K29	<b>5329-988-6903</b>	20490969
FM9	D9	9400		340	2002	K29	<b>5329-988-6903</b>	20490969
FM9	D9	9400		380	2001	K29	<b>5329-988-6900</b>	20412609
FM9	D9	9400		380	2002	K29	<b>5329-988-6901</b>	20490975
FM9	D9	9400		380	2001	K29	<b>5329-988-6904</b>	20364192
FM9	D9	9400		380	2002	K29	<b>5329-988-6905</b>	11127840
FS7	TD73ES	7000	6L		1991	H1E	<b>3530669</b>	477653
HX60	D16A	16000				HX60	<b>3534182</b>	1556571
N10	TD100G	9600	6L			TA4502	<b>465922-0012</b>	1545098
N10	TD100G	9600	6L			TA4502	<b>465922-0012</b>	1545098
N10	TD100A	9600	6L	250	1980	4LEK	<b>54334</b>	467368
N10	TD100A	9600	6L	250	1980	4LEK	<b>54334</b>	467369
N10	TD100G	9600	6L	257	1981	TA4502	<b>465922-0002</b>	1545098
N10	TD101G	9600	6L	257		TA4502	<b>465922-0011</b>	1545073
N10	TD100C	9600	6L	260		4LGK	<b>310817</b>	467921
N10	TD100C	9600	6L	260	1979	4LGK	<b>3503150</b>	467921
N10	TD100G	9600	6L	261	1981	TA4502	<b>465922-0001</b>	1545073
N10	TD101F	9600	6L	297		TA4513	<b>466818-0001</b>	1545820
N10	TD102F	9600	6L	297	1985	TA4513	<b>466818-0003</b>	422935
N10	TD100B	9600		310		4LGK	<b>3528323</b>	467272
N10	TD100B	9600	6L	310		4LGK	<b>3528323</b>	467693
N10	TD100B	9600		310	1974	4LGK	<b>54797</b>	467272
N10	TD100B	9600	6L	310	1974	4LGK	<b>54797</b>	467693
N12	TD120E	11950	6L		1977	4LFK	<b>3500354</b>	468734

N12	TD120A	11950	6L			4LFK	<b>3528317</b>	425037
N12	TD120D	11950	6L			4LGK	<b>3528320</b>	468931
N12	TD120G	11950	6L			TA5101	<b><u>466074-0011</u></b>	470387
N12	TD121F	11950	6L	329	1984	TA5102	<b><u>466076-0012</u></b>	470509
N12	TD122FS	11950	6L	382	1988	TA5102	<b><u>466076-0015</u></b>	470943
N12	TD122FS	11950	6L	382	1988	TA5102	<b><u>466076-0015</u></b>	470944
N12	TD122FS	12000				H2D	<b>3525408</b>	470931
N12	TD120A	12000				4LFK	<b>3528317</b>	468230
N12	TD120E	12000				4LGK	<b>3528319</b>	468734
N12	TD121F	12000				4LGK	<b>3528326</b>	468882
N12	TD120A	12000				4LGZ	<b>5232-988-3280</b>	468619
N12	TD120C	12000				4LGZ	<b>5232-988-3283</b>	468962
N12	TD120G	12000				4LGZ	<b>5232-988-6400</b>	468997
N12	TD120A	12000		330	1972	4LFK	<b>54196</b>	468230
N12	TD120D	12000		350	1977	4LGK	<b>3502594</b>	468932
N12	TD122FS	12000		360	1984	H2D	<b>3526008</b>	470931
N12	TD122FS	12000		361	1990	S3B	<b>312862</b>	470931
N12	TD121F	12000		385	1979	4LGK	<b>3503623</b>	468922
N12	TD121F	12000		385	1985	4LGK	<b>3521971</b>	470779
N12	TD123E	12000		400	1984	H2D	<b>3526008</b>	470932
N7	TD70C			180	1970	3LD	<b>54089</b>	466182
N7	TD70E	6720	6L			TO4B29	<b><u>409840-0003</u></b>	466395
N7	TD70G	6720	6L			TO4B29	<b><u>409840-0005</u></b>	466876
N7	TD70G	6720	6L			TO4B29	<b><u>409840-0005</u></b>	466730
N84	TD50					3A-275	<b>24073</b>	421228
N86	TD70C			180	1970	3LD	<b>54089</b>	466181
N88	TD100A				1969	4LE	<b>53483</b>	422582
N88	TD100A	9600			1969	4-450	<b>10488</b>	417597
N88	TD100A	9600	6L	250		4LEK	<b><u>54334</u></b>	467369
N88	TD96	9600		1969	1969	4-450	<b>10488</b>	422252
NL10	TD101G	9600				TA4502	<b>465922-0012</b>	1545098
NL10	TD101G	9600	6L			TA4502	<b>465922-0012</b>	1545098
NL10	TD101G	9600	6L	257		TA4502	<b>465922-0011</b>	1545073
NL10	TD101G	9600	6L	261	1981	TA4502	<b>465922-0001</b>	1545073
NL10	TD101G	9600		261	1981	TA4502	<b>465922-0002</b>	1545098
NL10	TD102F	9600		297	1985	TA4513	<b><u>466818-0003</u></b>	422935
NL12	TD120G	11950	6L			TA5101	<b><u>466074-0011</u></b>	470387
NL12	TD123ES	11950	6L			TA5102	<b>466076-0020</b>	478795
NL12	TD122FK	12000				H2D	<b>3525408</b>	470931
NL12	TD123ES	12000				TA5102	<b><u>466076-0019</u></b>	478794

<b>NL12</b>	TD122FK	12000		360	1984	H2D	<b>3526008</b>	470931
<b>NL12</b>	TD122FK	12000		361	1990	S3B	<b>312862</b>	470931
<b>NL12</b>	TD121	12000		395		H2D	<b>3528811</b>	478672
<b>NL12</b>	TD123E	12000		400	1984	H2D	<b>3526008</b>	470932

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

## APPLICATIONS

SUITABLE FOR:

**White**

Model	Motor	CC	Nº of Cylinders	CV	Year	Model	Part Number	O.E.M Part Number
	TD123ED					TBP4801	<b>452060-0001</b>	478796
	TD123ED					TBP4801	<b>452060-0002</b>	478797
	TD123ED					TBP4801	<b>452060-0003</b>	478798
	TD73EB	7000	6L			H1E	<b>3529680</b>	477581
	TD73EA	7000	6L			H1E	<b>3530474</b>	477670
	TD73ES	7000	6L			H1E	<b>3533595</b>	8192580
	TD121FH	11950	6L			TA4530	<b><u>466666-0001</u></b>	470977
	TD122F	11950	6L	400	1984	H2D	<b>3526008</b>	478122
	D12A	12130	6L			GT4594	<b><u>452164-0005</u></b>	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.