

# TurboMaster



[WWW.TURBOMASTER.INFO](http://WWW.TURBOMASTER.INFO)

MAR MEDITERRÁNEO, 1 - NAVE 7

28830 SAN FERNANDO DE HENARES (MADRID)

ESPAÑA - SPAIN

TELEPHONE: +34 916.569.273 - 916.569.288

FAX: +34 916.569.397

[SALES@TURBOMASTER.INFO](mailto:SALES@TURBOMASTER.INFO)

**Catalog 2.0 - 2006**



Click on the page:

**RHO Series**

RHO5

RHO6

RHO7

**RHB Series**

RHB3

RHB4

RHB5

RHB6

RHB7

RHB8

**RHC Series**

RHC6

RHC7

RHC9

**RHE Series**

RHE5

RHE6

RHE7

RHE8

**RHF Series**

RHF3

RHF3V

RHF4

RHF4V

RHF5

RHF6

#### RHG Series

RHG6

#### KHF Series

KHF5

**Catalog 2.0 - 2006**



**RHO5**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
<b>VB1</b>	<b>RHO5</b>				
IHIVB1	SHELBY				
<b>VB4</b>	<b>RHO5</b>				
IHIVB4	SHELBY				

**Catalog 2.0 - 2006**



**RHO6**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
AY1	YANMAR				
IHIAY1	YANMAR				
VE3	PERKINS				
NN970014	YANMAR				

Catalog 2.0 - 2006



**RHO7**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
<b>MD5</b>	<b>RHO724-W</b>				
NN780041	NISSAN				
<b>MK15</b>	<b>RHO7AW</b>				
NN780019	KUBOTA				
<b>MK16</b>	<b>RHO7AW</b>				
NN780032	KUBOTA				
<b>MK17</b>	<b>RHO7AW</b>				
NN780021	KUBOTA				NN780033
NN780033	KUBOTA				
<b>MK18</b>	<b>RHO7AW</b>				
NN780020	KUBOTA				NN780034
NN780034	KUBOTA				

Catalog 2.0 - 2006

**IHI****RHB3**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
<b>AI71</b>	<b>RHB31</b>				
VA11036	ISUZU				
<b>AY49</b>	<b>RHB31</b>				
NB130031	YANMAR	NZ852836	NB139837		VA110030
<b>AY68</b>	<b>RHB31-50001P12NFBR255AZ</b>				
VA110052	YANMAR			12	
<b>CIAT</b>	<b>RHB31</b>				
VA110098	ISUZU				
<b>CY26</b>	<b>RHB31-50001P12NFBR255AZ</b>				
NB130015	YANMAR	NZ852836	NB139837	12	VA110024
NB130024	YANMAR	NZ852836	NB139837	12	VA110024
VA110024	YANMAR	NZ852836	NB139837	12	
<b>CY43</b>	<b>RHB31</b>				
NB130025	YANMAR	NZ852836	NB139837		VA110028
VA110028	YANMAR	NZ852836	NB139837		
<b>CY46</b>	<b>RHB31</b>				
NB130028	YANMAR	NZ852836	NB139837		VA110032
VA110032	YANMAR	NZ852836	NB139837		
<b>CY47</b>	<b>RHB31</b>				
NB130026	YANMAR	NZ852836	NB139837		VA110029
VA110029	YANMAR	NZ852836	NB139837		VA110029
<b>CY50</b>	<b>RHB31</b>				
NB130032	YANMAR	NZ852836	NB139837		VA110030
VA110030	YANMAR	NZ852836	NB139837		
<b>CY62</b>	<b>RHB31-50001P9NFBR255AZ</b>				
VA110033	YANMAR		NB139837		VB110033
VB110033	YANMAR		NB139837		
<b>CY63</b>	<b>RHB31-50001P7NFBR255A</b>				
VA110034	YANMAR	NZ852836	NB139837		VB110034
VB110034	YANMAR	NZ852836	NB139837	7	
<b>GY28</b>	<b>RHB31-50001P7NFBR255A</b>				
NB130016	YANMAR	NZ852836	NB139837	7	VA110025

VA110025	YANMAR	NZ852836	NB139837	7	
<b>GY66</b>	<b>RHB31-55001P12NFBR255A</b>				
VA110044	YANMAR		NB139837	12	
<b>MY41</b>	<b>RHB31-5000IP7NFBR255A</b>				
NB130023	YANMAR	NZ852836	NB139837	7	VA110026
VA110026	YANMAR	NZ852836	NB139837	7	
<b>MY42</b>	<b>RHB31</b>				
VA110027	YANMAR		NB139837		
<b>MY61</b>	<b>RHB31-50001P12NFBR255AZ</b>				
VA110021	YANMAR	NZ852836	NB139837	12	VB110021
VB110021	YANMAR	NZ852836	NB139837	12	
<b>MY65</b>	<b>RHB31GW-55001GP7NWBR255A</b>				
<u>VA110017</u>	YANMAR	NZ852857	NB139837	7	
<b>MY69</b>	<b>RHB31GW-50001GP7NWBR255A</b>				
VA110073	YANMAR		NB139837	7	
<b>VI32</b>	<b>RHB32B-55001BP14NRBRL314BZ</b>				
NB130021	ISUZU		NB139837	14	VD110035
VA110035	ISUZU		NB139837	14	VD110035
VB110035	ISUZU		NB139837	14	VD110035
<u>VD110035</u>	ISUZU		NB139837	14	
<b>VI61</b>	<b>RHB32BW-68002BP14NR5BRL314CBZ</b>				
VA110022	ISUZU	NZ851412	NB139838	14	VE110094
VB110022	ISUZU	VA800012	NB139838	14	VE110094
<u>VE110022</u>	ISUZU	VA800012	NB139838	14	VE110094
<b>VIAL</b>	<b>RHB32BW-68002BP14NRBRL314CBZ</b>				
VA110094	ISUZU	VA800012	NB139838	14	VE110094
<u>VE110094</u>	ISUZU	VA800012	NB139838	14	
<b>VQ1</b>	<b>RHB32A-68002P14NRBRAL304BZ</b>				
NB130012	DAIHATSU	NE910016	NB139838	14	
<b>VQ11</b>	<b>RHB32A-68002P14NRBRAL304BZ</b>				
NB130037	DAIHATSU	NE910016		14	
<b>VQ12</b>	<b>RHB32A-68002P14NRBRAL304BZ</b>				
NB130038	DAIHATSU	NE910016		14	
<b>VQ13</b>	<b>RHB31AW-30004AP7NRBRAS245AZ</b>				
NB130040	DAIHATSU			7	VG110011
VA110011	DAIHATSU			7	VG110011
VD110050	DAIHATSU			7	VG110011
VG110011	DAIHATSU			7	
<b>VQ14</b>	<b>RHB31W-30004P7NRBR255AZ</b>				
NB130041	DAIHATSU			7	VF110051
VA110051	DAIHATSU			7	VF110051
VF110051	DAIHATSU			7	



<b>VQ16</b>	<b>RHB31AW-5000IAP7NRBRAS255DZ</b>				
VA110012	DAIHATSU			7	VH110014
VA110014	DAIHATSU			7	VH110014
VD110012	DAIHATSU			7	VH110014
VH110014	DAIHATSU			7	
<b>VQ18</b>	<b>RHB31AW</b>				
VA110042	DAIHATSU				VG110045
VA110045	DAIHATSU				VG110045
VG110045	DAIHATSU				
<b>VQ19</b>	<b>RHB31W</b>				
VA110046	DAIHATSU				VI110040
VH110046	DAIHATSU				VI110040
VI110040	DAIHATSU				
<b>VQ2</b>	<b>RHB31-5000IP7NRBRS225AZ</b>				
NB130011	DAIHATSU			7	
<b>VQ20</b>	<b>RHB31HW-50001AP9NRBRHS274EZ</b>				
VA110076	DAIHATSU			9	VG110076
VD110076	DAIHATSU			9	VG110076
VG110076	DAIHATSU			9	
<b>VQ25</b>	<b>RHB31HWB-55001AP9NRBRHS314CBZ</b>				
VA610011	DAIHATSU			9	
<b>VQ3</b>	<b>RHB31-5000IP7NRBRS225AZ</b>				
NB130013	DAIHATSU			7	
<b>VQ4</b>	<b>RHB32A-68002P14NRBRAL304BZ</b>				
<u>NB130014</u>	DAIHATSU	NE910016	NB139838	14	
<b>VQ6</b>	<b>RHB31-5000IP7NRBRS225AZ</b>				
NB130017	DAIHATSU			7	
<b>VQ7</b>	<b>RHB32A-68002P14NRBRAL304BZ</b>				
NB130018	DAIHATSU	NE910016	NB139838	14	
<b>VQ8</b>	<b>RHB31A-30004P7NRBRAS245AZ</b>				
NB130020	DAIHATSU			7	VF110015
VA110015	DAIHATSU			7	VF110015
VF110015	DAIHATSU			7	
<b>VQ9</b>	<b>RHB31-30004P7NRBRAS225AZ</b>				
NB130030	DAIHATSU			7	VE110049
VA110049	DAIHATSU			7	VE110049
VE110049	DAIHATSU			7	VE110049
<b>VZ10</b>	<b>RHB31DW-30004DP7NRBRDL245AZ</b>				
VK110016	SUZUKI			7	
<b>VZ13</b>	<b>RHB31CW-68002P14NRBRCL314BZ</b>				
VD110043	SUZUKI			14	
<b>VZ2</b>	<b>RHB32C-68002CP14NRBRCL314BZ</b>				

NB130019	SUZUKI			14	
NZ852469	SUZUKI			14	
<b>VZ24</b>	<b>RHB31FW-34004FP7NRBRFL2416CDZ</b>				
VA110079	SUZUKI			7	VD110079
VD110079	SUZUKI			7	
<b>VZ25</b>	<b>RHB31FW</b>				
VA110087	SUZUKI				VE110087
VC110087	SUZUKI				VE110087
<b>VZ25</b>	<b>RHB31FW-50001FP9NRBRFL275CDZ</b>				
VE110087	SUZUKI			9	
<b>VZ26</b>	<b>RHB31FW</b>				
VA110092	SUZUKI				VC110092
VC110092	SUZUKI				
<b>VZ27</b>	<b>RHB31CW-30004CP7NRBRDL245AZ</b>				
VA110093	SUZUKI			7	VD110093
VD110093	SUZUKI			7	
<b>VZ3</b>	<b>RHB31DW-50001DP7NRBRDL225AZ</b>				
VF110061	SUZUKI			7	
<b>VZ5</b>	<b>RHB32CW-68002CP14NRBRCL314BZ</b>				
VD110018	SUZUKI			14	
<b>VZ6</b>	<b>RHB31CW-30004CP7NRBRDL245AZ</b>				
VG110019	SUZUKI			7	
<b>VZ9</b>	<b>RHB31CW-30004CP7NRBRDL245AZ</b>				
NB130042	SUZUKI			7	VG110065
VA110023	SUZUKI			7	VG110065
VA110065	SUZUKI			7	VG110065
VB110023	SUZUKI			7	VG110065
VB110065	SUZUKI			7	VG110065
VC110023	SUZUKI			7	VG110065
VC110065	SUZUKI			7	VG110065
VD110023	SUZUKI			7	VG110065
VD110065	SUZUKI			7	VG110065
VE110065	SUZUKI			7	VG110065
VF110065	SUZUKI			7	VG110065
VG110065	SUZUKI			7	

Catalog 2.0 - 2006

**IHI****RHB4**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
<b>T3P9C</b>	<b>RHB4BW-46001BP9NR5BRBL343CAZ</b>				
VA120011	ISUZU	VA840012	NB149801	9	VE120011
<u>VE120011</u>	ISUZU	VA840012	NB149801	9	
<b>VI72</b>	<b>RHB4BW-46001BP11NRBRBL343CBZ</b>				
VA120012	ISUZU	VA840011	NH149801	11	VB420011
VC120012	ISUZU	VA840011	NB149801	11	VB420011
<u>VE120012</u>	ISUZU	VA840011	NB149801	11	VB420011
<b>VI84</b>	<b>RHB4BW</b>				
<u>VA120013</u>	ISUZU	VA840011	NH149801		
<b>VI94</b>	<b>RHB4BW-46001P9NHBRL343CBZ</b>				
<u>VA120015</u>	ISUZU	VA840011	NH149801	9	
<b>VIAU</b>	<b>RHB4BW-46001BP9NHBRDL343CBZ</b>				
<u>VA120019</u>	ISUZU	VA840011		9	
<b>VIAV</b>	<b>RHB4BW-46001BP11NRBRDL343CBZ</b>				
<u>VA120018</u>	ISUZU	VA840011	NB149801	11	

Catalog 2.0 - 2006

**IHI****RHB5**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
<b>AI11</b>	<b>RHB51</b>				
NN130013	ISUZU				VC130012
VA130012	ISUZU				VC130012
VB130012	ISUZU				VC130012
VC130012	ISUZU				
<b>AI24</b>	<b>RHB51</b>				
NN130033	ISUZU				VC130014
VA130014	ISUZU				VC130014
VB130014	ISUZU				VC130014
VC130014	ISUZU				VC130014
<b>AI79</b>	<b>RHB52</b>				
VA130094	ISUZU				VC130097
<b>AIAD</b>	<b>RHB52</b>				
VA180043	ISUZU				
<b>AS7</b>	<b>RHB51-34001P9NFBRL345CZ</b>				
VA180035				9	
<b>AS9</b>	<b>RHB51-34001P9NFBRS294DZ</b>				
VA180068		IHCAS9	NN139922	9	
<b>AY33</b>	<b>RHB51-34001P12NFBRL338C</b>				
NN130044	YANMAR			12	VA130038
VA130038	YANMAR			12	
<b>AY64</b>	<b>RHB52</b>				
VA130061	YANMAR				
<b>AY72</b>	<b>RHB51</b>				
VA180024	YANMAR				
<b>AY73</b>	<b>RHB51</b>				
VA180022	YANMAR				
<b>AY78</b>	<b>RHB52</b>				
VA180048	YANMAR				
<b>CI15</b>	<b>RHB51-52002P9NFBRS274D</b>				
NN130023	ISUZU			9	VB130013
VA130013	ISUZU			9	VB130013

VB130013	ISUZU			9	
<b>CI30</b>	<b>RHB52</b>				
NN130040	ISUZU				
<b>CICM</b>	<b>RHB52</b>				
VA190037	ISUZU				
<b>CY55</b>	<b>RHB51-34001P12NRBRL338CZ</b>				
NB150029	YANMAR				VA180025
VA180025	YANMAR			12	
<b>CYAR</b>	<b>RHB52-52002P15NFBRL3911CE</b>				
VA180078	YANMAR	VA810027	NN139921A	15	
<b>GI24</b>	<b>RHB52</b>				
NN130034	ISUZU				
<b>GX16</b>	<b>RHB52</b>				
NN130036	HINO				VC130058
VA130058	HINO				VC130058
VB130058	HINO				VC130058
VC130058	HINO				
<b>GX38</b>	<b>RHB52-52002P15NFBRL348C</b>				
NB150050	HINO			15	VB130059
VA130059	HINO		15		VB130059
VB130059	HINO			15	
<b>GY12</b>	<b>RHB51</b>				
NN130015	YANMAR				
<b>GY14</b>	<b>RHB51-34001P9NFBRS291A</b>				
NN130017	YANMAR			9	VA130032
VA130032	YANMAR	NZ853948	NN139921A	9	
<b>GY32</b>	<b>RHB51</b>				
NN130043	YANMAR				VA130037
VA130037	YANMAR				
<b>GY48</b>	<b>RHB51</b>				
NB150022	YANMAR				VA130040
VA130040	YANMAR				
<b>GY56</b>	<b>RHB52</b>				
VA130064	YANMAR				VA130065
<b>GY57</b>	<b>RHB52-100003P20NFBRL4016E</b>				
VA130065	YANMAR		NN139921A	20	
<b>GY74</b>	<b>RHB52</b>				
VA180031	YANMAR				
<b>MI45</b>	<b>RHB52</b>				
NB150020	ISUZU				
<b>MI57</b>	<b>RHB52</b>				
NB150039	ISUZU				VB130020

VB130020	ISUZU				
<b>MI64</b>	<b>RHB52</b>				
VA130020	ISUZU				VB130020
<b>MV1</b>	<b>RHB51FW-34001FP7NWBR294D</b>				
<u>NN130066</u>	VOLVO PENTA	VA810014	NN139921A	7	
<b>MY20</b>	<b>RHB52</b>				
NN130029	YANMAR				VA130035
<b>MY25</b>	<b>RHB52</b>				
NB150043	YANMAR				NN130037
NN130037	YANMAR				
<b>MY29</b>	<b>RHB52-52002P15NFBRL348C</b>				
NN130041	YANMAR	NE920018	NN139921A	15	VA130035
VA130035	YANMAR	NE920018	NN139921A	15	
<b>MY31</b>	<b>RHB52HW-90004HP12NWBRL348C</b>				
<u>NN130042</u>	YANMAR			12	
<b>MY34</b>	<b>RHB52-52002HP15NWBRL3511CE</b>				
NB150012	YANMAR	NZ853146	NN139921A	15	VA130039
VA130039	YANMAR	NZ853146	NN139921A	15	
<b>MY60</b>	<b>RHB52HW-90004HP12NWBRL348C</b>				
<u>NB150045</u>	YANMAR		NN139921A	12	
<b>MY67</b>	<b>RHB52-52002HP12NWBRL3511CE</b>				
<u>VA130085</u>	YANMAR	NZ853146	NN139921A	12	
<b>MY75</b>	<b>RHB52W-34001HP12BRL338C</b>				
<u>VA180032</u>	YANMAR			12	
<b>MY8</b>	<b>RHB52-52002P20NFBRL345C</b>				
NN130012	YANMAR			20	VA130030
VA130030	YANMAR			20	
<b>MYAZ</b>	<b>RHB52W-52002HP15NWBRL3611CE</b>				
<u>VA180097</u>	YANMAR			15	
<b>MYBD</b>	<b>RHB52HW-90004HP12NWBRL3911CE</b>				
<u>VA180099</u>	YANMAR	NZ854285	NN139922A	12	
<b>VA11</b>	<b>RHB52P-34001PP12NHBRL3511EZ</b>				
NN130082	RENAULT	VD810012	NN139922A	12	VE130044
VA130044	RENAULT	VD810012	NN139922A	12	VE130044
VE110044	RENAULT	VD810012	NN139922A	12	
<b>VA55B</b>	<b>RHB51P-56005PP10.5NHBRL3730CEZ</b>				
VA180053	VM	VC810052	NN139922B	10.5	VB180053
<u>VB180053</u>	CHRYSLER	VC810052	NN139922B	10.5	
<b>VA56A</b>	<b>RHB51R-70005PP12NHBRL3629CEZ</b>				
<u>VA180055</u>	ALFA ROMEO	VC810051	NN139922A	12	
<b>VA57A</b>	<b>RHB51P</b>				

VA180083	VM	VC810057			
<b>VA58A</b>	<b>RHB51P-70005PP12NHBRL3629CEZ</b>				
VA180056	FORD	VC810051	NN139922A	12	VC180056
<u>VB180056</u>	FORD	VC810051	NN139922A	12	VC180056
<u>VC180056</u>	FORD	VC810051	NN139922A	12	
<b>VA58B</b>	<b>RHB51P-70005PP12NHBRL3629CEZ</b>				
<u>VA190011</u>	FORD	VC810051	NN139922B	12	VA180086
VB190011	FORD	VC810051	NN139922B	12	VA180086
<b>VA59A</b>	<b>RHB51P-7000VPP12NHBRL3629CEZ</b>				
<u>VA180069</u>	CHRYSLER	VC810051	NN139922A	12	
<b>VA59B</b>	<b>RHB51P-56005IPP10.5NHBRL3730CEZ</b>				
<u>VA180086</u>	CHRYSLER	VC810052	NN139922B	10.5	
<b>VA60A</b>	<b>RHB51P-56005PP12NHBRL3629CEZ</b>				
<u>VA180062</u>	CHRYSLER	VC810057	NN139922A	12	
<b>VA63</b>	<b>RHB51P-70005PP12NHBRL3629CEZ</b>				
VA180071	VM	VB810044		12	VD180071
<u>VC180071</u>	VM	VC810051	NN139922A	12	VD180071
<u>VD180071</u>	VM	VC810051	NN139922A	12	
<b>VA63B</b>	<b>RHB51P-70005PP12NHBRL3629CEZ</b>				
VA190014	CHRYSLER	VB810044		12	VB190014
<u>VB190014</u>	CHRYSLER	VC810051	NN139922B	12	
<b>VC19</b>	<b>RHB52-52002P15NRBRL393BZ</b>				
VA130082				15	
<b>VC20</b>	<b>RHB52-52002P20NRBRL393BZ</b>				
VA130083	WARNER ISHI			20	VC130083
VC130083	FORD		NN139921A	20	
<b>VC31</b>	<b>RHB52-52002P12NRBRL358CZ</b>				
NN130057	FORD		NN139921A	12	
VA130043				12	
<b>VC34</b>	<b>RHB52-52002P15NRBRL393BZ</b>				
NN130063				15	
<b>VE105</b>	<b>RHB52-52002P9NRBRL345CZ</b>				
<u>NN130084</u>	FORD		NN139922A	9	VA130072
<b>VE106</b>	<b>RHB52-52002P12NRBRL3911EZ</b>				
VA130048	FORD	VA810027	NN139922A	12	VB130048
VB130048	FORD	VA810027	NN139922A	12	
<b>VE107</b>	<b>RHB52-52002P9NRBRL345CZ</b>				
VA130072	FORD		NN139922A	9	
<b>VE108</b>	<b>RHB52-52002P9NHBRL3711EZ</b>				
VA130095	FORD		NN139922A	9	VC130095
<u>VB130095</u>	FORD		NN139922A	9	VC130095

VC130095	FORD		NN139922A	9	
<b>VE109</b>	<b>RHB52-52002P12NRBRL348CZ</b>				
<u>VA180057</u>	FORD	NE920018	NN139922A	12	
<b>VF1</b>	<b>RHB52D-34001DP12NRBRDL345CZ</b>				
NN130014	SUBARU	NE920011		12	
<b>VF10</b>	<b>RHB52XW-52002P15NRBRXLL4225CFZ</b>				
VA130098	SUBARU		NN139922A	15	VH130099
VA130099	SUBARU		NN139922A	15	VH130099
VC130098	SUBARU		NN139922A	15	VH130099
VC130099	SUBARU		NN139922A	15	VH130099
VE130099	SUBARU			15	VH130099
VH130099	SUBARU		NN139922A	15	
VJ130098	SUBARU		NN139922A	15	VH130099
<b>VF11</b>	<b>RHB52XW-52002XP15NRBRL4016EZ</b>				
VA180017	SUBARU			15	VA180021
VA180021	SUBARU			15	
VB180017	SUBARU			15	VA180021
<b>VF12</b>	<b>RHB52XW-100003XP20NRBRXLL4726CFZ</b>				
VA180038	SUBARU	NZ853109		20	VB180039
VA180039	SUBARU	NZ853109		20	VB180039
VB180039	SUBARU	NZ853109	NN139922A	20	
<b>VF2</b>	<b>RHB52EW-52002EP12NRBREL3911EZ</b>				
NB150017	SUBARU	NE920028	NN139922A	12	VC130054
NN130031	SUBARU	NE920028	NN139922A	12	VC130054
<b>VF3</b>	<b>RHB52EW-52002EP15NRBREL3911EZ</b>				
NB150018	SUBARU	NE920028		15	VD130056
NN130038	SUBARU	NE920028		15	VD130056
<b>VF4</b>	<b>RHB52EW-52002EP12NRBREL3911EZ</b>				
NB150031	SUBARU	NE920028	NN139922A	12	VC130054
NB150033	SUBARU	NE920028	NN139922A	12	VC130054
NB150054	SUBARU	NE920028	NN139922A	12	VC130054
NB150055	SUBARU	NE920028	NN139922A	12	VC130054
VA130053	SUBARU	NE920028	NN139922A	12	VC130054
<b>VF5</b>	<b>RHB52EW-5200IIEP12NRBREL3911EZ</b>				
NB150034	SUBARU	NE920028	NN139922A	12	VC130054
NB150035	SUBARU	NE920028	NN139922A	12	VC130054
NB150056	SUBARU	NE920028	NN139922A	12	VC130054
NB150057	SUBARU	NE920028	NN139922A	12	VC130054
VA130054	SUBARU	NE920028	NN139922A	12	VC130054
VA130084	SUBARU	NE920028	NN139922A	12	VC130054
VC130054	SUBARU	NE920028	NN139922A	12	VC130054
<b>VF6</b>	<b>RHB52EW-5200IIEP15NRBREL3911EZ</b>				



NB150036	SUBARU	NE920028	NN139922A	15	VE130056
NB150037	SUBARU	NE920028	NN139922A	15	VE130056
NB150058	SUBARU	NE920028	NN139922A	15	VE130056
NB150059	SUBARU	NE920028	NN139922A	15	VE130056
VA130055	SUBARU	NE920028	NN139922A	15	VE130056
VA130056	SUBARU	NE920028	NN139922A	15	VE130056
VB130056	SUBARU	NE920028	NN139922A	15	VE130056
VC130055	SUBARU	NE920028	NN139922A	15	VE130056
VD130055	SUBARU	NE920028	NN139922A	15	VE130056
<b>VF6</b>	<b>RHB52EW-52002EP15NRBREL3911EZ</b>				
VD130056	SUBARU	NE920028	NN139922A	15	
<b>VF6</b>	<b>RHB52EW-5200IIEP15NRBREL3911EZ</b>				
VE130056	SUBARU	NE920028	NN139922A	15	VE130056
<b>VF7</b>	<b>RHB52DW-34001DP12NRBRDL345CZ</b>				
NN130048	SUBARU	NE920029	NN139921A	12	VA130086
VA130086	SUBARU	NE920029	NN139921A	12	
<b>VF8</b>	<b>RHB52XW-100003XP20NRBRXLL4625CFZ</b>				
VA130074	SUBARU			20	VG130075
VA130075	SUBARU			20	VG130075
VC130074	SUBARU			20	VG130075
VC130075	SUBARU			20	VG130075
VG730075	SUBARU			20	
<b>VG1</b>	<b>RHB51A-3400IAP9NRBRS291AZ</b>				
NN130011	HONDA			9	
<b>VG2</b>	<b>RHB51CW-34001CP9NRBRCS338CZ</b>				
NB150023	HONDA			9	
NN130016	HONDA			9	
<b>VG3</b>	<b>RHB51E-34001EP12NRBRL338CZ</b>				
NN130022	HONDA			12	
<b>VG4</b>	<b>RHB51DW-34001DP12NRBRDL338CZ</b>				
NB150024	HONDA			12	
<b>VI13</b>	<b>RHB52A-34001AP12NRBRL345CZ</b>				
NB150051	ISUZU	NE820013		12	
NN130021	ISUZU			12	NN130021
<b>VI14</b>	<b>RHB52-52002P20NRBRL393BZ</b>				
NN130024	ISUZU		NN139922A	20	
<b>VI19</b>	<b>RHB52A-52002AP12NRBRL348CZ</b>				
NB130052	ISUZU	NE920018	NN139922A	12	VB130049
NB150041	ISUZU	NE920018	NN139922A	12	VB130049
NN130027	ISUZU	NE920018	NN139922A	12	VB130049
VA130049	ISUZU	NE920018	NN139922A	12	VB130049
VB130049	ISUZU	NE920018	NN139922A	12	

<b>VI21</b>	<b>RHB52A-52002AP12NRBRL348CZ</b>				
NB150044	ISUZU	NE920018	NN139922A	12	VB130050
NB150053	ISUZU	NE920018	NN139922A	12	VB130050
NN130030	ISUZU	NE920018	NN139922A	12	VB130050
VA130050	ISUZU	NE920018	NN139922A	12	VB130050
<u>VB130050</u>	ISUZU	NE920018	NN139922A	12	
<b>VI23</b>	<b>RHB52A-100003P25NRBRL3911EZ</b>				
NN130032	ISUZU	NE920019	NN139922A	25	
<b>VI34</b>	<b>RHB52A-100003P25NRBRL3911EZ</b>				
NN130046	ISUZU	VA810038	NN139921A	25	VD130067
VA130067	ISUZU	VA810038	NN139922A	25	VD130067
<u>VC130067</u>	ISUZU	VA810038	NN139922A	25	VD130067
VD130067	ISUZU	VA810038	NN139922A	25	
<b>VI36</b>	<b>RHB52W</b>				
NB150011	ISUZU				VE130066
VA130066	ISUZU				VE130066
VC130066	ISUZU				
<b>VI37</b>	<b>RHB52W-100003P25NR5BRL3911EZ</b>				
VD130066	ISUZU	VA810038		25	VE130066
VE130066	ISUZU	VA810038		25	
<b>VI43</b>	<b>RHB52W-52002P15NRBRL348CZ</b>				
NB150019	ISUZU		NN139922A	15	NB150049
NB150049	ISUZU	NE920020	NN139922A	15	
<b>VI55</b>	<b>RHB52W-52002P15NRBRL348CZ</b>				
NB150030	ISUZU	VA810040		15	VB130070
VA130070	ISUZU	VA810040		15	VB130070
VB130070	ISUZU	VA810040		15	
<b>VI58</b>	<b>RHB52W-52002AP15NRBRL3911CZ</b>				
NB150040	ISUZU	VA810023	NN139922A	15	VF130047
VA130047	ISUZU	VA810023	NN139922A	15	VF130047
<u>VD130047</u>	ISUZU	VA810023	NN139922A	15	VF130047
VF130047	ISUZU	NE920028	NN139922A	15	
<b>VI74</b>	<b>RHB52W-70005P12NRBRL3911CZ</b>				
<u>VA130057</u>	ISUZU	VA810037	NN139921A	12	VC130057
<u>VC130057</u>	ISUZU	VA810037	NN139921A	12	
<b>VI77</b>	<b>RHB52TW-52002TP15NRBRL3911CEZ</b>				
VA130073	ISUZU	NE920028	NN139922A	15	VE130073
VB130073	ISUZU	NE920028	NN139922A	15	VE130073
VE130073	ISUZU	NE920028	NN139922A	15	
<b>VI78</b>	<b>RHB52TW-52002TP15NRBRL3911EZ</b>				
VA130087	ISUZU	NE920028		15	VD130087
VC130087	ISUZU	NE920028		15	VD130087

VD130087	ISUZU	NE920028		15	
<b>VI83</b>	<b>RHB52W-70005P12NRBRL3911CEZ</b>				
VA130097	ISUZU	VA810037		12	VC130097
VB130097	ISUZU	VA810037		12	VC130097
<u>VC130097</u>	ISUZU	VA810037		12	
<b>VI85</b>	<b>RHB52W-52002P15NRBRL3911EZ</b>				
VA180011	ISUZU	NE920028	NN139922A		VC130097
<b>VI86</b>	<b>RHB52W-52002P10.5NRBRL3711CEZ</b>				
VA130096	ISUZU	NE920038		10.5	VB130096
VB130096	ISUZU	NE920038		10.5	
<b>VI87</b>	<b>RHB52W-52002P10.5NRBRL3711CEZ</b>				
VA180018	ISUZU	NE920040		10.5	VC180018
VC180018	ISUZU	NE920040		10.5	
<b>VI95</b>	<b>RHB52W-70005NBR3911E</b>				
VA180027	ISUZU	VA810037	NN139922A		VE180027
VD180027	ISUZU	VA810037	NN139922A		VE180027
<u>VE180027</u>	ISUZU	VA810037	NN139922A		
<b>VIAH</b>	<b>RHB52W-70005P15NHBRL3911CEZ</b>				
VA180051	ISUZU	VA810037	NN139922A	15	VD180051
VC180051	ISUZU	VA810037	NN139922A	15	VD180051
<b>VIAH</b>	<b>RHB52W-70005P15NHBRL3911EZ</b>				
VD180051	ISUZU	VA180037	NN139922A	15	
<b>VIAJ</b>	<b>RHB52TW</b>				
VA180052	ISUZU				
<b>VJ1</b>	<b>RHB52B-52002BP12NRBRBL338CZ</b>				
NN130025	MAZDA	NE920015	NN139921A	12	
<b>VJ10</b>	<b>RHB52VW-52002Q14NSBRL3911EZ</b>				
VB330011	MAZDA	VA810025		14	VC130011
VC330011	MAZDA	VA810025		14	
<b>VJ11</b>	<b>RHB52KW-52002KP20NR5BRL3911EZ</b>				
NB150028	MAZDA	NE920031	NN139921A	20	VB130022
<u>VB130022</u>	MAZDA	NE920031	NN139921A	20	
<b>VJ12</b>	<b>RHB52BW-52002BP12NRBRKL3711EZ</b>				
NB150032	MAZDA	VA810033	NN139922A	12	
<b>VJ13</b>	<b>RHB52MW-52002MP12NRBRKL3711EZ</b>				
NB150038	MAZDA	VA810033	NN139922A	12	VB130025
VB130025	MAZDA	VA810033	NN139922A	12	
<b>VJ14</b>	<b>RHB52MW-52002MP12NRBRKL3711EZ</b>				
NB150042	MAZDA	NE920030	NN139921A	12	VB130024
<b>VJ14</b>	<b>RHB52MW-52002MP12NR5BRKL3711EZ</b>				
<u>NB150061</u>	MAZDA	NE920030	NN139921A	12	VB130024
VB130024	MAZDA	NE920030		12	

<b>VJ16</b>	<b>RHB52MW-52002MP15NR5BRKL3911EZ</b>				
NB150047	MAZDA	VA810030		15	
<b>VJ17</b>	<b>RHB52BW-100003BP25NR5BRL4016EZ</b>				
<u>NB150048</u>	MAZDA	VA810031		25	
<b>VJ18</b>	<b>RHB52MW-52002MP12NRBRKL3711EZ</b>				
VA130021	MAZDA	VA810033	NN139922A	12	VB130021
<u>VB130021</u>	MAZDA	VA810033	NN139922A		
<b>VJ19</b>	<b>RHB52VW</b>				
VA330013	MAZDA				
<b>VJ2</b>	<b>RHB52B-52002BP20NRBRBL348CZ</b>				
NN130026	MAZDA	NZ853872	NN139921A	20	
<b>VJ20</b>	<b>RHB52UW-52002UP15NR5BRUL3911EZ</b>				
VA130029	MAZDA	VA810030	NN139922A	15	VB130029
VB130029	MAZDA	VA810030	NN139922A	15	
<b>VJ21</b>	<b>RHB52UW-52002UP15NR5BRUL3911EZ</b>				
VA130068	MAZDA	VA810030	NN139922A	15	VB130068
VB130068	MAZDA	VA810030	NN139922A	15	
<b>VJ22</b>	<b>RHB52UW-52002UP15NRBRUL4016EZ</b>				
VA180044	MAZDA	VA810029		15	
<b>VJ3</b>	<b>RHB52B-5200IIBP12NRBRKL338CZ</b>				
NN130039	MAZDA			12	
<b>VJ4</b>	<b>RHB52B-52002BP20NRBRBL3911EZ</b>				
NN130045	MAZDA		NN139921A	20	
<b>VJ5</b>	<b>RHB52KW-52002KP20NRBRKL3911EZ</b>				
NN130049	MAZDA	NE920031	NN139921A	20	VA130079
VA130079	MAZDA	NE920031	NN139921A	20	
<b>VJ6</b>	<b>RHB52BW-52002BP12NRBRKL3711EZ</b>				
NB150014	MAZDA	VA810036	NN139922A	12	VA130078
VA130078	MAZDA	VA810036	NN139922A	12	
<b>VJ7</b>	<b>RHB52KW-52002KP20NRBRKL348CZ</b>				
NB150015	MAZDA	VA810035	NN139921A	20	
<b>VJ8</b>	<b>RHB52KW-52002KP20NRBRKL348CZ</b>				
NB150016	MAZDA	VA810035	NN139921A	20	
<b>VJ9</b>	<b>RHB52MW-52002MP15NR5BRKL3911EZ</b>				
NB150025	MAZDA	NZ851414	NN139922A	15	VB130023
NB150060	MAZDA	VA810030	NN139922A	15	VB130023
VB130023	MAZDA	VA810030	NN139922A	15	
<b>VL1</b>	<b>RHB52-34001P7NRBR338CZ</b>				
NN130060	LANCIA	NE920012	NN139921A	7	
<b>VL10</b>	<b>RHB52G-56006GP12NHBRKL3730CEZ</b>				
<u>VA180094</u>	FIAT	VB810059	NN139922B	12	

<b>VL11</b>	<b>RHB52G-56006GP12NHBRKL3730CEZ</b>				
<u>VA180098</u>	LANCIA	VB810059	NN139922B	12	
<b>VL2</b>	<b>RHB52W-34001P7NRBRL348CZ</b>				
NN130061	FIAT	NE920026	NN139921A	7	VC130016
<b>VL3</b>	<b>RHB52W-34001P7NRBRL348CZ</b>				
VA130016	FIAT	VA810013	NN139921A	7	VC130016
<u>VC130016</u>	FIAT	VA810013	NN139922A	7	
<b>VL4</b>	<b>RHB52-34001NR5BRPL3511EZ</b>				
VA130011	LANCIA	VB810011	NN139922A	5	VD130011
VC130011	LANCIA	VB810011	NN139922A	5	VD130011
<u>VD130011</u>	LANCIA	VB810011	NN139922A	5	
<b>VL5</b>	<b>RHB52PW-34001PP9NR5BRPL3511EZ</b>				
VA180014	FIAT	VB810026	NN139922A	5	VB180014
<u>VB180014</u>	FIAT	VB810026	NN139922A	5	
<b>VL6</b>	<b>RHB52G-70005GP12NHBRKL3629CEZ</b>				
<u>VA180070</u>	LANCIA	VC810055	NN139922A	12	
<b>VL7</b>	<b>RHB52PW-34001PP9NRBRPL3329EZ</b>				
VA180047	FIAT	NZ853187	NN139922	9	VC180047
<u>VB180047</u>	FIAT	VC810053	NN139922	9	VC180047
VC180047	FIAT	VC810053	NN139922	9	
<b>VL8</b>	<b>RHB52R-56006RP12NHBRIL3329CEZ</b>				
<u>VA180074</u>	ALFA ROMEO	VC810054	NN139922A	12	VB180074
<u>VB180074</u>	ALFA ROMEO	VC810054	NN139922A	12	
<b>VL9</b>	<b>RHB52-52002NPZ12HBRL3911CEZ</b>				
<u>VA180084</u>	FIAT	VA810041		12	
<b>VM1</b>	<b>RHB51-34001P12NRBRL338CZ</b>				
NN130053	MASERATI			12	NN130055
<u>NN130055</u>	MASERATI	VA810028	NN139921A	12	
<b>VM10R</b>	<b>RHB51W</b>				
VA130051	MASERATI				VC130051
<b>VM11L</b>	<b>RHB51W</b>				
VA130052	MASERATI				VC130052
<b>VM12R</b>	<b>RHB52GW</b>				
VA130076	MASERATI				VE130076
<b>VM13L</b>	<b>RHB52GW</b>				
VA130077	MASERATI				VE130077
<b>VM14R</b>	<b>RHB52GW-52002GP12NRBRL348CZ</b>				
VA130090	MASERATI	VA810040	NN139922A	12	VC130090
VC130090	MASERATI	VA810040	NN139922A	12	
<b>VM15L</b>	<b>RHB52GW-52002GP12NRBRL348CZ</b>				
VA130091	MASERATI	VA810040	NN139922A	12	VC130091

VC130091	MASERATI	VA810040	NN139922A	12	
<b>VM16R</b>	<b>RHB51W</b>				
VA130092	MASERATI				
<b>VM17L</b>	<b>RHB51W</b>				
VA130093	MASERATI				
<b>VM18R</b>	<b>RHB51W-34001P9NRBRL338CZ</b>				
VB130051	MASERATI	VA810017		9	VC130051
VC130051	MASERATI	VA810017	NN139922A	9	
<b>VM19L</b>	<b>RHB52W-34001P9NRBRL338CZ</b>				
VB130052	MASERATI	VA810017		9	VC130052
VC130052	MASERATI	VA810017		9	
<b>VM2</b>	<b>RHB51-34001P12NRBRL338CZ</b>				
NN130054	MASERATI			12	NN130056
<u>NN130056</u>	MASERATI	VA810028	NN139921A	12	
<b>VM20R</b>	<b>RHB52GW-52002GP12NRBRL3911EZ</b>				
VB130076	MASERATI	NE920028		12	VE130076
VC130076	MASERATI	NE920028		12	VE130076
<u>VE130076</u>	MASERATI	NE920028		12	
<b>VM21L</b>	<b>RHB52GW-52002GP12NRBRL3911EZ</b>				
VB130077	MASERATI	VA810019		12	VE130077
VC130077	MASERATI	VA810019		12	VE130077
VE130077	MASERATI	VA810019		12	
<b>VM22R</b>	<b>RHB52GW-52002GP12NRBRL4016EZ</b>				
VA180029	MASERATI	VA810022		12	VC180029
VC180029	MASERATI	VA810022		12	
<b>VM23L</b>	<b>RHB52GW-52002GP12NRBRL4016EZ</b>				
VA180030	MASERATI	VA810022			VC180030
VC180030	MASERATI	VA810022		12	
<b>VM24R</b>	<b>RHB52GW-52002GP12NR5BRL348CZ</b>				
VA180045	MASERATI			12	VB180045
VB180045	MASERATI			12	
<b>VM25L</b>	<b>RHB52GW-52002GP12NR5BRL348CZ</b>				
VA180046	MASERATI			12	VB180046
VB180046	MASERATI			12	
<b>VM26R</b>	<b>RHB5GW-52002GP12NRBRL3911EZ</b>				
NZ851964	MASERATI			12	
<b>VM26RB</b>	<b>RHB52GW-52002GP12NR5BRL3711CEZ</b>				
NZ853358	MASERATI			12	
<b>VM27L</b>	<b>RHB52GW-52002GP12NRBRL3911EZ</b>				
NZ851965	MASERATI		NN139922A	12	
<b>VM27LB</b>	<b>RHB52GW-52002GP12NR5BRL3711CEZ</b>				
NZ853359	MASERATI			12	

<b>VM28R</b>	<b>RHB52GW-52002GP12NRBRL3911EZ</b>				
<u>VA180060</u>	MASERATI	NE920028	NN139922A	12	
<b>VM29L</b>	<b>RHB52GW-52002GP12NRBRL3911EZ</b>				
<u>VA180061</u>	MASERATI	NE920028	NN139922A	12	
<b>VM30R</b>	<b>RHB52GW-52002GP12NRBRL3911CEZ</b>				
<u>VA180079</u>	MASERATI	NE920028	NN139922A	12	
<b>VM31L</b>	<b>RHB52GW</b>				
<u>VA180080</u>	MASERATI				
<b>VM32R</b>	<b>RHB52GW-52002GP12NRBRL348C</b>				
<u>VA180081</u>	MASERATI		NN139922A	12	VB180081
<u>VB180081</u>	MASERATI		NN139922A	12	
<b>VM33L</b>	<b>RHB52GW-52002GP12NRBRL348C</b>				
<u>VA180082</u>	MASERATI		NN139922A	12	
<b>VM3L</b>	<b>RHB51W-34001P12NRBRL338CZ</b>				
<u>NN130064</u>	MASERATI	VA810017	NN139921A	12	
<b>VM4R</b>	<b>RHB51W-34001P12NRBRL338CZ</b>				
<u>NN130065</u>	MASERATI	VA810017	NN139921A	12	
<b>VM5L</b>	<b>RHB51W-34001P12NRBRL338CZ</b>				
<u>NN130067</u>	MASERATI	VA810017	NN139921A	12	
<b>VM5R</b>	<b>RHB52GW-52002GP12NRBRL348CZ</b>				
<u>NN130076</u>	MASERATI	VA810040	NN139921A	12	VC130090
<b>VM6L</b>	<b>RHB52GW-52002GP12NRBRL348CZ</b>				
<u>NN130077</u>	MASERATI	VA810040	NN139921A	12	
<b>VM6R</b>	<b>RHB51W-34001P12NRBRL338CZ</b>				
<u>NN130068</u>	MASERATI	VA810017	NN139921A	12	
<b>VM7R</b>	<b>RHB51W-34001P9NRBS311AZ</b>				
<u>NN130080</u>	MASERATI		NN139921A	9	
<b>VM8L</b>	<b>RHB51W-34001P9NRBRS311AZ</b>				
<u>NN130081</u>	MASERATI		NN139921A	9	
<b>VM9</b>	<b>RHB52GW-100003GP20NRBRL4219EZ</b>				
<u>NN130083</u>	MASERATI	VA810018		20	VB130015
<u>VA130015</u>	MASERATI	VA810018		20	VB130015
<u>VB130015</u>	MASERATI	VA810018		20	
<b>VN1</b>	<b>RHB52W</b>				
<u>VA180058</u>	BUGATTI				
<b>VN1A</b>	<b>RHB52W</b>				
<u>VB180058</u>	BUGATTI				
<b>VN2</b>	<b>RHB52W</b>				
<u>VA180059</u>	BUGATTI				
<b>VN2A</b>	<b>RHB52W</b>				
<u>VB180059</u>	BUGATTI				

<b>VN62</b>	<b>RHB52-52002P12NRBRL338CZ</b>				
VA180073	BUGATTI			12	
<b>VN63</b>	<b>RHB52-100003P20NRBRL4016EZ</b>				
VA180077	BUGATTI			20	
<b>VN65</b>	<b>RHB52-52002P12NRBRL3911EZ</b>				
VA180093	BUGATTI			12	
<b>VQ10</b>	<b>RHB51-34001P12NRBRL338CZ</b>				
<u>NB150026</u>	DAIHATSU	VA810028	NN139922A	12	
<b>VQ15</b>	<b>RHB52-52002P15NRBRL3911EZ</b>				
NB150046	DAIHATSU	NZ851354	NN139921A	15	VH130071
VA130071	DAIHATSU	VA810027	NN139922A	15	VH130071
VC130071	DAIHATSU	VA810027	NN139922A	15	VH130071
VF130071	DAIHATSU	VA810027	NN139922A	15	VH130071
<u>VH130071</u>	DAIHATSU	VA810027	NN139922A	15	
<b>VQ17</b>	<b>RHB51W-34001P12NRBRL338CZ</b>				
VA130018	DAIHATSU	NZ853142	NN139922A	12	VG130018
<u>VE130018</u>	DAIHATSU	NZ853142	NN139922A	12	VG130018
VG130018	DAIHATSU	NZ853142	NN139922A	12	
<b>VQ22</b>	<b>RHB52W-52002P15NRBRL3911EZ</b>				
<u>VA180033</u>	DAIHATSU	NE920028	NN139922A	15	
<b>VR6</b>	<b>RHB52-52002P12NRBRL345CZ</b>				
IHIVR6	DAEWOO			12	
<b>VU1</b>	<b>RHB52F-52002FP15NRBRL3713CZ</b>				
NN130058	FERRARI	NE920024	NN139921A	15	
<b>VU10</b>	<b>RHB52LW-90004LP20NRBRL4225CF</b>				
VC130026	FERRARI	VA810015	NN139922A		VC130027
<b>VU11</b>	<b>RHB52LW-90004LP20NRBRL4225CF</b>				
VC130027	FERRARI	VA810015	NN139922A	20	
<b>VU2</b>	<b>RHB52F-52002FP15NRBRL3713CZ</b>				
NN130059	FERRARI	NE920024	NN139921A	15	
<b>VU3</b>	<b>RHB52LW-100003LP20NRBRL4323E</b>				
NN130075	FERRARI		NN139921A	20	
<b>VU4</b>	<b>RHB52LW-90004LP20NRBRL4225CF</b>				
VA130026	FERRARI	VA810015			VC130027
<b>VU5</b>	<b>RHB52LW</b>				
VA130027	FERRARI				VC130027
<b>VU6</b>	<b>RHB52LW-90004LP20NRBRL4225CF</b>				
VB130026	FERRARI	VA810015	NN139922A		VC130027
<b>VU7</b>	<b>RHB52LW-90004LP20NRBRL4225CF</b>				
VB130027	FERRARI	VA810015	NN139922A		VC130027
<b>VZ1</b>	<b>RHB51B-34001BP7NRBRL338CZ</b>				





Catalog 2.0 - 2006

**IHI****RHB6**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
<b>AE25</b>	<b>RHB6</b>				
NN190058					
<b>AI1</b>	<b>RHB6-5000IP9NFBR33TA</b>				
NN190012	ISUZU	VA140014		33	VA140014
VA140014	ISUZU	VA140014		33	
<b>AS3</b>	<b>RHB6-65003P16NFBRL376B</b>				
NN190018				16	
<b>AS4</b>	<b>RHB6-57002P13NFBR33TA</b>				
NN190019				13	
<b>AS6</b>	<b>RHB6-50001P9NFBR37TA</b>				
NN190024				9	
<b>AY2</b>	<b>RHB6</b>				
NN190011	YANMAR				VA140019
<b>AY2</b>	<b>RHB6-50001P9NFBR33TA</b>				
VA140019	YANMAR			9	
<b>AY4</b>	<b>RHB6-50001P7NFBR33TA</b>				
NN190021	YANMAR			7	VA140021
VA140021	YANMAR			7	
<b>AY5</b>	<b>RHB6-57002P13NFBRL376B</b>				
NN190022	YANMAR			13	VA140022
<b>CI38</b>	<b>RHB6A-65003P16NFBRL376B</b>				
NB190022	ISUZU	VA820014		16	NB190027
<b>CI42</b>	<b>RHB6A-50001P11NRBRL392B</b>				
NB190023	ISUZU	VA820011	NN199835	11	VB140012
VA140012	ISUZU	VA820011	NN199835	11	VB140012
VB140012	ISUZU	VA820011	NN199835	11	
<b>CI53</b>	<b>RHB6A-65003P16NFBRL376B</b>				
NB190027	ISUZU	VA820014		16	
<b>CI60</b>	<b>RHB6A-65003P16NFBRL376B</b>				
NB190044	ISUZU			16	
<b>CI65</b>	<b>RHB6A-65003P16NFBRL376B</b>				
VA140016	ISUZU			16	

<b>CI69</b>	<b>RHB6A-6500IIP13NFBRL376B</b>				
VA140018	ISUZU	VA820014	NN199835	13	
<b>GY10</b>	<b>RHB6</b>				
NN190029	YANMAR				
<b>GY11</b>	<b>RHB6</b>				
NN190030	YANMAR				VA140026
VA140026	YANMAR				
<b>GY13</b>	<b>RHB6</b>				
NN190031	YANMAR				VA140027
VA140027	YANMAR				
<b>GY16</b>	<b>RHB6-57002P13NFBR37TA</b>				
NN190034	YANMAR			13	VA140029
VA140029	YANMAR			13	
<b>GY17</b>	<b>RHB6</b>				
NN190035	YANMAR				VA140030
VA140030	YANMAR				
<b>GY19</b>	<b>RHB6</b>				
NN190037	YANMAR				VA140032
VA140032	YANMAR				
<b>GY21</b>	<b>RHB6-65003P18NFBRL406B</b>				
NN190038	YANMAR			18	VA140033
<b>GY21</b>	<b>RHB6</b>				
VA140033	YANMAR				
<b>GY23</b>	<b>RHB6</b>				
NB190011	YANMAR				
<b>GY45</b>	<b>RHB6-65003P16NFBRL406B</b>				
NB190026	YANMAR			16	VA140040
VA140040	YANMAR			16	
<b>GY6</b>	<b>RHB6</b>				
NN190023	YANMAR				VB140023
VB140023	YANMAR				
<b>GY70</b>	<b>RHB6-65003P22NFBRL406B</b>				
VA140045	YANMAR			22	
<b>MD6</b>	<b>RHB6-73004P22NFBRL406B</b>				
NN190027	NISSAN			22	NN190028
NN190028	NISSAN			22	
<b>MH1</b>	<b>RHB6</b>				
NN190020	YAMAHA				
<b>MH2</b>	<b>RHB6-73001VP27NFBRL436B</b>				
NN190032	YAMAHA			27	
<b>MI26</b>	<b>RHB6-65003P22NFBRL436B</b>				
VA140047	ISUZU			22	

<b>MI4</b>	<b>RHB6-65003P20NFBRL376B</b>				
NN190025	ISUZU	VA820017		20	VA140011
VA140011	ISUZU	VA820017		20	
VA140013	ISUZU	VA820017		20	
<b>MK21</b>	<b>RHB6</b>				
NB190028	KUBOTA				
<b>MK4</b>	<b>RHB6</b>				
NB190014	KUBOTA				
<b>MK5</b>	<b>RHB6</b>				
NB190015	KUBOTA				
<b>MY15</b>	<b>RHB6</b>				
NN190033	YANMAR				VB140028
VB140028	YANMAR				
<b>MY18</b>	<b>RHB6</b>				
NN190036	YANMAR				VB140031
VB140031	YANMAR				
<b>MY22</b>	<b>RHB6</b>				
NN190040	YANMAR				VB140034
VB140034	YANMAR				
<b>MY24</b>	<b>RHB6</b>				
NB190013	YANMAR				VA140036
VA140036	YANMAR				
<b>MY27</b>	<b>RHB6</b>				
NB190017	YANMAR				VB140037
VB140037	YANMAR				
<b>MY3</b>	<b>RHB6</b>				
NN190014	YANMAR				VB140020
VB140020	YANMAR				
<b>MY30</b>	<b>RHB6-65003P16NFBRL406B</b>				
NB190018	YANMAR			16	VA140038
VA140038	YANMAR			16	
<b>MY44</b>	<b>RHB6</b>				
NB190025	YANMAR				VB140039
VB140039	YANMAR				
<b>MY51</b>	<b>RHB6A</b>				
NB190029	YANMAR				VB140041
VB140041	YANMAR				
<b>MY52</b>	<b>RHB6</b>				
NB150027	YANMAR				NB150043
<b>MY53</b>	<b>RHB6A-65003P18NFBRL4362D</b>				
NB190030	YANMAR			18	VB140042
VB140042	YANMAR			18	

<b>MY7</b>	<b>RHB6-65003P16NFBRL406B</b>				
NN190026	YANMAR			16	VB140024
VB140024	YANMAR			16	
<b>MY77</b>	<b>RHB6</b>				
VA140046	YANMAR				
<b>VA1</b>	<b>RHB6</b>				
NN190057	M.ITAIY				
<b>VB2</b>	<b>RHB6</b>				
NN190061	SHELBY				
<b>VB3</b>	<b>RHB6</b>				
NN190062	SHELBY				
<b>VB5</b>	<b>RHB6B</b>				
NN190086	SHELBY				
<b>VE21</b>	<b>RHB6</b>				
NN190052	TOYOTA				
<b>VE41</b>	<b>RHB6</b>				
NN190067	PERKINS				
<b>VI22</b>	<b>RHB6A-50001P11NRBRL392BZ</b>				
NN190039	ISUZU	VA820011	NN199835	11	VA140017
<b>VI35</b>	<b>RHB6A-50001P11NRBRL392BZ</b>				
NB190021	ISUZU	VA820011	NN199835	11	VA140017
NB190024	ISUZU	VA820011	NN199835	11	VA140017
NB190031	ISUZU	VA820011	NN199835	11	VA140017
NB190032	ISUZU	VA820011	NN199835	11	VA140017
NB190043	ISUZU	VA820011	NN199835	11	VA140017
VA140017	ISUZU	VA820011	NN199835	11	
<b>VQ5</b>	<b>RHB6D-57002DP16NRBRL376BZ</b>				
NB190016	DAIHATSU	NE930011	NN199835	16	VA140015
VA140015	DAIHATSU	NE930011	NN199835	16	
<b>VR1</b>	<b>RHB6-50001P11NRBRL406BZ2</b>				
IHIVR1	DAEWOO			11	
<b>VR5</b>	<b>RHB6-57001P13NRBRL436BZ2</b>				
IHIVR5	DAEWOO			13	

Catalog 2.0 - 2006

**IHI****RHB7**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
<b>CI12</b>	<b>RHB7-78003P20NFBRL515B</b>				
NN177020	HITACHI	VA830011		20	VA150021
VA150021	HITACHI	VA830011	NN179810	20	
<b>CI2</b>	<b>RHB7-7800-III25NFBRL462A</b>				
NN170011	ISUZU	VA830012		25	VA150019
<b>CI39</b>	<b>RHB7-87004P28NFBRL515B</b>				
NN170024	ISUZU	VA830014		28	VA150022
VA150022	ISUZU	VA830014	NN179810	28	
<b>CI40</b>	<b>RHB7-87004P30NFBRL515B</b>				
NN170025	ISUZU	VA830014		30	VA150023
VA150023	ISUZU	VA830014	NN179810	30	
<b>CI7</b>	<b>RHB7-78003P25NFBRL462A</b>				
VA150019	ISUZU	VA830012	NN179810	25	
<b>GY9</b>	<b>RHB7</b>				
NN170017	YANMAR				
<b>MK22</b>	<b>RHB7</b>				
NN170026	KUBOTA				
<b>MK6</b>	<b>RHB7</b>				
NN170016	KUBOTA				
<b>MK7</b>	<b>RHB7</b>				
NN170018	KUBOTA				
<b>MK8</b>	<b>RHB7</b>				
NN170021	KUBOTA				
<b>MX1</b>	<b>RHB7</b>				
NN170013	HINO				VC150016
VA150016	HINO				VC150016
VC150016	HINO				
<b>MX15</b>	<b>RHB7A</b>				
NN170022	HINO				VC150018
VA150018	HINO				VC150018
VC150018	HINO				
<b>MX5</b>	<b>RHB7</b>				

NN170019	HINO				VC150017
VA150017	HINO				VC150017
VC150017	HINO				
<b>VC40</b>	<b>RHB7-87004P20NFBRL517BZ</b>				
VA150011			NN179810	20	VB150011
<b>VC40A</b>	<b>RHB7-87004P20NFBRL517BZ</b>				
VB150011			NN179810	20	
<b>VI10</b>	<b>RHB7-78003P20NABRL515BZ2</b>				
NN170015	ISUZU			20	VA150013
VA150013	ISUZU		NN179810	20	
<b>VI3</b>	<b>RHB7-7800IIIQ21NFBRL515BZ2</b>				
NN170012	ISUZU	VA830011	NN179810	21	VA150020
<b>VI6</b>	<b>RHB7-78003Q21NFBRL515BZ2</b>				
VA150020	ISUZU	VA830011	NN179810	21	

Catalog 2.0 - 2006

**IHI****RHB8**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
<b>CD14</b>	<b>RHB8A-10004Q32NABRL606C</b>				
VA160014				32	
<b>VD13</b>	<b>RHB8A-10004Q32NABRL607C</b>				
NN180021	NISSAN			32	VA160013
VA160013	NISSAN			32	
<b>VD15</b>	<b>RHB8A-1000IVQ32NABRL6613D</b>				
NN180023	NISSAN			32	VA160015
VA160015	NISSAN			32	
<b>VD19</b>	<b>RHB8A-1000IVQ32NABRL607C</b>				
NN180024	NISSAN			32	VA160016
VA160016	NISSAN			32	
<b>VD20</b>	<b>RHB8A-1000IVQ35NABRL607C</b>				
NN180025	NISSAN			35	
<b>VD3</b>	<b>RHB8A-10004P30NSBL564B</b>				
NN180011	NISSAN		NN189901	30	
<b>VD4</b>	<b>RHB8A-10004P30NSBL564B</b>				
NN180012	NISSAN	NZ853436	NN189901	30	
<b>VD8</b>	<b>RHB8A-10004Q32NABRL606C</b>				
NN180015	NISSAN			32	VA160012
VA160012	NISSAN	VA880011		32	
<b>VR7</b>	<b>RHB8B-1100VBQ35NABRL607C</b>				
NH170050	DAEWOO			35	VA160018
NN180055	DAEWOO			35	VA160018
NN180056	DAEWOO			35	VA160018
VA160018	DAEWOO			35	
<b>VR8</b>	<b>RHB8-11005BQ40NABRL607C</b>				
VA160011	DAEWOO			40	VB160011
VB160011	DAEWOO			40	



Catalog 2.0 - 2006

**IHI****RHC6**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
<b>CI89</b>	<b>RHC62C-1185CQ23NFBRLL4612B</b>				
VA240044	HITACHI	VA850014	NH169836	23	
<b>CX24</b>	<b>RHC61B</b>				
NH160014	HINO				VA240017
VA240017	HINO				
<b>CX92</b>	<b>RHC61B</b>				
VA240058	HINO				VB240058
VB240058	HINO				
<b>CX95</b>	<b>RHC62</b>				
VA240059	HINO				VB240059
VB240059	HINO				
<b>CX97</b>	<b>RHC6</b>				
VA240060	HINO				VB240060
VB240060	HINO				
<b>CX98</b>	<b>RHC62-1183P20NABRLL5213CBZ</b>				
VA240063	HINO	VA850016		20	VB240063
VB240063	HINO	VA850016		20	
<b>CXAD</b>	<b>RHC61A-574P13NABRS432AZ</b>				
VA240066	HINO			13	
<b>CXAG</b>	<b>RHC62-1183P20NABRLL5213CBZ</b>				
VA240070	HINO			20	
<b>CXAH</b>	<b>RHC61B</b>				
VA240073	HINO				
<b>CXAI</b>	<b>RHC62W</b>				
VA240069	HINO				
<b>CXBK</b>	<b>RHC6</b>				
VA240093	HINO				
<b>GX21</b>	<b>RHC61B-571BP16NFBR432A</b>				
NH160013	HINO			16	VA240016
VA240016	HINO			16	
<b>GX25</b>	<b>RHC61B-1182BP18NFBR432A</b>				
NH160015	HINO	VA850015		18	VA240018

VA240018	HINO	VA850015		18	
<b>GX26</b>	<b>RHC61B-1182BP18NFBR5432A</b>				
NH160016	HINO	VA850015		18	VA240019
VA240019	HINO	VA850015		18	
<b>GX51</b>	<b>RHC61B</b>				
VA240027	HINO				
<b>GX74</b>	<b>RHC61B</b>				
VA240049	HINO				VB240049
VB240049	HINO				
<b>GX85</b>	<b>RHC61B</b>				
VA240057	HINO				VB240057
VB240057	HINO				
<b>GY54</b>	<b>RHC61</b>				
NH160018	YANMAR				VB240045
VA240045	YANMAR				VB240045
VB240045	YANMAR				
<b>GYAI</b>	<b>RHC61</b>				
VA240067	YANMAR				
<b>MD21</b>	<b>RHC61</b>				
NH160020	NISSAN				
<b>MD22</b>	<b>RHC61</b>				
NH160021	NISSAN				
<b>MD25</b>	<b>RHC61</b>				
VA240013	NISSAN				
<b>MI90</b>	<b>RHC61</b>				
VA240051	ISUZU				VC240051
VC240051	ISUZU				
<b>MX22</b>	<b>RHC61</b>				
NH160012	HINO				VB240015
VA240015	HINO				VB240015
VB240015	HINO				
<b>MX30</b>	<b>RHC61C</b>				
NH160017	HINO				VD240020
VA240020	HINO				VD240020
VB240020	HINO				VD240020
VD240020	HINO				
<b>MX33</b>	<b>RHC61W-1182P20NWBRL504A</b>				
NH160019	HINO			20	VB240021
NH160023	HINO			20	VB240021
VA240021	HINO			20	VB240021
VB240021	HINO			20	
<b>MX45</b>	<b>RHC61C-118153CP27NABRL504A</b>				

VA240022	HINO			20	VD240022
VB240022	HINO			20	VD240022
VD240022	HINO	NZ853754	NH169843	20	
<b>MX58</b>	<b>RHC61W-943P27NWBRL489CB</b>				
VA240036	HINO			27	VB240036
<b>MX59</b>	<b>RHC61C</b>				
VA240037	HINO				VC240037
VC240037	HINO				
<b>MY58</b>	<b>RHC61W-1183P20NWBRL504A</b>				
NH160022	YANMAR			20	VB240076
VA240076	YANMAR			20	VB240076
VB240076	YANMAR			20	
<b>MY80</b>	<b>RHC61W</b>				
VA240062	HINO				
<b>MYAV</b>	<b>RHC61W-1063P18NWBRL4715CC</b>				
VA240080	YANMAR				VB240080
VB240080	YANMAR			18	
<b>MYBF</b>	<b>RHC61W-1183P18NWBRL4715CC</b>				
VA240086	YANMAR	NZ853147		18	
<b>MYDA</b>	<b>RHC61W-1063P16NWBRL4715CCZ</b>				
VB240090	YANMAR	VC240080		16	
<b>VD23</b>	<b>RHC62A-1183Q32NSBRL556CBZ</b>				
VA240011	NISSAN			32	VH240011
VB240011	NISSAN			32	VH240011
VC240011	NISSAN			32	VH240011
VD240011	NISSAN			32	VH240011
VE240011	NISSAN			32	VH240011
VF240011	NISSAN			32	VH240011
VG240011	NISSAN			32	VH240011
VH240011	NISSAN	VA850011		32	
<b>VD24</b>	<b>RHC6V-1183P27NABRL556CB</b>				
VA360011	NISSAN			27	VK360011
VB360011	NISSAN			27	VK360011
VD360011	NISSAN			27	VK360011
VE360011	NISSAN			27	VK360011
VF360011	NISSAN			27	VK360011
VG360011	NISSAN			27	VK360011
VJ360011	NISSAN			27	VK360011
VK360011	NISSAN			27	
<b>VD28</b>	<b>RHC62A-1183Q32NSBRL566CBZ</b>				
VA240024	NISSAN				VH240024
VB240024	NISSAN			32	VH240024
VC240024	NISSAN			32	VH240024

VD240024	NISSAN			32	VH240024
VE240024	NISSAN			32	VH240024
VF240024	NISSAN			32	VH240024
VH240024	NISSAN	VA850011	NH169846	32	
<b>VD30</b>	<b>RHC62A-1183Q24NSBRLL519CBZ</b>				
VA240038	NISSAN			24	VF240038
VB240038	NISSAN			24	VH240038
VE240038	NISSAN			24	VH240038
VF240038	NISSAN			24	VH240038
VH240038	NISSAN			24	
<b>VD31</b>	<b>RHC62A</b>				
VA240046	NISSAN				VG420046
VB240046	NISSAN				VG420046
VE240046	NISSAN				VG420046
VG240046	NISSAN				
<b>VD35</b>	<b>RHC6V</b>				
VA360012	NISSAN				VE360012
VB360012	NISSAN				VE360012
VE360012	NISSAN				
<b>VD36</b>	<b>RHC62E-1186Q26NHBRL5213CBZ</b>				
VA240061	NISSAN			26	VC240061
<b>VD36</b>	<b>RHC62E-1186Q26NR5BRLL5213CBZ</b>				
VA240096	NISSAN			26	
<b>VD36</b>	<b>RHC62E-1186Q26NHBRL5213CBZ</b>				
VB240061	NISSAN			26	VC240061
VC420061	NISSAN			26	
<b>VD37</b>	<b>RHC6V-1185P27NHBRL5213CUB</b>				
VA360013	NISSAN			27	VF360013
VF360013	NISSAN			27	
<b>VD43</b>	<b>RHC6V-1185P27NHBRL539CUB</b>				
VF360017	NISSAN			27	
<b>VD48</b>	<b>RHC61E-1186Q26NABRL5213BZ</b>				
VA240085	NISSAN			26	
VA240095	NISSAN			26	
<b>VD49</b>	<b>RHC62E</b>				
VA240087	NISSAN				
<b>VX18</b>	<b>RHC61B-574AP16NABRS432AZ</b>				
NH160011	HINO	NE960011	NN199382	16	VF240023
VA240023	HINO	NE960011	NN199382	16	VF240023
VB240023	HINO	NE960011	NN199382	16	VF240023
VE240023	HINO	NE960011	NN199382	16	VF240023
VF240023	HINO	NE960011	NN199382	16	VF240023

<b>VX40</b>	<b>RHC62W-943P14NALL506BZ</b>				
VA240012	HINO	VA850012		14	VE240012
VB240012	HINO	VA850012		14	VE240012
VC240012	HINO	VA850012		14	VE240012
VD240012	HINO	VA850012		14	VE240012
VE240012	HINO	VA850012		14	
<b>VX46</b>	<b>RHC61AW-574P16NABRS432CHAZ</b>				
VA240025	HINO	NE960012		16	VH240025
VE240025	HINO	NE960012		16	VH240025
VF240025	HINO	NE960012		16	VH240025
VG240025	HINO	NE960012		16	VH240025
VH240025	HINO	NE960012		16	
<b>VX53</b>	<b>RHC62W-1183P20NABRLL5213CHBZ</b>				
VA240039	HINO	VA850013		20	VI240039
VC240039	HINO	VA850013		20	VI240039
VD240039	HINO	VA850013		20	VI240039
VG240039	HINO	VA850013		20	VI240039
VI240039	HINO	VA850013		20	
<b>VX54</b>	<b>RHC62W-1183P20NABRLL5213CHBZ</b>				
VA240040	HINO			20	VI240040
VC240040	HINO			20	VI240040
VD240040	HINO			20	VI240040
VG240040	HINO			20	VI240040
VI240040	HINO			20	
<b>VX55</b>	<b>RHC62W-1183P17NABRLL5213CHBZ</b>				
VA240041	HINO			17	VI240041
VC240041	HINO			17	VI240041
VD240041	HINO			17	VI240041
VG240041	HINO			17	VI240041
VI240041	HINO			17	
<b>VX56</b>	<b>RHC62W-1183P17NABRLL5313CHBZ</b>				
VA240042	HINO			17	VI240042
VC240042	HINO			17	VI240042
VG240042	HINO			17	VI240042
VI240042	HINO			17	
<b>VX61</b>	<b>RHC61W</b>				
VA240047	HINO				VC240047
VB240047	HINO				VC240047
VC240047	HINO				
<b>VX75</b>	<b>RHC62W</b>				
VA240048	HINO				VC240048
VB240048	HINO				VC240048
VC240048	HINO				

<b>VX79</b>	<b>RHC62W</b>				
VA240052	HINO				VH240052
VB240052	HINO				VH240052
VF240052	HINO				VH240052
VH240052	HINO				
<b>VX80</b>	<b>RHC62W</b>				
VA240053	HINO				VH240053
VB240053	HINO				VH240053
VC240053	HINO				VH240053
VF240053	HINO				VH240053
VH240053	HINO				
<b>VX81</b>	<b>RHC62W</b>				
VA240054	HINO				VH240054
VB240054	HINO				VH240054
VF240054	HINO				VH240054
VH240054	HINO				
<b>VX82</b>	<b>RHC62W</b>				
VA240055	HINO				VH240055
VC240055	HINO				VH240055
VF240055	HINO				VH240055
VH240055	HINO				
<b>VX83</b>	<b>RHC62W-1183P17NABRLL5213CHBZ</b>				
VA240056	HINO	VA850013		17	VG240056
VB240056	HINO	VA850013		17	VG240056
VE240056	HINO	VA850013		17	VG240056
VG240056	HINO	VA850013		17	
<b>VX99</b>	<b>RHC61A</b>				
VA240064	HINO				VB240064
VB240064	HINO				

Catalog 2.0 - 2006

**IHI****RHC7**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
<b>CI33</b>	<b>RHC7</b>				
NH170030	ISUZU				
<b>CI56</b>	<b>RHC7-1100IP20NFBRL557A</b>				
NH170048	ISUZU	VA860012	NH179859	20	
<b>CI70</b>	<b>RHC7F-13335Q41NFBRL5715CC</b>				
VA250039	ISUZU	NZ853987	NH179859	41	
<b>CI76</b>	<b>RHC7</b>				
VA250050	ISUZU				
<b>CI92</b>	<b>RHC7-13335HQ41NFBRL5715CC</b>				
VB250062	ISUZU	VA860020		41	
<b>CI93</b>	<b>RHC7-11003Q30NFBRL557A</b>				
VB250090	ISUZU			30	
<b>CIAF</b>	<b>RHC7-13005HQ30NFBRL557A</b>				
VA250074	ISUZU			30	
<b>CIAQ</b>	<b>RHC7-12307HQ41NFBRL6424CC</b>				
VA290021	ISUZU	VA860021		41	VA290022
VA290022	ISUZU			41	
<b>CIBZ</b>	<b>RHC7F-13335Q41NFBRL5715CC</b>				
VA290037	ISUZU			41	
<b>CX11</b>	<b>RHC7-12001VAQ35NABRL603CB</b>				
NH170018	HINO	VA860014		35	VC250021
VA250021	HINO	VA860014		35	VC250021
VB250021	HINO	VA860014		35	VC250021
VC250021	HINO	VA860014		35	
<b>CX13</b>	<b>RHC7A-11003AP25NFBRL557A</b>				
VB250023	HINO	VA860023		25	
<b>CX35</b>	<b>RHC7A-11003AP23NFBRL557A</b>				
NH170049	HINO	VA860023		23	VA250027
VA250027	HINO	VA860023		23	
<b>CX37</b>	<b>RHC7A-11003AP23NFBRL5715C</b>				
VA250029	HINO	VA860016		23	
<b>CX42</b>	<b>RHC7F-11003AP23NFBRL5715C</b>				

VA250016	HINO	VA860016	23	
<b>CX49</b>	<b>RHC7A-12002AP20NFBRL5715C</b>			
VA250046	HINO	VA860027	20	
<b>CX78</b>	<b>RHC7A-11004AP25NFBRL557A</b>			
VA250088	HINO	VA860023	25	
<b>CX86</b>	<b>RHC7A-11004AP23NFBRL5715C</b>			
VA250092	HINO	VA860030	23	
<b>GC46</b>	<b>RHC7-11003Q30NFBRL5715C</b>			
VA250087			30	
<b>GR10</b>	<b>RHC7J-11001JP20NFBRL557A</b>			
VA250098	DAEWOO		20	
<b>GX12</b>	<b>RHC7A-11003P25NFBRL557A</b>			
VB250022	HINO		25	
<b>GX36</b>	<b>RHC7A-13535AP40NFBRL603B</b>			
VA250028	HINO		40	
<b>GX48</b>	<b>RHC7-12002P20NFBRL557A</b>			
VA250045	HINO		20	
<b>GX68</b>	<b>RHC7A-1353VAQ35NFBRL603CB</b>			
VA250071	HINO		35	
<b>GX7</b>	<b>RHC7A-12004AQ35NABRL603CB</b>			
VA250019	HINO	VA860014	35	VC250019
VC250019	HINO	VA860014	35	
<b>MI68</b>	<b>RHC7H-11003HQ30NFBRL557A</b>			
VB250013			30	
<b>MX31</b>	<b>RHC7GW-13005GP29NWBRL557A</b>			
NH170045	HINO	VA860023	29	VA250030
NH170053	HINO	VA860023	29	VA250030
VA250030	HINO	VA860023	29	
<b>MX39</b>	<b>RHC7D-13535DQ35NFBRL6115CC</b>			
VC250031	HINO		35	
<b>MX47</b>	<b>RHC7GW-13005GP37NWBRL6115CC</b>			
VA250043	HINO		37	
<b>MX60</b>	<b>RHC7D-13205DQ35NFBRL6115CC</b>			
VC250061	HINO		35	
<b>MX70</b>	<b>RHC7W-12001GP29NWBRL5715CC</b>			
VH250063	HINO		29	
<b>MX94</b>	<b>RHC7GW-11004GP29NWBRL6127CC</b>			
VA290011	HINO		29	
<b>MY79</b>	<b>RHC7W-12307P22NWBRL6026SUC</b>			
VB250096	YANMAR		22	
<b>MYAG</b>	<b>RHC7W-12407P22NWBRB6131SUC</b>			



VB290022	YANMAR		22	
<b>MYAN</b>	<b>RHC7W-12507P22NWBRB6136SUC</b>			
VA290024	YANMAR		22	VB290024
<b>MYAW</b>	<b>RHC7W-12307P22NWBRB6235SUCZ</b>			
VB290033	YANMAR	NH179859	22	
<b>MYBN</b>	<b>RHC7W-12507P22NWBRB6136SUC</b>			
VB290024	YANMAR		22	VC290024
VC290024	YANMAR		22	
<b>MYBO</b>	<b>RHC7W-12507P22NWBRB6136SUC</b>			
VC290035	YANMAR		22	
<b>VI29</b>	<b>RHC7E-11003BP20NABRL603BZ2</b>			
<u>VA250068</u>	ISUZU		20	
<b>VI31</b>	<b>RHC7E-11001EP20NABRL557AZ2</b>			
VA250069	ISUZU		20	
<b>VI63</b>	<b>RHCC7-11003EP20CABRL603BZ</b>			
<u>VA560011</u>	ISUZU		20	
<b>VI75</b>	<b>RHC7VW-12004P33NABRL5723CHCT</b>			
VB370011	ISUZU		33	
<b>VI81</b>	<b>RHC7EW-1100EP20NABRL5715CCZ</b>			
<u>VC250058</u>	ISUZU		20	
<b>VI82</b>	<b>RHCC7-11003EP20CABRL603BZ</b>			
<u>VA560012</u>	ISUZU		20	
<b>VIAE</b>	<b>RHC7SW-111510SP20NABRL5715CCZ</b>			
VC250094	ISUZU		20	
<b>VIAR</b>	<b>RHC7SW</b>			
VB290012	ISUZU			
<b>VU7B</b>	<b>RHC61EW-571EP16MRBRL504CA</b>			
NZ852119	FERRARI		16	
<b>VX14</b>	<b>RHC7A-12002AP20NABRL557AZ2</b>			
VC250033	HINO		20	
<b>VX17</b>	<b>RHC7A-12002AP20NHBRL557AZ2</b>			
VB250042	HINO	VA860015	20	
<b>VX23</b>	<b>RHC7F-13005AQ33NABRL5715CUC</b>			
NH170035	HINO	VA860034	33	VE250036
VA250036	HINO	VA860034	33	VE250036
<b>VX23</b>	<b>RHC7L-12304LQ33NABRL5715CUC</b>			
VB250049	HINO		33	VE250049
<b>VX23</b>	<b>RHC7F-13005AQ33NABRL5715CUC</b>			
VC250036	HINO	VA860034	33	VE250036
<b>VX23</b>	<b>RHC7L-12304LQ33NABRL5715CUC</b>			
VC250049	HINO		33	VE250049

<b>VX23</b>	<b>RHC7F-13005AQ33NABRL5715CUC</b>				
VE250036	HINO	VA860034		33	
<b>VX23</b>	<b>RHC7L-12304LQ33NABRL5715CUC</b>				
VE250049	HINO			33	
<b>VX27</b>	<b>RHC7CW-11004CQ30NMBRL5715CUC</b>				
VF250037	HINO			30	
<b>VX28</b>	<b>RHC7FW-13335AQ38NABRL6115CUC</b>				
VH250038	HINO			38	
<b>VX29</b>	<b>RHC7A-12002AP20NABRL557AZ</b>				
VA250041	HINO	VA860015		20	
<b>VX3</b>	<b>RHC7A-12001VAQ35NABRL603CUB</b>				
VE250047	HINO			35	
<b>VX41</b>	<b>RHC7FW-13435AQ38NABRL6115CUC</b>				
VH250015	HINO			38	
<b>VX62</b>	<b>RHC7CW-11004CQ25NMBRL5715CUC</b>				
VB250065	HINO			25	
<b>VX65</b>	<b>RHC7KW-13437KQ38NMBRL6115CUC</b>				
VD250075	HINO			38	
<b>VX72</b>	<b>RHC7A-12001AP20NABRL557AZ2</b>				
VA250072	HINO			20	
<b>VX8</b>	<b>RHC7-12002AP20NABRL557AZ</b>				
VA290027	HINO			20	

Catalog 2.0 - 2006

**IHI****RHC9**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
<b>CI44</b>	<b>RHC9-15004Q45NABRL696A</b>				
NH190040	ISUZU			45	VB270039
VA270039	ISUZU			45	VB270039
<b>CIDD</b>	<b>RHC9</b>				
VA300018	ISUZU				
<b>GQ10</b>	<b>RHC91</b>				
NH190045	DAIHATSU				
<b>GQ11</b>	<b>RHC91</b>				
NH190046	ISUZU				
<b>GQ12</b>	<b>RHC91</b>				
VA270051	DAIHATSU				
<b>GQ13</b>	<b>RHC91</b>				
VA270052	DAIHATSU				
<b>MD34</b>	<b>RHC92-19223Q39NABRL7515CC</b>				
VA270078	NISSAN			39	
<b>MI18</b>	<b>RHC9A-17435Q45NFBRAL696A</b>				
NH190028	ISUZU		NH199814	45	VA270091
VA270091	ISUZU			45	
<b>MI27</b>	<b>RHC9A</b>				
NH190036	ISUZU				
<b>MI52</b>	<b>RHC9A</b>				
NH190042	ISUZU				VA270085
VA270085	ISUZU				
<b>MI59</b>	<b>RHC9A-17435Q45NFBRAL696A</b>				
NH190047	ISUZU			45	VA270086
VA270086	ISUZU			45	
<b>MI66</b>	<b>RHC91A</b>				
VA270011	ISUZU				VE270011
VB270011	ISUZU				VE270011
VC270011	ISUZU				VE270011
VD270011	ISUZU				VE270011
VE270011	ISUZU				

<b>MI80</b>	<b>RHC91C</b>				
VA270050	ISUZU				VB270053
VA270053	ISUZU				VB270053
VB270050	ISUZU				VB270053
VB270053	ISUZU				
<b>MI97</b>	<b>RHC91C</b>				
VA270073	ISUZU				VC270073
VB270073	ISUZU				VC270073
VC270073	ISUZU				
<b>MIAB</b>	<b>RHC9C</b>				
VA270075	ISUZU				VC270075
VC270075	ISUZU				
<b>MIAC</b>	<b>RHC9C</b>				
VA270076	ISUZU				VC270076
VC270076	ISUZU				
<b>MIAP</b>	<b>RHC92</b>				
VA270083	ISUZU				VB270083
VB270083	ISUZU				
<b>MW1</b>	<b>RHC92</b>				
VA270026	KOMATSU				
<b>MW2</b>	<b>RHC92</b>				
VA270061	KOMATSU				
<b>MW3</b>	<b>RHC92</b>				
VA270082	KOMATSU				
<b>MX2</b>	<b>RHC9-1700VQ50NFBRL696A</b>				
VC270087	HINO			50	
<b>MX44</b>	<b>RHC91B-175BQ35NABRL6812CB</b>				
VD270037	HINO			35	
<b>MXAO</b>	<b>RHC9</b>				
VA270095	HINO				
<b>MY40</b>	<b>RHC9</b>				
VA270028	YANMAR				
<b>MY71</b>	<b>RHC92</b>				
VA270064	YANMAR				VD270064
VD270064	YANMAR				
<b>MY82</b>	<b>RHC92</b>				
VC270060	YANMAR				VD270060
VD270060	YANMAR				
<b>MY93</b>	<b>RHC92</b>				
VC270064	YANMAR				VD270064
<b>MY94</b>	<b>RHC91</b>				
VD270038	YANMAR				VE270038

VE270038	YANMAR				
<b>MYBR</b>	<b>RHC9-17005Q50NFBRL673A</b>				
VB270026	YANMAR			50	
<b>VI16</b>	<b>RHC9-15004Q39NABRL675A</b>				
VA270056	ISUZU			39	
<b>VI17</b>	<b>RHC9-13003Q28N2ABRL675A</b>				
VA270057	ISUZU			28	
<b>VI44</b>	<b>RHC9-15004Q45NABRL696A</b>				
VB270039	ISUZU			45	
<b>VI48</b>	<b>RHC9V-13002P39NABRL615CA</b>				
VF390011	ISUZU			39	
<b>VI54</b>	<b>RHC9-17005Q39NABRL696CUA</b>				
VD270040	ISUZU			39	
<b>VI8</b>	<b>RHC9-13003Q25NABRL673A</b>				
NH190012	ISUZU	VA870011		25	VA270054
VA270054	ISUZU	VA870011		25	
<b>VI9</b>	<b>RHC9-1300IIIQ25NABRL673A</b>				
NH190013	ISUZU				VB270055
VA270055	ISUZU				VB270055
VB270055	ISUZU				
<b>VI96</b>	<b>RHC91C</b>				
VA270072	ISUZU				VC270072
VB270072	ISUZU				VC270072
VC270072	ISUZU				
<b>VI98</b>	<b>RHC91-175Q28NABRL7012CUB</b>				
VA270074	ISUZU			28	VB270074
VB270074	ISUZU			28	
<b>VI99</b>	<b>RHC9V-155P39NABRL6812CUBT</b>				
VA390012	ISUZU			39	VH390012
VB390012	ISUZU			39	VH390012
VE390012	ISUZU			39	VH390012
VG390012	ISUZU			39	VH390012
VH390012	ISUZU			39	
<b>VIAA</b>	<b>RHC9V</b>				
VA390013	ISUZU				VE390013
VB390013	ISUZU				VE390013
VD390013	ISUZU				VE390013
VE390013	ISUZU				
<b>VIBN</b>	<b>RHC91-175Q35NABRL7012CUB</b>				
VA270096	ISUZU			35	
<b>VIBU</b>	<b>RHC9</b>				
VA270099	ISUZU				

VIBW	RHC92				
VA270097	ISUZU				

Catalog 2.0 - 2006

**IHI**



## RHE5

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
VICB	RHE52-70005P12NHBRL3711CEZ				
VA190013	ISUZU	VA810069		12	

Catalog 2.0 - 2006

**IHI****RHE6**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
<b>CIBC</b>	<b>RHE61-119002Q30NFBRL539CB</b>				
VA720015	HITACHI	VAX10013	NH369801	30	
<b>CIBL</b>	<b>RHE61-119002Q30NFBRL539CB</b>				
VA720024	ISUZU			30	
<b>CIBL</b>	<b>RHE61</b>				
VB720024	ISUZU				
<b>CIBT</b>	<b>RHE61-130141Q30NFBRL539CB</b>				
VA720031	ISUZU			30	
<b>CIBV</b>	<b>RHE61-13141Q30NFBRL539CB</b>				
VA720032	ISUZU		NH369801	30	
<b>CIDC</b>	<b>RHE61</b>				
VA720053	ISUZU				
<b>CIDK</b>	<b>RHE6</b>				
VA720061	ISUZU				
<b>CXAL</b>	<b>RHE61B</b>				
VA240074	HINO				
<b>MYAX</b>	<b>RHE62W-118003P20NWBRB584CCZ</b>				
VA720022	YANMAR	VAX10016	NH369801	20	VC720022
VB720022	YANMAR	VAX10016	NH369801		VC720022
<b>MYAX</b>	<b>RHE62W</b>				
VC720022	YANMAR	VAX10016	NH369801		
<b>MYBH</b>	<b>RHE62-118003P22NWBRB584CCZ</b>				
VA720033	YANMAR		NH369801	22	VC720033
VB720033	YANMAR		NH369801	22	VC720033
VC720033	YANMAR		NH369801	22	
<b>VIAX</b>	<b>RHE62-96001QZ27NABRL543CAZ</b>				
VB720016	ISUZU			27	VD720016
VD720016	ISUZU			27	
<b>VIAY</b>	<b>RHE62</b>				
VA720017	ISUZU				VD720017
VD720017	ISUZU				
<b>VICN</b>	<b>RHE62</b>				





Catalog 2.0 - 2006

**IHI****RHE7**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
<b>CIBQ</b>	<b>RHE7-14201Q41NMBRL612CA</b>				
VA730022	HITACHI	VAX30012	NH379806	41	VB730022
VB730022	HITACHI	VAX30012	NH379806	41	
<b>CICA</b>	<b>RHE7</b>				
VA730023	ISUZU				
<b>MXAB</b>	<b>RHE7W</b>				
VA730014	HINO				VC730014
VB730014	HINO				VC730014
VC730014	HINO				
<b>MXAC</b>	<b>RHE7W</b>				
VA730015	HINO				VC730015
VB730015	HINO				VC730015
VC730015	HINO				
<b>MXAJ</b>	<b>RHE7W</b>				
VA730017	HINO				
<b>MXAK</b>	<b>RHE7W</b>				
VA730018	HINO				
<b>VIAS</b>	<b>RHE7V-13008P33NABRB612CUAT</b>				
VA770011	ISUZU			33	
VB770011	ISUZU			33	
<b>VIBM</b>	<b>RHE7-14201Q33NABRLL582CUA</b>				
VB730020	ISUZU	VAX30011		33	
<b>VICE</b>	<b>RHE7-14201Q33NABRL612CUA</b>				
VA730024	ISUZU			33	
<b>VICK</b>	<b>RHE7</b>				
VB730026	ISUZU				
<b>VX88</b>	<b>RHE7</b>				
VA730011	HINO				VB730011
VB730011	HINO				
<b>VX89</b>	<b>RHE7-13601Q33NABRA612CUAT</b>				
VA730012	HINO			33	VD730012
VB730012	HINO			33	VD730012

VC730012	HINO			33	VD730012
VD730012	HINO		NH379806	33	VD730012

Catalog 2.0 - 2006



**RHE8**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
<b>MIBJ</b>	<b>RHE8</b>				
VA740014	ISUZU				
<b>MIBO</b>	<b>RHE8-13202Q30NMBRB665SUA</b>				
VA740018	ISUZU			30	
<b>MXAM</b>	<b>RHE8W-15402Q30NMBRB664CUA</b>				
VA740013	HINO			30	
<b>VD20</b>	<b>RHE8</b>				
VA160017	NISSAN				
<b>VX90</b>	<b>RHE8-14506Q30NABRL661CUAT</b>				
VA740011	HINO			30	VC740011
VC740011	HINO			30	
<b>VX91</b>	<b>RHE8</b>				
VA740012	HINO				VC740012
VC740012	HINO				
<b>VXAQ</b>	<b>RHE8-14201Q38NABRL661CUAT</b>				
VA740016	HINO			38	

Catalog 2.0 - 2006

**IHI****RHF3**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
<b>VIBG</b>	<b>RHF3-68002P14NRBRL314CBZ</b>				
VA410018	ISUZU			14	
VB410018	ISUZU	VAX70013		14	
<b>VJ27</b>	<b>RHF3H-550015P14NHBRL315CBZ</b>				
<u>VA410047</u>	MAZDA	NZ870386		14	VB410047
VB410047	MAZDA			14	
<b>VL20</b>	<b>RHF3H</b>				
<u>VA410059</u>	FIAT				
<b>VQ26</b>	<b>RHF3</b>				
VA410016	DAIHATSU				VB410016
VB410016	DAIHATSU				
<b>VQ27</b>	<b>RHF3B-44001P7NRBRL2616DZ</b>				
VA640012	DAIHATSU			7	VF640012
VA640016	DAIHATSU			7	VF640012
VB640012	DAIHATSU			7	VF640012
VB640016	DAIHATSU			7	VF640012
VC640012	DAIHATSU			7	VF640012
<u>VD640012</u>	DAIHATSU			7	VF640012
VF640012	DAIHATSU			7	
<b>VQ28</b>	<b>RHF3</b>				
VA410014	DAIHATSU				
<b>VQ29</b>	<b>RHF3</b>				
VA640013	DAIHATSU				
<b>VQ37</b>	<b>RHF3B-37004Q8NSBRL2416CDZ</b>				
<u>VE640021</u>	DAIHATSU			8	

**Catalog 2.0 - 2006**



**RHF3V**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
VVP2	RHF3V				
IHIVVP2	CITROEN/PEUGEOT	IHCVVP2			

Catalog 2.0 - 2006

**IHI****RHF4**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
<b>AS12</b>	<b>RHF4</b>				
VA420081		IHCAS12			
<b>VA69</b>	<b>RHF4H</b>				
IHIVA69	VM				VF40A023
<b>VA70</b>	<b>RHF4H</b>				
VF40A013	VM				
<b>VA71</b>	<b>RHF4H</b>				
VF40A004	VM				
<b>VA80</b>	<b>RHF4H</b>				
VF40A023	VM				
<b>VB10</b>	<b>RHF4H</b>				
IHIVB10	TOYOTA				
<b>VB11</b>	<b>RHF4H</b>				
IHIVB11	TOYOTA				
<b>VB6</b>	<b>RHF4H</b>				
IHIVB6	TOYOTA	IHCVB6		10.5	
<b>VB8</b>	<b>RHF4H</b>				
IHIVB8	TOYOTA				
<b>VF13</b>	<b>RHF4B-46001EP16NHBRL342CBZ</b>				
VA650011	SUBARU	VAX60013		16	VC650011
VB650011	SUBARU	VAX60013		16	VC650011
VC650011	SUBARU	VAX60013		16	
<b>VF14</b>	<b>RHF4B-57001EP16NHBRL3511CEZ</b>				
VA650012	SUBARU	NZ854182		16	VD650012
VB650012	SUBARU	NZ854182		16	VD650012
<b>VF14</b>	<b>RHF4B-46001P18NHBRL3511CEZ</b>				
VB650016	SUBARU	NZ854182		18	
<b>VF14</b>	<b>RHF4B-57001EP16NHBRL3511CEZ</b>				
VD650012	SUBARU	NZ854182		16	
<b>VF16</b>	<b>RHF4B-46001P16NHBRL3511CEZ</b>				
VA650015	SUBARU			16	VB650015

VB650015	SUBARU			16	
<b>VF17</b>	<b>RHF4B</b>				
VA650016	SUBARU				
<b>VF18</b>	<b>RHF4B-46001P16NHBRL3611CEZ</b>				
VA650017	SUBARU			16	
<u>VA650033</u>	SUBARU			16	
<b>VF19</b>	<b>RHF4B</b>				
VA650018	SUBARU				
<b>VF20</b>	<b>RHF4B-46001P16NHBRL3511CEZ</b>				
VA650019	SUBARU			16	
<u>VA650032</u>	SUBARU			16	
<b>VF21</b>	<b>RHF4B</b>				
VA650020	SUBARU				
<b>VF25</b>	<b>RHF4-62004P12NHBRL382CDZ</b>				
<u>VA420025</u>	SUBARU			12	
<b>VF26</b>	<b>RHF4-62004P14NHBRL382CDZ</b>				
VA420027	SUBARU			14	
<b>VF27</b>	<b>RHF4B-62004P18NHBRL382CD</b>				
VA650041	SUBARU			18	
<b>VF31</b>	<b>RHF4B-46001P11NHBRL3730CEZ</b>				
VB420047	SUBARU			11	
<b>VF32</b>	<b>RHF4B</b>				
VA660045	SUBARU				
<b>VF33</b>	<b>RHF4-46001P11NHBRL362CCZ</b>				
VA420042	SUBARU			11	
<b>VIBD</b>	<b>RHF4-46001P10NRBRL343CBZ</b>				
<u>VA420011</u>	ISUZU	VAX40020	NH449801	10	VB420011
VB420011	ISUZU	VAX40020	NH449801	10	
<b>VIBH</b>	<b>RHF4-46001P10NRBRL343CBZ</b>				
VA420012	ISUZU			10	VB420012
VB420012	ISUZU			10	
<b>VIBI</b>	<b>RHF4-44001P8.5NHBRL343CBZ</b>				
VB420013	ISUZU			8.5	
<b>VIBI</b>	<b>RHF4</b>				
VC420013	ISUZI				
<b>VIBR</b>	<b>RHF4H-64006P12NHBRL362CCZ</b>				
VA420014	ISUZU	VBX40011		12	VF420014
<u>VB420014</u>	ISUZU	VBX40011		12	VF420014
VC420014	ISUZU	VBX40011		12	VF420014
VD420014	ISUZU	VBX40011			
VF420014	ISUZU	VBX40011		12	



<b>VICL</b>	<b>RHF4H-64006P12NHBRL362CCZ</b>				
VA420018	ISUZU	VAX40019		12	VC420018
<u>VC420018</u>	ISUZU	VAX40019		12	
<b>VICQ</b>	<b>RHF4H-64006P12NHBRL362CCZ</b>				
<u>VC420028</u>	ISUZU			12	VF420028
VF420028	ISUZU			12	
<b>VIDA</b>	<b>RHF4H</b>				
VA420037	ISUZU				
<b>VIDE</b>	<b>RHF4H-64006P12NHBRL362CCZ</b>				
VA420054	ISUZU			12	
<b>VIDO</b>	<b>RHF4H</b>				
VC420056	ISUZU				
<b>VIDZ</b>	<b>RHF4H</b>				
VA420076	ISUZU				
<b>VN20</b>	<b>RHF4</b>				
IHIVN20	NISSAN	INCVN20			
<b>VN3</b>	<b>RHF4</b>				
VB420058	NISSAN	IHCVN3			
<b>VQ41</b>	<b>RHF4-46001P11NRBRL3511CEZ</b>				
<u>VB420039</u>	DAIHATSU			11	
<b>VR13</b>	<b>RHF4-62004P10.5NHBRL335CAZ</b>				
<u>IHIVR13</u>	KIA	VAX40012		10.5	
<b>VV11</b>	<b>RHF4</b>				
<u>VF400002</u>	MERCEDES				
<b>VV12</b>	<b>RHF4H</b>				
VF400001	MERCEDES				
<b>VV14</b>	<b>RHF4H</b>				
IHIVV14	MERCEDES				
<b>VVP1</b>	<b>RHF4H</b>				
<u>IHIVVP1</u>	CITROEN/PEUGEOT	IHCVVP1			

**Catalog 2.0 - 2006**



**RHF4V**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
VJ30	RHF4V-68006P15NHBRL345CD				
VAA10018	MAZDA			15	
VJ32	RHF4V				
VAA10019	MAZDA				

Catalog 2.0 - 2006

**IHI****RHF5**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
<b>CYDJ</b>	<b>RHF5</b>				
<u>VB430043</u>	KOMATSU				
<b>CYDM</b>	<b>RHF5-100003P20NHBRL4016CEZ</b>				
VA430052	YANMAR			20	
<b>VA67</b>	<b>RHF5</b>				
<u>VA430035</u>	VM				
<b>VA68</b>	<b>RHF5</b>				
VA430043	VM				
<b>VB7</b>	<b>RHF5H</b>				
IHIVB7	TOYOTA				
<b>VB9</b>	<b>RHF5H</b>				
IHIVB9	TOYOTA				
<b>VF22</b>	<b>RHF5HB-94001P20NHBRL485CBZ</b>				
VA660033	SUBARU	NZ853558		20	VC660033
VA660042	SUBARU	NZ853558		20	VC660033
VA660051	SUBARU	NZ853558		20	VC660033
VA660052	SUBARU	NZ853558		20	VC660033
<u>VB660033</u>	SUBARU	NZ853558		20	VC660033
<u>VB660042</u>	SUBARU	NZ853558		20	VC660033
<u>VB660052</u>	SUBARU	NZ853558		20	VC660033
VC660033	SUBARU	NZ853558		20	
<b>VF23</b>	<b>RHF5HB-94001P20NHBRL467CBZ</b>				
VA660035	SUBARU	VAX20013		20	VB660035
VB660035	SUBARU	VAX20013		20	
<b>VF24</b>	<b>RHF5HB-94001P18NHBRL467CBZ</b>				
VB660049	SUBARU	VAX20013		18	
VB660050	SUBARU			18	
<b>VF28</b>	<b>RHF5HB-94001P18NHBRL467CBZ</b>				
<u>VB660056</u>	SUBARU	VAX20013		18	
VB660058	SUBARU			18	
<b>VF29</b>	<b>RHF5HB-94001P18NHBRL467CBZ</b>				

VB660059	SUBARU			18	
<b>VF30</b>	<b>RHF55-94001P18NHBRL479CBZ</b>				
VA440017	SUBARU			18	VD440017
VD440017	SUBARU			18	
<b>VF34</b>	<b>RHF5HB</b>				
VA660060	SUBARU				VE660060
<u>VE660060</u>	SUBARU				
<b>VF35</b>	<b>RHF55</b>				
VA440022	SUBARU				
<b>VF36</b>	<b>RHF5HB</b>				
VE660065	SUBARU				VG660065
VG660065	SUBARU				
<b>VF37</b>	<b>RHF55</b>				
VE440027	SUBARU				VG440027
<u>VG440027</u>	SUBARU				
<b>VF42</b>	<b>RHF5H</b>				
IHIVF42	SUBARU				
<b>VI AK</b>	<b>RHF55-13003P23NHBR494BZ</b>				
VA440011	ISUZU			23	VD440011
<u>VC440011</u>	ISUZU			23	VD440011
VD440011	ISUZU			23	
<b>VIAM</b>	<b>RHF5B-70005P9NHBRL3711CEZ</b>				
VA660011	ISUZU	NZ853686		9	VI660011
VH660011	ISUZU	NZ853686		9	VI660011
<u>VI660011</u>	ISUZU	NZ854455		9	
<b>VIAN</b>	<b>RHF5B-70005P15NHBRL3911CEZ</b>				
<u>VA660012</u>	ISUZU	NZ853503		15	VB430023
VD660012	ISUZU	NZ853503		15	VB430023
VG660012	ISUZU	NZ853503		15	VB430023
VH660012	ISUZU	NZ853503		15	VB430023
<b>VIAO</b>	<b>RHF5B-70005P15NHBRL3911CEZ</b>				
VA660013	ISUZU			15	VD430024
VE660013	ISUZU			15	VD430024
VH660013	ISUZU			15	VD430024
<b>VIAW</b>	<b>RHF5B-70005P9NHBRL3711CEZ</b>				
VA660015	ISUZU	VAX20018		9	VF660015
VE660015	ISUZU	VAX20018		9	VF660015
VF660015	ISUZU	VAX20018		9	
<b>VIBA</b>	<b>RHF55-117003P23NHBR465BZ</b>				
VA440012	ISUZU			23	VC440012
VB440012	ISUZU			23	VC440012
VC440012	ISUZU			23	

<b>VIBB</b>	<b>RHF5</b>				
VE660022	ISUZU				
<b>VIBF</b>	<b>RHF5-70005P12NHBRL3911CEZ</b>				
VA430016	ISUZU	VAX50017		12	VB430016
VB430016	ISUZU	VAX50017		12	
<b>VIBP</b>	<b>RHF5</b>				
VB660024	ISUZU				
<b>VIBS</b>	<b>RHF5-56007P9NHBRL361EZ</b>				
VA430020	ISUZU	VAX50011		9	
<b>VIBX</b>	<b>RHF5-64006P15NHBRL382CAZ</b>				
VA430021	ISUZU			15	VE430021
VB430021	ISUZU			15	VE430021
VE430021	ISUZU			15	
<b>VIBY</b>	<b>RHF5B</b>				
VA430022	ISUZU				VD430022
VD430022	ISUZU				
<b>VICC</b>	<b>RHF5-64006P17NHBRL382CAZ</b>				
<u>VA430023</u>	ISUZU	VAX50016		17	VB430023
VB430023	ISUZU	VBX50016		17	
<b>VICD</b>	<b>RHF5-64006P17NHBRL382CAZ</b>				
VA430024	ISUZU			17	VD430024
VD430024	ISUZU			17	
<b>VICF</b>	<b>RHF5-64006P13.5NHBRL382CAZ</b>				
<u>VA430015</u>	ISUZU	VAX50016		13.5	VL430015
VB430015	ISUZU	VAX50016		13.5	VL430015
VC430015	ISUZU	VAX50016		13.5	VL430015
VE430015	ISUZU	VAX50016		13.5	VL430015
<u>VF430015</u>	ISUZU	VAX50016		13.5	VL430015
VG430015	ISUZU	VAX50016		13.5	VL430015
<u>VL430015</u>	ISUZU	VAX50016		13.5	
<b>VICI</b>	<b>RHF5</b>				
VK430027	ISUZU				
<b>VICX</b>	<b>RHF5-64006P17NHBRL382CAZ</b>				
VB430057	ISUZU			17	
<b>VIDF</b>	<b>RHF5</b>				
VA430064	ISUZU				
<b>VIDG</b>	<b>RHF5</b>				
VA430065	ISUZU				
<b>VIDH</b>	<b>RHF5</b>				
VA430056	ISUZU				VC430056
VC430056	ISUZU				
<b>VIDS</b>	<b>RHF5</b>				

<u>VA430070</u>	ISUZU	NZ870410			VB430070
VB430070	ISUZU				
<b>VIDW</b>	<b>RHF5</b>				
VA430077	ISUZU				
<b>VJ24</b>	<b>RHF5-70003P12NHBRL3730CEZ</b>				
<u>VC430011</u>	MAZDA			12	
<b>VJ25</b>	<b>RHF5-70003P12NHBRL3730CEZ</b>				
VB430012	MAZDA			12	VB430013
<b>VJ26</b>	<b>RHF5-70003P12NHBRL3730CFZ</b>				
VB430013	MAZDA	NZ854595		12	
VD430013	MAZDA			12	
<b>VL17</b>	<b>RHF5</b>				
<u>VA430047</u>	FIAT	VAX50018			
<b>VL18</b>	<b>RHF5-6400VIP10.5NHBRL3730CEZ</b>				
VA430048	FIAT	VAX50018		10.5	
<b>VM36R</b>	<b>RHF5B-52002GP12NR5BRL4016EZ</b>				
<u>VA660027</u>	MASERATI			12	
<b>VM37L</b>	<b>RHF5B-52002GP12NR5BRL4016EZ</b>				
<u>VA660028</u>	MASERATI			12	
<b>VM38R</b>	<b>RHF5B-70004GP12NR5BRL4016EZ</b>				
<u>VA660054</u>	MASERATI			12	
<b>VM39L</b>	<b>RHF5B-70004GP12NR5BRL4016EZ</b>				
<u>VA660055</u>	MASERATI			12	
<b>VN53</b>	<b>RHF5B-52002P12NR5BRL3730CEZ</b>				
VA660020	BUGATTI			12	
<b>VN54</b>	<b>RHF5B-52002P12NR5BRL3730CEZ</b>				
VA660021	BUGATTI			12	
<b>VQ35</b>	<b>RHF5-64006P17NHBRL3911EZ</b>				
<u>VB430026</u>	DAIHATSU			17	
<b>VR12A</b>	<b>RHF5-64006P15NHBRL401CEZ</b>				
<u>VA430036</u>	KIA	VAX50012		15	VB430036
<b>VR14</b>	<b>RHF5-6400N</b>				
IHIVR14	KIA	VAX50030			
<b>VR15</b>	<b>RHF5-64006P15NHBRL401CEZ</b>				
<u>VB430036</u>	KIA	VAX50030		15	
<b>VU12B</b>	<b>RHF5B-90004LP20NRBRL4626CF</b>				
NZ853050	FERRARI			20	NZ854108
NZ854108	FERRARI			20	
<b>VU13B</b>	<b>RHF5B-90004LP20NR5BRL4626CF</b>				
NZ853051	FERRARI			20	NZ854109
NZ854109	FERRARI			20	



**Catalog 2.0 - 2006**



**RHF6**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
<b>VIBC</b>	<b>RHF61</b>				
VA720013	ISUZU				
<b>VJ23</b>	<b>RHF6B-943P16NR5BRS504AZ</b>				
VA680011	MAZDA	VA890011		16	VB680011
<u>VB680011</u>	MAZDA	VA890011		16	



**Catalog 2.0 - 2006**



**RHG6**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
<b>CICY</b>	<b>RHG6</b>				
VA570019	ISUZU				
<b>CIDJ</b>	<b>RHG6</b>				
VA570038	ISUZU				
<b>CIDV</b>	<b>RHG6</b>				
VA570043	ISUZU				

Catalog 2.0 - 2006

**IHI**



**KHF5**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
<b>K1A</b>	<b>KHF5-1A</b>				
<u>IHIK1A</u>	KIA	VAX50012		15	VB430036
<b>K2B</b>	<b>KHF5-2B</b>				
<u>IHIK2B</u>	HYUNDAI	VAX50030		13	