

# TurboMaster

CATÁLOGO



2.0 - 2006

[WWW.TURBOMASTER.INFO](http://WWW.TURBOMASTER.INFO)

MAR MEDITERRÁNEO, 1 - NAVE 7

28830 SAN FERNANDO DE HENARES (MADRID)

ESPAÑA - SPAIN

TELÉFONO: +34 916.569.273 - 916.569.288

FAX: +34 916.569.397

[VENTAS@TURBOMASTER.INFO](mailto:VENTAS@TURBOMASTER.INFO)

Catálogo 2.0 - 2006



Pinche en la página:

### Series Clásicas

3LM

4HD

4LE

4LF

4MD

5MF

### Series TC

TC15

TCO3

TCO4

TCO5

TCO6

### Series TD

TD10

TD13

TDO2

TDO25

TDO3

TDO4

TDO4H

TDO5H

TDO6

TDO7

TD07S

TD08

TD08H

TD09

**Series TE**

TEO4H

TEO5

TEO6H

**Series TF**

TF15

TFO35

TFO7

TFO8

Catálogo 2.0 - 2006



## 3LM

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>3LM319</b>					
49166-00120		49166-09300			
<b>3LM</b>					
49166-00200		49166-08000			
49166-00210		49166-08000			
49166-00220		49166-08100			
49166-00230		49166-08200			
<b>3LM319</b>					
<u>49166-00300</u>	FURUKAWA	49166-09300			
<b>3LM</b>					
49166-00310		49166-09300			
49166-00311		49166-09300			
49166-00360		49166-09300			
<b>3LM319</b>					
49166-00370	FURUKAWA	49166-09300			
49166-00371	FURUKAWA	49166-09300			
<b>3LM</b>					
49166-00380		49166-09200			
49166-00381		49166-09200			
<b>3LM319</b>					
49166-00600		49166-09300			
49166-00610		49166-09300			
<b>3LM</b>					
49166-00830		49166-09300			
49166-00900		49166-09300			
49166-01220		49166-09400			
49166-01230		49166-09500			
49166-01300		49166-09200			
49166-01306		49166-09200			
<b>3LM259</b>					

49166-01310	MITSUBISHI	49166-09100			
<b>3LM</b>					
49166-01316		49166-09100			
<b>3LM259</b>					
49166-01340					
49166-01346					

Catálogo 2.0 - 2006



**4HD**

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>4HD</b>					
49161-00420		49161-09400			
49161-00602		49160-09200			
49161-01200		49161-09400			
<b>4HD857</b>					
49161-01220					49161-01230
49161-01230		49161-09400			
<b>4HD</b>					
49161-01240		49161-09400			
49161-01250		49161-09400			
49161-01900		49161-09400			
49161-02100		49161-09400			
<b>4HD854</b>					
49161-02203		49161-09200			
<b>4HD</b>					
49161-02551		49161-09300			
49161-02570		49161-09300			

Catálogo 2.0 - 2006



**4LE**

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>4LE</b>					
<u>49162-00230</u>	FURUKAWA	49162-08900			
49162-01230		49162-08810			
49162-01240		49162-08810			
49162-02240		49162-08810			
49162-03110		49162-08900			
49162-03200		49162-08900			
49162-03231		49162-08900			
49162-03240		49162-08900			
49162-03250		49162-08900			
49162-03500		49162-08300			

Catálogo 2.0 - 2006



## 4LF

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>4LF</b>					
49163-00220		49163-08200			
49163-00230		49163-08200			
49163-00240		49163-08200			
49163-00250		49163-08200			
<b>4LF302</b>					
49163-00432		49163-09100			
49163-00434		49163-09100			
49163-00435		49163-09100			
<b>4LF</b>					
49163-00436		49163-09200			
<b>4LF302</b>					
49163-00453		49163-09100			
<b>4LF602</b>					
49163-00471		49163-09300			
<b>4LF</b>					
49163-00490		49163-09200			
<b>4LF302</b>					
49163-01051		49163-09100			
<b>4LF602</b>					
49163-01120		49163-09300			
49163-01121		49163-09300			
<b>4LF302</b>					
49163-01140		49163-09100			
49163-01141		49163-09100			
49163-01147		49163-09100			
49163-01170		49163-09100			
49163-01171		49163-09100			
49163-01176		49163-09100			
<b>4LF</b>					



49163-01177		49163-09100			
49163-01190		49163-09300			
49163-01191		49163-09300			
49163-01210		49163-09300			
49163-01230		49163-09300			
49163-01236		49163-09300			
49163-01240		49163-09300			
<b>4LF302</b>					
49163-01300		49163-09100			
<b>4LF602</b>					
<u>49163-01310</u>	MITSUBISHI	49163-09300			
<b>4LF</b>					
49163-01312		49163-09200			
<b>4LF302</b>					
<u>49163-01320</u>	MITSUBISHI	49163-09100			
<b>4LF602</b>					
49163-01330		49163-09300			
<b>4LF</b>					
49163-01340		49163-09300			
49163-01350		49163-09100			
49163-01360		49163-09100			
49163-01380		49163-09600			
49163-01381		49163-09610			
49163-01382		49163-09610			
49163-01390		49163-09300			
49163-01410		49163-09100			
<b>4LF402</b>					
49163-01420					
<b>4LF</b>					
49163-01620		49163-09100			
49163-01650		49163-09100			
<b>4LF302</b>					
49163-01670		49163-09100			
<b>4LF602</b>					
49163-01700		49163-09300			
<b>4LF302</b>					
49163-01710		49163-09100			
49163-01731		49163-09100			
<b>4LF</b>					
49163-01740		49163-09100			

49163-01752		49163-09500			
49163-01780		49163-09500			
49163-01910		49163-09300			
49163-02000		49163-09100			
49163-02020		49163-09100			
49163-02021		49163-09100			
49163-02030		49163-09100			
49163-02031		49163-09100			
49163-02060		49163-09100			
49163-02201		49163-09610			
49163-02220		49163-09500			
49163-02221		49163-09510			
49163-02230		49163-09100			
49163-02302					
49163-02320					
49163-02400		49163-09600			
49163-02410		49163-09600			

Catálogo 2.0 - 2006



**4MD**

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>4MD</b>					
49160-00410		49160-09100			
49160-00600		49160-09600			
49160-00701		49160-09500			
49160-01100		49160-09100			
49160-01110		49160-09600			
49160-01120		49160-09100			
49160-01160		49160-09600			
49160-01301		49160-09100			
49160-02810		49160-09100			
49160-03411		49160-09100			
49160-04201		49160-09100			
49160-04301		49169-09100			
<b>4MD755</b>					
49160-04502		49160-09100			
49160-04510		49160-09100			
<b>4MD</b>					
49160-04902		49160-09600			
49160-04910		49160-09600			
49160-05301		49160-09100			
49160-4520		49160-09100			

Catálogo 2.0 - 2006



## 5MF

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>5MF781</b>					
<u>49167-00101</u>		49167-09500			
<b>5MF965</b>					
<u>49167-00106</u>		49167-09500			
<b>5MF</b>					
49167-00121		49167-09200			
<b>5MF741</b>					
<u>49167-00130</u>		49167-09500			
<u>49167-00131</u>		49167-09500			
<b>5MF</b>					
49167-00132		49167-09500			
<b>5MF965</b>					
<u>49167-00136</u>		49167-09500			
<b>5MF</b>					
49167-00137		49167-09500			
<b>5MF955</b>					
<u>49167-00160</u>		49167-09400			
<b>5MF</b>					
49167-00190		49167-09500			
49167-00230		49167-09600			
49167-00250		49167-09400			
49167-00320		49167-09500			
49167-00326		49167-09500			
49167-00330		49167-09500			
<b>5MF965</b>					
49167-00336		49167-09500			
<b>5MF995</b>					
49167-00360	MITSUBISHI	49167-09600			
<b>5MF</b>					

49167-00380		49167-09400			
49167-00381		49167-09500			
49167-00386		49167-09400			
49167-00520		49167-09500			
49167-00530		49167-09500			
49167-00540		49167-09500			
49167-00550		49167-09500			
49167-00741		49167-09500			
49167-00751		49167-09500			
49167-00761		49167-09500			

**5MF-721**

49167-00771					
-------------	--	--	--	--	--

**5MF**

49167-00791		49167-09500			
49167-01120		49167-09600			
49167-01610		49167-09500			
49167-01615		49167-09500			
49167-01620		49167-09500			

Catálogo 2.0 - 2006



## TC15

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
TC15					
<u>49124-00150</u>	MITSUBISHI				
<u>49124-00160</u>	MITSUBISHI				

Catálogo 2.0 - 2006



## TC03

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>TC03</b>					
49170-00200		49170-09200			
49170-01000		49170-09300			
49170-01001	YAMAHA	49170-09300			

Catálogo 2.0 - 2006



## TCO4

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>TCO4-09A</b>					
49171-01000	MITSUBISHI	49171-08010	49171-80200		
<b>TCO4-09A/5</b>					
49171-01100	MITSUBISHI	49171-08010	49171-80200	5,0	
<b>TCO4-09B/5</b>					
49171-01200	MITSUBISHI	49171-08020	49171-80200	5,0	
49171-01201	MITSUBISHI	49171-08030	49171-80200	5,0	
<b>TCO4-09B/6</b>					
49171-01300	MITSUBISHI	49171-08020	49171-80200	6,0	
49171-01301	MITSUBISHI	49171-08030	49171-80200	6,0	
49171-01310	MITSUBISHI	49171-08020	49171-80200	6,0	
<b>TCO4-09B</b>					
49171-01311	MITSUBISHI	49171-08030	49171-80200		
<b>TCO4</b>					
49171-01400	MITSUBISHI		49171-80200		
49171-02100	YAMAMOTO	49171-09600	49171-80200		
49171-03002	YAMAHA	49171-09200	49171-80200		
49171-04000		49171-09500	49171-80200		
<b>TCO4-09B</b>					
49171-91200		49171-08020	49171-80200		
49171-91201		49171-08030	49171-80200		
49171-91301		49171-08030	49171-80200		
49171-91311		49171-08030	49171-80200		



Catálogo 2.0 - 2006



## TCO5

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>TCO5</b>					
49168-00301		49169-09200			
49168-00314		49169-09200			
<b>TCO5-07A/6</b>					
49168-00330		49168-09710		6,0	
49168-00331		49168-09710		6,0	
<b>TCO5</b>					
49168-00360		49168-09420			
49168-00370		49168-09420			
49168-00410		49168-09510			
49168-00501		49168-09510			
49168-00510		49168-09410			
<b>TCO5-07A</b>					
49168-00512	FURUKAWA	49168-09100	49168-84100		
<b>TCO5</b>					
49168-00520		49168-09420			
49168-00521		49168-09420			
49168-00532		49168-09200			
49168-00542	FURUKAWA	49168-09730	49168-84100		
49168-00551		49169-09100			
49168-00563		49168-09200			
49168-00900		49169-09200			
49168-00910		49168-09410			
49168-00920		49168-09100			
<b>TCO5-10A</b>					
<u>49168-01200</u>	MITSUBISHI	49168-08020	49168-84100	6,0	
49168-01201	MITSUBISHI	49168-08020	49168-84100	6,0	
<b>TCO5-10A/6</b>					
<u>49168-01202</u>	MITSUBISHI	49168-08020	49168-84100	6,0	
<b>TCO5</b>					

49168-01300	mitsubishi	49168-08040	49168-84100		
<b>TCO5-12A</b>					
49168-01301	mitsubishi	49168-08030	49168-84100		
<b>TCO5</b>					
49168-01310	mitsubishi	49168-08040	49168-84100		
<b>TCO5-12A</b>					
49168-01311	mitsubishi	49168-08030	49168-84100		
49168-01321	mitsubishi	49168-08030	49168-84100		
49168-01322	mitsubishi	49168-08050	49168-84100		
49168-01330	mitsubishi	49168-08030	49168-84100		
49168-01331	mitsubishi	49168-08050	49168-84100		
49168-01340	mitsubishi	49168-08030	49168-84100		
49168-01341	mitsubishi	49168-08050	49168-84100		
<b>TCO5-11A</b>					
49168-01400	mitsubishi	49169-08010	49168-84100		
49168-01401	mitsubishi	49169-08020	49168-84100		
49168-01410	mitsubishi	49169-08010	49168-84100		
49168-01411	mitsubishi	49169-08020	49168-84100		
<b>TCO5</b>					
49168-01412	mitsubishi	49169-08030	49168-84100		
<b>TCO5-11A</b>					
49168-01420	mitsubishi	49169-08020	49168-84100		
<b>TCO5-10A</b>					
49168-01500	mitsubishi	49168-08020	49168-84100		
49168-01510	mitsubishi	49168-08020	49168-84100		
<b>TCO5-12A/8</b>					
49168-01600	mitsubishi	49168-08030	49168-84100	8,0	
49168-01601	mitsubishi	49168-08050	49168-84100	8,0	
<b>TCO5-12A</b>					
49168-01700	mitsubishi	49168-08030	49168-84100		
49168-01710	mitsubishi	49168-08050	49168-84100		
49168-01720	mitsubishi	49168-08050	49168-84100		
49168-01800	mitsubishi	49168-08030	49168-84100		
49168-01801	mitsubishi	49168-08050	49168-84100		
<b>TCO5-12A/6</b>					
49168-01810	mitsubishi	49168-08030	49168-84100	6,0	
49168-01811	mitsubishi	49168-08050	49168-84100	6,0	
<b>TCO5-12A</b>					
49168-01820	mitsubishi	49168-08030	49168-84100		
49168-01821	mitsubishi	49168-08050	49168-84100		

49168-01900	MITSUBISHI	49168-08050	49168-84100		
<b>TCO5</b>					
49168-02301		49169-09200			
49168-02312		49169-09200			
<b>TCO5-07A</b>					
49168-02400	TOYOTA	49168-09100	49168-84100		
<b>TCO5-12A</b>					
49168-03100		49168-08050			
49168-91331		49168-08050			
<b>TCO5</b>					
49168-91411		49169-08020			
49168-91412		49169-08030			
49168-91420		49169-08020			
49168-91601		49168-08030			
49168-91700		49168-08030			
49168-91710		49168-08050			
49168-91810		49168-08030			
49168-91811		49168-08050			
49168-91820		49168-08030			

Catálogo 2.0 - 2006



## TCO6

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>TCO6</b>					
49169-00111		49169-09300			
49169-00120		49169-09200			
<b>TCO6-17B</b>					
<u>49169-00300</u>	FURUKAWA	49169-09600	49168-84100		
<b>TCO6</b>					
49169-00310	MITSUBISHI	49169-09100	49168-84100		
<b>TCO6-17B</b>					
49169-00320	FURUKAWA	49169-09600	49168-84100		
<b>TCO6</b>					
49169-00330	FURUKAWA	49169-09200	49168-84100		
49169-00400	MITSUBISHI	49169-09200	49168-84100		
49169-00406	MITSUBISHI	49169-09200	49168-84100		
49169-00410	MITSUBISHI	49169-09300	49168-84100		
49169-00413	MITSUBISHI	49169-09300	49168-84100		
49169-00416	MITSUBISHI	49169-09300	49168-84100		
49169-00420	MITSUBISHI	49169-09200	49168-84100		
49169-00423	MITSUBISHI	49169-09200	49168-84100		
49169-00426		49169-09200	49168-84100		
49169-00500	MITSUBISHI	49169-09300	49168-84100		
49169-00510	MITSUBISHI	49169-09300	49168-84100		
49169-00520	MITSUBISHI	49169-09100	49168-84100		
49169-00530	MITSUBISHI	49169-09200	49168-84100		
49169-00610	MSK	49169-09100	49168-84100		
49169-00700		49169-09200			
<b>TCO6-11A/8</b>					
49169-01000	MITSUBISHI	49169-08030	49168-84100	8,0	
<b>TCO6-11A</b>					
49169-01100	MITSUBISHI	49169-08020	49168-84100		
<b>TCO6-11A/8</b>					

49169-01200	MITSUBISHI	49169-08020	49168-84100	8,0	
49169-01201	MITSUBISHI	49169-08020	49168-84100	8,0	
<b>TCO6-11A</b>					
49169-01410	MITSUBISHI	49169-08030	49168-84100		
<b>TCO6-11A/8</b>					
49169-01411	MITSUBISHI	49169-08030	49168-84100	8,0	
49169-01412	MITSUBISHI	49169-08030	49168-84100	8,0	
<b>TCO6-11A</b>					
49169-01420	MITSUBISHI	49169-08020	49168-84100		
49169-91000		49169-08030			
49169-91100		49169-08020			
49169-91201		49169-08020			

Catálogo 2.0 - 2006



## TD10

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>TD10</b>					
49171-00200		49181-09500	49181-82000		
<b>TD10</b>					
49181-00212		49181-09300	49181-82000		
49181-00213		49181-09300	49181-82000		
49181-00230		49181-09300	49181-82000		
49181-00240		49181-09400	49181-82000		
49181-00241		49181-09400	49181-82000		
<b>TD10-42F</b>					
49181-00250		49181-09640	49181-82000		
49181-00260		49181-09640	49181-82000		
<b>TD10L-36F</b>					
49181-00272		49181-09630	49181-82000		
49181-00273		49181-09630	49181-82000		
<b>TD10</b>					
49181-00280		49181-09650	49181-82000		
49181-00281		49181-09650	49181-82000		
49181-00282		49181-09650	49181-82000		
<b>TD10L-36F</b>					
49181-00290		49181-09630	49181-82000		
<b>TD10</b>					
49181-00300		49181-09300	49181-82000		
<b>TD10L-36F</b>					
49181-00320		49181-09630	49181-82000		
49181-00321		49181-09630	49181-82000		
49181-00330		49181-09630	49181-82000		
49181-00331		49181-09630	49181-82000		
49181-00336		49181-09630	49181-82000		
<b>TD10-42F</b>					
49181-00340		49181-09640	49181-82000		

49181-00341		49181-09640	49181-82000		
49181-00350		49181-09640	49181-82000		
49181-00400		49181-09640	49181-82000		
49181-00410		49181-09640	49181-82000		
<b>TD10L-36F</b>					
49181-01000		49181-09630	49181-82000		
<b>TD10-42F</b>					
49181-01001		49181-09640	49181-82000		
<b>TD10L-36F</b>					
49181-01010		49181-09630	49181-82000		
49181-01011		49181-09630	49181-82000		
<b>TD10-42F</b>					
49181-01020		49181-09640	49181-82000		
49181-01021		49181-09640	49181-82000		
49181-01023		49181-09640	49181-82000		
<b>TD10L-36F</b>					
49181-01030		49181-09630	49181-82000		
49181-01031		49181-09630	49181-82000		
<u>49181-01040</u>		49181-09630	49181-82000		
49181-01041		49181-09630	49181-82000		
49181-01050		49181-09630	49181-82000		
49181-01051		49181-09630	49181-82000		
<b>TD10</b>					
49181-01060		49181-09750	49181-82000		
49181-01061		49181-09750	49181-82000		
49181-01070		49181-09640	49181-82000		
49181-01080		49181-09620	49181-82000		
49181-01090		49181-09620	49181-82000		
49181-01100		49181-09750	49181-82000		
49181-01110		49181-09620	49181-82000		
<b>TD10-42F</b>					
49181-01120		49181-09640	49181-82000		
<b>TD10</b>					
49181-01130		49181-09640	49181-82000		
49181-01140		49181-09750	49181-82000		
49181-01150		49181-09640	49181-82000		
49181-01211		49181-09640	49181-82000		
49181-01220		49181-09640	49181-82000		
49181-01221		49181-09640	49181-82000		
49181-01230		49181-09640	49181-82000		

49181-01231		49181-09640	49181-82000		
49181-01240		49181-09640	49181-82000		
49181-01241		49181-09640	49181-82000		
49181-01251		49181-09640	49181-82000		
49181-01261		49181-09640			
49181-01271		49181-09640			
49181-01281		49181-09640			
49181-01350		49181-09620			
49181-01360		49181-09620			
49181-01370		49181-09620			
49181-01380		49181-09620			
49181-01390		49181-09640			
49181-01410		49181-09620			
49181-01420		49181-09620			
49181-01430		49181-09620			
49181-01440		49181-09620			
49181-02000		49181-09640			
49181-02200		49181-09500			
49181-02212		49181-09300			
49181-02213		49181-09300			
49181-02230		49181-09300			
49181-02240		49181-09400			
49181-02241		49181-09400			
49181-02250		49181-09840	49181-82000		
49181-02251		49181-09840			
49181-02260		49181-09840			
49181-02272		49181-09830			
49181-02273		49181-09830			
49181-02280		49181-09850			
49181-02281		49181-09850			
49181-02282		49181-09850			
49181-02290		49181-09830			
49181-02300		49181-09300	49181-82000		
49181-02320		49181-09830			
49181-02321		49181-09830			
49181-02330		49181-09830			
49181-02331		49181-09830			
49181-02336		49181-09830			
49181-02340		49181-09840	49181-82000		
49181-02341		49181-09840			
49181-02350		49181-09840			
49181-02351		49181-09830			



49181-02355		49181-09840	49181-82000		
49181-02356		49181-09840			
49181-02360		49181-09950			
49181-02400		49181-09840			
49181-02410		49181-09840			
49181-03002		49181-09840			
49181-03012		49181-09830	49181-82000		
49181-03023		49181-09840	49181-82000		
49181-03032		49181-09830			
49181-03042		49181-09830	49181-82000		
49181-03052		49181-09830			
49181-03062		49181-09850			
49181-03072		49181-09840			
49181-03080		49181-09820	49181-82000		
49181-03090		49181-09820			
49181-03100		49181-09850			
49181-03110		49181-09820	49181-82000		
49181-03122		49181-09840			
49181-03130		49181-09840	49181-82000		
49181-03140		49181-09850			
49181-03152		49181-09840	49181-82000		
49181-03211		49181-09840			
49181-03221		49181-09840	49181-82000		
49181-03231		49181-09840			
49181-03241		49181-09840	49181-82000		
49181-03251		49181-09840	49181-82000		
49181-03261		49181-09840	49181-82000		
49181-03271		49181-09840			
49181-03281		49181-09840	49181-82000		
49181-03350		49181-09830	49181-82000		
49181-03360		49181-09830	49181-82000		
49181-03370		49181-09830			
49181-03380		49181-09830	49181-82000		
49181-03390		49181-09840	49181-82000		
49181-03410		49181-09820	49181-82000		
49181-03420		49181-09820	49181-82000		
49181-03430		49181-09820	49181-82000		
49181-03440		49181-09820	49181-82000		
49181-03502		49181-09840	49181-82000		
49181-03512		49181-09830	49181-82000		
49181-03522		49181-09840	49181-82000		
49181-03542		49181-09830	49181-82000		

49181-03562		49181-09850	49181-82000		
49181-03572		49181-09840	49181-82000		
49181-03590		49181-09820	49181-82000		
49181-03622		49181-09840	49181-82000		

**TD10L**

49181-03850		49181-09830	49181-82000		
49181-03860		49181-09830	49181-82000		
49181-03870		49181-09830	49181-82000		
49181-03880		49181-09830	49181-82000		

**TD10**

49181-03890		49181-09840	49181-82000		
49181-03900		49181-09950	49181-82000		
49181-03910		49181-09950	49181-82000		

Catálogo 2.0 - 2006



## TD13

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>TD13</b>					
49182-01120			49182-80100		
<b>TD13-47B</b>					
49182-01400			49182-80100		
<b>TD13</b>					
49182-02011		49182-08100	49182-80100		
49182-02021		49182-08200	49182-80100		
49182-02031		49182-08300	49182-80100		
49182-02041		49182-08400	49182-80100		
49182-02051		49182-09100	49182-80100		
49182-02061		49182-09200	49182-80100		
49182-02071		49182-09300	49182-80100		
49182-02081		49182-09400	49182-80100		
49182-02102		49182-08200	49182-80100		
49182-02111		49182-08300	49182-80100		
49182-02121		49182-08400	49182-80100		
49182-02132		49182-08300	49182-80100		
49182-02140		49182-08400	49182-80100		
<b>TD13-51F</b>					
49182-02160		49182-09650	49182-80100		
<b>TD13</b>					
49182-02170		49182-09300	49182-80100		
49182-02180		49182-08540	49182-80100		
49182-02181		49182-09640	49182-80100		
49182-02200		49182-08400	49182-80100		
49182-02220		49182-08400	49182-80100		
49182-02300		49182-08300	49182-8010		
49182-02301		49182-08300	49182-80100		
49182-02303		49181-08300	49182-80100		
49182-02320		49182-08200	49182-80100		
49182-02321		49182-08200	49182-80100		

49182-02330		49182-09650	49182-80100		
49182-02340		49182-09650	49182-80100		
49182-02350		49182-09660	49182-80100		
49182-02360		49182-09660	49182-80100		
49182-02370		49182-09820	49182-80100		
49182-03002		49182-09300	49182-80100		
49182-03012		49182-09300	49182-80100		
49182-03013		49182-08300	49182-80100		
49182-03021		49182-08200	49182-80100		
49182-03031		49182-09300	49182-80100		
49182-03041		49182-09300	49182-80100		
49182-03051		49182-08300	49182-80100		
49182-03090		49182-08200	49182-80100		
49182-03100		49182-09300	49182-80100		
49182-03110		49182-09640	49182-80100		
<b>TD13-47F</b>					
<u>49182-03120</u>		49182-09640	49182-80100		
<b>TD13</b>					
49182-03130		49182-09640	49182-80100		
<b>TD13-51F</b>					
49182-03140		49182-09650	49182-80100		
<b>TD13</b>					
49182-03150		49182-09640	49182-80100		
49182-03160		49182-09650	49182-80100		
<b>TD13M-48O</b>					
<u>49182-03270</u>			49182-80100		
<b>TD13</b>					
49182-03300		49182-09640	49182-80100		
49182-03310		49182-08530	49182-80100		
49182-03311		49182-08520	49182-80100		
49182-03320		49182-08530	49182-80100		
49182-03321		49182-08520	49182-80100		
49182-03330		49182-08530	49182-80100		
49182-03331		49182-08520	49182-80100		
49182-03340		49182-08530	49182-80100		
49182-03341		49182-08520	49182-80100		
49182-03350		49182-09640	49182-80100		
49182-03360		49182-09640	49182-80100		
49182-03370		49182-08560	49182-80100		
49182-03380		49182-08520	49182-80100		
49182-03390		49182-08520	49182-80100		

49182-03400		49182-09640	49182-80100		
49182-03410		49182-08520	49182-80100		
49182-03420		49182-08520	49182-80100		
49182-03430		49182-09630	49182-80100		
49182-03440		49182-09660	49182-80100		
49182-03450		49182-09630	49182-80100		
49182-03460		49182-09630	49182-80100		
49182-03470		49182-08610	49182-80100		
49182-03480		49182-08610	49182-80100		
49182-03500		49182-08200	49182-80100		
49182-03510		49182-09640	49182-80100		
<b>TD13-47F</b>					
49182-03520		49182-09640	49182-80100		
<b>TD13</b>					
49182-03530		49182-08520	49182-80100		
49182-03540		49182-09640	49182-80100		
49182-03541			49182-80100		
49182-03550		49182-08520	49182-80100		
49182-03560		49182-09660	49182-80100		
49182-03570		49182-09630	49182-80100		
49182-03590		49182-08520	49182-80100		
49182-03610		49182-08520	49182-80100		
49182-03620		49182-08520	49182-80100		
49182-03630		49182-08520	49182-80100		
49182-03640		49182-08520	49182-80100		
49182-03650		49182-08520	49182-80100		
49182-03660		49182-09640	49182-80100		
49182-03661			49182-80100		
<b>TD13L-47PV</b>					
49182-04000			49182-80100		
<b>TD13</b>					
49182-04100	DETROIT DIESEL		49182-80100		
49182-04400		49182-08610	49182-80100		
49182-04410		49182-08610	49182-80100		
49182-04420		49182-08610	49182-80100		
49182-04430		49182-08610	49182-80100		
49182-04500		49182-08610	49182-80100		
49182-04510		49182-08610	49182-80100		
49182-04520		49182-08610	49182-80100		
49182-04530		49182-08610	49182-80100		
49182-04540		49182-09670	49182-80100		

49182-04550		49182-09750	49182-80100		
49182-04560	49182-09740		49182-80100		
49182-04570		49182-08720	49182-80100		
49182-04580		49182-08720	49182-80100		
49182-04590		49182-08720	49182-80100		
49182-04600		49182-08720	49182-80100		
49182-04610		49182-08710	49182-80100		
49182-04620		49182-08710	49182-80100		
49182-04630		49182-08710	49182-80100		
49182-04640		49182-08710	49182-80100		
49182-04650		49182-08710	49182-80100		
49182-04660		49182-08710	49182-80100		
49182-04670		49182-08710	49182-80100		
49182-04680		49182-08710	49182-80100		
49182-04690		49182-08700	49182-80100		
49182-04700		49182-08700	49182-80100		
49182-04710		49182-09700	49182-80100		
49182-04720		49182-08700	49182-80100		
49182-04730		49182-08610	49182-80100		
49182-04740		49182-08610	49182-80100		
49182-04750		49182-09860	49182-80100		
<b>TD13M-48QRO</b>					
<u>49182-05210</u>		49182-09040	49182-80100		
<b>TD13M</b>					
<u>49182-05300</u>	GUASCOR	49182-09020	49182-80100		

Catálogo 2.0 - 2006



## TDO2

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>TDO2R</b>					
49130-01000		49130-08010			
49130-01100		49130-08020			
49130-01200		49130-08030			
49130-01300		49130-08040			
49130-01400		49130-08050			
49130-01410		49130-08050			
49130-01420		49130-08070			
49130-01500		49130-08060			
49130-01510		49130-08060			
49130-01520		49130-08080			
<b>TDO2MR2-04K</b>					
49130-01600	MITSUBISHI	49130-08100			
49130-01610	MITSUBISHI	49130-08140			
<b>TDO2R</b>					
49130-91000		49130-08010			
49130-91100		49130-08020			
49130-91200		49130-08030			
49130-91300		49130-08040			
49130-91400		49130-08050			
49130-91410		49130-08050			
49130-91420		49130-08070			
49130-91520		49130-08080			
<b>TDO2</b>					
49172-01000		49172-08010			
49172-91000		49172-08010			

Catálogo 2.0 - 2006



## TDO25

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>TDO25</b>					
49173-00100		49173-09300			
49173-00600		49173-09650			
49173-00601		49173-09650			
49173-00611		49173-09650			
49173-00620		49173-09200			
49173-00621		49173-09200			
49173-00700		49173-09830			
49173-01110		49173-09840			
<b>TDO25L-07G/4</b>					
49173-01200	MITSUBISHI	49173-09840			
<b>TDO25</b>					
49173-01310		49173-09850			
<b>TDO25L-07G/4</b>					
49173-01400	MITSUBISHI	49173-09830			
<b>TDO25</b>					
49173-02000		49173-09500			
<b>TDO25M-09T/3.3</b>					
<u>49173-02401</u>	HYUNDAI	49173-08401		3,3	
<b>TDO25M-06T/2.8</b>					
49173-02610	HYUNDAI			2,8	49173-02620
<u>49173-02620</u>	HYUNDAI			2,8	
<b>TDO25</b>					
49173-03000	KUBOTA	49173-09500			
49173-03010	KUBOTA	49173-09500			
49173-03100	KUBOTA	49173-09500			
49173-03110	KUBOTA	49173-09500			
<b>TDO25L-03C</b>					
49173-03200	KUBOTA	49173-09730			
<b>TDO25</b>					



49173-03210	KUBOTA	49173-09730			
49173-03300	KUBOTA	49173-09530			
49173-03400	KUBOTA	49173-08200			
<b>TDO25M-05T</b>					
49173-03410	KUBOTA	49173-08200			
<b>TDO25</b>					
49173-04000		49173-09630			
49173-04100	MITSUBISHI	49173-09600			
49173-04110		49173-09600			
<b>TDO25M-03C</b>					
<u>49173-04200</u>	LOMBARDINI	49173-09530			
49173-04210	LOMBARDINI				
<b>TDO25</b>					
49173-0610		49173-09650			
<b>TDO25L-08T/3.3</b>					
<u>49173-06100</u>	ROVER	49173-08300		3,3	
<b>TDO25M-06T</b>					
<u>49173-06500</u>	OPEL	49173-08700			49173-06501
<u>49173-06501</u>	OPEL	49173-08700			
49173-06511	OPEL				
<b>TDO25</b>					
49173-06601					
<b>TDO25M-03C/2.8</b>					
<u>49173-07300</u>	LOMBARDINI	49173-09530		2,8	49173-07301
<u>49173-07301</u>	LOMBARDINI	49173-09630		2,8	
<u>49173-07310</u>	LOMBARDINI	49173-09630		2,8	
<u>49173-07311</u>	LOMBARDINI	49173-09630		2,8	
<b>TDO25M-03C/2.0</b>					
49173-07320	LOMBARDINI	49173-09530		2,0	
<b>TDO25</b>					
49173-07321	LOMBARDINI	49173-09530			
<b>TDO25L-05G/3.3</b>					
49173-07330	LOMBARDINI	49173-09900		3,3	
<b>TDO25</b>					
49173-07331	LOMBARDINI	49173-09900			
<b>TDO25L-05G/3.3</b>					
49173-07340	LOMBARDINI	49173-09900		3,3	
<b>TDO25</b>					
49173-07341	LOMBARDINI	49173-09900			

<b>TDO25S2-06T/4</b>					
49173-07502	CITROEN	49173-08750			
<b>TDO25</b>					
49173-91110		49173-09840			
49173-91200		49173-09810			
49173-91310		49173-09850			
49173-91400		49173-09830			
<b>TDO25R</b>					
49180-01000		49180-08010			
<b>TDO25MR-05G/2.3</b>					
49180-02030	HYUNDAI			2,3	

Catálogo 2.0 - 2006



## TDO3

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>TDO3</b>					
49131-01000		49131-08000			
49131-01010		49131-08000			
<b>TDO3-07G</b>					
49131-02000	KUBOTA	49131-08010			
<b>TDO3</b>					
49131-02010	KUBOTA	49131-08010			
49131-02020	KUBOTA	49131-08010			
49131-03500	ISEKI	49131-08000			
49131-03510	ISEKI	49131-08000			
49131-04100	MITSUBISHI	49131-08100			
49131-04300	MAZDA	49131-08110			
<u>49131-05000</u>	VOLVO	49131-08200			
<u>49131-05001</u>	VOLVO	49131-08200			49131-05011
49131-05010	VOLVO	49131-08200			
49131-05011	VOLVO				
49131-05050	VOLVO	49131-08210			49131-05051
49131-05051	VOLVO				
<u>49131-05100</u>	VOLVO	49131-08210			
<u>49131-05101</u>	VOLVO	49131-08210			
49131-05110	VOLVO	49131-08210			
49131-05150	VOLVO	49131-08210			49131-05151
49131-05151	VOLVO				
<b>TDO3L4-07T/VG</b>					
49131-06003	OPEL				
<b>TDO3</b>					
49131-94100		49131-08100			
49131-94300		49131-08110			

Catálogo 2.0 - 2006



## TDO4

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>TDO4</b>					
49177-00100	CHRYSLER	49377-08200	49177-80410		
49177-00110	CHRYSLER	49377-08220	49177-80410		
49177-00130	CHRYSLER	49377-08250	49177-80410		
49177-00140	CHRYSLER	49377-08250	49177-80410		
49177-00300		49177-09050	49177-80410		
49177-00301		49177-08230	49177-80410		
49177-00310		49177-08010	49177-80410		
<b>TDO4L-13G/6</b>					
49177-00320	MITSUBISHI	49377-08040	49177-80410	6,0	
<b>TDO4</b>					
49177-00400		49177-09050	49177-80410		
<b>TDO4-11G</b>					
49177-00401	MITSUBISHI	49177-08250	49177-80410		
<b>TDO4</b>					
49177-00410		49177-08010	49177-80410		
<b>TDO4L-13G/6</b>					
49177-00420	MITSUBISHI	49377-08040	49177-80410	6,0	
<b>TDO4-11B</b>					
49177-00600		49177-09400	49177-80410		
49177-00610		49177-09400	49177-80410		
49177-00620		49177-09400	49177-80410		
49177-00630		49177-09400	49177-80410		
<b>TDO4-09B</b>					
49177-00640		49177-08020	49177-80410		
<b>TDO4-11B</b>					
49177-00650		49177-09400	49177-80410		
49177-00660		49177-09400	49177-80410		
<b>TDO4-07B</b>					
49177-00700		49177-09200	49177-80410		

<b>TDO4-09B</b>					
49177-00710		49177-08020	49177-80410		
<b>TDO4-11B</b>					
49177-00720		49177-09400	49177-80410		
<b>TDO4-05B</b>					
49177-00730		49177-09100	49177-80410		
<b>TDO4-07B</b>					
49177-00740		49177-09200	49177-80410		
<b>TDO4-09B</b>					
49177-00750		49177-08030	49177-80410		
<b>TDO4L-13G</b>					
49177-00760		49177-09040	49177-80410		
49177-00770		49177-09040	49177-80410		
49177-00780		49177-09040	49177-80410		
<b>TDO4-09B/4</b>					
49177-01000	FORD	49177-08020	49177-80410	4,0	
49177-01010	MITSUBISHI	49177-08020	49177-80410	4,0	
49177-01020	MITSUBISHI	49177-08020	49177-80410	4,0	
<b>TDO4-09B/3</b>					
49177-01030	MITSUBISHI	49177-08020	49177-80410	3,0	
<b>TDO4-09B/4</b>					
49177-01100	MITSUBISHI	49177-08020	49177-80410	4,0	
<b>TDO4-09B/3</b>					
49177-01200	MITSUBISHI	49177-08020	49177-80410	3,0	
49177-01210	MITSUBISHI	49177-08020	49177-80410	3,0	
49177-01220	MITSUBISHI	49177-08020	49177-80410	3,0	
49177-01230	MITSUBISHI	49177-08020	49177-80410	3,0	
<b>TDO4-09B/5</b>					
49177-01300	MITSUBISHI	49177-08030	49177-80410	5,0	
<b>TDO4</b>					
49177-01301	MITSUBISHI		49177-80410		
<b>TDO4-09B/5</b>					
49177-01310	MITSUBISHI	49177-08030	49177-80410	5,0	
<b>TDO4-11B</b>					
49177-01400	MITSUBISHI	49177-08040	49177-80410		
<b>TDO4-11B/7</b>					
49177-01410	MITSUBISHI	49177-08040	49177-80410	7,0	
49177-01420	MITSUBISHI	49177-08040	49177-80410	7,0	
<b>TDO4-09B/4</b>					

<u>49177-01500</u>	MITSUBISHI	49177-08020	49177-80410	4,0	49177-01501
<u>49177-01501</u>	MITSUBISHI	49177-08020	49177-80410	4,0	
<b>TDO4-10T</b>					
<u>49177-01502</u>	MITSUBISHI	49177-08240	49177-80410		49177-01504
<b>TDO4-10T/4</b>					
<u>49177-01503</u>	MITSUBISHI	49177-08240	49177-80410	4,0	49177-01505
<u>49177-01504</u>	MITSUBISHI	49377-08400	49177-80410	4,0	
<u>49177-01505</u>	MITSUBISHI	49377-08400	49177-80410	4,0	
<b>TDO4-09B/4</b>					
<u>49177-01510</u>	MITSUBISHI	49177-08020	49177-80410	4,0	
<u>49177-01511</u>	MITSUBISHI	49177-08020	49177-80410	4,0	
<b>TDO4-10T/4</b>					
<u>49177-01512</u>	MITSUBISHI	49177-08240	49177-80410	4,0	
<u>49177-01513</u>	MITSUBISHI	49177-08240	49177-80410	4,0	49177-01515
<u>49177-01514</u>	MITSUBISHI	49377-08400	49177-80410	4,0	
<u>49177-01515</u>	MITSUBISHI	49377-08400	49177-80410	4,0	
<b>TDO4-10T</b>					
<u>49177-01520</u>	MITSUBISHI	49177-08240	49177-80410		
<u>49177-01521</u>	MITSUBISHI	49377-08400	49177-80410		
<u>49177-01530</u>	MITSUBISHI	49177-08240	49177-80410		
<u>49177-01531</u>	MITSUBISHI	49377-08400	49177-80410		
<b>TDO4-09B/6</b>					
<u>49177-01600</u>	MITSUBISHI	49177-08030	49177-80410	6,0	
<b>TDO4-11B</b>					
<u>49177-01700</u>	MITSUBISHI	49177-08040	49177-80410		
<u>49177-01710</u>	MITSUBISHI	49177-09020	49177-80410		
<u>49177-01800</u>	MITSUBISHI	49177-08040	49177-80410		
<b>TDO4-11B/4</b>					
<u>49177-01810</u>	MITSUBISHI	49177-09020	49177-80410	4,0	
<b>TDO4-13G/5</b>					
<u>49177-01900</u>	MITSUBISHI	49177-09010	49177-80410	5,0	
<u>49177-01901</u>	MITSUBISHI	49177-08210	49177-80410	5,0	
<b>TDO4</b>					
<u>49177-01910</u>	MITSUBISHI	49377-08030	49177-80410		
<u>49177-02000</u>	MITSUBISHI		49177-80410		
<b>TDO4-07B/5</b>					
<u>49177-02100</u>	MITSUBISHI	49177-09200	49177-80410	5,0	
<b>TDO4-07B/4</b>					
<u>49177-02110</u>	MITSUBISHI	49177-09210	49177-80410	4,0	

<b>TDO4-07B</b>					
49177-02120	mitsubishi	49177-09210	49177-80410		
<b>TDO4-11G</b>					
49177-02130	mitsubishi	49177-09710	49177-80410		
<b>TDO4S-05C</b>					
49177-02200	mitsubishi	49177-08060	49177-80410		
<b>TDO4-11B/6</b>					
<u>49177-02300</u>	mitsubishi	49177-09030	49177-80410	6,0	49177-02310
49177-02301	mitsubishi	49177-08220	49177-80410	6,0	
<u>49177-02310</u>	mitsubishi	49377-08020	49177-80410	6,0	
<b>TDO4</b>					
49177-02350	mitsubishi		49177-80410		
<b>TDO4-11B/6</b>					
<u>49177-02400</u>	mitsubishi	49177-09030	49177-80410	6,0	49177-02410
49177-02401	mitsubishi	49177-08220	49177-80410	6,0	
<u>49177-02410</u>	mitsubishi	49377-08020	49177-80410	6,0	
<b>TDO4-11G/4</b>					
<u>49177-02500</u>	mitsubishi	49177-08110	49177-80410	4,0	49177-02501
<u>49177-02501</u>	mitsubishi	49177-08110	49177-80410	4,0	
49177-02502	mitsubishi	49177-08250	49177-80410	4,0	49177-02503
49177-02503	mitsubishi	49177-08510	49177-80410	4,0	
<u>49177-02510</u>	mitsubishi	49177-08110	49177-80410	4,0	49177-02511
<u>49177-02511</u>	mitsubishi	49177-08110	49177-80410	4,0	49177-02501
<u>49177-02512</u>	mitsubishi	49177-08250	49177-80410	4,0	49177-02513
<u>49177-02513</u>	mitsubishi	49377-08510	49177-80410	4,0	
<u>49177-02520</u>	mitsubishi	49177-08270	49177-80410	4,0	49177-02521
<u>49177-02521</u>	mitsubishi	49377-08520	49177-80410	4,0	
<b>TDO4-10T/4</b>					
<u>49177-02530</u>	mitsubishi	49177-08260	49177-80410	4,0	49177-02531
49177-02531	mitsubishi	49377-08410	49177-80410	4,0	
<b>TDO4-11G</b>					
49177-02540	mitsubishi	49177-08270	49177-80410		
49177-02541	mitsubishi	49377-08520	49177-80410		
<b>TDO4-10T</b>					
49177-02550	mitsubishi	49177-08260	49177-80410		
49177-02551	mitsubishi	49377-08410	49177-80410		
<b>TDO4L-13G</b>					
49177-02600	mitsubishi	49177-09040	49177-80410		
49177-02610	mitsubishi	49177-09040	49177-80410		

49177-02620	MITSUBISHI	49177-09040	49177-80410		
49177-02630	MITSUBISHI	49377-08040	49177-80410		
<b>TDO4</b>					
49177-02640	MITSUBISHI	49377-08210	49177-80410		
<b>TDO4S-09G/3</b>					
49177-02700	MITSUBISHI	49177-09060	49177-80410	3,0	
49177-02701	MITSUBISHI	49177-09060	49177-80410	3,0	49177-02702
49177-02702	MITSUBISHI	49377-08500	49177-80410	3,0	
<b>TDO4S-09G</b>					
49177-02710	MITSUBISHI	49177-09060	49177-80410		
49177-02711	MITSUBISHI	49377-08500	49177-80410		
49177-02720	MITSUBISHI	49177-09060	49177-80410		
49177-02721	MITSUBISHI	49377-08500	49177-80410		
<b>TDO4S-09G/3</b>					
49177-02800	MITSUBISHI	49177-09060	49177-80410	3,0	
<b>TDO4-05B/2.5</b>					
49177-03000	KUBOTA	49177-09500	49177-80410	2,5	
49177-03100	KUBOTA	49177-09500	49177-80410	2,5	
49177-03110	KUBOTA	49177-09500	49177-80410	2,5	
49177-03120	KUBOTA	49177-09500	49177-80410	2,5	
<b>TDO4-12T</b>					
49177-03130	KUBOTA	49177-08300	49177-80410		
49177-03140	KUBOTA	49177-08300	49177-80410		
<b>TDO4S-05C</b>					
49177-03500	KUBOTA	49177-08060	49177-80410		
<b>TDO4L-05C</b>					
49177-03600	KUBOTA	49177-08080	49177-80410		
<b>TDO4-07B</b>					
49177-04010		49177-09510	49177-80410		
<b>TDO4-05B</b>					
49177-04020		49177-09500	49177-80410		
<b>TDO4-07B</b>					
49177-04500	KUBOTA	49177-09210	49177-80410		
<b>TDO4-11G</b>					
49177-04600		49177-08110	49177-80410		
49177-04610		49177-08110	49177-80410		
<b>TDO4-07B/6</b>					
49177-05000	M.W.M.	49177-09200	49177-80410	6,0	
49177-05100	M.W.M.	49177-09200	49177-80410	6,0	



<b>TDO4-07B</b>					
49177-05200	POLONEZ	49177-09200	49177-80410		
<b>TDO4-05B</b>					
49177-05300	BUKH	49177-09100	49177-80410		
49177-05400	BUKH	49177-09100	49177-80410		
<b>TDO4-07B/4</b>					
<u>49177-05500</u>	FIAT	49177-09420	49177-80410	4,0	
<b>TDO4-09B</b>					
49177-05600	FIAT	49177-09310	49177-80410		
<b>TDO4S-07B</b>					
49177-05700	FIAT	49177-09510	49177-80410		
<b>TDO4-09B/4</b>					
49177-05800	FIAT	49177-09310	49177-80410	4,0	
<b>TDO4-11B/4</b>					
<u>49177-06000</u>	BMW	49177-09600	49177-80410	4,0	
<u>49177-06100</u>	BMW	49177-09600	49177-80410	4,0	
<u>49177-06200</u>	BMW	49177-09600	49177-80410	4,0	
<b>TDO4-11G/4</b>					
<u>49177-06400</u>	BMW	49177-09610	49177-80410	4,0	
<b>TDO4-11G</b>					
49177-06402	BMW	49177-09612	49177-80410		
<b>TDO4-11G/4</b>					
<u>49177-06410</u>	BMW	49177-09610	49177-80410	4,0	
<u>49177-06420</u>	OPEL	49177-09610	49177-80410	4,0	49177-06492
49177-06422	BMW	49177-09610	49177-80410	4,0	
<u>49177-06430</u>	ROVER	49177-09610	49177-80410	4,0	49177-06432
<u>49177-06432</u>	ROVER	49177-09612	49177-80410	4,0	
49177-06440	BMW	49177-09620	49177-80410	4,0	
<b>TDO4</b>					
49177-06450	BMW	49177-09650	49177-80410		
<b>TDO4-13T/4</b>					
<u>49177-06451</u>	BMW	49177-09660	49177-80410	4,0	49177-06452
<u>49177-06452</u>	BMW	49177-09662	49177-80410	4,0	
<b>TDO4</b>					
49177-06460	BMW	49177-09650	49177-80410		
<b>TDO4-13T/4</b>					
<u>49177-06461</u>	BMW	49177-09660	49177-80410	4,0	
<b>TDO4</b>					

49177-06470	BMW	49177-09650	49177-80410		
<b>TDO4-13T/4</b>					
49177-06471	BMW	49177-09660	49177-80410	4,0	
<b>TDO4</b>					
49177-06480	BMW	49177-09650	49177-80410		
<b>TDO4-13T/4</b>					
49177-06481	BMW	49177-09660	49177-80410	4,0	
<b>TDO4-11G/4</b>					
<u>49177-06490</u>	OPEL	49177-09610	49177-80410	4,0	49177-06492
49177-06491	OPEL		49177-80410	4,0	49177-06492
49177-06492	OPEL		49177-80410	4,0	
<b>TDO4-11G/5</b>					
<u>49177-06500</u>	BMW	49177-09610	49177-80410	5,0	
49177-06501	BMW	49177-09610	49177-80410	5,0	
<u>49177-06510</u>	BMW	49177-09610	49177-80410	5,0	
49177-06540	BMW	49177-09710	49177-80410	5,0	
<b>TDO4-13T/4</b>					
49177-06570	BMW	49177-09660	49177-80410	4,0	49177-06572
49177-06571	BMW	49177-09660	49177-80410	4,0	49177-06572
<u>49177-06572</u>	BMW	49177-09660	49177-80410	4,0	
49177-06580	BMW	49177-09650	49177-80410	4,0	
49177-06581	BMW	49177-09660	49177-80410	4,0	
49177-06582	BMW	49177-09660	49177-80410	4,0	
<b>TDO4-09B/4</b>					
49177-07500	HYUNDAI	49177-08020	49177-80410	4,0	
49177-07501	HYUNDAI	49177-08020	49177-80410	4,0	
<b>TDO4-10T</b>					
49177-07502	HYUNDAI	49177-08240	49177-80410		
<b>TDO4-10T/4</b>					
49177-07503	HYUNDAI		49177-80410	4,0	
<b>TDO4-11G/4</b>					
<u>49177-07612</u>	HYUNDAI		49177-80410	4,0	
49177-07613	HYUNDAI		49177-80410	4,0	
<b>TDO4-11B/5</b>					
<u>49177-07900</u>	CITROEN/PEUGEOT	49177-09410	49177-80410	5,0	
<b>TDO4</b>					
49177-90300		49177-09050	49177-80410		
49177-90301	MITSUBISHI	49177-08230	49177-80410		
49177-90310	MITSUBISHI	49177-08010	49177-80410		

<b>TDO4L-13G/6</b>					
49177-90320	MITSUBISHI	49377-08040	49177-80410	6,0	
<b>TDO4</b>					
49177-90400		49177-09050	49177-80410		
49177-90401		49177-08230	49177-80410		
49177-90410	MITSUBISHI	49377-08010	49177-80410		
<b>TDO4L-13G/6</b>					
49177-90420	MITSUBISHI	49377-08040	49177-80410	6,0	
<b>TDO4-09B</b>					
49177-91100		49177-08020	49177-80410		
<b>TDO4</b>					
49377-00100	CHRYSLER	49377-08200	49177-80410		
49377-00110	CHRYSLER	49377-08220	49177-80410		
<b>TDO4L-14T/6</b>					
49377-00120	CHRYSLER	49377-08240	49177-80410		
<b>TDO4</b>					
49377-00130	CHRYSLER	49377-08250	49177-80410		
49377-00140	CHRYSLER	49377-08250	49177-80410		
49377-01500	KOMATSU	49177-08500	49177-80410		
<b>TDO4L-10T</b>					
49377-01502	KOMATSU	49177-08500	49177-80410		
<b>TDO4</b>					
49377-01510	KOMATSU	49177-08500	49177-80410		
49377-01520	KOMATSU	49177-08500	49177-80410		
49377-01530	KOMATSU	49177-08500	49177-80410		
<b>TDO4-10T</b>					
49377-01531	MITSUBISHI		49177-80410		
<b>TDO4</b>					
49377-01590	KOMATSU	49177-08500	49177-80410		
<b>TDO4-11B</b>					
49377-01700	MITSUBISHI		49177-80410		
49377-01710	MITSUBISHI		49177-80410		
<b>TDO4-10T/4</b>					
<u>49377-02001</u>	MITSUBISHI	49177-08260	49177-80410	4,0	49377-02002
<u>49377-02002</u>	MITSUBISHI	49377-08410	49177-80410	4,0	
<b>TDO4-10T</b>					
49377-02011	MITSUBISHI	49177-08260	49177-80410		
49377-02012	MITSUBISHI	49377-08410	49177-80410		
49377-02020	MITSUBISHI	49177-08260	49177-80410		

49377-02021	mitsubishi	49377-08410	49177-80410		
<b>TDO4</b>					
49377-02100	mitsubishi	49377-08210	49177-80410		
49377-03000	mitsubishi	49177-08120	49177-80410		
<b>TDO4-12T</b>					
49377-03010	mitsubishi	49177-08130	49177-80410		
49377-03020	mitsubishi	49177-08130	49177-80410		
<u>49377-03030</u>	mitsubishi	49177-08130	49177-80410		49377-03033
<u>49377-03031</u>	mitsubishi	49177-08130	49177-80410		49377-03033
<u>49377-03033</u>	mitsubishi	49177-08300	49177-80410		
<b>TDO4-12T/4</b>					
<u>49377-03040</u>	mitsubishi	49177-08130	49177-80410	4,0	49377-03043
<u>49377-03041</u>	mitsubishi	49177-08130	49177-80410	4,0	49377-03043
<u>49377-03043</u>	mitsubishi	49177-08300	49177-80410	4,0	
<b>TDO4-12T</b>					
49377-03050	mitsubishi	49177-08130	49177-80410		
<b>TDO4</b>					
49377-03051	mitsubishi	49177-08130	49177-80410		
<b>TDO4-12T/4</b>					
49377-03053	mitsubishi	49177-08300	49177-80410	4,0	
<b>TDO4</b>					
49377-03100	mitsubishi	49177-08140	49177-80410		
49377-03101	mitsubishi	49177-08140	49177-80410		
49377-04000	subaru	49377-08110	49177-80410		
49377-04090	subaru	49377-08110	49177-80410		
<b>TDO4L-13T/6</b>					
<u>49377-04100</u>	subaru	49377-08120	49177-80410	6,0	49377-04300
49377-04180	subaru	49377-08120	49177-80410	6,0	
49377-04190	subaru	49377-08120	49177-80410	6,0	
49377-04200	subaru	49377-08120	49177-80410	6,0	49377-04300
<b>TDO4L-13T</b>					
49377-04280	subaru	49377-08120	49177-80410		
<b>TDO4L-13T/6</b>					
49377-04290	subaru	49377-08120	49177-80410	6,0	
<u>49377-04300</u>	subaru	49377-08120	49177-80410	6,0	
<b>TDO4</b>					
49377-04504	subaru				
49377-05000	wiscon	49377-08600	49177-80410		
<b>TDO4-11G</b>					

49377-05100	WISCON	49177-08250	49177-80410		
<b>TDO4</b>					
49377-05110	WISCON	49177-09070	49177-80410		
<b>TDO4L-12T</b>					
49377-05200	HYUNDAI		49177-80410		
<b>TDO4-13G</b>					
49377-05500		49177-08210	49177-80410		
<b>TDO4L-14T/6</b>					
<u>49377-06000</u>	VOLVO	49377-08300	49177-80410	6,0	49377-06011
49377-06010	VOLVO	49377-08300	49177-80410	6,0	49377-06011
<b>TDO4L-12T/6</b>					
<u>49377-06011</u>	VOLVO	49377-08310	49177-80410	6,0	
<b>TDO4L-12T/8.5</b>					
<u>49377-06050</u>	VOLVO	49377-08310	49177-80410	8,5	49377-06060
<u>49377-06051</u>	VOLVO	49377-08310	49177-80410	8,5	49377-06060
<u>49377-06060</u>	VOLVO	49377-08310	49177-80410	8,5	
49377-06061	VOLVO	49377-08311	49177-80410	8,5	
<b>TDO4L</b>					
49377-06100	VOLVO	49377-08700	49177-80410		
49377-06101	VOLVO	49377-08700	49177-80410		
49377-06102	VOLVO		49177-80410		
49377-06110	VOLVO	49377-08700	49177-80410		
<b>TDO4L-14T/8.5</b>					
49377-06150	VOLVO	49377-08300	49177-80410	8,5	49377-06160
49377-06160	VOLVO	49377-08300	49177-80410	8,5	
<b>TDO4L-12T</b>					
49377-06250	VOLVO	49377-08310	49177-80410		
<b>TDO4L-12T/8.5</b>					
49377-06260	VOLVO	49377-08310	49177-80410	8,5	
49377-06351	VOLVO	49377-08321	49177-80410	8,5	
<b>TDO4L</b>					
49377-06361	VOLVO	49377-08320	49177-80410		
<b>TDO4</b>					
49377-06500	SAAB	49377-08330	49177-80410		
<b>TDO4L</b>					
<u>49377-07000</u>	IVECO	49377-08900	49177-80410		
<u>49377-07010</u>	IVECO	49377-08900	49177-80410		
<u>49377-07050</u>	IVECO	49377-08900	49177-80410		49377-07052
49377-07052	IVECO		49177-80410		

49377-07070	IVECO	49377-08900	49177-80410		
<b>TDO4-10T/8.5</b>					
49377-07300	RENAULT	49377-08350	49177-80410	8,5	
49377-07301	RENAULT			8.5	49377-07311
49377-07311	RENAULT			8,5	
<b>TDO4-08T/8</b>					
49377-07700	K.H.DEUTZ	49177-08630	49177-80410	8,0	
<b>TDO4-08T/6</b>					
<u>49377-07710</u>	K.H.DEUTZ	49177-08630	49177-80410	6,0	
<b>TDO4</b>					
49377-90301		49177-08230	49177-80410		
<b>TDO4-10T</b>					
49377-92001		49177-08260	49177-80410		

Catálogo 2.0 - 2006



## TDO4H

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>TDO4H</b>					
49189-00100		49189-08900	49189-84000		
49189-00300		49189-08210	49189-84000		
<b>TDO4HL-15G/8.5</b>					
49189-00501	ISUZU	49189-08100	49189-84000	8,5	
<b>TDO4HL-15G/11</b>					
49189-00511	ISUZU	49189-08100	49189-84000	11,0	
<b>TDO4HL-15G</b>					
49189-00520	ISUZU	49189-08100	49189-84000		
49189-00530	ISUZU	49189-08100	49189-84000		
<b>TDO4HL-15G/12</b>					
49189-00540	ISUZU	49189-08100	49189-84000	12,0	
<b>TDO4HL-15G</b>					
49189-00550	ISUZU	49189-08100	49189-84000		
<b>TDO4H</b>					
49189-00560	ISUZU	49189-08020	49189-84000		
49189-00561	ISUZU	49189-08030	49189-84000		
<b>TDO4HL</b>					
49189-00570	ISUZU	49189-08020	49189-84000		
<b>TDO4H</b>					
49189-00600		49189-08200	49189-84000		
49189-00610		49189-08100	49189-84000		
<b>TDO4HL-13G/6</b>					
49189-00800	MITSUBISHI	49189-08110	49189-84000	6,0	
<b>TDO4HL-13G</b>					
49189-00810	MITSUBISHI	49189-08110	49189-84000		
<b>TDO4HL-15G</b>					
49189-00820	MITSUBISHI	49189-08100	49189-84000		
<b>TDO4HL-13G</b>					
49189-00900	KUBOTA	49189-08110	49189-84000		

<b>TDO4H-13C/6</b>					
49189-01000	VOLVO	49189-08300	49189-84000	6,0	
<b>TDO4H-13C</b>					
49189-01010	VOLVO	49189-08300	49189-84000		
<b>TDO4H-13C/6</b>					
49189-01200	VOLVO	49189-08300	49189-84000	6,0	49189-01210
49189-01210	VOLVO	49189-08300	49189-84000	6,0	
49189-01260	VOLVO	49189-08300	49189-84000	6,0	49189-01270
49189-01270	VOLVO	49189-08310	49189-84000	6,0	
<b>TDO4HL-15G/7</b>					
<u>49189-01300</u>	VOLVO	49189-08500	49189-84000	7,0	49189-01301
<u>49189-01301</u>	VOLVO	49189-08505	49189-84000	7,0	
49189-01310	VOLVO	49189-08505	49189-84000	7,0	49189-01320
49189-01320	VOLVO	49189-08505	49189-84000	7,0	
<b>TDO4HL-16T/7</b>					
49189-01330	VOLVO	49189-08535	49189-84000	7,0	
49189-01335	VOLVO	49189-08535	49189-84000	7,0	
49189-01350	VOLVO	49189-08535	49189-84000	7,0	49189-01355
49189-01355	VOLVO	49189-08535	49189-84000	7,0	
<b>TDO4HL-13G/7</b>					
49189-01360	VOLVO	49189-08515	49189-84000	7,0	
49189-01365	VOLVO	49189-08515	49189-84000	7,0	
<b>TDO4HL-18T/7</b>					
49189-01370	VOLVO	49189-08540	49189-84000	7,0	49189-01375
49189-01375	VOLVO	49189-08540	49189-84000	7,0	
<b>TDO4HL-13G/6</b>					
49189-01400	VOLVO	49189-08515	49189-84000	6,0	49189-01401
49189-01401	VOLVO	49189-08515	49189-84000	6,0	
49189-01410	VOLVO	49189-08515	49189-84000	6,0	49189-01420
49189-01420	VOLVO	49189-08515	49189-84000	6,0	
49189-01430	VOLVO	49189-08515	49189-84000	6,0	
49189-01435	VOLVO	49189-08515	49189-84000	6,0	
<b>TDO4HL-16T/6</b>					
49189-01450	VOLVO	49189-08535	49189-84000	6,0	
49189-01455	VOLVO	49189-08535	49189-84000	6,0	
<b>TDO4H</b>					
49189-01500	HERCULES	49189-08420	49189-84000		
49189-01510	HERCULES	49189-08420	49189-84000		
49189-01540		49188-08130	49189-84000		
<b>TDO4HL-15G/6</b>					



49189-01600	SAAB	49189-08500	49189-84000	6,0	
<b>TDO4HL-15T/6</b>					
49189-01700	SAAB	49189-08525	49189-84000	6,0	
49189-01800	SAAB	49189-08525	49189-84000	6,0	
<b>TDO4H</b>					
49189-02100		49189-08010	49189-84000		
49189-02101		49189-08010	49189-84000		
49189-02110		49189-08010	49189-84000		
49189-02200	mitsubishi	49189-08720	49189-84000		
49189-02300	mitsubishi	49189-08720	49189-84000		
49189-02310	mitsubishi	49189-08030	49189-84000		
49189-02311	mitsubishi	49189-08020	49189-84000		
49189-02320	mitsubishi	49189-08740	49189-84000		
49189-02400		49189-08100	49189-84000		
<b>TDO4HL-13G</b>					
49189-02440	HYUNDAI		49189-84000		
<b>TDO4HL-15GA</b>					
49189-02450	CATERPILLAR				
<b>TDO4H</b>					
49189-02500	mitsubishi	49189-09000	49189-84000		
49189-02600	mitsubishi	49189-09010	49189-84000		
49189-03000		49189-08900	49189-84000		
49189-03100	mitsubishi	49189-08950	49189-84000		
49189-03110		49189-08950	49189-84000		
49189-03120		49189-09240	49189-84000		
49189-03200	MWM	49189-09100	49189-84000		
49189-03201	MWM	49189-09100	49189-84000		
49189-03210	MWM	49189-09100	49189-84000		
49189-03211		49189-09100	49189-84000		
49189-03300	CUMMINS	49189-08010	49189-84000		
49189-03310	CUMMINS	49189-08010	49189-84000		
49189-03350	CUMMINS		49189-84000		
<b>TDO4HL-11T/6</b>					
49189-03700	HYUNDAI		49189-84000	6,0	
<b>TDO4H</b>					
49189-04100	mitsubishi	49189-09000	49189-84000		
49189-04200	mitsubishi	49189-09010	49189-84000		
<b>TDO4HL-16T/7</b>					
49189-05000	VOLVO	49189-08535	49189-84000	7,0	
49189-05010	VOLVO	49189-08535	49189-84000	7,0	

49189-05100	VOLVO	49189-08535	49189-84000	7,0	
49189-05101	VOLVO	49189-08535	49189-84000	7,0	
49189-05111	VOLVO	49189-08535	49189-84000	7,0	
<b>TDO4HL-13T</b>					
49189-05200	VOLVO	49189-08550	49189-84000		
49189-05201	VOLVO	49189-08535	49189-84000		49189-05202
49189-05202	VOLVO		49189-84000		
49189-05210	VOLVO	49189-08550	49189-84000		
49189-05211	VOLVO	49189-08550	49189-84000		
<b>TDO4HL-18T</b>					
49189-05300	VOLVO	49189-08540	49189-84000		
49189-05310	VOLVO	49189-08540	49189-84000		
<b>TDO4L-19T</b>					
49189-05400	VOLVO	49189-08560	49189-84000		
49189-05410	VOLVO	49189-08560	49189-84000		
49189-05411	VOLVO	49189-08560	49189-84000		
<b>TDO4HL</b>					
49189-06070			49189-84000		

Catálogo 2.0 - 2006



## TDO5H

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>TDO5</b>					
49178-00200		49178-09200	49178-81100		
<b>TDO5H-12B</b>					
49178-00210		49178-09300	49178-81100		
49178-00300		49178-09300	49178-81100		
<b>TDO5</b>					
49178-00310		49178-09200	49178-81100		
49178-00340		49178-09700	49178-81100		
49178-00410		49178-09200	49178-81100		
<b>TDO5-10A/6</b>					
49178-00500	MITSUBISHI	49178-08110	49178-81100	6,0	
<b>TDO5-10A</b>					
49178-00510	MITSUBISHI	49178-08110	49178-81100		
49178-00520		49178-08110	49178-81100		
49178-00530	MITSUBISHI	49178-08110	49178-81100		
49178-00540		49178-08110	49178-81100		
49178-00550		49178-08110	49178-81100		
<b>TDO5-12B</b>					
49178-00590	MITSUBISHI	49178-09310	49178-81100		
<b>TDO5-12B/6</b>					
49178-00595	MITSUBISHI	49178-09310	49178-81100	6,0	
<b>TDO5</b>					
49178-00600		49178-09200	49178-81100		
<b>TDO5H-12B</b>					
49178-00610		49178-09300	49178-81100		
49178-00620		49178-09300	49178-81100		
49178-00630		49178-09300	49178-81100		
49178-00640		49178-09300	49178-81100		
49178-00650		49178-09300	49178-81100		
49178-00660		49178-09300	49178-81100		

TDO5					
49178-00670		49178-09400	49178-81100		
49178-00680		49178-09200	49178-81100		
49178-00690		49178-09300	49178-81100		
49178-00700		49178-09300	49178-81100		
49178-00800		49178-09200			
49178-00810		49178-08940			
49178-00820		49178-09300			
49178-00830		49178-08940			
49178-00840		49178-09300			
49178-00870		49178-09300			
49178-00880		49178-09400			
49178-00890		49178-09400			
49178-00900		49178-08940			
49178-00910		49178-08640			
49178-00930		49178-08630			
49178-00940		49178-09040			
49178-00970		49178-09030			
49178-00980		49178-08630			
49178-00990		49178-08630			
49178-01000		49178-09010	49178-81100		
TDO5H-14B/6					
<u>49178-01010</u>	MITSUBISHI	49178-09010	49178-81100	6,0	
<u>49178-01030</u>	MITSUBISHI	49178-09010	49178-81100	6,0	
TDO5					
49178-01100		49178-08010	49178-81100		
49178-01200		49178-08010	49178-81100		
49178-01340		49178-08010	49178-81100		
TDO5H					
49178-01400	MITSUBISHI	49178-08020	49178-81100		
TDO5H-14B/6					
49178-01410	MITSUBISHI	49178-09010	49178-81100	6,0	
TDO5H-16T/7					
49178-01411	MITSUBISHI		49178-81100	7,0	
TDO5H-16G/7					
49178-01420	MITSUBISHI	49178-09020	49178-81100	7,0	
TDO5H-16G					
49178-01450	MITSUBISHI	49178-09020	49178-81100		
49178-01460	MITSUBISHI	49178-09020	49178-81100		
TDO5H-16G/7					

49178-01470	MITSUBISHI	49178-09050	49178-81100	7,0	
<b>TDO5H-16G</b>					
49178-01500	MITSUBISHI	49178-08800	49178-81100		
<b>TDO5H-16G/7</b>					
49178-01510	MITSUBISHI	49178-08800	49178-81100	7,0	
<b>TDO5H-16G/6</b>					
49178-01520	MITSUBISHI	49178-08800	49178-81100	6,0	
<b>TDO5</b>					
49178-01540	MITSUBISHI	49178-08850	49178-81100		
<b>TDO5H-16G</b>					
49178-01550	MITSUBISHI	49178-08800	49178-81100		
<b>TDO5HRA-16G/10</b>					
49178-01560	MITSUBISHI	49178-08850	49178-81100	10,5	
<b>TDO5HRA-15G</b>					
49178-01570	MITSUBISHI	49178-08880			
<b>TDO5HRA-16GS</b>					
49178-01580	MITSUBISHI	49178-08880	49178-81100		
<b>TDO5HR-16G6/9.8</b>					
49178-01590	MITSUBISHI	49178-08880	49178-81100	9,8	
<b>TDO5</b>					
49178-01600	MITSUBISHI	49178-08010	49178-81100		
49178-01700	MITSUBISHI	49178-08010	49178-81100		
49178-01710	MITSUBISHI	49178-08010	49178-81100		
<b>TDO5-12A/8</b>					
49178-01730	MITSUBISHI	49178-08010	49178-81100	8,0	
49178-01740	MITSUBISHI	49178-08010	49178-81100	8,0	
<b>TDO5H-14G/8</b>					
49178-01750	MITSUBISHI	49178-08620	49178-81100		
<b>TDO5-14G/8</b>					
49178-01760	MITSUBISHI	49178-08620	49178-81100		
<b>TDO5</b>					
49178-01900	MITSUBISHI	49178-08010	49178-81100		
49178-02000	MITSUBISHI	49178-09650	49178-81100		
49178-02001	MITSUBISHI	49178-09650	49178-81100		
49178-02010		49178-09650	49178-81100		
<b>TDO5H-12B</b>					
49178-02100		49178-09300	49178-81100		
<b>TDO5H-12B/8</b>					
49178-02110	MITSUBISHI	49178-09300	49178-81100	8,0	

<b>TDO5H-12B</b>					
49178-02115	mitsubishi	49178-09300	49178-81100		
<b>TDO5</b>					
49178-02120	mitsubishi	49178-02120	49178-81100		
49178-02121	mitsubishi	49178-09620	49178-81100		
49178-02122	mitsubishi	49178-09640	49178-81100		
49178-02123	mitsubishi	49178-09610	49178-81100		
<b>TDO5H-12B</b>					
49178-02125	mitsubishi	49178-09300	49178-81100		
<b>TDO5</b>					
49178-02126	mitsubishi	49178-09620	49178-81100		
<b>TDO5H-14G/12</b>					
49178-02130	mitsubishi	49178-09610	49178-81100	12,0	
<b>TDO5</b>					
49178-02135	mitsubishi	49178-09610	49178-81100		
49178-02136	mitsubishi	49178-09610	49178-81100		
49178-02140	mitsubishi	49178-09620	49178-81100		
49178-02145	mitsubishi	49178-09620	49178-81100		
49178-02150	mitsubishi	49178-09610	49178-81100		
49178-02155	mitsubishi	49178-09610	49178-81100		
49178-02160	mitsubishi	49178-09640	49178-81100		
49178-02170	mitsubishi	49178-09610	49178-81100		
49178-02180	mitsubishi	49178-09620	49178-81100		
49178-02190	mitsubishi	49178-09610	49178-81100		
49178-02200		49178-08940	49178-81100		
49178-02210		49178-09400	49178-81100		
49178-02300	mitsubishi	49178-02305	49178-81100		
<b>TDO5H-12B</b>					
49178-02305	mitsubishi	49178-09300	49178-81100		
<b>TDO5</b>					
49178-02310	mitsubishi	49178-09620	49178-81100		
49178-02315	mitsubishi	49178-09610	49178-81100		
49178-02320	mitsubishi	49178-09620	49178-81100		
49178-02325	mitsubishi	49178-09610	49178-81100		
49178-02330	mitsubishi	49178-09640	49178-81100		
49178-02335	mitsubishi	49178-09610	49178-81100		
<b>TDO5H</b>					
49178-02350	mitsubishi		49178-81100		
<b>TDO5</b>					
49178-02380	mitsubishi	49178-09640	49178-81100		

<b>TDO5H</b>					
49178-02385	MITSUBISHI	49178-09610	49178-81100		
<b>TDO5</b>					
49178-02400		49178-09410	49178-81100		
49178-02500		49178-09410	49178-81100		
<b>TDO5H-12B/6</b>					
49178-03000	VOLVO	49178-09300	49178-81100	6,0	
<b>TDO5-12B</b>					
49178-03010	VOLVO	49178-08030	49178-81100		
<b>TDO5-12G/6</b>					
49178-03122	HYUNDAI		49178-81100	6,0	
<b>TDO5H-14G/10</b>					
49178-03123	HYUNDAI		49178-81100	10,0	
<b>TDO5H-12/6</b>					
49178-03200	KUBOTA	49178-09630	49178-81100	6,0	
<b>TDO5-10A/6</b>					
49178-03530	HYUNDAI	49178-08110	49178-81100	6,0	
<b>TDO5H-12B</b>					
49178-04000		49178-09300	49178-81100		
<b>TDO5</b>					
49178-04200		49178-08040	49178-81100		
49178-04300		49178-08040	49178-81100		
49178-04310		49178-08020	49178-81100		
49178-04320		49178-09520	49178-81100		
49178-04330		49178-09090	49178-81100		
49178-04340		49178-09090	49178-81100		
49178-04400		49178-09060	49178-81100		
49178-04410		49178-09070	49178-81100		
49178-04500		49178-09090	49178-81100		
49178-04510		49178-09090	49178-81100		
49178-05000		49178-09300	49178-81100		
49178-05010		49178-09300	49178-81100		
49178-05020		49178-09400	49178-81100		
49178-05040		49178-08210	49178-81100		
49178-05050		49178-08220			
49178-05060		49178-08220			
49178-05070		49178-08220			
49178-05080		49178-08210			
49178-05090		49178-08710			
49178-05100		49178-08710			

49178-05200	MITSUBISHI	49178-09090	49178-81100		
49178-05530		49178-08110			
<b>TDO5H-16G</b>					
49178-06200	SUBARU	49178-08310	49178-81100		
<b>TDO5</b>					
49178-06290	FUJI	49178-08310	49178-81100		
<b>TDO5H-16G</b>					
49178-06300	SUBARU	49178-08310	49178-81100		
49178-06310	SUBARU	49178-07300	49178-81100		
<b>TDO5</b>					
49178-06380	FUJI	49178-08310	49178-81100		
49178-06390	FUJI	49178-08310	49178-81100		
<b>TDO5H-12B/6</b>					
<u>49178-07200</u>	ALFA ROMEO	49178-07300	49178-81100	6,0	
<b>TDO5</b>					
49178-91200		49178-08010			
49178-91340		49178-08010			
49178-91400		49178-08020			
<b>TDO5H-16G</b>					
49178-91450	MITSUBISHI	49178-09020	49178-81100		
<b>TDO5</b>					
49178-91560	MITSUBISHI	49178-08850	49178-81100		
<b>TDO5HRA-16G6/9</b>					
49378-01510	MITSUBISHI	49178-08950		9,8	
49378-01520	MITSUBISHI	49178-08960		9,8	



Catálogo 2.0 - 2006



## TDO6

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>TDO6-17A</b>					
49179-00100	MITSUBISHI	49179-09720	49178-81100		
<b>TDO6-17A/12</b>					
49179-00110	MITSUBISHI	49179-09720	49178-81100	12,0	
<b>TDO6-17C</b>					
49179-00120	MITSUBISHI	49179-09400	49178-81100		
<b>TDO6-17A</b>					
49179-00130	MITSUBISHI	49179-09720	49178-81100		
<b>TDO6-19C</b>					
49179-00150	MITSUBISHI	49179-09500	49178-81100		
<b>TDO6-17C/10</b>					
49179-00160	MITSUBISHI	49179-09400	49178-81100	10,0	
<b>TDO6-17C</b>					
49179-00180	MITSUBISHI	49179-09400	49178-81100		
<b>TDO6-19C</b>					
49179-00191	MITSUBISHI	49179-09500	49178-81100		
<b>TDO6-19C/12</b>					
49179-00200	MITSUBISHI	49179-09500	49178-81100	12,0	
<b>TDO6-11A/8</b>					
49179-00210	MITSUBISHI	49179-09700	49178-81100	8,0	
49179-00220	MITSUBISHI	49179-09700	49178-81100	8,0	
<b>TDO6-14A/6</b>					
49179-00230	MITSUBISHI	49179-09710	49178-81100	6,0	
<b>TDO6-19C/12</b>					
49179-00240	MITSUBISHI	49179-09850	49178-81100	12,0	
<b>TDO6H</b>					
49179-00251	MITSUBISHI	49179-08530	49178-81100		
49179-00252	MITSUBISHI	49179-08530	49178-81100		
49179-00253	MITSUBISHI	49179-08530	49178-81100		
<b>TDO6</b>					

49179-00254	MITSUBISHI	49179-08670	49178-81100		
49179-00260	MITSUBISHI	49179-08540	49178-81100		
49179-00261	MITSUBISHI	49179-08540	49178-81100		
49179-00270	MITSUBISHI	49179-08540	49178-81100		
49179-00280	MITSUBISHI	49179-08540	49178-81100		
49179-00290	MITSUBISHI	49179-08540	49178-81100		
49179-00300	MITSUBISHI	49179-09100	49178-81100		
<b>TDO6-14A</b>					
49179-00400	MITSUBISHI	49179-09710	49178-81100		
<b>TDO6</b>					
49179-00440		49179-09300	49178-81100		
<b>TDO6H-14C</b>					
49179-00450		49179-09830	49178-81100		
<b>TDO6H-14C/14</b>					
<u>49179-00451</u>	CATERPILLAR	49179-09830	49178-81100	14,0	
<b>TDO6H-14C/12</b>					
49179-00460	CATERPILLAR	49179-09830	49178-81100	12,0	
<b>TDO6</b>					
49179-00490		49179-09300	49178-81100		
<b>TDO6-19C</b>					
49179-00510		49179-09850	49178-81100		
49179-00520		49179-09850	49178-81100		
<b>TDO6H-14C/12</b>					
49179-00530	CATERPILLAR	49179-09830	49178-81100	12,0	
<b>TDO6-17C</b>					
49179-00600		49179-09400	49178-81100		
<b>TDO6</b>					
49179-00610		49179-09200	49178-81100		
<b>TDO6-17C</b>					
49179-00620		49179-09400	49178-81100		
49179-00630		49179-09400	49178-81100		
49179-00640		49179-09400	49178-81100		
49179-00650		49179-09400	49178-81100		
<b>TDO6</b>					
49179-00660		49179-09300	49178-81100		
<b>TDO6-17C</b>					
49179-00670		49179-09400	49178-81100		
49179-00680		49179-09400	49178-81100		
49179-00690		49179-09400	49178-81100		

<b>TDO6</b>					
49179-00700		49179-09300	49178-81100		
49179-00800	HKS	49179-09300	49178-81100		
<b>TDO6-17C</b>					
49179-00810	HKS	49179-09400	49178-81100		
<b>TDO6</b>					
49179-00820	HKS	49179-09840	49178-81100		
<b>TDO6-17C</b>					
49179-00830	HKS	49179-09400	49178-81100		
<b>TDO6-19C</b>					
49179-00840	HKS	49179-09500	49178-81100		
49179-00850	HKS	49179-09500	49178-81100		
<b>TDO6H-14C</b>					
49179-00860	HKS	49179-09830	49178-81100		
<b>TDO6-17C</b>					
49179-00870	HKS	49179-09400	49178-81100		
<b>TDO6-19C</b>					
49179-00880	HKS	49179-09500	49178-81100		
<b>TDO6</b>					
49179-00890	HKS	49179-09300	49178-81100		
49179-00910	HKS	49179-08450	49178-81100		
49179-00920	HKS	49179-08550	49178-81100		
<b>TDO6-19C</b>					
49179-01000		49179-09500	49178-81100		
49179-01010		49179-09500	49178-81100		
<b>TDO6</b>					
49179-01020		49179-09500	49178-81100		
49179-01030		49179-09300	49178-81100		
49179-01040		49179-09400	49178-81100		
49179-01050		49179-09500	49178-81100		
49179-01060		49179-09500	49178-81100		
49179-01070		49179-09400	49178-81100		
49179-01080		49179-09500	49178-81100		
49179-01090		49179-09850	49178-81100		
49179-01100		49179-09850	49178-81100		
49179-01120		49179-09850	49178-81100		
49179-01130		49179-09500	49178-81100		
49179-01140		49179-09850			
49179-01150		49179-08440			
49179-01160		49179-08540			

49179-01170		49179-09500			
49179-01180		49179-08440			
49179-01190		49178-08540	49178-81100		
49179-01200		49179-08440			
49179-01210		49179-08540			
49179-01220		49179-08310			
49179-01230		49179-08310			
49179-02000		49179-09300	49178-81100		
<b>TDO6-17A/12</b>					
49179-02100	MITSUBISHI	49179-08730	49178-81100	12,0	
<b>TDO6-17C/10</b>					
49179-02110	MITSUBISHI	49179-09400	49178-81100	10,0	
<b>TDO6-19C</b>					
49179-02120	MITSUBISHI	49179-09500	49178-81100		
49179-02200		49179-09500	49178-81100		
<b>TDO6H-17C/12</b>					
49179-02210	HERCULES	49178-09830	49178-81100	12,0	
<b>TDO6H-16M/12</b>					
49179-02220	CATERPILLAR	49179-09940	49178-81100	12,0	49179-02260
49179-02230	CATERPILLAR	49179-08600	49178-81100	12,0	49179-02260
49179-02240	CATERPILLAR	49179-08600	49178-81100	12,0	49179-02260
<b>TDO6</b>					
49179-02250	HERCULES	49179-08850	49178-81100		
<b>TDO6H-16M/12</b>					
<u>49179-02260</u>	CATERPILLAR	49179-08600	49178-81100	12,0	
<b>TDO6H-16M</b>					
49179-02270	CATERPILLAR	49179-08600	49178-81100		
49179-02280	CATERPILLAR	49179-08600	49178-81100		
<b>TDO6H-16M/12</b>					
<u>49179-02300</u>	CATERPILLAR	49179-08600	49178-81100	12,0	
<b>TDO6</b>					
49179-02400	MITSUBISHI	49179-08540	49178-81100		
49179-02410	MITSUBISHI	49179-08540	49178-81100		
49179-03000	TOYOTA	49179-09600	49178-81100		
<b>TDO6-17C/8</b>					
49179-04000	GMC	49179-08940	49178-81100	8,0	
<b>TDO6</b>					
49179-04100	GMC	49179-08240	49178-81100		
<b>TDO6-18G/8</b>					

49179-05000	NISSAN	49179-08430	49178-81100	8,0	
<b>TDO6</b>					
49179-06000		49179-09840	49178-81100		

Catálogo 2.0 - 2006



## TD07

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>TD07</b>					
49175-00108		49175-08010	49187-80110		
49175-00120		49175-08050	49187-80110		
<b>TD07-22A</b>					
49175-00130		49175-08020	49187-80110		
<b>TD07</b>					
49175-00200			49187-80110		
49175-00201		49175-08100	49187-80110		
<b>TD07-18A/21</b>					
49175-00217			49187-80110	21,0	49175-00293
<b>TD07</b>					
49175-00240			49187-80110		
49175-00241			49187-80110		
49175-00250		49175-08100	49187-80110		
49175-00251		49175-08100	49187-80110		
49175-00260		49175-08110	49187-80110		
49175-00261		49175-08110	49187-80110		
49175-00270		49175-08030	49187-80110		
49175-00271		49175-08170	49187-80110		
49175-00272		49175-08030	49187-80110		
49175-00273		49175-08170	49187-80110		
49175-00280		49175-08000	49187-80110		
49175-00281		49175-08000	49187-80110		
<b>TD07-18A</b>					
49175-00282		49175-08160	49187-80110		
49175-00283		49175-08160	49187-80110		
<b>TD07</b>					
49175-00284		49175-08100	49187-80110		
49175-00285		49175-08100	49187-80110		
49175-00286		49175-08110	49187-80110		
49175-00287		49175-08110	49187-80110		

49175-00288		49175-08000			
49175-00289		49175-08000			
49175-00290		49175-08100			
49175-00291		49175-08100	49187-80110		
49175-00292		49175-08160			
<b>TDO7-18A/21</b>					
49175-00293		49175-08160	49187-80110	21,0	
<b>TDO7</b>					
49175-00294		49175-08110	49187-80110		
49175-00295		49175-08110			
49175-00318		49175-08010			
49175-00319		49175-08010			
49175-00328		49175-08010			
49175-00408		49175-08000			
<b>TDO7-22A/21</b>					
49175-00410			49187-80110	21,0	49175-00418
49175-00418	MITSUBISHI	49175-08020	49187-80110	21,0	
<b>TDO7-22A/17</b>					
49175-00428	MITSUBISHI	49175-08020	49187-80110	17,0	
<b>TDO7</b>					
49175-00458		49175-08000	49187-80110		
49175-00508		49175-08010			
49175-00608		49175-08020			
49175-00618		49175-08020	49188-80200		
49175-00628		49175-08030	49187-80110		
49175-00638		49175-08030			
49175-00648		49175-08050	49187-80110		
49175-00658		49175-08030	49187-80110		
49175-00668		49175-08030			
49175-00708		49175-08020			
49175-00718		49175-08030			
49175-00728		49175-08030			
49175-00808		49175-08020	49187-80110		
49175-00818		49175-08020			
49175-01200		49175-08030	49187-80110		
49175-01300		49175-08030	49187-80110		

Catálogo 2.0 - 2006



## TDO7S

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>TDO7S-25A/13</b>					
<u>49187-00200</u>	MITSUBISHI	49187-08010	49187-80110	13,0	
<b>TDO7S</b>					
49187-00211		49187-08000	49187-80110		
<b>TDO7S-25A/13</b>					
49187-00220		49187-08020	49187-80110	13,0	
<b>TDO7S</b>					
49187-00250		49187-08120	49187-80110		
<b>TDO7S-25A</b>					
49187-00270		49187-08070	49187-80110		
<b>TDO7S-25A/13</b>					
49187-00271			49187-80110	13,0	
49187-00280	MITSUBISHI	49187-08050	49187-80110	13,0	
<b>TDO7S</b>					
49187-00300		49187-08020	49187-80110		
49187-00310		49187-08000	49187-80110		
49187-00320		49187-08020			
49187-00330		49187-08000	49187-80110		
49187-00340		49187-08060	49187-80110		
49187-00350		49187-08000			
49187-00360		49187-08060			
49187-00400		49187-08500	49187-80110		
49187-00410		49187-08500			
49187-00900		49187-08200			
49187-00910		49187-08200	49187-80110		
49187-00920		49187-08200	49187-80110		
49187-00940		49187-08200			
49187-01510			49187-80110		



Catálogo 2.0 - 2006



## TDO8

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>TDO8-22B/22</b>					
49174-00105	MITSUBISHI		49188-80200	22,0	49174-01140
<b>TDO8-22D</b>					
49174-00108		49174-09200	49188-80200		
<b>TDO8-15B</b>					
49174-00118		49174-09100	49188-80200		
49174-00128		49174-09100	49188-80200		
<b>TDO8</b>					
49174-00138		49174-09400	49188-80200		
<b>TDO8-22B</b>					
49174-00148			49188-80200		
<b>TDO8</b>					
49174-00158		49174-08140	49188-80200		
<b>TDO8-4</b>					
49174-00160	MITSUBISHI		49188-80200		
<b>TDO8-22D</b>					
49174-00168	MITSUBISHI	49174-09200	49188-80200		
49174-00178		49174-09200	49188-80200		
<b>TDO8-15B</b>					
49174-00188		49174-09100	49188-80200		
49174-00198		49174-09100	49188-80200		
49174-00200			49188-80200		
49174-00208		49174-09100	49188-80200		
49174-00211			49188-80200		
49174-00212			49188-80200		
49174-00218		49174-09100	49188-80200		
49174-00219		49174-09100	49188-80200		
<b>TDO8-20B</b>					
49174-00221			49188-80200		
<b>TDO8</b>					

49174-00228		49174-09400	49188-80200		
<b>TDO8-15B</b>					
49174-00231			49188-80200		
49174-00238		49174-09100	49188-80200		
<b>TDO8-29B</b>					
49174-00240			49188-80200		
49174-00241			49188-80200		
<b>TDO8</b>					
49174-00248		49174-08120	49188-80200		
49174-00249		49174-08120	49188-80200		
<b>TDO8-29B</b>					
49174-00251			49188-80200		
<b>TDO8</b>					
49174-00258		49174-08120	49188-80200		
49174-00260			49188-80200		
<b>TDO8-20B</b>					
49174-00261			49188-80200		
<b>TDO8</b>					
49174-00268		49174-09400	49188-80200		
49174-00269		49174-09400	49188-80200		
49174-00270			49188-80200		
49174-00271			49188-80200		
49174-00278		49174-08120	49188-80200		
49174-00279		49174-08120	49188-80200		
<b>TDO8-29B</b>					
49174-00280			49188-80200		
<b>TDO8</b>					
49174-00288		49174-08120	49188-80200		
<b>TDO8-20B</b>					
49174-00290			49188-80200		
<b>TDO8</b>					
49174-00298		49174-09400	49188-80200		
<b>TDO8-22B</b>					
49174-00301			49188-80200		
<b>TDO8-22D</b>					
49174-00309		49174-09200	49188-80200		
<b>TDO8-22B</b>					
49174-00310			49188-80200		
<b>TDO8-22D</b>					

49174-00318		49174-09200	49188-80200		
<b>TDO8-20B</b>					
49174-00320			49188-80200		
<b>TDO8</b>					
49174-00328		49174-09400	49188-80200		
<b>TDO8-22B</b>					
49174-00400			49188-80200		
<b>TDO8</b>					
49174-00408		49174-09200	49188-80200		
<b>TDO8-22B</b>					
49174-00500			49188-80200		
49174-00501			49188-80200		
<b>TDO8-22B/22</b>					
49174-00508	MITSUBISHI	49174-09200	49188-80200	22,0	
<b>TDO8-22B</b>					
49174-00509	MITSUBISHI	49174-09200	49188-80200		
49174-00510			49188-80200		
<b>TDO8</b>					
49174-00518		49174-09200	49188-80200		
49174-00538		49174-09200	49188-80200		
<b>TDO8-22B</b>					
49174-00540	MITSUBISHI		49188-80200		
<b>TDO8</b>					
49174-00548		49174-09200	49188-80200		
<b>TDO8-22D/28</b>					
49174-00560	MITSUBISHI	49174-09200	49188-80200	22,0	
<b>TDO8-22D</b>					
49174-00561		49174-09200	49188-80200		
49174-00562	MITSUBISHI	49174-09200	49188-80200		
49174-00563		49174-09200	49188-80200		
<b>TDO8-22B/28</b>					
49174-00564		49174-09200	49188-80200	28,0	
<b>TDO8-22D/28</b>					
49174-00565	MITSUBISHI	49174-09200	49188-80200	28,0	
49174-00566	MITSUBISHI	49174-09200	49188-80200	28,0	
<b>TDO8</b>					
49174-00570		49174-09200	49188-80200		
49174-00571		49174-09200	49188-80200		
49174-00572		49174-09200	49188-80200		

49174-00580		49174-09200	49188-80200		
49174-00590		49174-09100	49188-80200		
49174-00591		49174-09100	49188-80200		
49174-00592		49174-09100	49188-80200		
49174-00593		49174-09100	49188-80200		
<b>TDO8-20B</b>					
49174-00600			49188-80200		
<b>TDO8</b>					
49174-00608		49174-09400	49188-80200		
<b>TDO8-29B</b>					
49174-00610			49188-80200		
<b>TDO8</b>					
49174-00618		49174-08120	49188-80200		
49174-00620		49174-08100	49188-80200		
49174-00621		49174-08100	49188-80200		
49174-00628		49174-09100	49188-80200		
49174-00629		49174-09100	49188-80200		
49174-00630		49174-08120	49188-80200		
49174-00650		49174-09400	49188-80200		
49174-00651		49174-09400	49188-80200		
49174-00652		49174-09200	49188-80200		
49174-00654		49174-09400	49188-80200		
49174-00655		49174-09400	49188-80200		
49174-00660		49174-08120	49188-80200		
49174-00670		49174-08120	49188-80200		
<b>TDO8-22D/28</b>					
49174-00680		49174-09200	49188-80200	28,0	
<b>TDO8-29B</b>					
49174-00700			49188-80200		
<b>TDO8</b>					
49174-00708		49174-08120	49188-80200		
49174-00710		49174-09200	49188-80200		
<b>TDO8-29B</b>					
49174-00800			49188-80200		
<b>TDO8</b>					
49174-00808		49174-08120	49188-80200		
<b>TDO8-22B</b>					
49174-00810			49188-80200		
<b>TDO8</b>					
49174-00818		49174-09200	49188-80200		

<b>TDO8-20B</b>					
49174-00820			49188-80200		
<b>TDO8</b>					
49174-00828		49174-09400	49188-80200		
49174-00840		49174-08120	49188-80200		
<b>TDO8-29B</b>					
49174-00850			49188-80200		
<b>TDO8</b>					
49174-00860		49174-08140	49188-80200		
49174-01110		49174-09400	49188-80200		
49174-01120		49174-09400	49188-80200		
49174-01130		49174-09200	49188-80200		
<b>TDO8-22D/22</b>					
49174-01140	mitsubishi	49174-09200	49188-80200	22,0	
<b>TDO8</b>					
49174-01141		49174-09400	49188-80200		
<b>TDO8-22D/28</b>					
49174-01142	mitsubishi	49174-09200	49188-80200	28,0	
<b>TDO8</b>					
49174-01143		49174-09200	49188-80200		
<b>TDO8-22B</b>					
49174-01144			49188-80200		
<b>TDO8</b>					
49174-01145		49174-08140	49188-80200		
49174-01146		49174-09200	49188-80200		
49174-01150		49174-09200	49188-80200		
49174-01160		49174-09100	49188-80200		
49174-01161		49174-09100	49188-80200		
49174-01162		49174-09100	49188-80200		
49174-01163		49174-09100	49188-80200		
49174-01164		49174-09400	49188-80200		
49174-01165		49174-09400	49188-80200		
49174-01166		49174-09100	49188-80200		
49174-01167		49174-09100	49188-80200		
<b>TDO8-22D/28</b>					
49174-01200	HYUNDAI	49174-09200	49188-80200	28,0	
49174-05565	HYUNDAI	49174-09200	49188-80200	28,0	
49174-05566	HYUNDAI	49174-09200	49188-80200	28,0	
<b>TDO8-15B/22</b>					
49174-05592	HYUNDAI	49174-09100	49188-80200	22,0	



Catálogo 2.0 - 2006



## TDO8H

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>TDO8H</b>					
49188-01000		49188-08120	49188-80200		
49188-01100		49188-08110	49188-80200		
49188-01110		49188-08410	49188-80200		
49188-01120		49188-08410	49188-80200		
49188-01130		49188-08410	49188-80200		
49188-01140		49188-08410	49188-80200		
49188-01252		49188-08410	49188-80200		
49188-01253		49188-08410	49188-80200		
49188-01254		49188-08710	49188-80200		
49188-01255		49188-08720	49188-80200		
49188-01256	MITSUBISHI	49188-08710	49188-80200	22,0	
49188-01257		49188-08710	49188-80200		
49188-01258		49188-08720	49188-80200		
49188-01260	MITSUBISHI	49188-08110	49188-80200		
<b>TDO8H-22B/28</b>					
49188-01261	MITSUBISHI	49188-08120	49188-80200	28,0	
<b>TDO8H-21D/22</b>					
49188-01262	MITSUBISHI	49188-08020	49188-80200	22,0	
<b>TDO8H</b>					
49188-01263		49188-08020	49188-80200		
49188-01280		49188-08710	49188-80200		
<b>TDO8H-26M/25</b>					
49188-01281	MITSUBISHI	49188-08710	49188-80200	25,0	
<b>TDO8H</b>					
49188-01282		49188-08710	49188-80200		
<b>TDO8H-26M/27</b>					
49188-01285	MITSUBISHI		49188-80200	27,0	
<b>TDO8H</b>					
49188-01300		49188-08130	49188-80200		
49188-01310		49188-08110	49188-80200		

49188-01320		49188-08130	49188-80200		
49188-01330		49188-08110	49188-80200		
49188-01340		49188-08130	49188-80200		
49188-01350		49188-08130	49188-80200		
49188-01400		49188-08130	49188-80200		
49188-01401		49188-08130	49188-80200		
49188-01410		49188-08130	49188-80200		
49188-01411		49188-08130	49188-80200		
49188-01420		49188-08110	49188-80200		
49188-01421		49188-08110	49188-80200		
49188-01430		49188-08130	49188-80200		
49188-01431		49188-08130	49188-80200		
49188-01450		49188-08120	49188-80200		
49188-01460		49188-08410	49188-80200		
49188-01500		49188-08130	49188-80200		
49188-01510	MITSUBISHI	49188-09500	49188-80200		
49188-01530		49188-08130	49188-80200		
49188-01550		49188-08710	49188-80200		
49188-01560		49188-08710	49188-80200		
49188-01580		49188-08110	49188-80200		
49188-01590		49188-08130	49188-80200		
49188-01640		49188-09500	49188-80200		
<b>TDO8H-22D</b>					
49188-01651	MITSUBISHI		49188-80200		
49188-01661	MITSUBISHI		49188-80200		
<b>TDO8H</b>					
49188-02000		49188-08130	49188-80200		
49188-02700	MITSUBISHI		49188-80200		
<b>TDO8H-27M/22</b>					
49188-03000	HYUNDAI	49188-08720	49188-80200	22,0	
<b>TDO8H-28M/18</b>					
49188-03020	HYUNDAI		49188-80200	18,0	
<b>TDO8H-27M/22</b>					
49188-03030	HYUNDAI		49188-80200	22,0	
<b>TDO8H-28M/22</b>					
49188-03100	HYUNDAI		49188-80200	22,0	
49188-03110	HYUNDAI		49188-80200	22,0	



Catálogo 2.0 - 2006



## TDO9

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>TDO9-31F/41</b>					
49132-00010	CATERPILLAR	49132-09110	49132-80010	41,0	
<b>TDO9-31F</b>					
49132-00020	CATERPILLAR	49132-09110	49132-80010		
<b>TDO9-35F/34</b>					
49132-01000	HYUNDAI		49132-80010	34,0	
<b>TDO9-45M</b>					
49132-03030			49132-80010		
<b>TDO9</b>					
<u>49132-04010</u>		49132-09550	49132-80010		
<b>TDO9-QRC/25</b>					
<u>49132-04020</u>		49132-09530	49132-80010	25,0	
<b>TDO9</b>					
49132-05050		49132-09200	49132-80010		
49132-05060		49132-09200	49132-80010		
49132-05070		49132-09300	49132-80010		
49132-05080		49132-09410	49132-80010		
49132-05090		49132-09200	49132-80010		
49132-06000		49132-09410	49132-80010		
49132-06010		49132-09410	49132-80010		

Catálogo 2.0 - 2006



## TEO4H

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>TEO4H-13C</b>					
49183-01000	CHRYSLER	49183-08020	49177-80400		
<b>TEO4H-13C/11</b>					
49183-01090	CHRYSLER	49183-08020	49177-80400	11,0	
<b>TEO4H</b>					
49183-01100		49183-08020			
<b>TEO4H-13C/11</b>					
49183-01190	CHRYSLER	49183-08020	49177-80400	11,0	
<b>TEO4H-13C/8</b>					
49183-02010	CHRYSLER	49183-08020	49177-80400	8,0	
<b>TEO4H-13C/11</b>					
49183-02110	CHRYSLER	49183-08020	49177-80400	11,0	
<b>TEO4H-13C</b>					
49183-02200	CHRYSLER	49183-08020	49177-80400		
<b>TEO4H-13C/11</b>					
49183-02210	CHRYSLER	49183-08020	49177-80400	11,0	
49183-02400	CHRYSLER	49183-08020	49177-80400	11,0	

Catálogo 2.0 - 2006



## TEO5

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>TEO5-12B/6</b>					
49184-01000	SAAB	49184-09000	49178-81100	6,0	
49184-02000	SAAB	49184-09000	49178-81100	6,0	
<b>TEO5</b>					
49184-02100		49184-09000			
<b>TEO5-12B/6</b>					
49184-02200	SAAB	49184-09000	49178-81100	6,0	
<b>TEO5</b>					
49184-02300		49184-09000			
49184-03000		49184-09000			
49184-03100		49184-09000			
<b>TEO5-12B/6</b>					
49184-03200	SAAB	49184-09000	49178-81100	6,0	
49184-03300	SAAB	49184-09000	49178-81100	6,0	
49184-03400	SAAB	49184-09000	49178-81100	6,0	

Catálogo 2.0 - 2006



## TEO6H

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>TEO6H</b>					
49185-00010		49185-08100	49185-80020		
49185-00020		49185-08100	49185-80020		
<b>TEO6H-14M/12</b>					
49185-00030	CATERPILLAR	49185-08210	49185-80020	12,0	
<b>TEO6H-17C/2</b>					
49185-00040	CATERPILLAR	49185-08300	49185-80020		
<b>TEO6H</b>					
49185-00050		49185-08100	49185-80020		
49185-00060		49185-08200	49185-80020		
<b>TEO6H-10M/12</b>					
49185-00070	CATERPILLAR		49185-80020	12,0	
<b>TEO6H-12M</b>					
49185-01010	MITSUBISHI	49185-08510	49185-80020		
<b>TEO6H-16M</b>					
49185-01020	MITSUBISHI	49185-08520	49185-80020		
49185-01040	MITSUBISHI		49185-80020		
<b>TEO6H</b>					
49185-02010		49185-08610	49185-80020		
49185-02020		49185-08620	49185-80020		
49185-03000		49185-08700	49185-80020		
49185-03010		49185-08700	49185-80020		
49185-03020		49185-08700	49185-80020		
49185-03030		49185-08700	49185-80020		

Catálogo 2.0 - 2006



**TF15**

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>TF15</b>					
49129-00050		49128-08040			
49129-00055		49129-08040			
49129-00060		49129-08040			
49129-00070		49129-08020			
49129-00080		49129-08040			
49129-00110		49129-08040			
49129-00120		49129-08020			
49129-00150		49129-08050			
49129-00160		49129-08060			
49129-00170		49129-08060			

Catálogo 2.0 - 2006



## TFO35

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>TFO35HM-10T/3</b>					
49135-00101	ISUZU			3,0	
49135-00102	ISUZU	49135-08710		3,0	
<b>TFO35HM</b>					
49135-00120	ISUZU				
<b>TFO35HS-10T</b>					
49135-02000	MITSUBISHI	49135-08010			
49135-02010	MITSUBISHI	49135-08010			
<b>TFO35HM-12T/4</b>					
<u>49135-02100</u>	MITSUBISHI	49135-08020		4,0	49135-02110
<u>49135-02110</u>	MITSUBISHI	49135-08020		4,0	
<b>TFO35HM-12T</b>					
<u>49135-02200</u>	MITSUBISHI	49135-08000			
<b>TFO35H</b>					
49135-02210	MITSUBISHI	49135-08040			
<b>TFO35HM-12T/4</b>					
<u>49135-02220</u>	MITSUBISHI	49135-08000		4,0	
<b>TFO35HM-10T/4</b>					
<u>49135-02230</u>	MITSUBISHI	49135-08040		4,0	
<b>TFO35H</b>					
49135-02240	MITSUBISHI	49135-08030			
<b>TFO35HM-10T/3</b>					
49135-02300	MITSUBISHI	49135-08030			
<b>TFO35HM-12T</b>					
49135-02310	MITSUBISHI	49135-08030			
<b>TFO35HM</b>					
49135-02400	MITSUBISHI	49135-08020			
<b>TFO35HM-10T</b>					
<u>49135-02500</u>	MITSUBISHI	49135-08040			

<b>TFO35</b>					
49135-02510	mitsubishi	49135-08040			
<b>TFO35HL2-12GK</b>					
<u>49135-02652</u>	mitsubishi	49135-08800		12,0	
<b>TFO35HS-10T</b>					
49135-02700	mitsubishi	49135-08010			
49135-02710	mitsubishi	49135-08010			
49135-02730	mitsubishi	49135-08010			
49135-02800	MAZDA	49135-08010			
<b>TFO35HM-12T</b>					
49135-03100	mitsubishi	49135-08000			
49135-03101	mitsubishi	49135-08000			
49135-03110	mitsubishi	49135-08000			
49135-03111	mitsubishi	49135-08000			
49135-03112	mitsubishi	49135-08001			
49135-03120	mitsubishi	49135-08000			
<b>TFO35HM-12T/4</b>					
<u>49135-03130</u>	mitsubishi	49135-08000		4,0	
<b>TFO35HM-12T</b>					
49135-03200	mitsubishi	49135-08000			
49135-03210	mitsubishi	49135-08001			
49135-03220	mitsubishi	49135-08002			
<u>49135-03300</u>	mitsubishi	49135-08000			
49135-03301	mitsubishi	49135-08000			
49135-03310	mitsubishi	49135-08000			
<b>TFO35HL-14GK</b>					
<u>49135-03410</u>	mitsubishi	49135-08500			49135-03411
<u>49135-03411</u>	mitsubishi				
<b>TFO35HM-12T</b>					
<u>49135-03500</u>	mitsubishi	49135-08700			
<b>TFO35</b>					
<u>49135-03610</u>	mitsubishi	49135-08500			
49135-03611	mitsubishi				
<b>TFO35HM-10T/4</b>					
<u>49135-04000</u>	HYUNDAI	49135-08030		4,0	
<u>49135-04010</u>	HYUNDAI	49135-08030		4,0	
<b>TFO35HM-12T/4</b>					
49135-04020	HYUNDAI			4,0	
49135-04030	HYUNDAI			4,0	

<b>TFO35HM-10T/4</b>					
49135-04101	HYUNDAI			4,0	
49135-04111	HYUNDAI			4,0	
<b>TFO35HM-12T/4</b>					
49135-04121	HYUNDAI			4,0	
49135-04131	HYUNDAI			4,0	
<b>TFO35HM</b>					
<u>49135-04400</u>		49135-08535			
<b>TDO35HM-14T/4</b>					
<u>49135-04600</u>	SUBARU	49135-08300		4,0	
49135-04690	SUBARU	49135-08300		4,0	
<b>TDO35HM-14T</b>					
49135-04700	SUBARU	49135-08300			
<b>TFO35HM-13T/6</b>					
<u>49135-05000</u>	IVECO	49135-08100		6,0	
<u>49135-05010</u>	IVECO	49135-08100		6,0	
<u>49135-05020</u>	IVECO	49135-08100		6,0	
<u>49135-05030</u>	IVECO	49135-08100		6,0	
49135-05040	IVECO	49135-08100		6,0	
<u>49135-05050</u>	IVECO	49135-08100		6,0	
<u>49135-05060</u>	IVECO	49135-08100		6,0	
49135-05070	SANTANA	49135-08100			
49135-05080	IVECO	49135-08100		6,0	
<b>TFO35HM</b>					
49135-05090	IVECO	49135-08100			
<b>TFO35HL</b>					
<u>49135-05500</u>	VM	49135-08400			
<b>TFO35</b>					
<u>49135-06000</u>	FORD	49135-08200			
<b>TFO35HM-12T</b>					
49135-06010	FORD	49135-08200			
<b>TFO35HM-10T</b>					
49135-06020	FORD	49135-08210			
<b>TFO35HM-12T</b>					
49135-06030	FORD	49135-08200			
<b>TFO35HM-12T/6</b>					
<u>49135-06500</u>	M.W.M.	49135-08600	M.W.M.	6,0	
<b>TFO35HM</b>					
49135-07430	mitsubishi				





Catálogo 2.0 - 2006



## TFO7

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>TFO7</b>					
49186-00100		49186-08100			
<b>TFO7-17M/17</b>					
49186-00200	HERCULES	49186-08240		17,0	
<b>TFO7</b>					
49186-00300		49186-08310			
49186-00310		49186-08310			
49186-00320		49186-08310			
49186-00330		49186-08310			
49186-00340		49186-08310			
49186-00350		49186-08310			
<b>TFO7-15M/21</b>					
49186-02000	HYUNDAI			21,0	
49186-02010	HYUNDAI			21,0	

Catálogo 2.0 - 2006



## TFO8

Referencia	Aplicación	Cartucho	Juego Reparación	A/R	Sustituido por
<b>TFO8</b>					
49134-00020		49134-08210			
<b>TFO8L-26M/18</b>					
49134-00101	HYUNDAI			18,0	
<b>TFO8L-26M/15</b>					
49134-00110	HYUNDAI			15,0	
<b>TFO8L-26M/18</b>					
49134-00130	HYUNDAI			18,0	
<b>TFO8L-28M/22</b>					
49134-00220	HYUNDAI			22,0	
49134-00230	HYUNDAI			22,0	
<b>TFO8L-28M1/22</b>					
49134-00240	HYUNDAI			22,0	
<b>TFO8L-28M/22</b>					
49134-00250	HYUNDAI			22,0	
<b>TFO8L-24M/18</b>					
49134-00410	HYUNDAI			18,0	