




GASKETS




190096




190098




190099




210018




210019



210021




210023




210060




210085




210086




210121




210123




210126




210127




210140




210150




210160



210161




210162




210163




210164




210165



210167




210168



210169




210170




210172




210175




210200




210204




210208




210217







210218



210219



210220



210221




210222




210223



210224



210225




210226




210227




210228



210229




210230



210231




210232



210233



210234




210235




210236




210237




210239




210240




210241




210242




210243




210244



210245




210249




210255




210256




210257




210258




210259




210260




210261




210262




210263



210264




210265



210266




210267




210268




210269




210270




210271




210273



210274



210275





210276



210277



210278



210279




210280




210281



210282



210283




210284




210285



210286



210287



210288




210289




210292



210293



210294



210295



210296




210299



210300



210301



210302




210303



210304




210305




210306



210307



210308



210310



210311



210312



210313




210314



210315



210316



210317



210318



210319



210320



210321



210322



210323



210324



210325




210326




210327



210328



210329



210330



210331



210332



210333



210334



210335




210336




210337



210338



210339



210340




210341



210342



210343



210344



210345



210346




210347




210349



210350



210351



210352



210353



210354




210355




210357



210358




210359



210360



210361




210362



210363



210364




210365



210366




210367



210368



210369



210370




210371




210372

210368




210369




210370



210371




210372




210374




210375




210376



210377




210378




210379




210380




210381



210382




210383




210384



210385




210386




210387



210389



210390



210392



210395




210397




210398



210399




210500




210501




210502



210503



210504




210505




210506



210507




210508




210509



210510




210511




210512




210514




210515




210516




210517



210518




210519






210520




210521




210525



210526




210527




210528




210529




210530



210531




210532




210533




210534



210535




210536




210537




210538



210539



210540



210541




210542



210543




210544




210545



210546




210547




210548




210549




210550




210551



210552




210553



210554



210555




210556



210557




210558




210559







210560



210561



210562




210563



210564




210565




210566




210567




210568




210569




210570



210571




210572



210573




210574



210575




210576




210577




210578




210579




210580




210581




210582




210584




210585




210586



210587




210588



210589



210590




210591



210592




210593



210594




210595




210596



210597




210598




210599




210600




210601



210602



210603




210604

210605


210606

210608


210609




210610



210611



210612



210613




210614




210615



210616




210617



210618




210619



210620



210621



210622



210623




210624




210625



210626




210627




210628




210629




210630



210631



210632




210633




210634




210635




210636




210637




210638




210640




210641



210642




210643




210644




210645



210646



210647




210648



210649



210650




210652




211000



407294-0001




407294-0002




409038-0000




409038-0001




409039-0000



409039-0001




409049-0000



409123-0002




409196-0000



409196-0001




409196-0002




409196-0003




409196-0004



409262-0000




409262-0001



409265-0000



409377-0000



409645-0000




409805-0001



410197-0001




413667-0001




413709-0001




413805-0001



413805-0002



431343-0001



432197-0001



432557-0001




600481-0000




600482-0000




600483-0000




600764-0000



709375-0000




725249-0001



725743-0001

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


190096

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

KTR130

CUMMINS

TOYOTA

HITACHI


CZ

Copper layers

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


190098

GARRETT

HOLSET

3K

SCHWITZER

S500

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

KTR130

CUMMINS

TOYOTA

HITACHI


CZ

Copper layers

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


190099


GARRETT	
HOLSET	
3K	
SCHWITZER	S500
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	KTR130
CUMMINS	
TOYOTA	
HITACHI	
CZ	

Gasket paper

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210018

GARRETT	Varios / Various
HOLSET	Varios / Various
3K	Varios / Various
SCHWITZER	Varios / Various
MITSUBISHI	Varios / Various
I.H.I.	
RAJAY	
KOMATSU	KTR110
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210019

GARRETT	Varios / Various
HOLSET	Varios / Various
3K	Varios / Various
SCHWITZER	Varios / Various
MITSUBISHI	Varios / Various
I.H.I.	
RAJAY	
KOMATSU	KTR110, KTR130
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210021

GARRETT	Varios / Various
HOLSET	Varios / Various
3K	Varios / Various
SCHWITZER	Varios / Various
mitsubishi	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	HT15
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210023

GARRETT	Varios / Various
HOLSET	Varios / Various
3K	Varios / Various
SCHWITZER	Varios / Various
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	HT15
CZ	C14
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210060

GARRETT	Varios / Various
HOLSET	Varios / Various
3K	Varios / Various
SCHWITZER	Varios / Various
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	C14
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210085

GARRETT	
HOLSET	HT3B,HT4B,HT4C
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	T46,T46B,T50,ST50,VT50
TOYOTA	
HITACHI	
CZ	
Steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210086

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

T50

TOYOTA

HITACHI


CZ

Steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS



210121

GARRETT	
HOLSET	
3K	3HD,4LF
SCHWITZER	S3B
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	

Copper layers
replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210123

GARRETT	
HOLSET	
3K	3HD
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Copper layers	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210126

GARRETT

HOLSET

H1C

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Copper layers

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210127


GARRETT	TV61
HOLSET	
3K	4LGZ,K33
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	

Metal & paper gasket

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210140


GARRETT	GT40
HOLSET	HY40V
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210150

GARRETT	
HOLSET	
3K	
SCHWITZER	V4MD
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Copper layers	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210160

GARRETT	
HOLSET	H1A
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210161

GARRETT	TL61,77,78,81,91,92,UTL89
HOLSET	H1A,H1B
3K	K26
SCHWITZER	S4AC,S4DC
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210162

GARRETT

HOLSET

3",3A

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Gasket paper

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210163

GARRETT	
HOLSET	3",3A
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210164

GARRETT	
HOLSET	6,6D,6U,6LD
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210167

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RHB6

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Copper layers

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210168

GARRETT	
HOLSET	H1B,H1C,H1E
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS



210169

GARRETT	
HOLSET	
3K	K26
SCHWITZER	S2BW
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	

Copper layers
replace by 210294

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210170

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RHB6

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Copper layers

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210172

GARRETT	TL61,77,78,81,91,92,UTL89
HOLSET	
3K	
SCHWITZER	4LEC,4LFC,S4AC,S4DC
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210175

GARRETT

HOLSET

3K

SCHWITZER

V4HD

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Metal & paper gasket

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210200

GARRETT

HOLSET

4HDS

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Copper layers

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210204

GARRETT	TBO2, TB25, TB28
HOLSET	
3K	K14, K16, K26
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210208

GARRETT	
HOLSET	
3K	
SCHWITZER	V4HD
MITSUBISHI	
I.H.I.	RHC6
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Copper layers	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210217

GARRETT	TBO2
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	RHB5
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210218

GARRETT	Varios / Various
HOLSET	
3K	K14,K16
SCHWITZER	S1A,S1B
MITSUBISHI	TDO4,TDO4H,TDO5H
I.H.I.	RHB5
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	HT12
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210219

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Copper layers

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210220

GARRETT	
HOLSET	H1A
3K	K24
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	C14
Copper layers	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210221

GARRETT	TA45
HOLSET	H2C,H2D,WH2D
3K	K28,K29
SCHWITZER	S2C,S3A,S300
mitsubishi	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210222

GARRETT	GT42
HOLSET	4"
3K	4B,4LG,4LGZ,K361
SCHWITZER	S3A,S3B
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210223

GARRETT	TA31
HOLSET	
3K	K14,K24,K26
SCHWITZER	S2A,S200
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	C14
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210224

GARRETT	TBO2,TD25,GT17,GT20,GT20V
HOLSET	
3K	K16
SCHWITZER	
MITSUBISHI	TDO4
I.H.I.	RHB5
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210225

GARRETT	TBO2,TAO3,TCO3,TA31
HOLSET	H1B,H1D
3K	KI14,K24,K26
SCHWITZER	S2A
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210226

GARRETT	TO4B, TO4E, TBP4, TB41, GT32
HOLSET	H2A, HX40W
3K	
SCHWITZER	S2B
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210227

GARRETT	TBO2,TD25,GT20V,GT22V
HOLSET	
3K	K14,K16
SCHWITZER	S1B
MITSUBISHI	TDO4
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210228

GARRETT	TA31
HOLSET	
3K	K26
SCHWITZER	S2A
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210229

GARRETT	GT15
HOLSET	
3K	K04,K06
SCHWITZER	
MITSUBISHI	
I.H.I.	RHB5
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210230

GARRETT	TB25
HOLSET	
3K	K14,K16
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210231

GARRETT	
HOLSET	
3K	K04
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210232

GARRETT	
HOLSET	
3K	K06
SCHWITZER	
MITSUBISHI	
I.H.I.	RHB5
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210233

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

CT12,CT20,CT26

HITACHI


CZ

Gasket paper

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS



210234

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

CT12,CT20,CT26

HITACHI


CZ

Gasket paper

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210235

GARRETT	TA31
HOLSET	
3K	K27
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210236

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210237

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210239

GARRETT	TA45,TBP48,TA51,TV61
HOLSET	4LEK,4LGK,H2C,H2D,H2E,H3B
3K	4LG,4LGZ,K28,K29,K33,K36, K361
SCHWITZER	4LGZ,S3A,S3B,S4,S4A
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210240


GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	CT26
HITACHI	
CZ	

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210241

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210242

GARRETT	TBO2,TBO3
HOLSET	
3K	K03,K24
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210243

GARRETT	Varios / Various
HOLSET	
3K	K03,K04,K06
SCHWITZER	
MITSUBISHI	TFO35,TDO4,TDO4H,TDO5H
I.H.I.	RHB4,RHF4,RHB5
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210244

GARRETT	TBO2,TAO3
HOLSET	
3K	K14,K24
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210245

GARRETT	TO4B,TO4E
HOLSET	H1E
3K	3LD,3LDZ,3LEP,3LEU,K27,K28
SCHWITZER	S2A,S2B,S200S
MITSUBISHI	3LM
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210249

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Copper layers

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210255

GARRETT	TW91,TW94
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Copper layers	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210256


GARRETT	TBO2
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210257

GARRETT	TBO2
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210258

GARRETT	K26
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210259

GARRETT	TBO2,GT22
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	210357

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210260


GARRETT	TBO2,T250
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210261

GARRETT	
HOLSET	H1E
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210262

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	CT12,GT20,CT26
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210263

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	CT20
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210264

GARRETT	
HOLSET	
3K	K26
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210265

GARRETT	TB25
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210266

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	RHB3,RHB4,RHF4
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210267

GARRETT	TB25
HOLSET	
3K	K14
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210268

GARRETT	TB25
HOLSET	
3K	K14
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210269

GARRETT	TB25,TB28
HOLSET	
3K	
SCHWITZER	
mitsubishi	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210270

GARRETT	TB25,GT22
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	HT12
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210271

GARRETT	TB22
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210614

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210273

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Copper layers

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210274

GARRETT	TB41
HOLSET	H1E
3K	K27
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210275

GARRETT	TBO3, TB25
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	TEO5
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210276

GARRETT	TD25,VNT25,GT22V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	RHB3,RHB5
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210277

GARRETT	
HOLSET	
3K	
SCHWITZER	
mitsubishi	TCO4
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210278

GARRETT	TB25,GT15,GT15V,GT17V, GT25V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	TDO25,TDO4
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210563

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210279

GARRETT	TB25
HOLSET	
3K	K14
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210280

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	RHB5
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Copper layers	
replace by	210342

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210281

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	TDO25
I.H.I.	RHB3
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210575

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210282

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	RHB3
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Copper layers	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210283

GARRETT	TA51
HOLSET	
3K	K33
SCHWITZER	
mitsubishi	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210284

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RHB3

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Gasket paper

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210285

GARRETT	GT17V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	RHB4,RHF4,RHB5
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210385

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210286

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RHB4,RHF4

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Copper layers

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210287

GARRETT	TB25
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210288

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	CT9,CT20
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210289

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	CT26
HITACHI	
CZ	
Metal & paper gasket	
replace by	210354

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210292

GARRETT	GT15
HOLSET	
3K	K03
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210293

GARRETT	GT15,GT17V
HOLSET	
3K	K03,KP39
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210294

GARRETT	
HOLSET	
3K	K26
SCHWITZER	S2BW
mitsubishi	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210295

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

CT20

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210296

GARRETT	GT15
HOLSET	
3K	K03
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210299

GARRETT	
HOLSET	
3K	
SCHWITZER	
mitsubishi	
I.H.I.	RHB5, RHF5
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Copper layers	
replace by	210582

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210300

GARRETT	GT15,GT17V
HOLSET	
3K	
SCHWITZER	
mitsubishi	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210301

GARRETT	TBO2
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210302

GARRETT	
HOLSET	3LD
3K	K27,K28
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Copper layers	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210303

GARRETT	
HOLSET	3LD
3K	K27,K28
SCHWITZER	
MITSUBISHI	
I.H.I.	RHE7
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Copper layers	
replace by	210652

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210304

GARRETT	TBO2
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210305


GARRETT	GT25
HOLSET	
3K	K03,K14
SCHWITZER	
MITSUBISHI	
I.H.I.	RHF4
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210306

GARRETT	TBO2, TB25, TB28, GT25
HOLSET	
3K	K14, K16, K26
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210307

GARRETT	GT15
----------------	------

HOLSET	
---------------	--

3K	
-----------	--

SCHWITZER	
------------------	--

MITSUBISHI	
-------------------	--

I.H.I.	
---------------	--

RAJAY	
--------------	--

KOMATSU	
----------------	--

CUMMINS	
----------------	--

TOYOTA	
---------------	--

HITACHI	
----------------	--


CZ	
-----------	--

Metal & paper gasket	
---------------------------------	--

replace by	
-------------------	--

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210308

GARRETT	GT12,GT15,GT15Z
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210310

GARRETT	
HOLSET	
3K	K03,K16
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	


TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210311

GARRETT	GT17V
HOLSET	
3K	KP39
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	


GASKETS


210312

GARRETT	
HOLSET	
3K	K14
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Stell layers	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210313

GARRETT	GT17V
HOLSET	
3K	KP39
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210314

GARRETT	GT17V
HOLSET	
3K	KP39
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210315

GARRETT	TB25,TA31
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210316

GARRETT	
HOLSET	
3K	
SCHWITZER	S1A,S1B
MITSUBISHI	TDO4
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210317

GARRETT	
HOLSET	
3K	K03,K04
SCHWITZER	
MITSUBISHI	TDO6H
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Cartón	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210318

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	KTR110G
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Cartón	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210319

GARRETT	GT17
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	TFO35,TDO4,TCO5
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210501

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210320

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	TFO35,TDO4,TCO5
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210502

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210321

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	TFO35,TDO4
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210346

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210322

GARRETT	GT20
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	TFO35,TDO4
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210323

GARRETT	GT17
HOLSET	
3K	
SCHWITZER	
mitsubishi	TFO35,TDO4
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210525

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210324

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

TDO4

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI

CZ


Metal & paper gasket

replace by

210627

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210325

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	TDO4
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210628

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210326

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	TDO4
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210627


TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210327
GARRETT
HOLSET
3K
SCHWITZER
MITSUBISHI
I.H.I.
RAJAY
KOMATSU
CUMMINS
TOYOTA
HITACHI
CZ
Copper layers
replace by


TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS



210328

GARRETT	T250
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	




Metal & paper gasket

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210329

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210330

GARRETT	GT15,GT17V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210537

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210331

GARRETT	
HOLSET	
3K	K04
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210332

GARRETT	GT20
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210333

GARRETT	GT15,GT20
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210334

GARRETT	T250
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210335

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210336

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	CT26
HITACHI	
CZ	
Metal & paper gasket	
replace by	210355

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210337

GARRETT	
HOLSET	
3K	K03
SCHWITZER	
mitsubishi	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210338

GARRETT	GT17
HOLSET	
3K	K14
SCHWITZER	
mitsubishi	TFO35
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210339

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	RHB5
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210340

GARRETT	
HOLSET	
3K	K36
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210341

GARRETT

HOLSET

3K

K36

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Metal & paper gasket

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210342

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	RHB5,RHF5
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210578

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210343

GARRETT	TB28
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210344

GARRETT	GT15
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210345

GARRETT	GT15
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210346

GARRETT	GT17
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210347

GARRETT	GT17
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210349

GARRETT	TB15
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210350

GARRETT	GT17,GT20
HOLSET	
3K	K03,K14
SCHWITZER	
MITSUBISHI	TFO35
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210351

GARRETT	GT15
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210352

GARRETT	GT15
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210353

GARRETT	GT15
HOLSET	
3K	K03
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210354


GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	CT26
HITACHI	
CZ	

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210355

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	CT26
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210357

GARRETT	TBO2,GT20,GT22
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210358

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210359

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210360

GARRETT	GT17V,GT20,GT22,GT25, GT25V
HOLSET	
3K	K03,K16
SCHWITZER	
MITSUBISHI	TDO4,TDO5H
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210361

GARRETT	GT22
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210362

GARRETT	TW41
----------------	------

HOLSET	
---------------	--

3K	
-----------	--

SCHWITZER	
------------------	--

MITSUBISHI	
-------------------	--

I.H.I.	
---------------	--

RAJAY	
--------------	--

KOMATSU	
----------------	--

CUMMINS	
----------------	--

TOYOTA	
---------------	--

HITACHI	
----------------	--

CZ	
-----------	--

Metal & paper gasket	
---------------------------------	--


replace by	
-------------------	--

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210363

GARRETT	GT15
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	



TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210364

GARRETT	GT15
HOLSET	
3K	K03
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210365

GARRETT	GT15
HOLSET	
3K	K03
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210366

GARRETT	GT15
HOLSET	
3K	K03
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210579

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210367

GARRETT	GT15
HOLSET	
3K	K03
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210580

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210368

GARRETT	GT17
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210603

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210369

GARRETT	GT17
HOLSET	
3K	
SCHWITZER	
mitsubishi	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210604

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210370

GARRETT	GT1749V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS



210371

GARRETT	GT15
HOLSET	
3K	K03
SCHWITZER	
MITSUBISHI	
I.H.I.	RHF4
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	

Inox steel
replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210372

GARRETT	GT15
HOLSET	
3K	K03
SCHWITZER	
MITSUBISHI	
I.H.I.	RHF4
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210374

GARRETT	GT15,GT17V,GT18V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	RHF4
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210375

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210376

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

CT12B

HITACHI


CZ

Metal & paper gasket
replace by

210612

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210377

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	CT12B
HITACHI	
CZ	
Metal & paper gasket	
replace by	210613

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210378

GARRETT	GT18V,GT20,GT22V,GT25V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	RHB6
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210379

GARRETT	
HOLSET	
3K	K14
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210593

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210380

GARRETT	
HOLSET	
3K	K14
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210594

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210381

GARRETT	GT15Z,GT17V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210595

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210382

GARRETT	GT15Z
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210383

GARRETT	GT15,GT17V,GT18V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	RHF4
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210384

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	RHB3
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210385

GARRETT	GT17V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	RHB4,RHF4
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210386

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	CT9,CT12
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210387

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

CT26

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210389

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RHB3

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210390

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

CT9,CT12

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210392

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	RHB5
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210395

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	CT26
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210397

GARRETT	GT15
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210398

GARRETT	
HOLSET	H1C
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210399

GARRETT	GT25BB
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210500

GARRETT	GT15,GT15P
HOLSET	
3K	K03
SCHWITZER	
MITSUBISHI	
I.H.I.	RHF4
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210501

GARRETT	GT17
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	TFO35,TDO4,TCO5
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210502

GARRETT	
HOLSET	
3K	K16
SCHWITZER	
MITSUBISHI	TFO35,TDO4,TCO5
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210503

GARRETT	TBO2
HOLSET	
3K	K14
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210504

GARRETT	TBO2
HOLSET	
3K	K14,K16
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210505


GARRETT	GT12,GT15,GT18V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210506

GARRETT	GT15,GT17V,GT18V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	RHF4
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210549

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210507

GARRETT	GT15
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	RHF4
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210550

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210508

GARRETT	GT18V,GT20V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	210642

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210509

GARRETT	GT20V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210560

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210510

GARRETT	GT20V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210561

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210511

GARRETT	GT18V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210512

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	TDO25
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210514

GARRETT	
HOLSET	
3K	K16
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210640

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210515

GARRETT	GT22
HOLSET	
3K	K16
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210541

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210516

GARRETT	
HOLSET	
3K	K27
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210517

GARRETT	
HOLSET	
3K	K03
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210518

GARRETT	
HOLSET	
3K	K03
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	


TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210519
GARRETT GT15,GT15P,GT18V

HOLSET
3K
SCHWITZER
MITSUBISHI
I.H.I.
RAJAY
KOMATSU
CUMMINS
TOYOTA
HITACHI
CZ
Metal & paper gasket
replace by
210587


GASKETS


210520

GARRETT	GT15
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210602

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210521

GARRETT

HOLSET

HX82

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210525

GARRETT	GT17
HOLSET	
3K	
SCHWITZER	
mitsubishi	TFO35,TDO4
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210526

GARRETT	GT17V,GT18V
HOLSET	
3K	
SCHWITZER	
mitsubishi	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210585

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210527

GARRETT	GT15P
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210528

GARRETT	GT17V,GT20
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210537

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210529

GARRETT	
HOLSET	
3K	K31
SCHWITZER	S400
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210648

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210530

GARRETT	
HOLSET	
3K	
SCHWITZER	
mitsubishi	TDO25
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210531

GARRETT	GT25
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210574

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210532

GARRETT	
HOLSET	HT60
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210533

GARRETT	GT20V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	TF35
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	210615

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210534

GARRETT	GT15
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210535

GARRETT	GT15,GT17V
HOLSET	
3K	K03
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	210542

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210536

GARRETT	GT17V
----------------	-------

HOLSET	
---------------	--

3K	
-----------	--

SCHWITZER	
------------------	--

MITSUBISHI	
-------------------	--

I.H.I.	
---------------	--

RAJAY	
--------------	--

KOMATSU	
----------------	--

CUMMINS	
----------------	--

TOYOTA	
---------------	--

HITACHI	
----------------	--


CZ	
-----------	--

Metal & paper gasket	
---------------------------------	--

replace by	210543
-------------------	--------

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210537

GARRETT	GT17V,GT20
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210539

GARRETT	
HOLSET	
3K	KP35
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210540

GARRETT	
HOLSET	
3K	KP35
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metal & paper gasket	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210541

GARRETT	GT22
HOLSET	
3K	K16
SCHWITZER	
mitsubishi	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210542

GARRETT	GT15,GT17V
HOLSET	
3K	K03
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210543

GARRETT	GT17V
---------	-------

HOLSET	
--------	--

3K	
----	--

SCHWITZER	
-----------	--

MITSUBISHI	
------------	--

I.H.I.	
--------	--

RAJAY	
-------	--

KOMATSU	
---------	--

CUMMINS	
---------	--

TOYOTA	
--------	--

HITACHI	
---------	--


CZ	
----	--

Inox steel	
------------	--

replace by	
------------	--

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210544

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210545

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210546

GARRETT	GT17V,GT20
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS



210547

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210548

GARRETT	GT17V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210549

GARRETT	GT15,GT17V,GT18V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	RHF4
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210550

GARRETT	GT15
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	RHF4
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210551

GARRETT	TBP4,GT32
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inoz steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210552

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210553

GARRETT	GT15,GT20
HOLSET	
3K	KP35
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210554

GARRETT	GT15
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210555

GARRETT	GT17
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210556


GARRETT	GT12
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210557

GARRETT	GT17V
HOLSET	
3K	
SCHWITZER	
mitsubishi	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inoz steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210558

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210559

GARRETT	GT15
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox Steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210560

GARRETT	GT20V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS



210561

GARRETT	GT20V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	

Inox steel
replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210562

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RHB5

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI

CZ


Metal & paper gasket

replace by

210635

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210563

GARRETT	TB25,GT15,GT15V,GT17V,GT25V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	TDO25,TDO4
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210564

GARRETT	GT17
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210565


GARRETT	GT17
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210566

GARRETT	GT30
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210567

GARRETT	
HOLSET	
3K	K03
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210568

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	TFO35
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210569

GARRETT	GT17
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210570

GARRETT	GT17
HOLSET	
3K	
SCHWITZER	
mitsubishi	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210571

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

TFO35

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210572

GARRETT	GT17V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210573

GARRETT	GT17V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210574

GARRETT	GT25
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210575

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	TDO25
I.H.I.	RHB3
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210576

GARRETT	
HOLSET	
3K	
SCHWITZER	
mitsubishi	TDO25
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210577

GARRETT	GT17V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210578

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	RHB5,RHF5
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210579

GARRETT	GT15
HOLSET	
3K	K03
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210580

GARRETT	GT14
HOLSET	
3K	K03
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210581

GARRETT	GT15V
---------	-------

HOLSET	
--------	--

3K	
----	--

SCHWITZER	
-----------	--

MITSUBISHI	
------------	--

I.H.I.	
--------	--

RAJAY	
-------	--

KOMATSU	
---------	--

CUMMINS	
---------	--

TOYOTA	
--------	--


HITACHI	
---------	--

CZ	
----	--

Inox steel	
------------	--

replace by	
------------	--


GASKETS


210582

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	RHB5, RHF5
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210584

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	CT12,CT12B
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210585

GARRETT	GT17V,GT18V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210586

GARRETT	GT20V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210587

GARRETT	GT15,GT15P,GT18V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210588

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210589

GARRETT	
HOLSET	
3K	K03
SCHWITZER	
mitsubishi	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210590

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	TFO35
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210591

GARRETT	
HOLSET	
3K	
SCHWITZER	
mitsubishi	TDO25
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210592

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

TDO25

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210593

GARRETT	
HOLSET	
3K	K14
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210594


GARRETT	
HOLSET	
3K	K14
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210595
GARRETT GT15Z,GT17V

HOLSET
3K
SCHWITZER
MITSUBISHI
I.H.I.
RAJAY
KOMATSU
CUMMINS
TOYOTA
HITACHI
CZ
Inox steel
replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210596

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	RHF5
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210597


GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	RHF5
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210598

GARRETT	
HOLSET	
3K	KP35
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210599

GARRETT	
HOLSET	
3K	KP35
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210600

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

TFO35HL

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210601

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

CT9

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210602

GARRETT	GT15
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210603

GARRETT	GT17
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210604

GARRETT	GT17
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210605

GARRETT	GT15V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210606

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	TFO35
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210608

GARRETT	GT20V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210609

GARRETT	GT20V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210610

GARRETT	GT17V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210611

GARRETT	GT17V
---------	-------

HOLSET	
--------	--

3K	
----	--

SCHWITZER	
-----------	--

MITSUBISHI	
------------	--

I.H.I.	
--------	--

RAJAY	
-------	--

KOMATSU	
---------	--

CUMMINS	
---------	--

TOYOTA	
--------	--

HITACHI	
---------	--


CZ	
----	--

Inox steel	
------------	--

replace by	
------------	--

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210612

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

CT12B

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210613

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	CT12B
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210614

GARRETT	TB22
HOLSET	
3K	
SCHWITZER	
mitsubishi	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




210615

GARRETT	GT17V,GT20V
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	TFO35
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	CT,CT12B
HITACHI	
CZ	
Graphitized steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210616

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	CT
HITACHI	
CZ	
Graphitized steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210617

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	CT
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210618

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	KT10
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210619

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	RHF4
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	KT10
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210620

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	CT26
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210621

GARRETT	TB25,GT20
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210622

GARRETT	TB25
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210623

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	CT
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210624

GARRETT	TBO2
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210625

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	CT
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210626

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RHB5,RHF5

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210627

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

TDO4

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210628

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	TDO4
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210629

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	CT
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210630

GARRETT

HOLSET

3K

KP35

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210631

GARRETT	
HOLSET	
3K	KP35
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210632

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	KHF5,RHF5
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210633

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	TDO4
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210634

GARRETT	
HOLSET	K03
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210635

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

RHB5

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210636

GARRETT	
HOLSET	
3K	
SCHWITZER	
mitsubishi	
I.H.I.	RHF4,RHB5,RHF5
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210637

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

TFO35,TDO4

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210638

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	RHF4,RHF5
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel graphitized	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210640

GARRETT

HOLSET

3K

K16

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210641

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

KOMATSU

CUMMINS

TOYOTA

CT12B

HITACHI


CZ

Graphitized steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210642
GARRETT GT18V,GT20V

HOLSET
3K
SCHWITZER
mitsubishi
I.H.I.
RAJAY
KOMATSU
CUMMINS
TOYOTA
HITACHI
CZ
Graphitized steel
replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210643


GARRETT	GT22
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210644

GARRETT	
HOLSET	
3K	KO3
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	210337

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210645

GARRETT	GT15
HOLSET	
3K	K03
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210646


GARRETT	
HOLSET	
3K	K04
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


210647

GARRETT	GT22V
----------------	-------

HOLSET	
---------------	--

3K	
-----------	--

SCHWITZER	
------------------	--

MITSUBISHI	
-------------------	--

I.H.I.	
---------------	--

RAJAY	
--------------	--

KOMATSU	
----------------	--

CUMMINS	
----------------	--

TOYOTA	
---------------	--

HITACHI	
----------------	--


CZ	
-----------	--

Inox steel

replace by	
-------------------	--

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210648

GARRETT	
HOLSET	
3K	K31
SCHWITZER	S400
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210649

GARRETT	GT25,GT28
HOLSET	
3K	
SCHWITZER	
mitsubishi	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210650

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	RHF5,KHF5
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


210652

GARRETT	
HOLSET	3LD
3K	K27,28
SCHWITZER	
mitsubishi	
I.H.I.	RHE7
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


211000

GARRETT	
HOLSET	
3K	K03
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Metaloplastic	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




407294-0001

GARRETT	Varios / Various
HOLSET	H1E,HX40W
3K	
SCHWITZER	3LK,3LM
MITSUBISHI	
I.H.I.	RHE7
RAJAY	300,370,375
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


407294-0002

GARRETT	Varios / Various
HOLSET	3LD
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




409038-0000

GARRETT	Varios / Various
HOLSET	Varios / Various
3K	Varios / Various
SCHWITZER	Varios / Various
MITSUBISHI	Varios / Various
I.H.I.	
RAJAY	
KOMATSU	KTR110
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




409038-0001

GARRETT	Varios / Various
HOLSET	Varios / Various
3K	Varios / Various
SCHWITZER	Varios / Various
MITSUBISHI	Varios / Various
I.H.I.	
RAJAY	
KOMATSU	KTR110
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




409039-0000

GARRETT	Varios / Various
HOLSET	Varios / Various
3K	Varios / Various
SCHWITZER	Varios / Various
MITSUBISHI	3LM,TDO6H
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




409039-0001

GARRETT	Varios / Various
HOLSET	3FD,3FJ,3LD
3K	3LD,3LDZ,3LEP,K24.K27,K28
SCHWITZER	S2A,S65
MITSUBISHI	TEO5,TD06H
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	HT15
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




409049-0000

GARRETT	TO4B,TO4E,TB41
HOLSET	
3K	3LKS,K27
SCHWITZER	S81
mitsubishi	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




409123-0002

GARRETT	Varios / Various
HOLSET	Varios / Various
3K	K27,K28,K29
SCHWITZER	S2C,S3A,S81,S300
mitsubishi	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


409196-0000

GARRETT	TO4B,TO4E,TBP4,TA35,TB41
HOLSET	3FD,3FJ,3LD,H1E
3K	3LM,S2B
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	409196-0001

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


409196-0001

GARRETT	TO4B,TO4E,TBP4,TA35,TB41
HOLSET	3FD,3FJ,3LD,H1E
3K	3LM,S2B
SCHWITZER	S2B
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


409196-0002

GARRETT	TO4B,TA31,TA35
HOLSET	3LD,H1C
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


409196-0003

GARRETT	TO4B,TO4E,GT37
HOLSET	H1E
3K	K27
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


409196-0004

GARRETT	TO4,TO4B,TA45
HOLSET	3LD
3K	
SCHWITZER	S3A
MITSUBISHI	
I.H.I.	
RAJAY	300,370,375
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


409262-0000

GARRETT	TAO3
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


409262-0001

GARRETT	TAO3
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


409265-0000

GARRETT	T18A,TV94
----------------	-----------

HOLSET	HC5A
---------------	------

3K	
-----------	--

SCHWITZER	
------------------	--

MITSUBISHI	
-------------------	--

I.H.I.	
---------------	--

RAJAY	
--------------	--

KOMATSU	
----------------	--

CUMMINS	
----------------	--

TOYOTA	
---------------	--

HITACHI	
----------------	--


CZ	
-----------	--

Inox steel	
-------------------	--

replace by	
-------------------	--

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


409377-0000

GARRETT	Varios / Var Varios / Various
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	409038-0001

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




409645-0000

GARRETT	TAO3.TBP4
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




409805-0001

GARRETT	TBO3
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Inox steel	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


410197-0001


GARRETT	TBO3
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	

Inox steel

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


413667-0001

GARRETT	TB25,TB28
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


413709-0001

GARRETT	TBO2, TB22, TB25, GT25, TB28
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


413805-0001

GARRETT	TBO2
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	413805-0002

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


413805-0002


GARRETT	TBO2
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	

Gasket paper

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


431343-0001

GARRETT	TBO3
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


432197-0001

GARRETT	TBO3,TO4B,TO4E
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


432557-0001

GARRETT	TBO3,GT17
HOLSET	
3K	
SCHWITZER	
mitsubishi	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	709375-0001

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


600481-0000

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

300,370,375

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Metal & paper gasket

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


600482-0000

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

300,370,375

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Metal & paper gasket

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


600483-0000

GARRETT

HOLSET

3K

SCHWITZER

MITSUBISHI

I.H.I.

RAJAY

300,370,375

KOMATSU

CUMMINS

TOYOTA

HITACHI


CZ

Metal & paper gasket

replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS




600764-0000

GARRETT	
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	300,370,375
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS



709375-0000

GARRETT	TBO3, TB28
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	

Gasket paper
replace by

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.


GASKETS


725249-0001

GARRETT	GT17
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

GASKETS


725743-0001

GARRETT	GT17
HOLSET	
3K	
SCHWITZER	
MITSUBISHI	
I.H.I.	
RAJAY	
KOMATSU	
CUMMINS	
TOYOTA	
HITACHI	
CZ	
Gasket paper	
replace by	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) España
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.