

**APPLICATIONS**

<b>Alsthom</b>	<b>Baudoin</b>	<b>Caterpillar</b>
<b>Cummins</b>	<b>Daewoo</b>	<b>DDC-MTU</b>
<b>Detroit Diesel</b>	<b>Dorman</b>	<b>John Deere</b>
<b>K.H.Deutz</b>	<b>Komatsu</b>	<b>Lister-Petter</b>
<b>Mercedes</b>	<b>Mitsubishi</b>	<b>Navistar</b>
<b>Nissan</b>	<b>Perkins</b>	<b>Rolls Royce</b>
<b>SACM</b>	<b>SSCM</b>	<b>Waukesha</b>

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: [turbomaster@turbomaster.info](mailto:turbomaster@turbomaster.info).

### APPLICATIONS

SUITABLE FOR:

**Alstom**

Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
472 AS				TA3112	<u>465896-0003</u>	140081
672 AS				TO4B47	<u>465610-0002</u>	1400666C
672 AS				TO4B47	<u>465610-0003</u>	1400661C

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

**APPLICATIONS**

SUITABLE FOR:

**Baudoin**

Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
6P15.2.SR				TV9403	<u>466986-0001</u>	15600130N

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

## APPLICATIONS

SUITABLE FOR:

## Caterpillar

Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
3116				UTW8303	<u>466745-0002</u>	113-6051
3196				GT4594	<u>701287-0001</u>	144-7282
3196		380		GT4594	<u>471174-0001</u>	135-5394
3196		500		GT4594	<u>471174-0002</u>	133-3844
3204	4L		5211	TO4B65	<u>465088-0001</u>	6N8477
3204	4L		5211	TO4B65	<u>465088-0003</u>	8N4774
3208	8V			TM5401	<u>466010-0005</u>	7W2874
3208	8V			TM5401	<u>466010-0007</u>	7W9132
3208	8V			TM5410	<u>465693-0002</u>	9Y1344
3304	4L		7000	TW6146	<u>466096-0003</u>	2W7276
3306	6L		10500	T1224	<u>407640-0009</u>	8S8039
3306	6L		10500	T1224	<u>407640-0010</u>	8S8198
3306	6L		10500	T1224	<u>407640-0011</u>	9L5345
3306	6L		10500	T1224	<u>407640-0013</u>	4N9210
3306	6L		10500	T1226	<u>408100-0002</u>	4N4746
3306	6L		10500	TV6139	<u>465474-0002</u>	8N2356
3306	6L		10500	TV6139	<u>465474-0006</u>	7W7125
3306	6L		10500	TV6142	<u>465774-0001</u>	1N3846
3306	6L		10500	TV6142	<u>465774-0002</u>	1W1606
3306	6L		10500	TV6142	<u>465774-0003</u>	1N3429
3306	6L		10500	TV6142	<u>465774-0012</u>	2W7277
3306	6L		10500	TV6306	<u>471134-0001</u>	133-5106
3306	6L		10500	TW4C01	<u>466108-0001</u>	4W2276
3306	6L		10500	TW4C01	<u>466108-0002</u>	110-3866
3306	6L		10500	TW6138	<u>465588-0001</u>	8N5500
3306	6L		10500	TW6141	<u>465586-0001</u>	8N5499
3306	6L		10500	TW6146	<u>466096-0001</u>	2W3556
3404	4L			TW4B91	<u>465592-0002</u>	2W7095
3406	6L		14600	BTV7504	<u>471107-0001</u>	131-8108
3406	6L		14600	CTV7301	<u>466161-0005</u>	108-5450
3406	6L		14600	CTV7301	<u>466161-0006</u>	108-5451

3406	6L		14600	T1232	<u>409720-0004</u>	9L6308
3406	6L		14600	TL8112	<u>465338-0008</u>	1W2583
3406	6L		14600	TV8112	<u>465332-0001</u>	9N2703
3406	6L		14600	TW4B91	<u>465592-0001</u>	8N5501
3406	6L		14600	TW4C01	<u>466108-0003</u>	7C4763
3406	6L		14600	TW4C02	<u>465617-0001</u>	7C9038
3406	6L		14600	TW6156	<u>466015-0001</u>	9Y9810
3406	6L		14600	UTV7123	<u>466909-0001</u>	7E3835
3406	6L		14600	UTV7504	<u>471071-0001</u>	128-6617
3406	6L		14600	UTV7507	<u>466869-0001</u>	119-6210
3406	6L		14600	UTV7507	<u>466869-0002</u>	124-7622
3406	6L		14600	UTV7801	<u>466901-0001</u>	7W9472
3406	6L		14600	UTV7801	<u>466901-0002</u>	7C6648
3406C	6L	425	14600	BTG7506	<u>471066-0001</u>	131-2427
3406E	6L		14600	BTV5501	<u>466423-0004</u>	124-3030
3406E	6L		14600	BTV7504	<u>471107-0002</u>	132-5301
3406E	6L		14600	GT5002	<u>701756-0005</u>	
3406E	6L		14600	UTV7506	<u>471032-0001</u>	126-5045
3406E	6L		14600	UTV7508	<u>471143-0001</u>	134-8449
3406E	6L	410	14600	BTG5501	<u>471091-0001</u>	130-6233
3406E	6L	410	14600	BTG5501	<u>471091-0002</u>	135-8139
3406E	6L	410	14600	BTG5501	<u>471119-0001</u>	132-3651
3406E	6L	425	14600	BTG7506	<u>466445-0014</u>	124-3031
3406E	6L	435	14600	BTG7506	<u>466445-0017</u>	124-3034
3406E	6L	435	14600	BTG7506	<u>466445-0018</u>	124-3035
3406E	6L	475	14600	BTG7506	<u>466445-0015</u>	124-3032
3406E	6L	500	14600	BTG7506	<u>466445-0016</u>	124-3033
3406E	6L	500	14600	BTG7506	<u>466445-0020</u>	127-4260
3406E	6L	550	14600	BTG7508	<u>471036-0001</u>	124-3759
3406E	6L	550	14600	BTG7508	<u>471120-0001</u>	132-3649
3406E	6L	550	14600	BTG7513	<u>471142-0005</u>	146-4328
3406E	6L	600	14600	BTG7513	<u>471142-0004</u>	138-3200
3406E	6L	600	14600	BTG7513	<u>471142-0008</u>	
3408	8V		18000	TV8105	<u>465694-0002</u>	1N3988
3408	8V		18000	TV8105	<u>465694-0003</u>	1N3989
3408	8V		18000	TV8113	<u>465792-0006</u>	1W5580
3408	8V		18000	TV8113	<u>465792-0007</u>	1W5579
3408	8V		18000	TW6147	<u>466378-0001</u>	4W6167
3408	8V		18000	TW6350	<u>466647-0001</u>	109-2839
3408	8V		18000	TW7202	<u>466432-0001</u>	4W7637

3408	8V		18000	TW8104	<u>465692-0002</u>	1N3987
3408	8V		18000	TW8105	<u>465696-0002</u>	1N3991
3408	8V		18000	TW8109	<u>466602-0002</u>	4W6166
3408	8V		18000	TW8113	<u>465788-0003</u>	1W1654
3412	12V		27000	TL8112	<u>465338-0012</u>	9Y0619
3412	12V		27000	TV8107	<u>465054-0001</u>	6N7968
3412	12V		27000	TV8107	<u>465054-0003</u>	7W8546
3412	12V		27000	TV8112	<u>465332-0006</u>	1W6931
3412	12V		27000	TV8112	<u>465332-0007</u>	1W6932
3412	12V		27000	TV8112	<u>465332-0011</u>	134-3592
3412	12V		27000	TV8112	<u>465332-0012</u>	144-4568
3412	12V		27000	TV8116	<u>465969-0004</u>	4P2782
3412	12V		27000	TV8116	<u>465969-0005</u>	4P2783
3412	12V		27000	TV8116	<u>465969-0006</u>	4P2784
3412	12V		27000	TV8122	<u>466428-0001</u>	4W7500
3412	12V		27000	TV8122	<u>466428-0002</u>	7W7348
3412	12V		27000	TV9102	<u>466056-0002</u>	4W1237
3412	12V		27000	TV9215	<u>465965-0001</u>	9Y9617
3412	12V		27000	TW8107	<u>465052-0002</u>	4W9061
3412	12V		27000	TW8107	<u>465052-0003</u>	7W4866
3412	12V		27000	TW8117	<u>465095-0002</u>	114-6360
3412	12V		27000	TW8127	<u>466668-0003</u>	7C4017
3412	12V		27000	TW9101	<u>466050-0005</u>	4W1148
3412	12V		27000	TW9101	<u>466050-0006</u>	7C2731
3412	12V		27000	TW9102	<u>465456-0007</u>	4W1226
3412	12V		27000	TW9102	<u>465456-0010</u>	4W1236
3412	12V		27000	TW9211	<u>466612-0007</u>	122-8043
3412	12V		27000	UTW8303	<u>466745-0001</u>	106-3561
3456	6L		15800	UTG7508	<u>471146-0003</u>	137-4529
3508	8V		34500	BTL7509	<u>466759-0001</u>	114-2656
3508	8V		34500	BTL7510	<u>700144-0001</u>	119-5999
3508	8V		34500	BTL7510	<u>700144-0002</u>	136-6301
3508	8V		34500	BTL8501	<u>466725-0001</u>	113-5180
3508	8V		34500	BTL8503	<u>466857-0002</u>	119-5998
3508	8V		34500	BTW8501	<u>466807-0001</u>	118-0398
3508	8V		34500	BTW8501	<u>466807-0002</u>	112-7489
3508	8V		34500	BTW8503	<u>466705-0002</u>	115-2256
3508	8V		34500	TV7204	<u>466662-0001</u>	7C3820

3508	8V		34500	TV7204	<u>466662-0002</u>	7C3822
3508	8V		34500	TV7204	<u>466662-0005</u>	107-7305
3508	8V		34500	TV8106	<u>465048-0005</u>	7N6377
3508	8V		34500	TV8106	<u>465048-0008</u>	1W6551
3508	8V		34500	TV8106	<u>465048-0012</u>	7W8008
3508	8V		34500	TV8118	<u>466357-0001</u>	4Q5959
3508	8V		34500	TV8302	<u>466353-0001</u>	6I0852
3508	8V		34500	TV9214	<u>466922-0002</u>	102-0280
3508	8V		34500	TW4B92	<u>466897-0001</u>	121-6630
3508	8V		34500	TW4C03	<u>466149-0001</u>	7E8465
3508	8V		34500	TW6141	<u>465586-0002</u>	6I2084
3508	8V		34500	TW6145	<u>466048-0001</u>	1W8429
3508	8V		34500	TW6145	<u>466048-0002</u>	1W8430
3508	8V		34500	TW6146	<u>466096-0005</u>	7C4470
3508	8V		34500	TW6146	<u>466096-0006</u>	107-3127
3508	8V		34500	TW7204	<u>466664-0001</u>	7C3821
3508	8V		34500	TW8106	<u>465988-0003</u>	7W8010
3508	8V		34500	TW8106	<u>465988-0005</u>	7W8011
3508	8V		34500	TW8113	<u>465788-0004</u>	1N4450
3508B	8V		34500	BTL8501	<u>466725-0004</u>	113-5180
3508B	8V		34500	BTL8503	<u>471028-0001</u>	126-1085
3508B	8V	637	34500	BTL7510	<u>700144-0003</u>	
3512	12V		51800	BTV7510	<u>466809-0001</u>	118-0402
3512	12V		51800	BTV7510	<u>466809-0002</u>	113-5181
3512	12V		51800	BTV7511	<u>466739-0001</u>	115-2257
3512	12V		51800	TL9214	<u>471167-0001</u>	134-6704
3512	12V		51800	TV8106	<u>465048-0009</u>	1W6552
3512	12V		51800	TV9101	<u>465330-0015</u>	7W1393
3512	12V		51800	TV9211	<u>466610-0004</u>	102-0297
3512	12V		51800	TV9211	<u>466610-0005</u>	102-0300
3512	12V		51800	TV9215	<u>465965-0001</u>	9Y9617
3512	12V		51800	TV9215	<u>465965-0003</u>	131-5366
3512	12V		51800	TW6144	<u>466020-0001</u>	1W8418
3512	12V		51800	TW8112	<u>466638-0002</u>	7W5969
3512	12V		51800	TW8112	<u>466638-0003</u>	7W4382
3512	12V		51800	TW8129	<u>465293-0002</u>	100-3765
3512	12V		51800	TW9101	<u>466050-0003</u>	4W1232
3512	12V		51800	TW9101	<u>466050-0004</u>	4W1233

<b>3512</b>	12V		51800	TW9206	<u><b>466375-0002</b></u>	102-0301
<b>3512</b>	12V		51800	TW9211	<u><b>466612-0004</b></u>	102-0294
<b>3512</b>	12V		51800	TW9211	<u><b>466612-0005</b></u>	102-0296
<b>3512</b>	12V		51800	TW9211	<u><b>466612-0006</b></u>	102-0291
<b>3512B</b>	12V		51800	GT6041	<b>702228-0014</b>	
<b>3512B</b>	12V		51800	GT6041	<b>703224-0004</b>	
<b>3516</b>	16V		69000	BTL7511	<u><b>700142-0001</b></u>	133-9524
<b>3516</b>	16V		69000	BTL8505	<u><b>471168-0001</b></u>	132-3647
<b>3516</b>	16V		69000	BTV8503	<u><b>466705-0001</b></u>	118-0400
<b>3516</b>	16V		69000	TL9211	<u><b>466582-0008</b></u>	123-6476
<b>3516</b>	16V		69000	TV8302	<b>466353-0002</b>	108-9341
<b>3516</b>	16V		69000	TV9215	<b>465965-0002</b>	102-0296
<b>3516</b>	16V		69000	TW8108	<b>466376-0002</b>	4P3571
<b>3516</b>	16V		69000	TW8129	<b>465293-0001</b>	9Y1037
<b>3516</b>	16V		69000	TW9102	<u><b>465456-0006</b></u>	4W1227
<b>3516</b>	16V		69000	TW9214	<u><b>466249-0003</b></u>	102-0279
<b>3516</b>	16V		69000	TW9214	<u><b>466249-0004</b></u>	102-0278
<b>3516</b>	16V		69000	TW9216	<u><b>466651-0001</b></u>	107-5660
<b>3516</b>	16V		69000	TW9217	<u><b>466981-0001</b></u>	123-6478
<b>3516</b>	16V		69000	UTL8330	<u><b>466817-0001</b></u>	118-3597
<b>3516</b>	16V		69000	UTV8302	<u><b>466837-0005</b></u>	
<b>3516B</b>	16V		69000	BTL7511	<u><b>700142-0001</b></u>	133-9524
<b>3516B</b>	16V	1475	69000	GT6041	<b>701144-0001</b>	119-5999
<b>3516B</b>	16V	1970	69000	GT6041	<b>701145-0001</b>	
<b>3524B</b>	24V		117120	GT65	<b>704871-0204</b>	
<b>3524B</b>	24V	2965	117120	GT65	<b>704871-0205</b>	
<b>C-12</b>	6L		12000	GT4294	<b>471172-0001</b>	
<b>C-12</b>	6L		12000	GT4294	<b>471172-0002</b>	
<b>C-12</b>	6L		12000	GT4294	<u><b>471172-0003</b></u>	
<b>C-12</b>	6L		12000	GT4294	<u><b>471172-0004</b></u>	
<b>C-12</b>	6L		12000	GT4594	<u><b>702335-0001</b></u>	150-7201
<b>C-12</b>	6L		12000	GTA4294	<u><b>716023-0002</b></u>	
<b>C-12</b>	6L	410	12000	GT4294	<u><b>471065-0002</b></u>	130-9201
<b>C-12</b>	6L	430	12000	GT4294	<b>471112-0003</b>	151-3082
<b>C-12</b>	6L	430	12000	GT4294	<b>471112-0004</b>	151-5937
<b>C-15</b>				GT4702	<u><b>704604-0007</b></u>	167-9271
<b>C-15</b>				S410G	<b>174260</b>	
<b>G3412</b>	12V		27000		<b>716480-0001</b>	



TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

## APPLICATIONS

SUITABLE FOR:

**Cummins**

Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
6BT5.9	6L		5900	TA3406	<u>466563-0003</u>	
6BT5.9	6L		5900	TB3404	471182-0001	3960404
6BT5.9	6L		5900	TB3405	700793-0001	3960407
6BTA5.9	6L		5900	TA3406	<u>466563-0003</u>	
6BTA5.9	6L		5900	TA3408	<u>466575-0002</u>	
6BTAA	6L		5900	TBP444	702646-0004	3802348
6CT	6L		8300	TO4E	466589-0001	
6CTA	6L		8300	TO4E	466589-0001	
KT-1150	6L		18846	T18A55	<u>465038-0004</u>	3008660
KT-1150	6L		18846	T18A73	<u>408820-0003</u>	206275
KT-1150	6L		18846	T18A73	408820-0005	207132
KT-1150-C	6L		18846	T18A73	<u>408820-0003</u>	206275
KT-1150-C	6L		18846	T18A73	408820-0009	3004586
KT-1150-C	6L		18846	T18A73	408820-0017	3033557
KT-1150-C	6L		18846	T18A77	409810-0004	3004588
KT-1150-C	6L		18846	T18A95	465126-0004	3022510
KT-1150-C	6L		18846	T18A95	465126-0012	3033549
KT-1150-G	6L		18846	T18A73	<u>408820-0013</u>	
KT-1150-GC	6L		18846	T18A73	<u>408820-0013</u>	
KT-1150-GS	6L		18846	T18A73	<u>408820-0013</u>	
KT-1150-P	6L		18846	T18A95	465126-0004	3022510
KTA-3067-P	16V		50262	T18A98	465436-0002	3016310
KTA-3067-P	16V		50262	T18A98	465436-0004	3017218
KTA-3067-P	16V		50262	T18A98	465436-0006	3026227
KTA-3067-P	16V		50262	T18A98	465436-0008	
KTA-3067-P	16V		50262	T18A98	<u>465436-0011</u>	3045459
KTA-3067-P	16V		50262	T18A98	<u>465436-0013</u>	3045461
KTTA-2300-C	12V		37690	T18A88	<u>466000-0001</u>	3029080
KTTA-2300-C	12V		37690	T18A95	465126-0010	3029079
KTTA-2300-C	12V		37690	T18A95	<u>465126-0024</u>	3044473
KTTA-38-G	12V		37690	T18A95	<u>465126-0023</u>	3042785
KTTA-38-GC	12V		37690	T18A88	<u>466000-0001</u>	3029080

<b>KTTA-38-GC</b>	12V		37690	T18A95	<b><u>465126-0023</u></b>	3042785
<b>KTTA-38-GS</b>	12V		37690	T18A88	<b><u>466000-0001</u></b>	3029080
<b>KTTA-38-GS</b>	12V		37690	T18A95	<b><u>465126-0023</u></b>	3042785
<b>KTTA-50-G</b>	16V		50259	T18A83	<b><u>465364-0003</u></b>	3029081
<b>KTTA-50-GC</b>	16V		50259	T18A83	<b><u>465364-0003</u></b>	3029081
<b>KTTA-50-GS</b>	16V		50259	T18A83	<b><u>465364-0003</u></b>	3029081
<b>KTTAC-1500-E</b>				HC5A	<b><u>3529718</u></b>	3538268
<b>KV-16</b>				TW1802	<b><u>466682-0001</u></b>	
<b>QSK60</b>				HX83	<b><u>3595429</u></b>	4025351
<b>VTA-1710</b>		730	28022	T18A15	<b><u>408060-0001</u></b>	210833
<b>VTA-1710</b>		730	28022	T18A15	<b><u>408060-0002</u></b>	210834
<b>VTA-1710</b>		730	28022	T18A15	<b><u>408060-0003</u></b>	207420
<b>VTA-1710</b>		730	28022	T18A15	<b><u>408060-0004</u></b>	207421

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: [turbomaster@turbomaster.info](mailto:turbomaster@turbomaster.info).

## APPLICATIONS

SUITABLE FOR:

**Daewoo**

Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
D1146T	6L	200	8000	TO4E55	<u>466721-0005</u>	
D2842L	12V	677	21600	TA4538	<u>466617-0009</u>	
DS2840LE	10V	700	18600	TA45	<u>710223-0001</u>	
DS2840LE	10V	700	18600	TA45	<u>710223-0002</u>	
DS2842LB	12V	716	21900	GT4594	<u>713119-0001</u>	
DS2842LB	12V	716	21900	GT4594	<u>713119-0002</u>	
DS2842LE	12V		21900	TV48	<u>710224-0001</u>	
DV15T	8V		14600	TO4E55	<u>466721-0001</u>	
DV15T	8V		14600	TO4E55	<u>466721-0002</u>	
MK3TI	6L	308	11000	TA4538	<u>466617-0003</u>	
V2-8TC	8V		14600	TO4E55	<u>466721-0001</u>	
V2-8TC	8V		14600	TO4E55	<u>466721-0002</u>	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: [turbomaster@turbomaster.info](mailto:turbomaster@turbomaster.info).

## APPLICATIONS

SUITABLE FOR:

**DDC-MTU**

Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
12V-2000	12V	725	24000	TMF5505	471187-0002	
12V-2000	12V	807	24000	TMF5505	471187-0003	
12V-2000	12V	807	24000	UTW75	<u>704330-0003</u>	
12V-2000	12V	1100	24000	GT5002	704322-0003	
12V-2000	12V		32000	GT5002	704322-0001	
12V-2000	12V		32000	GT5002	704322-0002	
12V-2000	12V		32000	UTW75	<u>704330-0002</u>	
8V-2000	8V	775	15930	K31	5331-988-7103	5310 096 0499

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

## APPLICATIONS

SUITABLE FOR:

## Detroit Diesel

Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
12V149T	12V		29302	T18A40	<u>407370-0005</u>	5144566
12V149T	12V		29302	T18A40	<u>407370-0006</u>	5103875
12V149T	12V		29302	TV7310	<u>466655-0001</u>	23514798
12V149T	12V	272	29302	TV7101	<u>465030-0004</u>	5103760
12V149TI	12V		29302	T18A40	<u>407370-0010</u>	5103837
12V149TIB	12V		29302	BTW7504	<u>466707-0002</u>	23515505
12V149TIB	12V	1350	29302	TV7111	<u>465438-0005</u>	8924861
12V149TIB	12V	1500	29302	TV7302	<u>466360-0001</u>	23502335
12V149TIB	12V	1500	29302	TV7302	<u>466360-0002</u>	23503073
12V149TIB	12V	1750	29302	TV7303	<u>466039-0001</u>	23504622
12V149TIB	12V	1750	29302	TV7303	<u>466039-0002</u>	23508809
12V149TIB	12V	1800	29302	UTW7501	<u>471193-0001</u>	
12V150T	12V			T18A40	<u>407370-0009</u>	5103838
12V71T	12V		13963	T1805	<u>404480-0007</u>	5137379
12V71T	12V		13963	T1805	<u>404480-0008</u>	5137380
12V71T	12V		13963	T1805	<u>404480-0021</u>	
12V71T	12V		13963	T18A40	<u>407370-0005</u>	5144566
12V71T	12V		13963	TV7111	<u>465438-0001</u>	DX100867
12V71TA	12V		13963	TV7309	<u>466625-0001</u>	
12V71TA	12V	560	13963	TV7304	<u>466087-0001</u>	23504998
12V71TA	12V	740	13963	TV7302	<u>466360-0002</u>	23503073
12V71TAB	12V	600	13963	TV7502	<u>466498-0003</u>	8927200
12V71TAB	12V	600	13963	TV7503	<u>466566-0001</u>	8927162
12V71TAB	12V	670	13963	TV7301	<u>466176-0005</u>	23502240
12V92TA	12V	625	18092	TV7302	<u>466360-0001</u>	23502335
12V92TA	12V	720	18092	TV7302	<u>466360-0002</u>	23503073
12V92TA	12V	880	18092	TV7302	<u>466360-0003</u>	23503647
16V149T	16V	1800	39069	TV8115	<u>465516-0001</u>	5108082
16V149TI	16V		39069	T18A90	<u>409750-0004</u>	5108083
16V71T	16V		18600	T1865	<u>405670-0005</u>	5138883
16V71T	16V		18600	T1865	<u>405670-0006</u>	5138884

16V71T	16V		18600	T1865	<b>405670-0012</b>	8925850
16V71T	16V		18600	TV8101	<b>465010-0001</b>	5101508
16V71TA	16V		18600	TV8503	<b>466584-0003</b>	8927199
16V92TA	16V		18092	TV8403	<b>465945-0002</b>	
16V92TA	16V		18092	TV9406	<b>465329-0004</b>	23504652
16V92TA	16V	880	18092	T18A90	<b>409750-0003</b>	5104478
3L53T	3L	125	2600	TO4B08	<b>465424-0001</b>	5107067
4L53T	4L			TO4B98	<b>465242-0001</b>	5103905
4L71T	4L		4650	TV7502	<b>466498-0004</b>	8927413
4L71T	4L	208	4650	TO4B98	<b>465242-0003</b>	5106335
4L71TI	4L	210	4650	TV6502	<b>710252-0001</b>	
6L71T	6L	246	6980	TV7308	<b>466623-0003</b>	23517917
6L71T	6L	330	6980	TV7302	<b>466360-0002</b>	23503073
6L71TE	6L		6980	TV7101	<b>465030-0004</b>	5103760
6V53TA	6V	385	5200	TV7312	<b>700892-0001</b>	
6V71TAB				TV7503	<b>466566-0001</b>	8927162
6V92T	6V		9050	TV7506	<b>471186-0001</b>	
6V92TA	6V		9050	TV7502	<b>466498-0004</b>	8927413
6V92TA	6V	422	9050	TV7506	<b>471186-0001</b>	
6V92TA	6V	475	9050	TV8403	<b>465945-0002</b>	23504447
6V92TAB	6V		9050	TV7512	<b>465369-0002</b>	23501979
6V92TAB	6V		9050	TV7512	<b>465369-0005</b>	8927413
8V30G	8V	210	7300	GT3776	<b>466871-0003</b>	
8V71T	8V		9300	T18A40	<b>407370-0004</b>	5141854
8V71T	8V		9300	T18A40	<b>407370-0009</b>	5141854
8V71TAB	8V		9300	TV8503	<b>466584-0003</b>	8927199
8V92TA	8V	525	12060	TV7502	<b>466498-0006</b>	23516675
8V92TA	8V	550	12060	TV8406	<b>702377-0001</b>	
8V92TA	8V	568	12060	TV8403	<b>465945-0002</b>	23504447
8V92TA	8V		12600	TV8513	<b>465745-0001</b>	23503264
8V92TAB	8V		12060	TV8301	<b>466178-0001</b>	
S30G			7300	GT3776	<b>466787-0002</b>	23516207
S30G			7300	GT3776	<b>466871-0002</b>	23516207
S30G			7300	GT3776	<b>466871-0003</b>	
S50	4L		8500	GT4294	<b>471087-0005</b>	
S50	4L	275	8500	GT4288	<b>702690-0001</b>	
S50	4L	275	8500	GT4288	<b>702690-0005</b>	
S50	4L	320	8500	GT4088DEJN	<b>706156-0001</b>	23524013
S50	4L	320	8500	GT4088DEJN	<b>706156-0002</b>	23524014

<b>S50</b>	4L	320	8500	GT4088DEJN	<b>706156-0003</b>	23524015
<b>S50</b>	4L	320	8500	GT4088DEJN	<b>706156-0004</b>	23524016
<b>S50</b>	4L	320	8500	GT4088DEJN	<b>706156-0005</b>	23524017
<b>S50</b>	4L	320	8500	GT4088DEJN	<b>706156-0006</b>	23524809
<b>S50</b>	4L	350	8500	GT4294DEJN	<b>700228-0005</b>	23520922
<b>S50</b>	4L	350	8500	GT4294DEJN	<b>700228-0009</b>	23521368
<b>S50</b>	4L	350	8500	GT4294DEJN	<b>700228-0011</b>	23521670
<b>S50G</b>	4L		8500	GT3571	<b>702686-0003</b>	
<b>S50G</b>	4L		8500	GT3571	<b>702686-0004</b>	
<b>S50G</b>	4L		8500	GT3576	<b>466859-0003</b>	
<b>S50G</b>	4L		8500	GT3576	<b>466859-0005</b>	
<b>S50G</b>	4L	275	8500	GT3571	<b>466767-0001</b>	
<b>S50G</b>	4L	275	8500	GT3571	<b>466767-0002</b>	
<b>S50G</b>	4L	275	8500	GT3571	<b>466767-0003</b>	23516430
<b>S50G</b>	4L	275	8500	GT3571	<b>466767-0005</b>	23517008
<b>S50G</b>	4L	275	8500	GT3571	<b>466767-0006</b>	23517882
<b>S50G</b>	4L	275	8500	GT3571	<b>466859-0001</b>	
<b>S60</b>	6L			GT4202DJNU	<b>702303-0002</b>	23522191
<b>S60</b>	6L			GT4202DJNU	<b>703768-0002</b>	23523478
<b>S60</b>	6L			GT4202JNS	<b>702885-0001</b>	23522312
<b>S60</b>	6L			GT4294JNS	<b>702468-0002</b>	23522190
<b>S60</b>	6L		11100	GT4294DEJN	<b>700228-0013</b>	23522195
<b>S60</b>	6L		11100	GT4294DEJN	<b>703767-0001</b>	23523038
<b>S60</b>	6L		11100	GT4294DEJN	<b>703767-0003</b>	23523476
<b>S60</b>	6L		11100	GT4294JNS	<b>702015-0002</b>	23522194
<b>S60</b>	6L		11100	GT4294JNS	<b>702284-0002</b>	23522300
<b>S60</b>	6L		11100	GT4294JNS	<b>702284-0004</b>	23522780
<b>S60</b>	6L		11100	TV4502	<b>466998-0009</b>	23515894
<b>S60</b>	6L	350	11100	TV4502	<b>466998-0001</b>	
<b>S60</b>	6L	370	11100	K31	<b>5331-988-7113</b>	23521168
<b>S60</b>	6L		12700	GT4294DEJN	<b>700228-0003</b>	23522189
<b>S60</b>	6L		12700	GT4294DEJN	<b>703767-0002</b>	23523039
<b>S60</b>	6L		12700	GT4294DEJN	<b>703767-0004</b>	23523477
<b>S60</b>	6L		12700	GT4294JNS	<b>702015-0001</b>	23522188
<b>S60</b>	6L		12700	GT4294JNS	<b>702284-0001</b>	23522306
<b>S60</b>	6L		12700	GT4294JNS	<b>702284-0003</b>	23522781
<b>S60</b>	6L		12700	TMF5502	<b>466713-0003</b>	23516431
<b>S60</b>	6L	370	12700	K31	<b>5331-988-7101</b>	23522188
<b>S60</b>	6L	382	12700	TMF5504	<b>701272-0001</b>	
<b>S60</b>	6L	385	12700	GT4202DJNU	<b>703768-0001</b>	23523040
<b>S60</b>	6L	425	12700	TV5101	<b>466838-0004</b>	



<b>S60</b>	6L	466	12700	K31	<b>5331-988-</b>	
<b>S60</b>	6L	470	12700	TMF5502	<b>466713-0001</b>	23515635
<b>S60</b>	6L	500	12700	GT4202JNS	<b>702885-0002</b>	
<b>S60</b>	6L	550	14000	GT4702	<b><u>706224-0001</u></b>	
<b>S60</b>	6L	550	14000	GT4702	<b>706224-0003</b>	
<b>S60</b>	6L	550	14000	GT4702	<b>706224-0005</b>	
<b>S60</b>	6L	550	14000	GT4702	<b>706224-0006</b>	
<b>S60</b>	6L	600	14000	GT4702	<b><u>707866-0001</u></b>	23524100
<b>S60</b>	6L	600	14000	GT4702	<b>707866-0002</b>	
<b>S60G</b>				GT4088	<b>466840-0010</b>	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

## APPLICATIONS

SUITABLE FOR:

**Dorman**

Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
12SE				TV9405	<u>465193-0001</u>	
12SE				TV9405	<u>465193-0002</u>	
12SE				TV9405	<u>465193-0003</u>	
12SETCA				TV8118	<u>466070-0020</u>	
12SETCA				TV8118	<u>466070-0021</u>	
12SETCA				TV9405	<u>465193-0004</u>	
12SETCA2				TV9405	<u>465193-0007</u>	
12SETCA2				TV9405	<u>465193-0009</u>	
12SETCR				TV9405	<u>465193-0010</u>	
12SETCR2				TV9405	<u>465193-0006</u>	
12STCA				TV8118	<u>466070-0001</u>	SV652E
12STCA				TV8118	<u>466070-0009</u>	SV652H
12STCA				TV8118	<u>466070-0010</u>	SV652N
12STCA		900		TV8118	<u>466070-0002</u>	SV652G
12STCA		1083		TV8118	<u>466070-0003</u>	
12STCAG				TV8118	<u>466070-0011</u>	SV652Q
12STCAR2				TV8118	<u>466070-0008</u>	SV652F
12STCAR3				TV8118	<u>466070-0001</u>	SV652E
12STCAWR2				TV8118	<u>466070-0003</u>	
12STCWR2				TV8118	<u>466070-0002</u>	SV652G
12STCWR3				TV8118	<u>466070-0009</u>	SV652H
12STCWR3				TV8118	<u>466070-0010</u>	SV652N
16SETCA				TV8118	<u>466070-0020</u>	
16SETCA				TV8118	<u>466070-0021</u>	
16SETCWG				TV9405	<u>465193-0114</u>	SE652BD

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: [turbomaster@turbomaster.info](mailto:turbomaster@turbomaster.info).

## APPLICATIONS

SUITABLE FOR:

## John Deere

Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
<b>300 SERIES</b>				TA3404	<u><b>465593-0005</b></u>	RE40415
<b>3179T</b>	3L		2930	TA2501	<u><b>466874-0001</b></u>	RE30239
<b>3179T</b>	3L	62	2930	TA2501	<u><b>466874-0003</b></u>	RE52019
<b>3179T</b>	3L	62	2930	TA2501	<u><b>466874-0004</b></u>	RE53173
<b>3179T</b>	3L	62	2930	TA2501	<u><b>466874-0005</b></u>	RE53845
<b>4039T</b>	4L		3900	TA3404	<u><b>465593-0004</b></u>	RE40414
<b>6059T</b>	6L		5900	TA3401	<u><b>466334-0015</b></u>	RE39100
<b>6059TF</b>	6L		5900	TA3404	<u><b>465593-0008</b></u>	RE49313
<b>6068T</b>	6L		6800	GT3271	<u><b>700437-0001</b></u>	RE71430
<b>6068T</b>	6L		6800	T350-04	<u><b>471050-0024</b></u>	
<b>6068T</b>	6L		6800	T350-04	<u><b>471050-0030</b></u>	
<b>6068T</b>	6L		6800	TA3801	<u><b>466201-0001</b></u>	RE44801
<b>6068T</b>	6L		6800	TA3803	<u><b>466689-0001</b></u>	RE57437
<b>6076T</b>	6L		7600	TO4E54	<u><b>466567-0003</b></u>	RE55679
<b>6105T</b>	6L		10500	TV4504	<u><b>466973-0004</b></u>	
<b>6466T</b>	6L		7640	TB4116	<u><b>466122-0003</b></u>	RE19776
<b>6466T</b>	6L		7640	TB4129	<u><b>466608-0004</b></u>	
<b>8955A</b>	8V	456	15650	TV7112	<u><b>465972-0001</b></u>	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: [turbomaster@turbomaster.info](mailto:turbomaster@turbomaster.info).

## APPLICATIONS

SUITABLE FOR:

**K.H. Deutz**

Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
BF4L1011/T		72	2730	S1A	313834	04176561KZ
BF4M1013EC		143	4760	S2AW	318039	04229806KZ
BF4M1013EW		110	4760	S2AW	317630	04229538KZ
BF4M1013EW		110	4760	S2AW	318040	04229811KZ
BF4M1013EW		143	4760	S2AW	317627	04229536KZ
BF4M1013EW		177	4760	S2AW	317631	04229537KZ
BF4M1013EW		177	4760	S2AW	318041	04229807KZ
BF6G1015C		261	11910	S300W	317963	04229081KZ
BF6M1013EW		208	7150	S2BW	317635	04229604KZ
BF8G1015C		348	15870	S300W	318292	04229083KZ

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

## APPLICATIONS

SUITABLE FOR:

**Komatsu**

Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
EG275				TA4532	<u>465105-0009</u>	6152-81-8610
S6D105	6L		6490	TO4B59	<u>465044-0018</u>	6137-81-8300
S6D105	6L		6490	TO4B59	<u>465044-0019</u>	6137-81-8400
S6D105	6L		6490	TO4B59	<u>465044-0033</u>	
S6D105	6L		6490	TO4B59	<u>465044-0037</u>	
S6D105	6L		6490	TO4B59	<u>465044-0133</u>	
S6D110	6L	190	7128	TO4B59	<u>465044-0040</u>	6138-82-8300
S6D125	6L		11040	TA4532	<u>465105-0011</u>	6152-81-8320
S6D125	6L		11040	TA4532	<u>465105-0012</u>	6152-81-8340
S6D95	6L		6522	TA3103	<u>465636-0004</u>	
S6D95	6L		6522	TA3103	<u>465636-0104</u>	6207-81-8120
S6D95	6L		6522	TA3103	<u>465636-0204</u>	
SA4D95L	4L		2933	TA3103	<u>465636-0015</u>	
SA4D95L	4L		2933	TA3103	<u>465636-0115</u>	6205-81-8140
SA4D95L	4L		2933	TA3103	<u>465636-0215</u>	
SA6D110	6L	190	7128	TO4B59	<u>465044-0040</u>	6138-82-8300
SAA6D170	6L	805	23150	TL7701	<u>466293-0013</u>	
SAA6D170	6L	805	23150	TL7701	<u>466293-0014</u>	
SAA6D170	6L	805	23150	TL7701	<u>466293-0015</u>	
SAA6D170	6L	805	23150	TL7701	<u>466293-0018</u>	
SSA6D140	6L		15230	TV7831	<u>466894-0001</u>	6213-81-1400

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

### APPLICATIONS

SUITABLE FOR:

## Lister Petter

Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
ALPHA-LPWT4	4L	50	1800	GT1544	<u>452195-0001</u>	
ALPHA-LPWT4	4L	50	1800	GT1544	452195-0003	
ALPHA-LPWT4	4L	50	1800	GT1544	452195-0004	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

**APPLICATIONS**

SUITABLE FOR:

**Mercedes Benz**

Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
OM352A	6L		5700	TO4B27	<u>409300-0019</u>	352 096 4799
OM364A	4L		4000	TA3164	<u>466192-0006</u>	364 096 1399
OM364LA	4L		4000	TA3164	<u>466192-0007</u>	364 096 1499

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: [turbomaster@turbomaster.info](mailto:turbomaster@turbomaster.info).

**APPLICATIONS**

SUITABLE FOR:

**Mitsubishi**

Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
4D31-B	4L			TDO5	49178-00590	ME013736

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain

Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: [turbomaster@turbomaster.info](mailto:turbomaster@turbomaster.info).



## APPLICATIONS

SUITABLE FOR:

**Navistar**

Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
DT282			4620	TO606	<b>404310-0003</b>	324032R91
DT360			5900	TO4B18	<b>409570-0005</b>	749263C91
DT360			5900	TO4B18	<b><u>409570-0014</u></b>	684200C91
DT414			6785	TO4B18	<b>409570-0003</b>	749267C92
DT414			6785	TO4B18	<b><u>409570-0012</u></b>	684239C91
DT414			6785	TO4B18	<b><u>409570-0017</u></b>	684239C92
DT429			7030	TO455	<b>407710-0002</b>	
DT466	6L		7600	TO4B18	<b>409570-0003</b>	749267C92
DT466	6L		7600	TO4B18	<b><u>409570-0012</u></b>	684239C91
DT466	6L		7600	TO4B18	<b><u>409570-0017</u></b>	684239C92
DT466	6L		7600	TO4B25	<b>409770-0004</b>	
DT466B	6L	185	7640	TO4E13	<b><u>466772-0003</u></b>	1810312C91
DT466C	6L		7640	TO4E13	<b><u>466772-0003</u></b>	1810312C91
DT466D	6L	185	7640	TO4E13	<b><u>466772-0003</u></b>	1810312C91
DT466E	6L	185	7640	TO4E13	<b><u>466772-0003</u></b>	1810312C91
DT530	6L		8700	GT4082	<b>466417-0015</b>	
DT530	6L		8700	GT4082	<b>466417-0016</b>	1822559C91
DT530	6L		8700	GT4082	<b>466741-0014</b>	1822557C92
DT530	6L		8700	GT4082	<b>466741-0015</b>	1822557C91
DT531				GT4082	<b>466531-0001</b>	1820939C92
DTA466B	6L	210	7640	TO4E13	<b><u>466772-0001</u></b>	1808749C91
DTA466C	6L		7640	TO4E13	<b><u>466772-0003</u></b>	1810312C91
DTA466C	6L	245	7640	TO4E13	<b><u>466772-0001</u></b>	1808749C91
DTA466E	6L	215	7640	TO4E13	<b><u>466772-0001</u></b>	1808749C91

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

### APPLICATIONS

SUITABLE FOR:

**Nissan**

Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
ED33T				TA3113	<u>465936-0002</u>	14201-90000
ED33T				TA3113	<u>465936-0003</u>	
PF6TA				TA5103	<u>466242-0017</u>	14201-96062

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

## APPLICATIONS

SUITABLE FOR:

**Perkins**

Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
1004-4T	4L		4000	TA3121	<u>466908-0001</u>	2674A137
1004-4T	4L	111	4000	GT2052	<u>452264-0001</u>	2674A323
1004-4T	4L	111	4000	GT2052	<u>452264-0002</u>	2674A324
1004-4T	4L	111	4000	GT2052	<u>452271-0001</u>	2674A321
1004-4T2	4L	93	4000	T250-02	<u>452061-0001</u>	2674A142
1004-4THR3	4L		4000	TB2565	<u>452073-0004</u>	2674A056
1004-4THR3	4L	106	4000	T250-03	<u>452073-0001</u>	2674A054
1004-4THR3	4L	106	4000	T250-03	<u>452073-0002</u>	2674A056
1006TAG	6L		6000	GT3267	<u>452234-0006</u>	2674A335
ATC6.354.1	6L		5800	TO458	<u>408860-0002</u>	2674351
ATV8.640	8V		10500	TO4B28	<u>409860-0001</u>	2674353
ATV8.640	8V		10500	TO4B28	<u>409860-0002</u>	2674357
ATV8.640	8V		10500	TO4B28	<u>409860-0003</u>	2674361
C4.236	4L		3860	TA3107	<u>465778-0002</u>	2674371
C4.236	4L		3860	TA3107	<u>465778-0003</u>	2674372
C4.236	4L		3860	TA3107	<u>465778-0006</u>	2674383
C6.354.4	6L		5800	TO4B71	<u>465154-0007</u>	2674365
C6.354.4	6L		5800	TO4B71	<u>465154-0008</u>	2674367
T3.152	3L		2500	TA3117	<u>466346-0001</u>	2674A101
T4.236	4L		3860	TA3106	<u>465776-0003</u>	996634
T4.236	4L		3860	TA3106	<u>465776-0004</u>	996601
T4.236	4L		3860	TA3107	<u>465778-0004</u>	2674373
T4.236	4L		3860	TA3107	<u>465778-0005</u>	2674374
T4.236	4L		3860	TA3107	<u>465778-0007</u>	2674384
T4.236	4L		3860	TA3107	<u>465778-0011</u>	2674390
T4.236	4L		3860	TAO315	<u>466778-0004</u>	2674A108
T4.40	4L		4000	GT2052S	<u>452191-0001</u>	2674A093
T4.40	4L		4000	GT2052S	<u>452191-0002</u>	2674A318
T4.40	4L		4000	GT2052S	<u>452222-0002</u>	2674A304
T4.40	4L		4000	GT2052S	<u>452301-0001</u>	2674A326
T4.40	4L		4000	GT2052S	<u>452301-0002</u>	2674A327

<b>T4.40</b>	4L		4000	GT2052S	<b><u>452301-0003</u></b>	2674A328
<b>T4.40</b>	4L		4000	GT2052S	<b><u>727264-0001</u></b>	2674A371
<b>T4.40</b>	4L		4000	GT2052S	<b><u>727264-0002</u></b>	2674A372
<b>T4.40</b>	4L		4000	GT2052S	<b><u>727266-0001</u></b>	2674A391
<b>T4.40</b>	4L		4000	GT2052S	<b><u>727266-0002</u></b>	2674A392
<b>T4.40</b>	4L		4000	GT2052S	<b><u>727266-0003</u></b>	2674A393
<b>T4.40</b>	4L		4000	TB2558	<b><u>452065-0003</u></b>	2674A150
<b>T4.40</b>	4L	80	4000	GT2052	<b><u>452264-0002</u></b>	2674A324
<b>T4.40</b>	4L	80	4000	GT2052	<b><u>727265-0002</u></b>	2674A382
<b>T4.40</b>	4L	106	4000	TA3120	<b><u>466854-0001</u></b>	2674394
<b>T4.40</b>	4L	106	4000	TB2558	<b><u>452065-0002</u></b>	2674A149
<b>T4.40</b>	4L	107	4000	GT2052S	<b><u>705104-0002</u></b>	2674A332
<b>T4.40</b>	4L	109	4000	TA3121	<b><u>466908-0001</u></b>	2674A137
<b>T6.354.1</b>	6L		5800	TO4B51	<b><u>465740-0001</u></b>	2674352
<b>T6.354.3</b>	6L		5800	TO4B71	<b><u>465154-0012</u></b>	996541
<b>T6.354.3</b>	6L		5800	TO4B71	<b><u>465154-0013</u></b>	996548
<b>T6.354.3</b>	6L		5800	TO4B71	<b><u>465154-0017</u></b>	996708
<b>T6.354.3</b>	6L		5800	TO4B71	<b><u>465154-0027</u></b>	
<b>T6.354.4</b>	6L		5800	TO4B51	<b><u>465740-0002</u></b>	2674354
<b>T6.354.4</b>	6L		5800	TO4B51	<b><u>465740-0003</u></b>	2674355
<b>T6.354.4</b>	6L		5800	TO4B51	<b><u>465740-0005</u></b>	2674366
<b>T6.354.4</b>	6L		5800	TO4B51	<b><u>465740-0006</u></b>	2674382
<b>T6.354.4</b>	6L		5800	TO4B58	<b><u>465960-0003</u></b>	2674358
<b>T6.354.4</b>	6L		5800	TO4B58	<b><u>465960-0006</u></b>	2674363
<b>T6.354.4</b>	6L		5800	TO4B58	<b><u>465960-0007</u></b>	2674364
<b>T6.354.4</b>	6L		5800	TO4B58	<b><u>465960-0009</u></b>	2674381
<b>T6.354.4</b>	6L		5800	TO4B71	<b><u>465154-0001</u></b>	2674152
<b>T6.354.4</b>	6L		5800	TO4B71	<b><u>465154-0002</u></b>	2674356
<b>T6.354.4</b>	6L		5800	TO4B71	<b><u>465154-0003</u></b>	
<b>T6.354.4</b>	6L		5800	TO4B71	<b><u>465154-0009</u></b>	2674368
<b>T6.354.4</b>	6L		5800	TO4B71	<b><u>465154-0010</u></b>	2674369
<b>T6.354.4</b>	6L		5800	TO4B71	<b><u>465154-0011</u></b>	2674370
<b>T6.354.4</b>	6L		5800	TO4B71	<b><u>465154-0014</u></b>	2674375
<b>T6.354.4</b>	6L		5800	TO4B71	<b><u>465154-0018</u></b>	2674387
<b>T6.354.4</b>	6L		5800	TO4B71	<b><u>465154-0019</u></b>	2674388
<b>T6.354.4</b>	6L		5800	TO4B71	<b><u>465154-0020</u></b>	2674389
<b>T6.354.4</b>	6L		5800	TO4B71	<b><u>465154-0021</u></b>	2674391
<b>T6.354.4</b>	6L		5800	TO4B71	<b><u>465154-0022</u></b>	2674392
<b>T6.60</b>	6L		5980	GT3267	<b><u>452234-0001</u></b>	2674A090

<b>T6.60</b>	6L		5980	GT3267	<b><u>452234-0004</u></b>	2674A333
<b>T6.60</b>	6L		5980	TB4131	<b><u>466828-0001</u></b>	2674A107
<b>T6.60</b>	6L		5980	TB4135	<b><u>465191-0003</u></b>	2674A135
<b>TV8.540</b>	8V		8850	TO4B28	<b><u>409860-0004</u></b>	2674378
<b>TV8.540</b>	8V		8850	TO4B28	<b><u>409860-0005</u></b>	2674379
<b>TV8.640</b>	8V		10500	TB4112	<b><u>466058-0001</u></b>	2674376
<b>TV8.640</b>	8V		10500	TB4112	<b><u>466058-0002</u></b>	2674377

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: [turbomaster@turbomaster.info](mailto:turbomaster@turbomaster.info).

**APPLICATIONS**

SUITABLE FOR:

**Rolls Royce**

Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
C6.240G				TA5104	<u>466478-0013</u>	OE50009
C6T				T6010	409500-0003	OE48255
CV12				TV6106	465580-0003	
CV12-450				TV6106	465580-0006	CV8560
CV12TCA				TA5104	<u>466478-0012</u>	
CV12TCA				TV6106	465580-0006	CV8560
CV8TCA				TV7106	465182-0003	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

### APPLICATIONS

SUITABLE FOR:

**SACM**

Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
UD18L4S3		118		TO4E26	<u>454004-0001</u>	45883141
UD25V12S4G		737		TL7101	<u>454146-0001</u>	40309246
UD30V12S6		1059		T18A87	<b>465934-0013</b>	DLT613040
UD30V12S6		1059		T18A87	<b>465934-0014</b>	DLT613041
UD30V16S6				TV8118	<u>466070-0012</u>	DLT611146
UD30V16S6D		2075		TV8504	<u>454079-0001</u>	DLT613612

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: [turbomaster@turbomaster.info](mailto:turbomaster@turbomaster.info).

**APPLICATIONS**

SUITABLE FOR:

**SSCM**

Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
UD25V12S5				TV8109	<u>465152-0010</u>	45870933

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.



## APPLICATIONS

SUITABLE FOR:

## Waukesha

Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
18 GLD				TV7125	<u>466125-0001</u>	305864
36 GLD				TV7125	<u>466125-0001</u>	305864
5774LT V				UTL9406	<u>704837-0009</u>	
5794GL				UTL9406	<u>704837-0008</u>	241007B
F18 GL				TV7204	<u>466662-0003</u>	
F18 GL				TV7204	<u>466662-0004</u>	
F2895 GL	6L	636	47000	TV9104	<u>465327-0001</u>	
F2895 GL	6L	636	47000	TV9104	<u>465327-0002</u>	
F2895 GL	6L	636	47000	TV9406	<u>465329-0001</u>	
F2895 GL	6L	636	47000	TV9406	<u>465329-0002</u>	
F2895 GSI	6L	636	47000	T18A96	<u>465282-0007</u>	208350F
F2895 GSIE	6L	636	47000	T18A73	<u>408820-0026</u>	A177390M
F2896 DSI				T18A96	<u>465282-0002</u>	208350B
F310DB				TO455	<u>407710-0003</u>	169057A
F3521 GL	6L	773	58000	TV9404	<u>466978-0002</u>	
F3521 GL	6L	773	58000	TV9406	<u>465329-0005</u>	211391G
F3521 GL	6L	773	58000	TV9406	<u>465329-0006</u>	211391H
F3521 GL	6L	773	58000	TV9407	<u>466035-0002</u>	211009C
F3521 GSI				TV9402	<u>466556-0002</u>	211009
F3521 GSI				TV9402	<u>466556-0003</u>	
F3521 GSIE	6L	773	58000	T18A96	<u>465282-0004</u>	208350C
F3521 GSIE	6L	773	58000	T18A96	<u>465282-0005</u>	208350D
G4807			78770	T18A96	<u>465282-0010</u>	208350K
H24 GL	8L	585	24000	TV8130	<u>465255-0001</u>	305347B
H24 GL	8L	585	24000	TV8130	<u>465255-0002</u>	305347C
H24 GL-LFP				TV7125	<u>466125-0002</u>	305864A
H24 GLD				UTV8133	<u>721853-0001</u>	305866
H48 GLD				UTV8133	<u>721853-0001</u>	305866
L5108 GSI			83700	T18A96	<u>465282-0009</u>	208350J
L5790 GL	12V	1272	95000	T18A73	<u>408820-0029</u>	A177390S
L5790 GL	12V	1272	95000	TV9104	<u>465327-0001</u>	
L5790 GL	12V	1272	95000	TV9406	<u>465329-0001</u>	

L5790 GL	12V	1272	95000	TV9406	<b>465329-0002</b>	
L5790 GL	12V	1272	95000	TV9408	<b>466175-0001</b>	
L5790 GL	12V	1272	95000	TV9408	<b>466175-0002</b>	211391J
L5790 GSIE	12V	1272	95000	T18A73	<b>408820-0026</b>	A177390M
L5790 GSIE	12V	1272	95000	T18A96	<b>465282-0006</b>	208350E
L6670 DSIH			109300	T18A96	<b>465282-0003</b>	208350A
L6670 DSIM			109300	T18A93	<b>465790-0003</b>	207773C
L6670 DSIM			109300	T18A96	<b>465282-0003</b>	208350A
L7042 GL	8L			UTV9406	<b>701100-0007</b>	
L7042 GL	12V	1547	115000	TV9404	<b>466978-0002</b>	
L7042 GL	12V	1547	115000	TV9406	<b>465329-0005</b>	211391G
L7042 GL	12V	1547	115000	TV9406	<b>465329-0006</b>	211391H
L7042 GL	12V	1547	115000	TV9407	<b>466035-0002</b>	211009C
L7042 GSIE	12V	1547	115000	T18A96	<b>465282-0004</b>	208350C
L7042 GSIE	12V	1547	115000	T18A96	<b>465282-0005</b>	208350D
P8894 D			145700	T18A71	<b>408710-0004</b>	207930C
P8894 D			145700	T18A71	<b>408710-0005</b>	207930D
P895 GL				T18A73	<b>408820-0028</b>	A177390R
P9390 GSIE	16V	2063	154000	T18A73	<b>408820-0018</b>	A177390D
P9390 GSIE	16V	2063	154000	T18A73	<b>408820-0019</b>	A177390E
P9390 GSIE	16V	2063	154000	T18A73	<b>408820-0020</b>	A177390F
P9390 GSIE	16V	2063	154000	T18A73	<b>408820-0021</b>	A177390G
VRD310T				TO4B38	<b>465300-0001</b>	169057B
VRD310T				TO4B38	<b>465300-0004</b>	169057C
VRD310T				TO4B38	<b>465300-0007</b>	169057D
VRD310T				TO4B38	<b>465300-0009</b>	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.