

TurboMaster**Mitsubishi Catalog 2005****SERIES (classic)**

3LM 4HD 4LE 4LF 4MD 5MF

TC SERIES

TCO3 TCO4 TCO5 TCO6 TC15

TD SERIES

TDO2 TDO25 TDO3 TDO4 TDO4H TDO5H TDO6 TDO7 TDO7S TDO8 TDO8H TDO9 TD10 TD13

TE SERIES

TEO4H TEO5 TEO6H

TF SERIES

TFO35 TFO7 TFO8

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

TurboMaster**Mitsubishi Catalog 2005****3LM**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
3LM319					
49166-00370	FURUKAWA				
49166-00371	FURUKAWA				
3LM259					
49166-01310	MITSUBISHI				

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

TurboMaster**Mitsubishi Catalog 2005****4HD**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
4HD857					
49161-01220					49161-01230
49161-01230					
4HD854					
49161-02203					

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

TurboMaster**Mitsubishi Catalog 2005****4LE**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
4LE504					
30031-90100	FURUKAWA				

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

TurboMaster**Mitsubishi Catalog 2005****4LF**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
4LF302					
49163-01140					
4LF602					
49163-01310					
4LF402					
49163-01420					

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

TurboMaster**Mitsubishi Catalog 2005****4MD**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
4MD755					
49160-04502					
49160-04510					

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

TurboMaster**Mitsubishi Catalog 2005****5MF**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
5MF781					
49167-00101					
5MF965					
49167-00106		49167-09500			
5MF741					
49167-00130					
49167-00131					
5MF965					
49167-00136		49167-09500			
5MF955					
49167-00160		49167-09400			
5MF965					
49167-00336					
5MF995					
49167-00360	MITSUBISHI				

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

TurboMaster**Mitsubishi Catalog 2005****TCO3**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
TCO3					
49170-00200		49170-09200			
49170-01001	YAMAHA	49170-09300			

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

TurboMaster**Mitsubishi Catalog 2005****TCO4**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
TCO4					
49171-01000	MITSUBISHI	49171-08010	49171-80200		
TCO4-09A/5					
49171-01100	MITSUBISHI	49171-08010	49171-80200	5,0	
TCO4-09B/5					
49171-01200	MITSUBISHI	49171-08020	49171-80200	5,0	
49171-01201	MITSUBISHI	49171-08030	49171-80200	5,0	
TCO4-09B/6					
49171-01300	MITSUBISHI	49171-08020	49171-80200	6,0	
49171-01301	MITSUBISHI	49171-08030	49171-80200	6,0	
49171-01310	MITSUBISHI	49171-08020	49171-80200	6,0	
TCO4					
49171-01311	MITSUBISHI	49171-08030	49171-80200		
49171-01400	MITSUBISHI		49171-80200		
49171-02100	YAMAMOTO	49171-09600	49171-80200		
49171-03002	YAMAHA	49171-9200	49171-80200		

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

TCO5

Part number	Application	C.H.R.A.	Service kit	A/R	Replaces by
TCO5					
49168-00512	FURUKAWA	49168-09100	49168-84100		
49168-00542	FURUKAWA	49168-09730	49168-84100		
TCO5-10A					
<u>49168-01200</u>	MITSUBISHI	49168-08020	49168-84100	6,0	
49168-01201	MITSUBISHI	49168-08020	49168-84100	6,0	
TCO5-10A/6					
<u>49168-01202</u>	MITSUBISHI	49168-08020	49168-84100	6,0	
TCO5					
49168-01300	MITSUBISHI	49168-08040	49168-84100		
49168-01301	MITSUBISHI	49168-08030	49168-84100		
49168-01310	MITSUBISHI	49168-08040	49168-84100		
49168-01311	MITSUBISHI	49168-08030	49168-84100		
49168-01321	MITSUBISHI	49168-08030	49168-84100		
49168-01322	MITSUBISHI	49168-08050	49168-84100		
49168-01330	MITSUBISHI	49168-08030	49168-84100		
49168-01331	MITSUBISHI	49168-08050	49168-84100		
49168-01340	MITSUBISHI	49168-08030	49168-84100		
49168-01341	MITSUBISHI	49168-08050	49168-84100		
49168-01400	MITSUBISHI	49169-08010	49168-84100		
TCO5-11A					
49168-01401	MITSUBISHI	49169-08020	49168-84100		
49168-01410	MITSUBISHI	49169-08010	49168-84100		
TCO5					
49168-01411	MITSUBISHI	49169-08020	49168-84100		
49168-01412	MITSUBISHI	49169-08030	49168-84100		
49168-01420	MITSUBISHI	49169-08020	49168-84100		
49168-01500	MITSUBISHI	49168-08020	49168-84100		
49168-01510	MITSUBISHI	49168-08020	49168-84100		
TCO5-12A/8					
49168-01600	MITSUBISHI	49168-08030	49168-84100	8,0	
49168-01601	MITSUBISHI	49168-08050	49168-84100	8,0	
TCO5					
49168-01700	MITSUBISHI	49168-08030	49168-84100		
49168-01710	MITSUBISHI	49168-08050	49168-84100		
49168-01720	MITSUBISHI	49168-08050	49168-84100		
49168-01800	MITSUBISHI	49168-08030	49168-84100		
49168-01801	MITSUBISHI	49168-08050	49168-84100		

TCO5-12A/6					
49168-01810	MITSUBISHI	49168-08030	49168-84100	6,0	
49168-01811	MITSUBISHI	49168-08050	49168-84100	6,0	
TCO5					
49168-01820	MITSUBISHI	49168-08030	49168-84100		
49168-01821	MITSUBISHI	49168-08050	49168-84100		
49168-01900	MITSUBISHI	49168-08050	49168-84100		
TCO5-07A					
49168-02400	TOYOTA	49168-09100	49168-84100		
TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.					

TCO6

Part number	Application	C.H.R.A.	Service kit	A/R	Replaces by
TCO6-17B					
49169-00300	FURUKAWA	49169-09600	49168-84100		
TCO6					
49169-00310	mitsubishi	49169-09100	49168-84100		
TCO6-17B					
49169-00320	FURUKAWA	49169-09600	49168-84100		
TCO6					
49169-00330	FURUKAWA	49169-09200	49168-84100		
49169-00400	mitsubishi	49169-09200	49168-84100		
49169-00406	MITSUI	49169-09200	49168-84100		
49169-00410	MITSUI	49169-09300	49168-84100		
49169-00413	MITSUI	49169-09300	49168-84100		
49169-00416	MITSUI	49169-09300	49168-84100		
49169-00420	MITSUI	49169-09200	49168-84100		
49169-00423	MITSUI	49169-09200	49168-84100		
49169-00426		49169-09200	49168-84100		
49169-00500	mitsubishi	49169-09300	49168-84100		
49169-00510	mitsubishi	49169-09300	49168-84100		
49169-00520	mitsubishi	49169-09100	49168-84100		
49169-00530	mitsubishi	49169-09200	49168-84100		
49169-00610	MSK	49169-09100	49168-84100		
TCO6-11A/8					
49169-01000	mitsubishi	49169-08030	49168-84100	8,0	
TCO6					
49169-01100	mitsubishi	49169-08020	49168-84100		
TCO6-11A/8					
49169-01200	mitsubishi	49169-08040	49168-84100	8,0	
49169-01201	mitsubishi	49169-08040	49168-84100	8,0	
TCO6-11A					
49169-01410	mitsubishi	49169-08030	49168-84100		
TCO6-11A/8					
49169-01411	mitsubishi	49169-08030	49168-84100	8,0	
49169-01412	mitsubishi	49169-08030	49168-84100	8,0	
TCO6-11A					
49169-01420	mitsubishi	49169-08020	49168-84100		

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

TurboMaster**Mitsubishi Catalog 2005****TC15**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
TC15					
49124-00150	MITSUBISHI				
49124-00160	MITSUBISHI				

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

TurboMaster**Mitsubishi Catalog 2005****TDO2**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
TDO2MR2-04K					
49130-01600	MITSUBISHI	49130-08100			
49130-01610	MITSUBISHI	49130-08140			

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

TDO25

Part number	Application	C.H.R.A.	Service kit	A/R	Replaces by
TDO25L-07G/4					
49173-01200	mitsubishi	49173-09840			
49173-01400	mitsubishi	49173-09810			
TDO25M-09T/3.3					
<u>49173-02401</u>	HYUNDAI	49173-08401		3,3	
TDO25M-06T/2.8					
49173-02610	HYUNDAI			2,8	
TDO25					
49173-03000	KUBOTA	49173-09500			
49173-03010	KUBOTA	49173-09500			
49173-03100	KUBOTA	49173-09500			
49173-03110	KUBOTA	49173-09500			
TDO25L-03C					
49173-03200	KUBOTA	49173-09730			
TDO25					
49173-03210	KUBOTA	49173-09730			
49173-03300	KUBOTA	49173-09530			
49173-03400	KUBOTA	49173-08200			
TDO25M-05T					
49173-03410	KUBOTA	49173-08200			
TDO25					
49173-04100	mitsubishi	49173-09600			
TDO25M-03C					
<u>49173-04200</u>	LOMBARDINI	49173-09530			
49173-04210	LOMBARDINI				
TDO25L-08T/3.3					
<u>49173-06100</u>	ROVER	49173-08300		3,3	
TDO25M-06T					
<u>49173-06500</u>	OPEL	49173-08700			49173-06501
<u>49173-06501</u>	OPEL	49173-08700			
TDO25M-03C/2.8					
<u>49173-07300</u>	LOMBARDINI	49173-09530		2,8	49173-07301
<u>49173-07301</u>	LOMBARDINI	49173-09630		2,8	
<u>49173-07310</u>	LOMBARDINI	49173-09630		2,8	
<u>49173-07311</u>	LOMBARDINI	49173-09630		2,8	
TDO25M-03C/2.0					
49173-07320	LOMBARDINI	49173-09530		2,0	

TDO25					
49173-07321	LOMBARDINI	49173-09530			
TDO25L-05G/3.3					
49173-07330	LOMBARDINI	49173-09900		3,3	
TDO25					
49173-07331	LOMBARDINI	49173-09900			
TDO25L-05G/3.3					
49173-07340	LOMBARDINI	49173-09900		3,3	
TDO25					
49173-07341	LOMBARDINI	49173-09900			
TDO25MR-05G/2.3					
49180-02030	HYUNDAI			2,3	
TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.					

TurboMaster**Mitsubishi Catalog 2005****TDO3**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
TDO3-07G					
49131-02000	KUBOTA	49131-08010			
TDO3					
49131-02010	KUBOTA	49131-08010			
49131-02020	KUBOTA	49131-08010			
49131-03500	ISEKI	49131-08000			
49131-03510	ISEKI	49131-08000			
49131-04100	MITSUBISHI	49131-08100			
49131-04300	MAZDA	49131-08110			
<u>49131-05000</u>	VOLVO	49131-08200			
<u>49131-05001</u>	VOLVO	49131-08200			
49131-05010	VOLVO	49131-08200			
49131-05050	VOLVO	49131-08210			
<u>49131-05100</u>	VOLVO	49131-08210			
<u>49131-05101</u>	VOLVO	49131-08210			
49131-05110	VOLVO	49131-08210			
49131-05150	VOLVO	49131-08210			
49131-06003	OPEL				
49131-94100		49131-08100			
49131-94300		49131-08110			

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

TDO4

Part number	Application	C.H.R.A.	Service kit	A/R	Replaces by
TDO4					
49177-00100	CHRYSLER	49377-08200	49177-80410		
49177-00110	CHRYSLER	49377-08220	49177-80410		
49177-00130	CHRYSLER	49377-08250	49177-80410		
49177-00140	CHRYSLER	49377-08250	49177-80410		
TDO4L-13G/6					
49177-00320	MITSUBISHI	49377-08040	49177-80410	6,0	
TDO4					
49177-00401	MITSUBISHI	49177-08250	49177-80410		
TDO4L-13G/6					
49177-00420	MITSUBISHI	49377-08040	49177-80410	6,0	
TDO4-11B					
49177-00600			49177-80410		
49177-00620			49177-80410		
49177-00630			49177-80410		
TDO4-09B					
49177-00640		49177-08020	49177-80410		
TDO4-11B					
49177-00650		49177-09400	49177-80410		
49177-00660		49177-09400	49177-80410		
TDO4-09B					
49177-00710			49177-80410		
TDO4-11B					
49177-00720			49177-80410		
TDO4-05B					
49177-00730			49177-80410		
TDO4-09B					
49177-00750			49177-80410		
TDO4-09B/4					
49177-01000	FORD	49177-08020	49177-80410	4,0	
<u>49177-01010</u>	MITSUBISHI	49177-08020	49177-80410	4,0	
49177-01020	MITSUBISHI	49177-08020	49177-80410	4,0	
TDO4-09B/3					
49177-01030	MITSUBISHI	49177-08020	49177-80410	3,0	
TDO4-09B/4					
49177-01100	MITSUBISHI	49177-08020	49177-80410	4,0	
TDO4-09B/3					

49177-01200	mitsubishi	49177-08020	49177-80410	3,0	
49177-01210	mitsubishi	49177-08020	49177-80410	3,0	
49177-01220	mitsubishi	49177-08020	49177-80410	3,0	
49177-01230	mitsubishi	49177-08020	49177-80410	3,0	
TDO4-09B/5					
49177-01300	mitsubishi	49177-08030	49177-80410	5,0	
TDO4					
49177-01301	mitsubishi		49177-80410		
TDO4-09B/5					
49177-01310	mitsubishi	49177-08030	49177-80410	5,0	
TDO4					
49177-01400	mitsubishi	49177-08040	49177-80410		
TDO4-11B/7					
49177-01410	mitsubishi	49177-08040	49177-80410	7,0	
49177-01420	mitsubishi	49177-08040	49177-80410	7,0	
TDO4-09B/4					
49177-01500	mitsubishi	49177-08020	49177-80410	4,0	49177-01501
49177-01501	mitsubishi	49177-08020	49177-80410	4,0	
TDO4-10T					
49177-01502	mitsubishi	49177-08240	49177-80410		49177-01504
TDO4-10T/4					
49177-01503	mitsubishi	49177-08240	49177-80410	4,0	49177-01505
49177-01504	mitsubishi	49377-08400	49177-80410	4,0	
49177-01505	mitsubishi	49377-08400	49177-80410	4,0	
TDO4-09B/4					
49177-01510	mitsubishi	49177-08020	49177-80410	4,0	
49177-01511	mitsubishi	49177-08020	49177-80410	4,0	
TDO4-10T/4					
49177-01512	mitsubishi	49177-08240	49177-80410	4,0	
49177-01513	mitsubishi	49177-08240	49177-80410	4,0	49177-01515
49177-01514	mitsubishi	49377-08400	49177-80410	4,0	
49177-01515	mitsubishi	49377-08400	49177-80410	4,0	
TDO4-10T					
49177-01520	mitsubishi	49177-08240	49177-80410		
49177-01521	mitsubishi	49377-08400	49177-80410		
TDO4					
49177-01530	mitsubishi	49177-08240	49177-80410		
49177-01531	mitsubishi	49377-08400	49177-80410		
TDO4-09B/6					
49177-01600	mitsubishi	49177-08030	49177-80410	6,0	

TDO4					
49177-01700	mitsubishi	49177-08040	49177-80410		
49177-01710	mitsubishi	49177-09020	49177-80410		
TDO4-11B					
49177-01800	mitsubishi	49177-08040	49177-80410		
TDO4-11B/4					
49177-01810	mitsubishi	49177-09020	49177-80410	4,0	
TDO4-13G/5					
49177-01900	mitsubishi	49177-09010	49177-80410	5,0	
49177-01901	mitsubishi	49177-08210	49177-80410	5,0	
TDO4					
49177-01910	mitsubishi	49377-08030	49177-80410		
49177-02000	mitsubishi		49177-80410		
TDO4-07B/5					
49177-02100	mitsubishi	49177-09200	49177-80410	5,0	
TDO4-07B/4					
49177-02110	mitsubishi	49177-09210	49177-80410	4,0	
TDO4					
49177-02120	mitsubishi	49177-09210	49177-80410		
49177-02130	mitsubishi	49177-09710	49177-80410		
TDO4S-05C					
49177-02200	mitsubishi	49177-08060	49177-80410		
TDO4-11G/6					
<u>49177-02300</u>	mitsubishi	49177-09030	49177-80410	6,0	49177-02310
TDO4					
49177-02301	mitsubishi	49177-08220	49177-80410		
TDO4-11G/6					
<u>49177-02310</u>	mitsubishi	49377-08020	49177-80410	6,0	
TDO4					
49177-02350	mitsubishi		49178-81100		
TDO4-11G/6					
<u>49177-02400</u>	mitsubishi	49177-09030	49177-80410	6,0	49177-02410
TDO4					
49177-02401	mitsubishi	49177-08220	49177-80410		
TDO4-11G/6					
<u>49177-02410</u>	mitsubishi	49377-08020	49177-80410	6,0	
TDO4-11G/4					
<u>49177-02500</u>	mitsubishi	49177-08110	49177-80410	4,0	49177-02501
<u>49177-02501</u>	mitsubishi	49177-08110	49177-80410	4,0	
TDO4-11G					
49177-02502	mitsubishi	49177-08250	49177-80410		

TDO4-11G/4					
49177-02503	mitsubishi	49177-08510	49177-80410	4,0	
<u>49177-02510</u>	mitsubishi	49177-08110	49177-80410	4,0	49177-02511
<u>49177-02511</u>	mitsubishi	49177-08110	49177-80410	4,0	
<u>49177-02512</u>	mitsubishi	49177-08250	49177-80410	4,0	49177-02513
<u>49177-02513</u>	mitsubishi	49377-08510	49177-80410	4,0	
<u>49177-02520</u>	mitsubishi	49177-08270	49177-80410	4,0	49177-02521
<u>49177-02521</u>	mitsubishi	49377-08520	49177-80410	4,0	
TDO4-10T					
<u>49177-02530</u>	mitsubishi	49177-08260	49177-80410		
49177-02531	mitsubishi	49377-08410	49177-80410		
TDO4					
49177-02540	mitsubishi	49177-08270	49177-80410		
49177-02541	mitsubishi	49377-08520	49177-80410		
TDO4-10T					
49177-02550	mitsubishi	49177-08260	49177-80410		
49177-02551	mitsubishi	49377-08410	49177-80410		
TDO4L-13G					
49177-02600	mitsubishi	49177-09040	49177-80410		
49177-02610	mitsubishi	49177-09040	49177-80410		
49177-02620	mitsubishi	49177-09040	49177-80410		
49177-02630	mitsubishi	49377-08040	49177-80410		
TDO4					
49177-02640	mitsubishi	49377-08210	49177-80410		
TDO4S-09G/3					
<u>49177-02700</u>	mitsubishi	49177-09060	49177-80410	3,0	
<u>49177-02701</u>	mitsubishi	49177-09060	49177-80410	3,0	49177-02702
<u>49177-02702</u>	mitsubishi	49377-08500	49177-80410	3,0	
TDO4					
49177-02710	mitsubishi	49177-09060	49177-80410		
49177-02711	mitsubishi	49377-08500	49177-80410		
49177-02720	mitsubishi	49177-09060	49177-80410		
49177-02721	mitsubishi	49377-08500	49177-80410		
TDO4S-09G/3					
49177-02800	mitsubishi	49177-09060	49177-80410	3,0	
TDO4-05B/2.5					
49177-03000	KUBOTA	49177-09500	49177-80410	2,5	
49177-03100	KUBOTA	49177-09500	49177-80410	2,5	
49177-03110	KUBOTA	49177-09500	49177-80410	2,5	
49177-03120	KUBOTA	49177-09500	49177-80410	2,5	
TDO4-12T					

49177-03130	KUBOTA	49177-08300	49177-80410		
49177-03140	KUBOTA	49177-08300	49177-80410		
TDO4S-05C					
49177-03500	KUBOTA	49177-08060	49177-80410		
TDO4L-05C					
49177-03600	KUBOTA	49177-08080	49177-80410		
TDO4-07B					
49177-04010		49177-09510	49177-80410		
49177-04500	KUBOTA	49177-09210	49177-80410		
TDO4-07B/6					
49177-05000	M.W.M.	49177-09200	49177-80410	6,0	
49177-05100	M.W.M.	49177-09200	49177-80410	6,0	
TDO4-07B					
49177-05200	POLONEZ	49177-09200	49177-80410		
TDO4-05B					
49177-05300	BUKH	49177-09100	49177-80410		
49177-05400	BUKH	49177-09100	49177-80410		
TDO4-07B/4					
<u>49177-05500</u>	FIAT	49177-09420	49177-80410	4,0	
TDO4-09B					
49177-05600	FIAT	49177-09310	49177-80410		
TDO4S-07B					
49177-05700	FIAT	49177-09510	49177-80410		
TDO4-09B/4					
49177-05800	FIAT	49177-09310	49177-80410	4,0	
TDO4-11B/4					
<u>49177-06000</u>	BMW	49177-09600	49177-80410	4,0	
<u>49177-06100</u>	BMW	49177-09600	49177-80410	4,0	
<u>49177-06200</u>	BMW	49177-09600	49177-80410	4,0	
TDO4-11G/4					
<u>49177-06400</u>	BMW	49177-09610	49177-80410	4,0	
TDO4					
49177-06402	BMW	49177-09612	49177-80410		
TDO4-11G/4					
<u>49177-06410</u>	BMW	49177-09610	49177-80410	4,0	
49177-06420	OPEL	49177-09610	49177-80410	4,0	49177-06490
49177-06422	BMW	49177-09610	49177-80410	4,0	
TDO4-11B/4					
<u>49177-06430</u>	ROVER	49177-09610	49177-80410	4,0	
TDO4-11G/4					
49177-06440	BMW	49177-09620	49177-80410	4,0	

TDO4					
49177-06450	BMW	49177-09650	49177-80410		
TDO4-13T/4					
<u>49177-06451</u>	BMW	49177-09660	49177-80410	4,0	49177-06452
<u>49177-06452</u>	BMW	49177-09660	49177-80410	4,0	
TDO4					
49177-06460	BMW	49177-09650	49177-80410		
TDO4-13T/4					
<u>49177-06461</u>	BMW	49177-09660	49177-80410	4,0	
TDO4					
49177-06470	BMW	49177-09650	49177-80410		
TDO4-13T/4					
49177-06471	BMW	49177-09660	49177-80410	4,0	
TDO4					
49177-06480	BMW	49177-09650	49177-80410		
TDO4-13T/4					
<u>49177-06481</u>	BMW	49177-09660	49177-80410	4,0	
TDO4-11G/4					
<u>49177-06490</u>	OPEL	49177-09610	49177-80410	4,0	
TDO4					
49177-06492	OPEL		49177-80410		
TDO4-11G/5					
<u>49177-06500</u>	BMW	49177-09610	49177-80410	5,0	
49177-06501	BMW	49177-09610	49177-80410	5,0	
<u>49177-06510</u>	BMW	49177-09610	49177-80410	5,0	
49177-06540	BMW	49177-09710	49177-80410	5,0	
TDO4-13T/4					
49177-06570	BMW	49177-09660	49177-80410	4,0	49177-06572
49177-06571	BMW	49177-09660	49177-80410	4,0	49177-06572
<u>49177-06572</u>	BMW	49177-09660	49177-80410	4,0	
49177-06580	BMW	49177-09650	49177-80410	4,0	
49177-06581	BMW	49177-09660	49177-80410	4,0	
49177-06582	BMW	49177-09660	49177-80410	4,0	
TDO4-09B/4					
49177-07500	HYUNDAI	49177-08020	49177-80410	4,0	
49177-07501	HYUNDAI	49177-08020	49177-80410	4,0	
TDO4-10T					
49177-07502	HYUNDAI	49177-08240	49177-80410		
TDO4-10T/4					
49177-07503	HYUNDAI		49177-80410	4,0	
TDO4-11G/4					

<u>49177-07612</u>	HYUNDAI		49177-80410	4,0	
49177-07613	HYUNDAI			4,0	
TDO4-11B/5					
<u>49177-07900</u>	CITROEN/ PEUGEOT	49177-09410	49177-80410	5,0	
TDO4					
49177-90300		49177-09050	49177-80410		
49177-90301	MITSUBISHI	49177-08230	49177-80410		
49177-90310	MITSUBISHI	49177-08010	49177-80410		
TDO4-13G/6					
49177-90320	MITSBISHI	49377-08040	49177-80410	6,0	
TDO4					
49177-90410	MITSUBISHI	49377-08010	49177-80410		
TDO4-13G/6					
49177-90420	MITSBISHI	49377-08040	49177-80410	6,0	
TDO4					
49377-00100	CHRYSLER	49377-08200	49177-80410		
49377-00110	CHRYSLER	49377-08220	49177-80410		
TDO4L-14T/6					
49377-00120	CHRYSLER	49377-08240	49177-80410		
TDO4					
49377-00130	CHRYSLER	49377-08250	49177-80410		
49377-00140	CHRYSLER	49377-08250	49177-80410		
49377-01500	KOMATSU	49177-08500	49177-80410		
49377-01510	KOMATSU	49177-08500	49177-80410		
49377-01520	KOMATSU	49177-08500	49177-80410		
49377-01530	KOMATSU	49177-08500	49177-80410		
TDO4-10T					
49377-01531	MITSUBISHI		49177-80410		
TDO4					
49377-01590	KOMATSU	49177-08500	49177-80410		
TDO4-11B					
49377-01700	MITSUBISHI		49177-80410		
49377-01710	MITSUBISHI		49177-80410		
TDO4-10T/4					
<u>49377-02001</u>	MITSUBISHI	49177-08260	49177-80410	4,0	49377-02002
<u>49377-02002</u>	MITSUBISHI	49377-08410	49177-80410	4,0	
TDO4-10T					
49377-02011	MITSUBISHI	49177-08260	49177-80410		
49377-02012	MITSUBISHI	49377-08410	49177-80410		
49377-02020	MITSUBISHI	49177-08260	49177-80410		
49377-02021	MITSUBISHI	49377-08410	49177-80410		

TDO4					
49377-02100	mitsubishi	49377-08210	49177-80410		
49377-03000	mitsubishi	49177-08120	49177-80410		
TDO4-12T					
49377-03010	mitsubishi	49177-08130	49177-80410		
49377-03020	mitsubishi	49177-08130	49177-80410		
49377-03030	mitsubishi	49177-08130	49177-80410		49377-03033
<u>49377-03031</u>	mitsubishi	49177-08130	49177-80410		49377-03033
49377-03033	mitsubishi	49177-08300	49177-80410		
TDO4-12T/4					
49377-03040	mitsubishi	49177-08130	49177-80410	4,0	49377-03043
<u>49377-03041</u>	mitsubishi	49177-08130	49177-80410	4,0	49377-03043
<u>49377-03043</u>	mitsubishi	49177-08300	49177-80410	4,0	
TDO4					
49377-03050	mitsubishi	49177-08130	49177-80410		
49377-03051	mitsubishi	49177-08130	49177-80410		
TDO4-12T/4					
49377-03053	mitsubishi	49177-08300	49177-80410	4,0	
TDO4					
49377-03100	mitsubishi	49177-08140	49177-80410		
49377-03101	mitsubishi	49177-08140	49177-80410		
49377-04000	subaru	49377-08110	49177-80410		
49377-04090	subaru	49377-08110	49177-80410		
TDO4L-13T/6					
49377-04100	subaru	49377-08120	49177-80410	6,0	49377-04300
49377-04180	subaru	49377-08120	49177-80410	6,0	
49377-04190	subaru	49377-08120	49177-80410	6,0	
49377-04200	subaru	49377-08120	49177-80410	6,0	49377-04300
TDO4L-13T					
49377-04280	subaru	49377-08120	49177-80410		
TDO4L-13T/6					
49377-04290	subaru	49377-08120	49177-80410	6,0	
<u>49377-04300</u>	subaru	49377-08120	49177-80410	6,0	
TDO4					
49377-05000	wiscon	49377-08600	49177-80410		
TDO4-11G					
49377-05100	wiscon	49177-08250	49177-80410		
TDO4					
49377-05110	wiscon	49177-09070	49177-80410		
TDO4L-12T					
49377-05200	hyundai				

TDO4					
49377-05500		49177-08210	49177-80410		
TDO4L-14T/6					
<u>49377-06000</u>	VOLVO	49377-08300	49177-80410	6,0	49377-06011
49377-06010	VOLVO	49377-08300	49177-80410	6,0	49377-06011
49377-06011	VOLVO	49377-08310	49177-80410	6	
TDO4L-12T/8.5					
<u>49377-06050</u>	VOLVO	49377-08310	49177-80410	8,5	49377-06060
<u>49377-06051</u>	VOLVO	49377-08310	49177-80410	8,5	49377-06060
<u>49377-06060</u>	VOLVO	49377-08310	49177-80410	8,5	
49377-06061	VOLVO	49377-08311	49177-80410	8,5	
TDO4L					
49377-06100	VOLVO	49377-08700	49177-80410		
49377-06101	VOLVO	49377-08700	49177-80410		
49377-06102	VOLVO				
49377-06110	VOLVO	49377-08700	49177-80410		
TDO4L-14T/8.5					
49377-06150	VOLVO	49377-08300	49177-80410	8,5	49377-06160
49377-06160	VOLVO	49377-08300	49177-80410	8,5	
TDO4L-12T					
49377-06250	VOLVO	49377-08310	49177-80410		
TDO4L-12T/8.5					
49377-06260	VOLVO	49377-08310	49177-80410	8,5	
49377-06351	VOLVO	49377-08321	49177-80410	8,5	
TDO4L					
49377-06361	VOLVO	49377-08320	49177-80410		
TDO4					
49377-06500	SAAB	49377-08330	49177-80410		
TDO4L					
<u>49377-07000</u>	IVECO	49377-08900	49177-80410		
<u>49377-07010</u>	IVECO	49377-08900	49177-80410		
<u>49377-07050</u>	IVECO	49377-08900	49177-80410		49377-07052
49377-07052	IVECO		49177-80410		
49377-07070	IVECO	49377-08900	49177-80410		
TDO4-10T/8.5					
49377-07300	RENAULT	49377-08350	49177-80410	8,5	
TDO4-08T/8					
49377-07700	K.H.DEUTZ	49177-08630	49177-80410	8,0	
TDO4-08T/6					
<u>49377-07710</u>	K.H.DEUTZ	49177-08630	49177-80410	6,0	
TDO4					

49377-90301

49177-08230

49177-80410

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

TurboMaster**Mitsubishi Catalog 2005****TDO4H**

Part number	Application	C.H.R.A.	Service kit	A/R	Replaces by
TDO4HL-15G/8.5					
49189-00501	ISUZU	49189-08100	49189-84000	8,5	
TDO4HL-15G/11					
49189-00511	ISUZU	49189-08100	49189-84000	11,0	
TDO4HL-15G					
49189-00520	ISUZU	49189-08100	49189-84000		
49189-00530	ISUZU	49189-08100	49189-84000		
TDO4HL-15G/12					
49189-00540	ISUZU	49189-08100	49189-84000	12,0	
TDO4HL-15G					
49189-00550	ISUZU	49189-08100	49189-84000		
TDO4H					
49189-00560	ISUZU	49189-08020	49189-84000		
49189-00561	ISUZU	49189-08030	49189-84000		
TDO4HL					
49189-00570	ISUZU		49189-84000		
TDO4H					
49189-00600		49189-08200	49189-84000		
TDO4HL-13G					
49189-00800	KATO	49189-08110	49189-84000		
49189-00810	KATO	49189-08110	49189-84000		
TDO4HL-15G					
49189-00820	KATO	49189-08100	49189-84000		
TDO4HL-13G					
49189-00900	KUBOTA	49189-08110	49189-84000		
TDO4H-13C/6					
49189-01000	VOLVO	49189-08300	49189-84000	6,0	
TDO4H-13C					
49189-01010	VOLVO	49189-08300	49189-84000		
TDO4H-13C/6					
49189-01200	VOLVO	49189-08300	49189-84000	6,0	49189-01210
49189-01210	VOLVO	49189-08300	49189-84000	6,0	
49189-01260	VOLVO	49189-08300	49189-84000	6,0	49189-01270
49189-01270	VOLVO	49189-08310	49189-84000	6,0	
TDO4HL-15G/7					
<u>49189-01300</u>	VOLVO	49189-08500	49189-84000	7,0	49189-01301
<u>49189-01301</u>	VOLVO	49189-08505	49189-84000	7,0	

49189-01310	VOLVO	49189-08505	49189-84000	7,0	49189-01320
49189-01320	VOLVO	49189-08505	49189-84000	7,0	
TDO4HL-16T/7					
49189-01330	VOLVO	49189-08535	49189-84000	7,0	
49189-01335	VOLVO	49189-08535	49189-84000	7,0	
49189-01350	VOLVO	49189-08535	49189-84000	7,0	49189-01355
49189-01355	VOLVO	49189-08535	49189-84000	7,0	
TDO4HL-13G/7					
49189-01360	VOLVO	49189-08515	49189-84000	7,0	
49189-01365	VOLVO	49189-08515	49189-84000	7,0	
TDO4HL-18T/7					
49189-01370	VOLVO	49189-08540	49189-84000	7,0	
49189-01375	VOLVO	49189-08540	49189-84000	7,0	
TDO4HL-13G/6					
49189-01400	VOLVO	49189-08515	49189-84000	6,0	49189-01401
49189-01401	VOLVO	49189-08515	49189-84000	6,0	
49189-01410	VOLVO	49189-08515	49189-84000	6,0	49189-01420
49189-01420	VOLVO	49189-08515	49189-84000	6,0	
49189-01430	VOLVO	49189-08515	49189-84000	6,0	
49189-01435	VOLVO	49189-08515	49189-84000	6,0	
TDO4HL-16T/6					
49189-01450	VOLVO	49189-08535	49189-84000	6,0	
49189-01455	VOLVO	49189-08535	49189-84000	6,0	
TDO4H					
49189-01500	HERCULES	49189-08420	49189-84000		
49189-01510	HERCULES	49189-08420	49189-84000		
TDO4HL-15G/6					
49189-01600	SAAB	49189-08500	49189-84000	6,0	
TDO4HL-15T/6					
49189-01700	SAAB	49189-08525	49189-84000	6,0	
<u>49189-01800</u>	SAAB	49189-08525	49189-84000	6,0	
TDO4H					
49189-02100		49189-08010	49189-84000		
49189-02101		49189-08010	49189-84000		
49189-02110		49189-08010	49189-84000		
49189-02200	MITSUBISHI	49189-08720	49189-84000		
49189-02300	MITSUBISHI	49189-08720	49189-84000		
49189-02310	MITSUBISHI	49189-08030	49189-84000		
49189-02311	MITSUBISHI	49189-08020	49189-84000		
49189-02320	MITSUBISHI	49189-08740	49189-84000		
TDO4HL-13G					
49189-02440	HYUNDAI				

TDO4H					
49189-02500	MITSUBISHI	49189-09000	49189-84000		
49189-02600	MITSUBISHI	49189-09010	49189-84000		
49189-03000		49189-08900	49189-84000		
49189-03100	MITSUBISHI	49189-08950	49189-84000		
49189-03110		49189-08950	49189-84000		
49189-03120		49189-09240	49189-84000		
49189-03200	MWM	49189-09100	49189-84000		
49189-03201	MWM	49189-09100	49189-84000		
49189-03210	MWM	49189-09100	49189-84000		
49189-03211		49189-09100	49189-84000		
49189-03300	CUMMINS	49189-08010	49189-84000		
49189-03310	CUMMINS	49189-08010	49189-84000		
49189-03350	CUMMINS		49189-84000		
TDO4HL-11T/6					
49189-03700	HYUNDAI			6,0	
TDO4H					
49189-04100	MITSUBISHI	49189-09000	49189-84000		
49189-04200	MITSUBISHI	49189-09010	49189-84000		
TDO4HL-16T/7					
49189-05000	VOLVO	49189-08535	49189-84000		
49189-05010	VOLVO	49189-08535	49189-84000	7,0	
49189-05100	VOLVO	49189-08535	49189-84000	7,0	
49189-05101	VOLVO	49189-08535	49189-84000	7,0	
49189-05111	VOLVO	49189-08535	49189-84000		
TDO4HL-13T					
49189-05200	VOLVO	49189-08550	49189-84000		
49189-05201	VOLVO	49189-08535	49189-84000		49189-05202
49189-05202	VOLVO		49189-84000		
49189-05210	VOLVO	49189-08550	49189-84000		
49189-05211	VOLVO	49189-08550	49189-84000		
TDO4HL-18T					
49189-05300	VOLVO	49189-08540	49189-84000		
49189-05310	VOLVO	49189-08540	49189-84000		
TDO4L-19T					
49189-05400	VOLVO	49189-08560	49189-84000		
49189-05410	VOLVO	49189-08560	49189-84000		
49189-05411	VOLVO	49189-08560	49189-84000		
TDO4HL					
49189-06070					
<p>TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.</p>					

TDO5H

Part number	Application	C.H.R.A.	Service kit	A/R	Replaces by
TDO5-10A					
49178-00500	mitsubishi		49178-81100		
TDO5					
49178-00510	mitsubishi	49178-08110	49178-81100		
TDO5-10A					
49178-00530	mitsubishi		49178-81100		
TDO5-1					
49178-00590	mitsubishi	49178-09310	49178-81100		
TDO5-12B/6					
49178-00595	mitsubishi		49178-81100	6,0	
TDO5H-14B/6					
<u>49178-01010</u>	mitsubishi	49178-08020	49178-81100	6,0	
<u>49178-01030</u>	mitsubishi	49178-09010	49178-81100	6,0	
TDO5H					
49178-01400	mitsubishi	49178-08020	49178-81100		
TDO5H-14B/6					
49178-01410	mitsubishi	49178-09010	49178-81100	6,0	
TDO5H-16T/7					
49178-01411	mitsubishi		49178-81100	7,0	
TDO5H-16G/7					
49178-01420	mitsubishi	49178-09020	49178-81100	7,0	
TDO5					
49178-01450	mitsubishi	49178-09020	49178-81100		
49178-01460	mitsubishi	49178-09020	49178-81100		
TDO5H-16G/7					
49178-01470	mitsubishi	49178-09050	49178-81100	7,0	
TDO5H					
49178-01500	mitsubishi	49178-08800	49178-81100		
TDO5H-16G/7					
49178-01510	mitsubishi	49178-08800	49178-81100	7,0	
TDO5HR-16G/6					
49178-01520	mitsubishi	49178-08800	49178-81100	6,0	
TDO5					
49178-01540		49178-08850	49178-81100		
49178-01550		49178-08800	49178-81100		
TDO5HRA-16G/10					
<u>49178-01560</u>	mitsubishi	49178-08850	49178-81100	10,5	

TDO5HRA-15G					
49178-01570	mitsubishi	49178-08880			
TDO5HRA-16GS					
49178-01580	mitsubishi	49178-08880	49178-81100		
TDO5HR-16G6/9.8					
49178-01590	mitsubishi	49178-0880	49178-81100	9,8	
TDO5					
49178-01600	mitsubishi	49178-08010	49178-81100		
49178-01700	mitsubishi	49178-08010	49178-81100		
49178-01710	mitsubishi	49178-08010	49178-81100		
TDO5-12A/8					
49178-01730	mitsubishi	49178-08010	49178-81100	8,0	
49178-01740	mitsubishi	49178-08010	49178-81100	8,0	
TDO5H-14G/8					
49178-01750	mitsubishi	49178-08620	49178-81100		
TDO5-14G/8					
49178-01760	mitsubishi	49178-08620	49178-81100		
TDO5					
49178-01900	mitsubishi	49178-08010	49178-81100		
49178-02000	mitsubishi	49178-09650	49178-81100		
49178-02001	mitsubishi	49178-09650	49178-81100		
49178-02010		49178-09650	49178-81100		
49178-02100		49178-09300	49178-81100		
TDO5H-12B/8					
49178-02110	mitsubishi	49178-09300	49178-81100	8,0	
TDO5H					
49178-02115	mitsubishi	49178-09300	49178-81100		
TDO5					
49178-02120	mitsubishi	49178-02120	49178-81100		
49178-02121	mitsubishi	49178-09620	49178-81100		
49178-02122	mitsubishi	49178-09640	49178-81100		
49178-02123	mitsubishi	49178-09610	49178-81100		
49178-02125	mitsubishi	49178-09300	49178-81100		
49178-02126	mitsubishi	49178-09620	49178-81100		
TDO5H-14G/12					
49178-02130	mitsubishi	49178-09610	49178-81100	12,0	
TDO5					
49178-02135	mitsubishi	49178-09610	49178-81100		
49178-02136	mitsubishi	49178-09610	49178-81100		
49178-02140	mitsubishi	49178-09620	49178-81100		
49178-02145	mitsubishi	49178-09620	49178-81100		
49178-02150	mitsubishi	49178-09610	49178-81100		

49178-02155	mitsubishi	49178-09610	49178-81100		
49178-02160	mitsubishi	49178-09640	49178-81100		
49178-02170	mitsubishi	49178-09610	49178-81100		
49178-02180	mitsubishi	49178-09620	49178-81100		
49178-02190	mitsubishi	49178-09610	49178-81100		
49178-02300	mitsubishi	49178-02305	49178-81100		
49178-02305	mitsubishi	49178-09300	49178-81100		
49178-02310	mitsubishi	49178-09620	49178-81100		
49178-02315	mitsubishi	49178-09610	49178-81100		
49178-02320	mitsubishi	49178-09620	49178-81100		
49178-02325	mitsubishi	49178-09610	49178-81100		
49178-02330	mitsubishi	49178-09640	49178-81100		
49178-02335	mitsubishi	49178-09610	49178-81100		
TDO5H					
49178-02350	mitsubishi		49178-81100		
TDO5					
49178-02380	mitsubishi	49178-09640	49178-81100		
TDO5H					
49178-02385	mitsubishi	49178-09610	49178-81100		
TDO5H-12B/6					
49178-03000	VOLVO	49178-09300	49178-81100	6,0	
TDO5-12B					
49178-03010	VOLVO	49178-08030	49178-81100		
TDO5H-12/6					
49178-03200	KUBOTA	49178-09630	49178-81100	6,0	
TDO5-10A/6					
49178-03530	HYUNDAI	49178-08110	49178-81100	6,0	
TDO5					
49178-04000		49178-09300	49178-81100		
49178-04200		49178-08040	49178-81100		
49178-04300		49178-08040	49178-81100		
49178-04310		49178-08020	49178-81100		
49178-04320		49178-09520	49178-81100		
49178-04330		49178-09090	49178-81100		
49178-04340		49178-09090	49178-81100		
49178-04400		49178-09060	49178-81100		
49178-04410		49178-09070	49178-81100		
49178-04500		49178-09090	49178-81100		
49178-04510		49178-09090	49178-81100		
49178-05200	mitsubishi	49178-09090	49178-81100		
TDO5H-16G					
49178-06200	SUBARU	49178-08310	49178-81100		

TDO5					
49178-06290	FUJI	49178-08310	49178-81100		
TDO5H-16G					
49178-06300	SUBARU	49178-08310	49178-81100		
49178-06310	SUBARU	49178-07300	49178-81100		
TDO5					
49178-06380	FUJI	49178-08310	49178-81100		
49178-06390	FUJI	49178-08310	49178-81100		
TDO5H-12B/6					
49178-07200	ALFA ROMEO	49178-07300	49178-81100	6,0	
TDO5					
49178-91450	MITSUBISHI	49178-09020	49178-81100		
49178-91560	MITSUBISHI	49178-08850			
TDO5HRA-16G6/9					
49378-01510	MITSUBISHI	49178-08950		9,8	
49378-01520	MITSUBISHI	49178-08960		9,8	
TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.					

TDO6

Part number	Application	C.H.R.A.	Service kit	A/R	Replaces by
TDO6H					
	49179-00460				
TDO6					
49179-00100	MITSUBISHI	49179-08730	49178-81100		
TDO6-17A					
49179-00110	MITSUBISHI	49179-08730	49178-81100		
TDO6					
49179-00120	MITSUBISHI	49179-09400	49178-81100		
49179-00130	MITSUBISHI	49179-08730	49178-81100		
49179-00150	MITSUBISHI	49179-09500	49178-81100		
TDO6-17C/10					
49179-00160	MITSUBISHI	49179-09400	49178-81100	10,0	
TDO6					
49179-00180	MITSUBISHI	49179-09400	49178-81100		
TDO6-19C					
49179-00191	MITSUBISHI	49179-09500	49178-81100		
TDO6-19C/12					
49179-00200	MITSUBISHI	49179-09500	49178-81100	12,0	
TDO6-11A/8					
49179-00210	MITSUBISHI	49179-09700	49178-81100	8,0	
49179-00220	MITSUBISHI	49179-09700	49178-81100	8,0	
TDO6-14A					
49179-00230	MITSUBISHI	49179-09710	49178-81100		
TDO6-19C/12					
49179-00240	MITSUBISHI	49179-09850	49178-81100	12,0	
TDO6H					
49179-00251	MITSUBISHI	49179-08530	49178-81100		
TDO6					
49179-00252	MITSUBISHI	49179-08530	49178-81100		
49179-00253	MITSUBISHI	49179-08530	49178-81100		
49179-00254	MITSUBISHI	49179-08670	49178-81100		
49179-00260	MITSUBISHI	49179-08540	49178-81100		
49179-00261	MITSUBISHI	49179-08540	49178-81100		
49179-00270	MITSUBISHI	49179-08540	49178-81100		
49179-00280	MITSUBISHI	49179-08540	49178-81100		
49179-00290	MITSUBISHI	49179-08540	49178-81100		
49179-00300	MITSUBI	49179-09100	49178-81100		
49179-00400	MITSUBISHI	49179-09300	49178-81100		

TDO6H-14C/14					
<u>49179-00451</u>	CATERPILLAR	49179-09830	49178-81100	14,0	
TDO6					
49179-00530	CATERPILLAR	49179-09830	49178-81100		
49179-00610		49179-09200	49178-81100		
49179-00620		49179-09400	49178-81100		
49179-00630		49179-09400	49178-81100		
49179-00640		49179-09400	49178-81100		
49179-00650		49179-09400	49178-81100		
49179-00660		49179-09300	49178-81100		
49179-00670		49179-09400	49178-81100		
49179-00800	HKS	49179-09300			
49179-00810	HKS	49179-09400	49178-81100		
49179-00820	HKS	49179-09840	49178-81100		
49179-00830	HKS	49179-09400	49178-81100		
49179-00840	HKS	49179-09500	49178-81100		
49179-00850	HKS	49179-09500	49178-81100		
49179-00860	HKS	49179-09830	49178-81100		
49179-00870	HKS	49179-09400	49178-81100		
49179-00880	HKS	49179-09500	49178-81100		
49179-00890	HKS	49179-09300	49178-81100		
49179-00910	HKS	49179-08450	49178-81100		
49179-00920	HKS	49179-08550	49178-81100		
49179-01190					
49179-02000		49179-09300	49178-81100		
49179-02100	MITSUBISHI	49179-08730	49178-81100		
TDO6-17C/10					
49179-02110	MITSUBISHI	49179-09400	49178-81100	10,0	
TDO6					
49179-02120	MITSUBISHI	49179-09500	49178-81100		
49179-02200					
TDO6H-17C/12					
49179-02210	HERCULES		49178-81100	12,0	
TDO6H-16M/12					
49179-02220	CATERPILLAR	49179-09940	49178-81100	12,0	49179-02260
49179-02230	CATERPILLAR		49178-81100	12,0	49179-02260
49179-02240	CATERPILLAR		49178-81100	12,0	49179-02260
TDO6					
49179-02250	HERCULES	49179-08850	49178-81100		
TDO6H-16M/12					
<u>49179-02260</u>	CATERPILLAR	49179-08600	49178-81100	12,0	
TDO6					

49179-02270	CATERPILLAR	49179-08600	49178-81100		
TDO6H-16M/12					
49179-02300	CATERPILLAR	49179-08600	49178-81100	12,0	
TDO6					
49179-02400	MITSUBISHI	49179-08540	49178-81100		
49179-02410	MITSUBISHI	49179-08540	49178-81100		
49179-03000	TOYOTA	49179-09600	49178-81100		
TDO6-17C/8					
49179-04000	GMC	49179-08940	49178-81100	8,0	
TDO6					
49179-04100	GMC	49179-08240	49178-81100		
TDO6-18G/8					
49179-05000	NISSAN	49179-08430	49178-81100	8,0	
<p>TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.</p>					

TurboMaster**Mitsubishi Catalog 2005****TDO7**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
TDO7					
49175-00200			49187-80110		
49175-00201			49187-80110		
TDO7-18A/21					
49175-00217			49187-80110	21,0	49175-00293
49175-00293			49187-80110	21,0	
TDO7-22A/21					
49175-00410			49187-80110		49175-00418
49175-00418			49187-80110		
TDO7-22A/17					
49175-00428			49187-80110	17,0	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

TurboMaster**Mitsubishi Catalog 2005****TDO7S**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
TDO7S-25A/13					
49187-00200	MITSUBISHI	49187-08010	49187-80110	13	
TDO7S					
49187-00211			49187-80110		
TDO7S-25A/13					
49187-00220			49187-80110	13	
TDO7S					
49187-00250			49187-80110		
TDO7S-25A/13					
49187-00271			49187-80110	13	
49187-00280	MITSUBISHI	49187-08010	49187-80110	13	
TDO7S					
49187-00340		49187-08060	49187-80110		
TDO7S-25A					
49787-00270			49187-80110		

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

TDO8

Part number	Application	C.H.R.A.	Service kit	A/R	Replaces by
TDO8-22B/22					
49174-00105	mitsubishi		49188-80200	22,0	49174-01140
TDO8-4					
49174-00160	mitsubishi		49188-80200		
TDO8					
49174-00168	mitsubishi		49188-80200		
TDO8-22D/28					
49174-00560	mitsubishi		49188-80200	28,0	
TDO8-22D					
49174-00562	mitsubishi		49188-80200		
TDO8-22D/28					
<u>49174-00565</u>	mitsubishi		49188-80200	28,0	
49174-00566	mitsubishi	49174-08110	49188-80200	28,0	
TDO8-22B/22					
49174-01140	mitsubishi		49188-80200	22,0	
TDO8-22B/28					
49174-01142	mitsubishi		49188-80200	28,0	
TDO8-22D/28					
49174-01200	HYUNDAI			28,0	
49174-05565	HYUNDAI			28,0	
49174-05566	HYUNDAI			28,0	
TDO8-15B/22					
49174-05592	HYUNDAI			22,0	
49174-06163	HYUNDAI			22,0	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

TDO8H

Part number	Application	C.H.R.A.	Service kit	A/R	Replaces by
TDO8H-26M/22					
49188-01256	MITSUBISHI		49188-80200	22,0	
TDO8H					
49188-01260	MITSUBISHI		49188-80200		
TDO8H-22B/28					
49188-01261	MITSUBISHI		49188-80200	28,0	
TDO8H-21D/22					
49188-01262	MITSUBISHI		49188-80200	22,0	
TDO8H-26M/25					
49188-01281	MITSUBISHI		49188-80200	25,0	
TDO8H-26M/27					
49188-01285	MITSUBISHI		49188-80200	27,0	
TDO8H					
49188-01510	MITSUBISHI		49188-80200		
TDO8H-22D					
49188-01651	MITSUBISHI		49188-80200		
49188-01661	MITSUBISHI		49188-80200		
TDO8H					
49188-02700	MITSUBISHI		49188-80200		
TDO8H-27M/22					
49188-03000	HYUNDAI		49188-80200	22,0	
TDO8H-28M/18					
49188-03020	HYUNDAI		49188-80200	18,0	
TDO8H-27M/22					
49188-03030	HYUNDAI		49188-80200	22,0	
TDO8H-28M/22					
49188-03100	HYUNDAI		49188-80200	22,0	
49188-03110	HYUNDAI		49188-80200	22,0	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

TurboMaster**Mitsubishi Catalog 2005****TDO9**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
TDO9-31F/41					
49132-00010	CATERPILLAR	49132-09110	49132-80010	41,0	
TDO9-31F					
49132-00020	CATERPILLAR				
TDO9-35F/34					
49132-01000	HYUNDAI		49132-80010	34,0	
TDO9					
<u>49132-04010</u>		49132-09550	49132-80010		
TDO9-QRC/25					
49132-04020		49132-09530			

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

TurboMaster**Mitsubishi Catalog 2005****TD10**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
TD10L-36F					
49181-01040			49181-82000		
TD10-42F					
49181-01120					
TD10L					
49181-03850					
49181-03860					
49181-03870					
49181-03880					

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

TurboMaster**Mitsubishi Catalog 2005****TD13**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
TD13					
49182-01120					
TD13-47B					
49182-01400					
TD13-47F					
<u>49182-03120</u>		49182-09540	49182-80100		
TD13-51F					
49182-03140		49182-09660	49182-80100		
TD13-48O					
49182-03270					
TD13					
49182-03520					
49182-04100	DETROIT DIESEL				
TD13M-48QRO					
<u>49182-05210</u>		49182-09040	49182-80100	48,0	
TD13M					
<u>49182-05300</u>	GUASCOR	49182-09020	49182-80100		

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

TurboMaster**Mitsubishi Catalog 2005****TEO4H**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
TEO4H					
49183-01000	CHRYSLER		49177-80400		
TEO4H-13C/11					
49183-01090	CHRYSLER	49183-08020	49177-80400	11,0	
49183-01190	CHRYSLER		49177-80400	11,0	
TEO4H-13C/8					
49183-02010	CHRYSLER	49183-08020	49177-80400	8,0	
TEO4H-13C/11					
49183-02110	CHRYSLER	49183-08020	49177-80400	11,0	
TEO4H					
49183-02200	CHRYSLER	49183-08020	49177-80400		
TEO4H-13C/11					
49183-02210	CHRYSLER		49177-80400	11,0	
49183-02400	CHRYSLER	49183-08020	49177-80400	11,0	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

TurboMaster**Mitsubishi Catalog 2005****TEO5**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
TEO5-12B/6					
49184-01000	SAAB		49178-81100	6,0	
49184-02000	SAAB	49184-09000	49178-81100	6,0	
49184-02200	SAAB	49184-09000	49178-81100	6,0	
49184-03200	SAAB	49184-09000	49178-81100	6,0	
49184-03300	SAAB	49184-09000	49178-81100	6,0	
49184-03400	SAAB	49184-09000	49178-81100	6,0	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

TurboMaster**Mitsubishi Catalog 2005****TEO6H**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
TEO6H-14M/12					
49185-00030	CATERPILLAR	49185-08210		12	
TEO6H-17C/2					
49185-00040	CATERPILLAR	49185-08300			
TEO6H-10M/12					
49185-00070	CATERPILLAR				
TEO6H					
49185-01010	MITSUBISHI				
49185-01020	MITSUBISHI				
TEO6H-16M					
49185-01040	MITSUBISHI				

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

TFO35

Part number	Application	C.H.R.A.	Service kit	A/R	Replaces by
TFO35HM-10T/3					
49135-00101				3,0	
49135-00102	ISUZU	49135-08710		3,0	
TFO35HS-10T					
49135-02000	mitsubishi	49135-08010			
49135-02010	mitsubishi	49135-08010			
TFO35HM-12T/4					
49135-02100	mitsubishi	49135-08020		4,0	49135-02110
49135-02110	mitsubishi	49135-08020		4,0	
TFO35HM-12T					
49135-02200	mitsubishi	49135-08000			
TFO35H					
49135-02210	mitsubishi	49135-08040			
TFO35HM-12T/4					
49135-02220	mitsubishi	49135-08000		4,0	
TFO35HM-10T/4					
49135-02230	mitsubishi	49135-08040		4,0	
TFO35H					
49135-02240	mitsubishi	49135-08030			
TFO35HM-10T/3					
49135-02300	mitsubishi	49135-08030			
TFO35HM-12T					
49135-02310	mitsubishi	49135-08030			
TFO35HM					
49135-02400	mitsubishi	49135-08020			
TFO35HM-10T					
49135-02500	mitsubishi	49135-08040			
TFO35					
49135-02510	mitsubishi	49135-08040			
TFO35HL2-12GK					
49135-02652	mitsubishi	49135-08800		12,0	
TFO35HS-10T					
49135-02700	mitsubishi	49135-08010			
49135-02710	mitsubishi	49135-08010			
49135-02730	mitsubishi	49135-08010			
49135-02800	MAZDA	49135-08010			
TFO35HM-12T					

49135-03100	mitsubishi	49135-08000			
49135-03101	mitsubishi	49135-08000			
49135-03110	mitsubishi	49135-08000			
49135-03111	mitsubishi	49135-08000			
49135-03112	mitsubishi	49135-08001			
49135-03120	mitsubishi	49135-08000			
TFO35HM-12T/4					
<u>49135-03130</u>	mitsubishi	49135-08000		4,0	
TFO35HM-12T					
49135-03200	mitsubishi	49135-08000			
49135-03210	mitsubishi	49135-08001			
49135-03220	mitsubishi	49135-08002			
<u>49135-03300</u>	mitsubishi	49135-08000			
49135-03301	mitsubishi	49135-08000			
49135-03310	mitsubishi	49135-08000			
TFO35HL-14GK					
<u>49135-03410</u>	mitsubishi	49135-08500			49135-03411
<u>49135-03411</u>	mitsubishi				
TFO35HM-12T					
<u>49135-03500</u>	mitsubishi	49135-08700			
TFO35					
<u>49135-03610</u>	mitsubishi	49135-08500			
TFO35HM-10T/4					
<u>49135-04000</u>	HYUNDAI	49135-08030		4,0	
<u>49135-04010</u>	HYUNDAI	49135-08030		4,0	
TFO35HM-12T/4					
49135-04020	HYUNDAI			4,0	
49135-04030	HYUNDAI			4,0	
TFO35HM-10T/4					
49135-04101	HYUNDAI			4,0	
49135-04111	HYUNDAI			4,0	
TFO35HM-12T/4					
49135-04121	HYUNDAI			4,0	
49135-04131	HYUNDAI			4,0	
TDO35HM-14T/4					
<u>49135-04600</u>	SUBARU	49135-08300		4,0	
49135-04690	SUBARU	49135-08300		4,0	
TDO35HM-14T					
49135-04700	SUBARU	49135-08300			
TFO35HM-13T/6					
<u>49135-05000</u>	IVECO	49135-08100		6,0	

<u>49135-05010</u>	IVECO	49135-08100		6,0	
<u>49135-05020</u>	IVECO	49135-08100		6,0	
<u>49135-05030</u>	IVECO	49135-08100		6,0	
<u>49135-05040</u>	IVECO	49135-08100		6,0	
<u>49135-05050</u>	IVECO	49135-08100		6,0	
<u>49135-05060</u>	IVECO	49135-08100		6,0	
<u>49135-05070</u>	SANTANA	49135-08100			
<u>49135-05080</u>	IVECO	49135-08100		6,0	

TFO35HM

<u>49135-05090</u>	IVECO	49135-08100			
--------------------	-------	-------------	--	--	--

TFO35HL

<u>49135-05500</u>	VM	49135-08400			
--------------------	----	-------------	--	--	--

TFO35

<u>49135-06000</u>	FORD	49135-08200			
--------------------	------	-------------	--	--	--

TFO35HM-12T

<u>49135-06010</u>	FORD	49135-08200			
--------------------	------	-------------	--	--	--

TFO35HM-10T

<u>49135-06020</u>	FORD	49135-08210			
--------------------	------	-------------	--	--	--

TFO35HM-12T

<u>49135-06030</u>	FORD	49135-08200			
--------------------	------	-------------	--	--	--

TFO35HM-12T/6

<u>49135-06500</u>	M.W.M.	49135-08600		6,0	
--------------------	--------	-------------	--	-----	--

TFO35HM

<u>49135-07430</u>	MITSUBISHI				
--------------------	------------	--	--	--	--

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

TurboMaster**Mitsubishi Catalog 2005****TFO7**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
TFO7-17M/17					
49186-00200	HERCULES	49186-08240		17,0	
TFO7-15M/21					
49186-02000	HYUNDAI			21,0	
49186-02010	HYUNDAI			21,0	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

TurboMaster**Mitsubishi Catalog 2005****TFO8**

Part number	Aplication	C.H.R.A.	Service kit	A/R	Replaces by
TFO8					
49134-00020		49134-08210			
TFO8L-26M/18					
49134-00101	HYUNDAI			18,0	
TFO8L-26M/15					
49134-00110	HYUNDAI			15,0	
TFO8L-26M/18					
49134-00130	HYUNDAI			18,0	
TFO8L-28M/22					
49134-00220	HYUNDAI			22,0	
49134-00230	HYUNDAI			22,0	
TFO8L-28M1/22					
49134-00240	HYUNDAI			22,0	
TFO8L-28M/22					
49134-00250	HYUNDAI			22,0	
TFO8L-24M/18					
49134-00410	HYUNDAI			18,0	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES (Madrid) Spain
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.