

**TurboMaster**

GARRETT TURBOS OFFICIAL DISTRIBUTOR FOR SPAIN

**Offway** Catalog**APPLICATIONS**

Allis-Chalmers	Caterpillar	Fiat-Allis
Hitachi	J.I.Case	JCB
I.H. - Dresser	John Deere	Kobelco
Komatsu	Liebherr	Perlini
Samsung	Volvo	

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

**TurboMaster**

GARRETT TURBOS OFFICIAL DISTRIBUTOR FOR SPAIN

**Offway** Catalog**APPLICATIONS**

SUITABLE FOR:

**Allis-Chalmers**

Model	Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
D262	2900				TO448	408270-0003	
D560	15000				T1817	404940-0003	4387701
D560	15000				T1817	404940-0006	4389968
D560	25000				T1817	404940-0003	4387701
HD12G	11000				TEO648	406090-0008	4357655
HD12GB	685T				TEO648	<u>406090-0016</u>	4320973
HD160D	16000 MK2				TEO673	408290-0002	4392272

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

## APPLICATIONS

SUITABLE FOR:

## Caterpillar

Model	Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
120G	3304T	4L		7000	TO4B91	<u>409410-0001</u>	4N6858
120G	3304T	4L		7000	TO4B91	<u>409410-0002</u>	4N6859
120G	3304T	4L		7000	TO4B91	<u>409410-0006</u>	7N4651
130G	3304T	4L		7000	TO4B91	<u>409410-0001</u>	4N6858
130G	3304T	4L		7000	TO4B91	<u>409410-0002</u>	4N6859
130G	3304T	4L		7000	TO4B91	<u>409410-0006</u>	7N4651
14G					3LM319	<b>159623</b>	4N8969
14G					3LM373	<b>184119</b>	7N7748
16	D343	6L			T1814	<u>404200-0001</u>	4S5791
16	D343	6L			T1814	<u>404200-0002</u>	8S6475
16	D343	6L			T1814	<u>404200-0003</u>	4N5644
16G	3406T	6L		14600	T1232	<u>409720-0004</u>	9L6308
16G	3406T	6L		14600	T1232	<u>409720-0006</u>	7N0011
16H					S4DSL	<u>167053</u>	107-2060
213	3116				S2BS	<b>194878</b>	7C2183
214	3116				S2BS	<b>194878</b>	7C2183
215D	3304	4L		7000	TO4B91	<u>409410-0013</u>	7E2601
225	3304T	4L		7000	TO4B91	<u>409410-0002</u>	4N6859
245	3406T	6L		14600	T1232	<u>409720-0002</u>	4N7157
245	3406T	6L		14600	TL8112	<u>465338-0008</u>	1W2583
245	3406T	6L		14600	TV6138	<u>465426-0001</u>	7N9478
245B	3406	6L		14600	TL7804	<u>465303-0001</u>	7C9894
245B	3406	6L		14600	TL7804	<u>465303-0002</u>	7C9895
283D	3306	6L		10500	TV6142	<u>465774-0004</u>	1W3430
285D	D342	6L			TL6137	<u>465584-0001</u>	8N5510
286D	D353	6L			TL8106	<u>465622-0001</u>	8N6554
315					TB2548	<u>452044-0001</u>	127-2929
322D	3408	8V		18000	TL8106	<u>465622-0002</u>	4W9104
345B	3176		312		GT4294	<u>471086-0002</u>	135-5392
351D	3412	12V		27000	TL8107	<u>465502-0004</u>	2W5697
375					S4DC	<b>199515</b>	4P7499

<b>385B</b>					GTA50	<b><u>716481-0002</u></b>	194-7923
<b>426</b>	3306	6L		10500	T1224	<b><u>407640-0011</u></b>	9L5345
<b>426</b>	3306	6L		10500	TV6135	<b><u>465984-0008</u></b>	2W3476
<b>427</b>	3406	6L		14600	TL7501	<b><u>466271-0002</u></b>	6I1338
<b>438C</b>					TA3107	<b><u>465778-0016</u></b>	7C3446
<b>515</b>	3304	4L		7000	TO4B91	<b><u>409410-0014</u></b>	6I2975
<b>516G</b>	3406	6L		14600	T1232	<b><u>409720-0006</u></b>	7N0011
<b>516G</b>	3406	6L		14600	TV6138	<b><u>465426-0004</u></b>	4W4257
<b>518</b>	3304T	4L		7000	TO490	<b><u>408450-0001</u></b>	1P0035
<b>518</b>	3304T	4L		7000	TO4B91	<b><u>409410-0001</u></b>	4N6858
<b>518</b>	3304T	4L		7000	TO4B91	<b><u>409410-0002</u></b>	4N6859
<b>571A</b>	D339	4L			T1210	<b><u>405490-0016</u></b>	4S9706
<b>572E</b>	D339	4L			T1210	<b><u>405490-0016</u></b>	4S9706
<b>583C</b>	D342	6L			T1504	<b><u>403000-0007</u></b>	6H9577
<b>583H</b>	D342	6L			T1227	<b><u>408110-0001</u></b>	9S2611
<b>583H</b>	D342	6L			T1227	<b><u>408110-0006</u></b>	1P1163
<b>583H</b>	D342	6L			T1404	<b><u>403680-0001</u></b>	2M5488
<b>583H</b>	D342	6L			T1404	<b><u>403680-0012</u></b>	1S4376
<b>583H</b>	D342	6L			T1404	<b><u>403680-0023</u></b>	3S8271
<b>583H</b>	D342	6L			T1867	<b><u>406400-0002</u></b>	8S6476
<b>583H</b>	D342	6L			T1867	<b><u>406400-0003</u></b>	4N5645
<b>583K</b>	D342	6L			T1238	<b><u>465032-0001</u></b>	6N7203
<b>594</b>	D353	6L			T1810	<b><u>402910-0003</u></b>	2S9804
<b>594</b>	D353	6L			T1810	<b><u>402910-0007</u></b>	8S6471
<b>594</b>	D353	6L			T1810	<b><u>402910-0043</u></b>	4N5643
<b>594</b>	D353	6L			TL8106	<b><u>465622-0001</u></b>	8N6554
<b>594</b>	D353	6L			TV8106	<b><u>465048-0002</u></b>	7N1758
<b>621B</b>	3406	6L		14600	TV6138	<b><u>465426-0003</u></b>	8N5308
<b>621E</b>	3406	6L		14600	TL6138	<b><u>466390-0001</u></b>	4W6725
<b>621F</b>	3406	6L		14600	UTL7507	<b><u>466911-0001</u></b>	122-6776
<b>627</b>	3306T	6L		10500	T1224	<b><u>407640-0009</u></b>	8S8039
<b>627</b>	3306T	6L		10500	T1224	<b><u>407640-0010</u></b>	8S8198
<b>627B</b>	3306T	6L		10500	T1224	<b><u>407640-0009</u></b>	8S8039
<b>627B</b>	3306T	6L		10500	T1224	<b><u>407640-0010</u></b>	8S8198
<b>627B</b>	3306T	6L		10500	T1224	<b><u>407640-0011</u></b>	9L5345
<b>627B</b>	3306T	6L		10500	TV6139	<b><u>465474-0002</u></b>	8N2356
<b>630</b>	D343	6L			T1402	<b><u>403650-0010</u></b>	7M4692
<b>630</b>	D343	6L			T1402	<b><u>403650-0023</u></b>	2S2836
<b>630</b>	D343	6L			T1402	<b><u>403650-0030</u></b>	3S8277

630B	D343	6L			T1402	403650-0010	7M4692
630B	D343	6L			T1402	403650-0023	2S2836
630B	D343	6L			T1810	402910-0001	3S1412
630B	D343	6L			T1810	<u>402910-0008</u>	8S6473
630B	D343	6L			T1810	402910-0101	1S9161
631	D343	6L			T1810	402910-0001	3S1412
631	D343	6L			T1810	<u>402910-0008</u>	8S6473
631	D343	6L			T1810	<u>402910-0033</u>	4N5633
631	D343	6L			T1810	402910-0101	1S9161
631A	D343	6L			T1402	403650-0010	7M4692
631A	D343	6L			T1402	403650-0023	2S2836
631A	D343	6L			T1402	403650-0030	3S8277
631B	D343	6L			T1402	403650-0010	7M4692
631B	D343	6L			T1402	403650-0023	2S2836
631B	D343	6L			T1810	402910-0001	3S1412
631B	D343	6L			T1810	<u>402910-0008</u>	8S6473
631B	D343	6L			T1810	<u>402910-0033</u>	4N5633
631B	D343	6L			T1810	402910-0101	1S9161
631C	D343	6L			T1810	<u>402910-0018</u>	8S6548
631C	D343	6L			T1810	<u>402910-0039</u>	4N5639
631D					4MF731	181009	4N8882
632	D343	6L			T1402	403650-0010	7M4692
632	D343	6L			T1402	403650-0023	2S2836
632	D343	6L			T1810	402910-0001	3S1412
632	D343	6L			T1810	<u>402910-0008</u>	8S6473
632	D343	6L			T1810	402910-0101	1S9161
633	D343	6L			T1810	402910-0001	3S1412
633	D343	6L			T1810	<u>402910-0008</u>	8S6473
633	D343	6L			T1810	<u>402910-0033</u>	4N5633
633C	D343	6L			T1810	<u>402910-0018</u>	8S6548
633C	D343	6L			T1810	<u>402910-0039</u>	4N5639
633D					4MF731	181009	4N8882
637	3306	6L		10500	T1224	<u>407640-0009</u>	8S8039
637	3306	6L		10500	T1224	<u>407640-0010</u>	8S8198
637	D343	6L			T1810	<u>402910-0018</u>	8S6548
637	D343	6L			T1810	<u>402910-0039</u>	4N5639
637D					4MF731	181009	4N8882
637D	3306	6L		10500	TV6136	<u>465840-0001</u>	6N3678
641					T2410	404510-0002	8M1742
641					T2410	404510-0003	2S2835

650					T2410	<b>404510-0002</b>	8M1742
650					T2410	<b>404510-0003</b>	2S2835
651					T2410	<b>404510-0002</b>	8M1742
651					T2410	<b>404510-0003</b>	2S2835
651E					TL9102	<b>465902-0003</b>	4W1238
651E	3412	12V		27000	UTL8901	<b>466793-0002</b>	130-8141
651E	3412	12V		27000	UTL8901	<b>466793-0004</b>	130-8141
651E	3412	12V		27000	UTL8901	<b>466793-0006</b>	167-9265
651L	3508	8V		34500	TV6145	<b>466022-0001</b>	1W8424
651L	3508	8V		34500	TV6145	<b>466022-0002</b>	1W8425
651L	3508	8V		34500	TV7203	<b>466808-0001</b>	7W8012
657					T1402	<b>403650-0010</b>	7M4692
657					T1402	<b>403650-0023</b>	2S2836
657					T1402	<b>403650-0030</b>	3S8277
657					T1810	<b>402910-0001</b>	3S1412
657					T1810	<b>402910-0033</b>	4N5633
657					T1810	<b>402910-0101</b>	1S9161
657					T2410	<b>404510-0002</b>	8M1742
657					T2410	<b>404510-0003</b>	2S2835
657B	D346	8V			T1810	<b>402910-0008</b>	8S6473
657B	D346	8V			T1810	<b>402910-0033</b>	4N5633
657E	3412	12V		27000	UTL8901	<b>466793-0002</b>	130-8141
657E	3412	12V		27000	UTL8901	<b>466793-0004</b>	130-8141
657E	3412	12V		27000	UTL8901	<b>466793-0006</b>	167-9265
660					T2410	<b>404510-0002</b>	8M1742
660					T2410	<b>404510-0003</b>	2S2835
666					T1402	<b>403650-0010</b>	7M4692
666					T1402	<b>403650-0023</b>	2S2836
666					T1402	<b>403650-0030</b>	3S8277
666					T1810	<b>402910-0001</b>	3S1412
666					T1810	<b>402910-0008</b>	8S6473
666					T1810	<b>402910-0033</b>	4N5633
768B	D343	6L			T1810	<b>402910-0006</b>	8S6472
768B	D343	6L			T1810	<b>402910-0040</b>	4N5640
769B	D343	6L			T1810	<b>402910-0002</b>	3S1414
769B	D343	6L			T1810	<b>402910-0006</b>	8S6472
769B	D343	6L			T1810	<b>402910-0040</b>	4N5640
772					V4HD855	<b>151518</b>	1P3088
772B	3412	12V		27000	TV6137	<b>465244-0001</b>	7N2839
772B	3412	12V		27000	TV6137	<b>465244-0002</b>	7N2838

<b>773</b>					V4HD855	<b>151518</b>	1P3088
<b>773B</b>					4MF701	<b>186551</b>	1W1810
<b>773B</b>	3412TA	12V		27000	TV6137	<b><u>465244-0001</u></b>	7N2839
<b>773B</b>	3412TA	12V		27000	TV6137	<b><u>465244-0002</u></b>	7N2838
<b>773D</b>					S4DSL	<b><u>167617</u></b>	
<b>775</b>	3412				S4DSL	<b>166669</b>	103-4051
<b>776</b>	D348	12V			T1810	<b><u>402910-0047</u></b>	6N7256
<b>776</b>	D348	12V			T1810	<b><u>402910-0048</u></b>	6N7257
<b>776B</b>	3508	8V		34500	TL8118	<b><u>465955-0001</u></b>	9Y8266
<b>777</b>	D348	12V			T1810	<b><u>402910-0047</u></b>	6N7256
<b>777</b>	D348	12V			T1810	<b><u>402910-0048</u></b>	6N7257
<b>777</b>	D348	12V			T1810	<b><u>402910-0050</u></b>	8N9133
<b>777</b>	D348	12V			T1810	<b><u>402910-0051</u></b>	8N9134
<b>777</b>	D348	12V			TL8118	<b><u>465955-0002</u></b>	7E9495
<b>777B</b>	3508	8V		34500	TL8118	<b><u>465955-0004</u></b>	115-3306
<b>777D</b>					BTL8503	<b><u>710024-0001</u></b>	172-0913
<b>779</b>	D348	12V			T1810	<b><u>402910-0010</u></b>	7S6769
<b>779</b>	D348	12V			T1810	<b><u>402910-0011</u></b>	7S6770
<b>783B</b>	3512	12V		51800	TL9211	<b><u>466582-0007</u></b>	115-2258
<b>785</b>	3512	12V		51800	TL9211	<b><u>466582-0006</u></b>	102-0303
<b>785C</b>	3512B	12V		51800	GT6041	<b><u>471094-0002</u></b>	122-0700
<b>785C</b>	3512B	12V		51800	GT6041	<b><u>700245-0001</u></b>	140-0393
<b>789</b>	3516	16V		69000	TL8118	<b><u>465955-0001</u></b>	9Y8266
<b>789C</b>					TL8118	<b><u>465955-0003</u></b>	7E9497
<b>793</b>	3516A	16V		69000	TL9216	<b><u>466657-0003</u></b>	121-3850
<b>793</b>	3516A	16V		69000	TL9216	<b><u>466657-0004</u></b>	
<b>793</b>	3516A	16V		69000	TL9216	<b><u>466657-0005</u></b>	128-3321
<b>793B</b>	3516A	16V		69000	UTL9216	<b><u>700241-0001</u></b>	138-2292
<b>793C</b>	3516B	16V		69000	GT6041	<b><u>466991-0002</u></b>	134-0386
<b>793C</b>	3516B	16V		69000	GT6041	<b><u>700246-0001</u></b>	138-2305
<b>824B</b>	D343	6L			T1810	<b><u>402910-0002</u></b>	3S1414
<b>824B</b>	D343	6L			T1810	<b><u>402910-0006</u></b>	8S6472
<b>824B</b>	D343	6L			T1810	<b><u>402910-0040</u></b>	4N5640
<b>824C</b>	3406	6L		14600	T1232	<b><u>409720-0001</u></b>	4N7156
<b>824C</b>	3406	6L		14600	T1232	<b><u>409720-0002</u></b>	4N7157
<b>824C</b>	3406	6L		14600	TV6138	<b><u>465426-0001</u></b>	7N9478
<b>825B</b>	D343	6L			T1810	<b><u>402910-0006</u></b>	8S6472
<b>825B</b>	D343	6L			T1810	<b><u>402910-0040</u></b>	4N5640
<b>825C</b>	3406	6L		14600	T1232	<b><u>409720-0001</u></b>	4N7156

<b>825C</b>	3406	6L		14600	T1232	<b><u>409720-0002</u></b>	4N7157
<b>825C</b>	3406	6L		14600	TV6138	<b><u>465426-0001</u></b>	7N9478
<b>826B</b>	D343	6L			T1810	<b><u>402910-0006</u></b>	8S6472
<b>826B</b>	D343	6L			T1810	<b><u>402910-0040</u></b>	4N5640
<b>826C</b>	3406T	6L		14600	T1232	<b><u>409720-0001</u></b>	4N7156
<b>826C</b>	3406T	6L		14600	T1232	<b><u>409720-0002</u></b>	4N7157
<b>826C</b>	3406T	6L		14600	TV6138	<b><u>465426-0001</u></b>	7N9478
<b>834</b>	D343	6L			T1810	<b><u>402910-0002</u></b>	3S1414
<b>834</b>	D343	6L			T1810	<b><u>402910-0006</u></b>	8S6472
<b>834</b>	D343	6L			T1810	<b><u>402910-0040</u></b>	4N5640
<b>834G</b>					GTA5002	<b><u>716875-0003</u></b>	192-2827
<b>835</b>	D343	6L			T1810	<b><u>402910-0002</u></b>	3S1414
<b>835</b>	D343	6L			T1810	<b><u>402910-0006</u></b>	8S6472
<b>835</b>	D343	6L			T1810	<b><u>402910-0040</u></b>	4N5640
<b>910</b>	3114T				S2AS	<b><u>196521</u></b>	7C1244
<b>910F</b>	3114				TEO6H	<b><u>49185-00070</u></b>	4P7716
<b>916F</b>	3114				S2AS	<b><u>166005</u></b>	6I0193
<b>922A</b>	D311				TO605	<b><u>404250-0001</u></b>	7M9731
<b>922A</b>	D311				TO605	<b><u>404250-0002</u></b>	3S5855
<b>922A</b>	D311				TO605	<b><u>404250-0006</u></b>	7S0578
<b>922B</b>					TO605	<b><u>404250-0001</u></b>	7M9731
<b>922B</b>					TO605	<b><u>404250-0002</u></b>	3S5855
<b>922B</b>					TO605	<b><u>404250-0006</u></b>	7S0578
<b>924F</b>	3114				S2ASL	<b><u>167560</u></b>	114-3601
<b>926E</b>	3204	4L		5211	TO4B65	<b><u>465088-0001</u></b>	6N8477
<b>933</b>					TO607	<b><u>406950-0001</u></b>	3S9226
<b>933</b>					TO607	<b><u>406950-0002</u></b>	5S9140
<b>938F</b>	3116T				S2ESL	<b><u>168360</u></b>	125-1123
<b>938F</b>	3116T		180		S2ESL	<b><u>167085</u></b>	104-5857
<b>941</b>	3508	8V		34500	TW6134	<b><u>465982-0001</u></b>	1W6863
<b>950</b>	3304	4L		7000	TO4B91	<b><u>409410-0002</u></b>	4N6859
<b>950</b>	D330	4L			T1210	<b><u>405490-0003</u></b>	3S4415
<b>950</b>	D330	4L			T1210	<b><u>405490-0006</u></b>	4S9704
<b>950</b>	D330	4L			T1210	<b><u>405490-0009</u></b>	7S8871
<b>950</b>	D330	4L			TO490	<b><u>408450-0002</u></b>	1P9136
<b>950B</b>	3304	4L		7000	TO4B91	<b><u>409410-0006</u></b>	7N4651
<b>950E</b>	3304	4L		7000	TO4B91	<b><u>409410-0007</u></b>	7N9851
<b>950F</b>					S2BS	<b><u>197840</u></b>	9Y4230
<b>950F</b>	3116				S2EGL	<b><u>167302</u></b>	105-5059



<b>950G</b>					S200G	<b>167865</b>	120-8362
<b>953</b>	3204	4L		5211	TO4B65	<b><u>465088-0001</u></b>	6N8477
<b>963</b>	3304	4L		7000	TO4B91	<b><u>409410-0006</u></b>	6N7155
<b>963B</b>	3116TA		175		S2ES	<b>167027</b>	105-5057
<b>966D</b>					4LFA302	<b>186514</b>	1W1227
<b>966E</b>					4LF302	<b>188127</b>	1W9383
<b>966E</b>					4LF302	<b>188127</b>	1W9382
<b>966E</b>	3306T	6L		10500	TV6304	<b><u>471045-0001</u></b>	133-5107
<b>966F</b>					S4DC	<b>196562</b>	7C7575
<b>980B</b>					4LF302	<b>182453</b>	6N7519
<b>980B</b>					4LF504	<b>180318</b>	4N9541
<b>980C</b>	3406	6L		14600	T1232	<b><u>409720-0004</u></b>	9L6308
<b>980C</b>	3406	6L		14600	T1232	<b><u>409720-0006</u></b>	7N0011
<b>980C</b>	3408	8V		18000	TV6138	<b><u>465426-0001</u></b>	7N9478
<b>980F</b>	3406	6L		14600	S4DSL	<b>167053</b>	107-2060
<b>980F</b>	3406	6L	275	14600	TDO9	<b><u>49132-00010</u></b>	7E7987
<b>980F</b>	3406	6L	275	14600	TDO9	<b><u>49132-00020</u></b>	7E7984
<b>980S</b>	3306T	6L		10500	TV6306	<b><u>471134-0002</u></b>	133-5105
<b>983</b>	D343	6L			T1810	<b><u>402910-0019</u></b>	9S1263
<b>983</b>	D343	6L			T1810	<b><u>402910-0034</u></b>	4N5634
<b>983</b>	D343	6L			T1810	<b><u>402910-0039</u></b>	4N5639
<b>983B</b>	D343	6L			T1232	<b><u>409720-0004</u></b>	9L6308
<b>983B</b>	D343	6L			T1232	<b><u>409720-0008</u></b>	8N2132
<b>988</b>	D343	6L			T1810	<b><u>402910-0002</u></b>	3S1414
<b>988</b>	D343	6L			T1810	<b><u>402910-0006</u></b>	8S6472
<b>988</b>	D343	6L			T1810	<b><u>402910-0032</u></b>	
<b>988</b>	D343	6L			T1810	<b><u>402910-0040</u></b>	4N5640
<b>988B</b>					4MF701	<b><u>186552</u></b>	1W1809
<b>988B</b>					4MF731	<b>180218</b>	9N0888
<b>988B</b>					4MF731	<b>181010</b>	6N1661
<b>988B</b>	3408	8V		18000	TV8105	<b><u>465694-0006</u></b>	8N6160
<b>988B</b>	3408T	8V		18000	TV8106	<b><u>465048-0003</u></b>	7N2495
<b>988F</b>	3408				S4DS	<b>166095</b>	4P7395
<b>988G</b>	3456	6L	520	15800	GT5002	<b><u>701756-0001</u></b>	148-9102
<b>990F</b>	3412				S4DCL	<b>167616</b>	113-7923
<b>992</b>	D348	12V			T1810	<b><u>402910-0012</u></b>	7S8901
<b>992</b>	D348	12V			T1810	<b><u>402910-0013</u></b>	7S8902
<b>992</b>	D348	12V			T1810	<b><u>402910-0035</u></b>	4N5635
<b>992</b>	D348	12V			T1810	<b><u>402910-0036</u></b>	4N5636
<b>992B</b>	D348	12V			T1810	<b><u>402910-0012</u></b>	7S8901

992B	D348	12V			T1810	<a href="#">402910-0013</a>	7S8902
992B	D348	12V			T1810	<a href="#">402910-0035</a>	4N5635
992B	D348	12V			T1810	<a href="#">402910-0036</a>	4N5636
992C	3412T	12V		27000	TL8115	<a href="#">466040-0001</a>	1W9571
992C	3412T	12V		27000	TL8115	<a href="#">466040-0002</a>	1W9572
992C	3412T	12V		27000	TL8115	<a href="#">466040-0003</a>	6N9624
992D	3412T	12V		27000	TL8115	<a href="#">466040-0004</a>	6N9625
992D	3412T	12V		27000	TL8115	<a href="#">466040-0005</a>	7C0353
994	3516				S4DC	<a href="#">198749</a>	9Y9204
D10					4LFC555	<a href="#">183972</a>	7N6725
D10					4LFC555	<a href="#">183973</a>	7N6726
D10	D348	12V			TL8112	<a href="#">465338-0002</a>	8N9656
D10	D348	12V			TL8112	<a href="#">465338-0003</a>	8N9657
D10	D348	12V			TL8112	<a href="#">465338-0006</a>	1N3580
D10	D348	12V			TL8112	<a href="#">465338-0007</a>	1N3579
D10R	3412T	12V	613	27000	UTL8901	<a href="#">466793-0001</a>	127-6462
D10R	3412T	12V	613	27000	UTL8901	<a href="#">466793-0003</a>	127-6462
D10R	3412T	12V	613	27000	UTL8901	<a href="#">466793-0005</a>	164-4610
D11	3508	8V		34500	TL8118	<a href="#">465955-0002</a>	7E9495
D11N	3508	8V		34500	TL8106	<a href="#">465622-0004</a>	7W9083
D11N	3508	8V		34500	TL8106	<a href="#">465622-0009</a>	9Y1488
D11N	3508	8V		34500	TL8106	<a href="#">465622-0010</a>	9Y1489
D11R	3508	8V		34500	TL8118	<a href="#">465955-0004</a>	115-3306
D4E	3304	4L		7000	TO4B91	<a href="#">409410-0008</a>	1W5160
D5H	3304	4L		7000	TO4B91	<a href="#">409410-0015</a>	110-8762
D6D	3306T	6L		10500	TB4146	<a href="#">471044-0001</a>	133-5109
D7E	D339	4L			T1210	<a href="#">405490-0016</a>	4S9706
D7F	3306T	6L		10500	T1218	<a href="#">408750-0001</a>	1P6933
D7G	3306T	6L		10500	TV6305	<a href="#">471133-0001</a>	133-5108
D8					T1227	<a href="#">408110-0006</a>	1P1163
D8					T1404	<a href="#">403680-0001</a>	2M5488
D8					T1404	<a href="#">403680-0012</a>	1S4376
D8					T1404	<a href="#">403680-0023</a>	3S8271
D8					T1504	<a href="#">403000-0007</a>	6H9577
D8H	D342	6L			T1227	<a href="#">408110-0001</a>	9S2611
D8H	D342	6L			T1227	<a href="#">408110-0005</a>	4N4441
D8H	D342	6L			T1227	<a href="#">408110-0006</a>	1P1163
D8H	D342	6L			T1238	<a href="#">465032-0001</a>	6N7203
D8H	D342	6L			T1867	<a href="#">406400-0001</a>	8S1348

<b>D8H</b>	D342	6L			T1867	<b><u>406400-0002</u></b>	8S6476
<b>D8H</b>	D342	6L			T1867	<b><u>406400-0003</u></b>	4N5645
<b>D8H</b>	D342	6L			TL6137	<b><u>465584-0001</u></b>	8N5510
<b>D8L</b>	3408	8V		18000	TL8106	<b><u>465622-0002</u></b>	4W9104
<b>D8L</b>	3408	8V		18000	TL8109	<b><u>465454-0002</u></b>	8N1147
<b>D8L</b>	3408	8V		18000	TL8118	<b><u>465955-0001</u></b>	7C0353
<b>D8N</b>	3406				S4DCL	<b>167056</b>	107-2061
<b>D8N</b>	3406				S4DS	<b>196547</b>	7C7691
<b>D9D</b>	D353	6L			T1402	<b><u>403650-0006</u></b>	4M4336
<b>D9D</b>	D353	6L			T1402	<b><u>403650-0025</u></b>	3S8274
<b>D9D</b>	D353	6L			T1402	<b><u>403650-0028</u></b>	3S8274
<b>D9D</b>	D353	6L			T1418	<b><u>402120-0007</u></b>	4M8169
<b>D9D</b>	D353	6L			T1418	<b><u>402120-0011</u></b>	3S8272
<b>D9D</b>	D353	6L			T1504	<b><u>403000-0001</u></b>	5H4253
<b>D9E</b>	D353	6L			T1402	<b><u>403650-0006</u></b>	4M4336
<b>D9E</b>	D353	6L			T1402	<b><u>403650-0019</u></b>	
<b>D9G</b>	D353	6L			T1402	<b><u>403650-0020</u></b>	4M3302
<b>D9G</b>	D353	6L			T1402	<b><u>403650-0027</u></b>	2S8112
<b>D9G</b>	D353	6L			T1402	<b><u>403650-0029</u></b>	3S8273
<b>D9G</b>	D353	6L			T1810	<b><u>402910-0003</u></b>	2S9804
<b>D9G</b>	D353	6L			T1810	<b><u>402910-0007</u></b>	8S6471
<b>D9G</b>	D353	6L			T1810	<b><u>402910-0030</u></b>	1S1104
<b>D9G</b>	D353	6L			T1810	<b><u>402910-0043</u></b>	4N5643
<b>D9H</b>	D353	6L			TL8106	<b><u>465622-0001</u></b>	8N6554
<b>D9H</b>	D353	6L			TV8106	<b><u>465048-0002</u></b>	7N1758
<b>D9L</b>	3412	12V		27000	TL8107	<b><u>465502-0002</u></b>	1W2503
<b>D9L</b>	3412	12V		27000	TL8107	<b><u>465502-0003</u></b>	2W5697
<b>D9R</b>	3408E	8V	474	18000	TL7501	<b><u>466271-0001</u></b>	4P8730
<b>IT12B</b>					S2AS	<b>314656</b>	9Y6593
<b>IT18C</b>	3114				S2AS	<b>166005</b>	6I0193
<b>IT28B</b>	3204T	4L		5211	TO4B65	<b><u>465088-0003</u></b>	8N4774

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

# TurboMaster

GARRETT TURBOS OFFICIAL DISTRIBUTOR FOR SPAIN

# Offway Catalog

## APPLICATIONS

SUITABLE FOR:

### Fiat Allis

Model	Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
FD30B	8285.22.002			17200	TO4B05	465468-0015	4805335
FD30B	8285.22.002			17200	TO4B05	465468-0016	4805334

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

## APPLICATIONS

SUITABLE FOR:

## Hitachi

Model	Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
EX200-1	6BD1T		168	5800	RHC7	<b>NH170048</b>	1-14400-210-0
EX400	E120TS				TV6140	<b><u>465482-0004</u></b>	1-14400-028-0
EX400-1	6RB1TPF				TA5108	<b><u>466860-0005</u></b>	1-14400-208-0
EX400-1	6RB1TTB2				TV6140	<b><u>465482-0005</u></b>	1-14400-096-0
EX400-3	6RB1				TA51	<b><u>466569-0001</u></b>	1-14400-317-1
EX450-5					TA51	<b><u>479034-0001</u></b>	1-14400-336-0
EX450-5	6RB1TQA				TA51	<b><u>466569-0002</u></b>	1-14400-340-0
FH150W	8045T				TAO302	<b><u>465318-0010</u></b>	4846414
FH200W	8065.25.08		190	5500	TB4141	<b><u>465547-0002</u></b>	98420722
LX150-2	NE6T				TO4B93	<b><u>467034-0007</u></b>	14201-95007
LX200	PE6T				TA4507	<b><u>466314-0006</u></b>	14201-96567
UH07-7	6BD1T		152	5800	RHB7	<b>VA150021</b>	1-14400-107-1
UH16-6	6RB1TTB2				TV6140	<b><u>465482-0005</u></b>	1-14400-096-0
X100	8065.25.290		134	5500	TB4141	<b><u>465547-0003</u></b>	99459813
X120	8065.25.290		134	5500	TB4141	<b><u>465547-0003</u></b>	99459813

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

## APPLICATIONS

SUITABLE FOR:

**J.I. Case**

Model	Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
1170	A451DT				TO489	<u>408310-0001</u>	A41264
1175	A451DT				TO489	<u>408310-0001</u>	A41264
1175	A451DT				TO4B37	<u>465260-0001</u>	A66770
1270	A451DT				TO489	<u>408310-0001</u>	A41264
1270	A451DT				TO4B37	<u>465260-0001</u>	A66770
1350	A504DT				TO4B12	<u>409000-0005</u>	A76015
1370	504BDT				TO486	<u>407720-0001</u>	A58855
1370	504BDT				TO4B19	<u>409640-0004</u>	A157336
1370	504BDTI				TO4B19	<u>409640-0004</u>	A157336
1370	A504DT				TO489	<u>408310-0002</u>	A60104
1370	A504DTI				TO4B19	<u>409640-0001</u>	A76341
1370	A504DTI				TO4B19	<u>409640-0004</u>	A138116
1470	504BDT				TO486	<u>407720-0001</u>	A58855
1470	A504DT				TO489	<u>408310-0002</u>	A60104
2470	A504DT				TO4B12	<u>409000-0005</u>	A76015
2470	A504DTI				TO4B19	<u>409640-0001</u>	A76341
2470	A504DTI				TO4B19	<u>409640-0002</u>	A138116
2670	A504DT				TO4B12	<u>409000-0005</u>	A76015
2670	A504DT				TO4B19	<u>409640-0001</u>	A76341
780	336DBT				TO445	<u>408190-0001</u>	
780B	336BDT		120		TO4B72	<u>465184-0002</u>	A157337
850C	336BDT		92		TO445	<u>408190-0007</u>	
850C	336BDT		120		TO4B72	<u>465184-0002</u>	A157337
W14	336BDT				TO445	<u>408190-0001</u>	
W14	336BDT		86		TO445	<u>408190-0007</u>	
W14H	336BDT				TO445	<u>408190-0001</u>	
W24D	504BD		147		TO4B19	<u>409640-0005</u>	
W26B	A504DT				TO489	<u>408310-0002</u>	A60104

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

## APPLICATIONS

SUITABLE FOR:

**JCB**

Model	Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
315					TB2571	<u>452181-0001</u>	2674A079
3CX	T4.40	4L		4000	GT2052	<u>452301-0003</u>	2674A328
3CX	T4.40	4L		4000	GT2052	<u>727266-0003</u>	2674A393

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

## APPLICATIONS

SUITABLE FOR:

### I.H Dresser

Model	Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
175C	DT414			6785	TO476	<b>407480-0004</b>	674985C91
175C	DT414			6785	TO4B12	<b>409000-0004</b>	680319C91
175C	DT466	6L		7600	TO4B18	<b>409570-0003</b>	
175C	DT466	6L		7600	TO4B18	<b><u>409570-0012</u></b>	684239C91
175C	DT466	6L		7600	TO4B18	<b>409570-0017</b>	684239C92
175C	DT466B	6L		7600	TO4B18	<b>409570-0003</b>	
175C	DT466B	6L		7600	TO4B18	<b><u>409570-0012</u></b>	684239C91
175C	DT466B	6L		7600	TO4B18	<b><u>409570-0017</u></b>	684239C92
250C	DT573			9390	TO4B25	<b><u>409770-0006</u></b>	
250C	DT573			9390	TO4B25	<b><u>409770-0014</u></b>	684663C91
330	DTI817			13390	THO8A61	<b><u>409280-0001</u></b>	681441C92
340	DTI817			13390	THO8A61	<b><u>409280-0001</u></b>	681441C92
4070B	DVT800			13110	THO8A61	<b><u>409280-0001</u></b>	681441C92
4070B	DVT800			13110	THO8A61	<b><u>409280-0003</u></b>	681443C92
4070B	DVT800			13110	THO8A61	<b><u>409280-0004</u></b>	684155C92
412	DT414			6785	TO4B18	<b><u>409570-0004</u></b>	
412	DT436			7145	TO476	<b>407480-0004</b>	674985C91
412	DT466	6L		7600	TO4B18	<b>409570-0003</b>	
412	DT466	6L		7600	TO4B18	<b><u>409570-0013</u></b>	684237C91
412	DT466	6L		7600	TO4B18	<b><u>409570-0018</u></b>	684237C92
4370	DVT800			13110	THO8A61	<b><u>409280-0001</u></b>	681441C92
4370	DVT800			13110	THO8A61	<b><u>409280-0004</u></b>	684155C92
4370B	DVT800			13110	THO8A61	<b><u>409280-0003</u></b>	681443C92
5070	DVT800			13110	THO8A61	<b><u>409280-0003</u></b>	681443C92
5070	DVT800			13110	THO8A61	<b><u>409280-0004</u></b>	684155C92
520	DT358			5860	TO4B94	<b><u>465288-0005</u></b>	3228601R91
530	DT414			6785	TO4B18	<b><u>409570-0002</u></b>	
530	DT414			6785	TO4B18	<b><u>409570-0011</u></b>	684240C91
530	DT414			6785	TO4B18	<b><u>409570-0016</u></b>	684240C92
540	DT466	6L		7600	TO4B18	<b>409570-0001</b>	
540	DT466	6L		7600	TO4B18	<b>409570-0010</b>	684238C91



<b>550</b>	DT817			13390	THO8A61	<b><u>409280-0001</u></b>	681441C92
<b>560</b>	DTI817			13390	THO8A61	<b><u>409280-0001</u></b>	681441C92
<b>E200</b>	DT414			6785	TO476	<b><u>407480-0004</u></b>	674985C91
<b>E200</b>	DT414			6785	TO4B12	<b><u>409000-0004</u></b>	680319C91
<b>E200</b>	DT414			6785	TO4B18	<b><u>409570-0002</u></b>	
<b>E200</b>	DT414			6785	TO4B18	<b><u>409570-0004</u></b>	
<b>E200</b>	DT414			6785	TO4B18	<b><u>409570-0011</u></b>	684240C91
<b>E200</b>	DT414			6785	TO4B18	<b><u>409570-0013</u></b>	684237C91
<b>E200</b>	DT414			6785	TO4B18	<b><u>409570-0016</u></b>	684240C92
<b>E200</b>	DT414			6785	TO4B18	<b><u>409570-0018</u></b>	684237C92
<b>E200</b>	DT466	6L		7600	TO4B18	<b><u>409570-0001</u></b>	
<b>E295</b>	DTI817B			13390	THO8A48	<b><u>408280-0001</u></b>	625443C91
<b>E295</b>	DTI817B			13390	THO8A61	<b><u>409280-0001</u></b>	681441C92
<b>H65C</b>	DT414			6785	TO4B18	<b><u>409570-0004</u></b>	
<b>H65C</b>	DT414			6785	TO4B18	<b><u>409570-0013</u></b>	684237C91
<b>H65C</b>	DT414			6785	TO4B18	<b><u>409570-0018</u></b>	684237C92
<b>H65C</b>	DT466	6L		7600	TO4B18	<b><u>409570-0018</u></b>	684237C92
<b>H80</b>	DT429			7030	TO476	<b><u>407480-0001</u></b>	702300C91
<b>H80</b>	DT429			7030	TO4B12	<b><u>409000-0006</u></b>	684012C91
<b>H80</b>	DT466	6L		7600	TO476	<b><u>407480-0003</u></b>	674953C91
<b>H80B</b>	DT466	6L		7600	TO4B12	<b><u>409000-0001</u></b>	674997C91
<b>H80B</b>	DT466	6L		7600	TO4B12	<b><u>409000-0003</u></b>	680099C91
<b>H80B</b>	DT466	6L		7600	TO4B18	<b><u>409570-0001</u></b>	
<b>H80B</b>	DT466	6L		7600	TO4B18	<b><u>409570-0010</u></b>	684238C91
<b>H80B</b>	DT466	6L		7600	TO4B25	<b><u>409770-0004</u></b>	
<b>H80B</b>	DT466	6L		7600	TO4B25	<b><u>409770-0012</u></b>	684498C91
<b>H90</b>	DT573			9390	TO4B25	<b><u>409770-0005</u></b>	
<b>H90</b>	DT573			9390	TO4B25	<b><u>409770-0013</u></b>	684596C91
<b>H90</b>	DT573			9390	TO4B25	<b><u>409770-0020</u></b>	1806077C91
<b>H91E</b>	DT573			9390	TO4B25	<b><u>409770-0013</u></b>	684596C91
<b>H91E</b>	DT573			9390	TO4B25	<b><u>409770-0020</u></b>	1806077C91
<b>L250</b>	DVT573			9390	TO4B25	<b><u>409770-0006</u></b>	
<b>L250</b>	DVT573			9390	TO4B25	<b><u>409770-0014</u></b>	684663C91
<b>L250</b>	DVT573			9390	TO4B25	<b><u>409770-0021</u></b>	684663C92
<b>S10</b>	DT360			5900	TO4B18	<b><u>409570-0005</u></b>	
<b>S10</b>	DT360			5900	TO4B18	<b><u>409570-0014</u></b>	684200C91
<b>S11B</b>	DT436			7145	TO4B12	<b><u>409000-0004</u></b>	680319C91
<b>S11B</b>	DT436			7145	TO4B18	<b><u>409570-0003</u></b>	
<b>S9B</b>	DT360			5900	TO466	<b><u>408630-0001</u></b>	675710C91
<b>S9B</b>	DT360			5900	TO4B12	<b><u>409000-0004</u></b>	680319C91

<b>S9B</b>	DT360			5900	TO4B18	<b>409570-0005</b>	
<b>S9B</b>	DT360			5900	TO4B18	<b>409570-0014</b>	684200C91
<b>TD15</b>	DT360			5900	TO705	<b>404330-0003</b>	321380R91
<b>TD15</b>	DT361			5915	TEO616	<b>405280-0001</b>	343607R91
<b>TD15</b>	DT361			5915	TEO617	<b>406360-0001</b>	606052C91
<b>TD15C</b>	DT466	6L		7600	TO476	<b>407480-0004</b>	674985C91
<b>TD15C</b>	DT466	6L		7600	TO4B18	<b>409570-0003</b>	
<b>TD15C</b>	DT466	6L		7600	TO4B18	<b>409570-0012</b>	684239C91
<b>TD15C</b>	DT466	6L		7600	TO4B18	<b>409570-0017</b>	684239C92
<b>TD15C</b>	DT466	6L	163	7600	TO4B18	<b>409570-0019</b>	1808035C91
<b>TD15C</b>	DT466B	6L		7600	TO4B18	<b>409570-0012</b>	684239C91
<b>TD15C</b>	DT466B	6L		7600	TO4B18	<b>409570-0017</b>	684239C92
<b>TD15CGC</b>	DT414			6785	TO4B12	<b>409000-0004</b>	680319C91
<b>TD15E</b>	DT466	6L		7600	TO4B18	<b>409570-0020</b>	1808646C91
<b>TD20</b>	DT436			7145	TO476	<b>407480-0001</b>	702300C91
<b>TD20C</b>	DVT573			9390	TO4B25	<b>409770-0006</b>	
<b>TD20C</b>	DVT573			9390	TO4B25	<b>409770-0014</b>	684663C91
<b>TD20E</b>	DVT800			13110	THO8A61	<b>409280-0004</b>	684155C92

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

## APPLICATIONS

SUITABLE FOR:

## John Deere

Model	Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
<b>300 SERIES</b>	4039T	4L		3900	TA3404	<u><a href="#">465593-0001</a></u>	RE29883
<b>300 SERIES</b>	4039T	4L	90	3900	T300-03	<u><a href="#">454044-0001</a></u>	
<b>300 SERIES</b>	4039T	4L	90	3900	TA3404	<u><a href="#">465593-0007</a></u>	RE29883
<b>300 SERIES</b>	4045T	4L	90	4500	T300-02	<u><a href="#">454041-0001</a></u>	
<b>300 SERIES</b>	4239T	4L		3917	TA3112	<u><a href="#">466932-0001</a></u>	RE25902
<b>300 SERIES</b>	4239T	4L		3917	TA3401	<u><a href="#">466334-0002</a></u>	RE26287
<b>300 SERIES</b>	4239T	4L		3917	TA3401	<u><a href="#">466334-0004</a></u>	RE26287
<b>300 SERIES</b>	4608T	4L			T350-01	<u><a href="#">466007-0001</a></u>	
<b>300 SERIES</b>	6068HZ	6L		6800	T350-01	<u><a href="#">466007-0005</a></u>	RE52921
<b>300 SERIES</b>	6068T	6L		6800	TA3802	<u><a href="#">466203-0001</a></u>	RE44804
<b>300 SERIES</b>	6359T	6L		5900	TA3401	<u><a href="#">466334-0006</a></u>	RE26289
<b>300 SERIES</b>	6359T	6L		5900	TA3401	<u><a href="#">466334-0007</a></u>	RE26289
<b>300 SERIES</b>	6359T	6L		5900	TA3401	<u><a href="#">466334-0010</a></u>	RE26291
<b>300 SERIES</b>	6359T	6L		5900	TO4B33	<u><a href="#">465040-0002</a></u>	AR73796
<b>310D</b>	4039T	4L		3900	TA3401	<u><a href="#">466334-0004</a></u>	RE36513
<b>310D</b>	4045T	4L		4500	TA3401	<u><a href="#">466334-0004</a></u>	RE36513
<b>330LC</b>	6081H	6L	250	8100	S200G	<u><a href="#">169920</a></u>	RE71280
<b>344G</b>					T300-04	<u><a href="#">466619-0001</a></u>	RE56385
<b>344G</b>					T300-04	<u><a href="#">466619-0003</a></u>	RE65850
<b>350 SERIES</b>	4045T	4L	125	4500	T300-08	<u><a href="#">471049-0001</a></u>	
<b>350 SERIES</b>	6068	6L		6800	T350-04	<u><a href="#">471050-0017</a></u>	
<b>350 SERIES</b>	6068T	6L		6800	T350-04	<u><a href="#">471050-0001</a></u>	
<b>3840</b>	4039T	4L		3900	TA3401	<u><a href="#">466334-0004</a></u>	RE36513
<b>3840</b>	4045T	4L		4500	TA3401	<u><a href="#">466334-0004</a></u>	RE36513
<b>400 SERIES</b>	6466A	6L		7636	TO4E45	<u><a href="#">465355-0004</a></u>	RE33786
<b>418</b>	6466	6L		7636	TO4E45	<u><a href="#">465355-0001</a></u>	RE29308
<b>440</b>	4219T	4L		3589	TO434	<u><a href="#">407820-0001</a></u>	AT28925
<b>440</b>	4219T	4L		3589	TO4B32	<u><a href="#">409940-0003</a></u>	AR77169
<b>440A</b>	4219A	4L		3589	TO434	<u><a href="#">407820-0001</a></u>	AT28925
<b>440A</b>	4219T	4L		3589	TO434	<u><a href="#">407820-0001</a></u>	AT28925
<b>440B</b>	4219T	4L		3589	TO434	<u><a href="#">407820-0001</a></u>	AT28925

<b>440C</b>	4276TT	4L		4523	TO4B32	<u><a href="#">409940-0001</a></u>	AR66692
<b>444E</b>	4045T	4L		4500	TA3401	<u><a href="#">466334-0005</a></u>	RE26341
<b>450</b>	4219T	4L		3589	TO434	<u><a href="#">407820-0001</a></u>	AT28925
<b>450</b>	4219T	4L		3589	TO4B32	<u><a href="#">409940-0001</a></u>	AR77169
<b>450</b>	6329T	6L		5392	TO4B32	<u><a href="#">409940-0007</a></u>	AT29738
<b>450 SERIES</b>					GT3571	<u><a href="#">466937-0001</a></u>	RE60346
<b>450 SERIES</b>					GT3571	<u><a href="#">466937-0002</a></u>	RE60346
<b>450B</b>	4219T	4L		3589	TO434	<u><a href="#">407820-0001</a></u>	AT28925
<b>450C</b>	4219T	4L		3589	TO434	<u><a href="#">407820-0001</a></u>	AT28925
<b>450C</b>	4219T	4L		3589	TO4B32	<u><a href="#">409940-0003</a></u>	AR77169
<b>450G</b>	4045T	4L		4500	TA3401	<u><a href="#">466334-0005</a></u>	RE26341
<b>455G</b>	4045T	4L		4500	TA3401	<u><a href="#">466334-0005</a></u>	RE26341
<b>490E</b>	4045T	4L		4500	TA3404	<u><a href="#">465593-0006</a></u>	RE45326
<b>510D</b>	4045T	4L		4500	TA3401	<u><a href="#">466334-0005</a></u>	RE26341
<b>540</b>	6329T	6L		5392	TO444	<u><a href="#">407950-0001</a></u>	
<b>540A</b>	6329T	6L		5392	TO444	<u><a href="#">407950-0001</a></u>	
<b>540A</b>	6329T	6L		5392	TO4B31	<u><a href="#">409930-0004</a></u>	AR77168
<b>540C</b>	4276TT	4L		4523	TO4B32	<u><a href="#">409940-0001</a></u>	AR66692
<b>540E</b>	4045T	4L		4500	T300-01	<u><a href="#">466003-0001</a></u>	RE46185
<b>540E</b>	4045T	4L		4500	T300-01	<u><a href="#">466003-0002</a></u>	RE54088
<b>544</b>	6329T	6L		5392	TO444	<u><a href="#">407950-0001</a></u>	
<b>544</b>	6329T	6L		5392	TO4B32	<u><a href="#">409940-0007</a></u>	AT29738
<b>544A</b>	6329T	6L		5392	TO444	<u><a href="#">407950-0001</a></u>	
<b>544A</b>	6329T	6L		5392	TO4B31	<u><a href="#">409930-0004</a></u>	AR77168
<b>544A</b>	6329T	6L		5392	TO4B32	<u><a href="#">409940-0007</a></u>	AT29738
<b>544B</b>	6329T	6L		5392	TO4B32	<u><a href="#">409940-0007</a></u>	AT29738
<b>544B</b>	6359T	6L		5883	TO4B33	<u><a href="#">465040-0004</a></u>	AR71504
<b>544B</b>	6414T	6L		6785	TO4B31	<u><a href="#">409930-0001</a></u>	AR66397
<b>544B</b>	6414T	6L		6785	TO4B31	<u><a href="#">409930-0002</a></u>	AR72166
<b>544E</b>	6059T	6L		5900	TA3401	<u><a href="#">466334-0010</a></u>	RE26120
<b>544E</b>	6068T	6L		6800	TA3401	<u><a href="#">466334-0010</a></u>	RE26120
<b>548E</b>	4045T	4L		4500	T300-01	<u><a href="#">466003-0002</a></u>	RE54088
<b>550</b>	4276T	4L		4523	TO4B32	<u><a href="#">409940-0001</a></u>	AR66692
<b>554B</b>	6414T	6L		6785	TO4B31	<u><a href="#">409930-0001</a></u>	AR66397
<b>555</b>	4239T	4L		3917	TO4B32	<u><a href="#">409940-0002</a></u>	AR75757
<b>555</b>	4276T	4L		4523	TO4B32	<u><a href="#">409940-0001</a></u>	AR66692
<b>555</b>	4276TT	4L		4523	TO4B32	<u><a href="#">409940-0001</a></u>	AR66692
<b>556A</b>	4045T	4L		4500	T300-01	<u><a href="#">466003-0001</a></u>	RE46185

570	4219T	4L		3589	TO4B32	<u>409940-0004</u>	
570	6059T	6L		5900	TA3401	<u>466334-0010</u>	RE26120
570	6068T	6L		6800	TA3401	<u>466334-0010</u>	RE26120
570	6329A	6L		5392	TO444	<u>407950-0001</u>	
570	6329A	6L		5392	TO4B32	<u>409940-0007</u>	AT29738
570	6329T	6L		5392	TO444	<u>407950-0001</u>	
570	6329T	6L		5392	TO4B32	<u>409940-0007</u>	AT29738
570A	6329A	6L		5392	TO444	<u>407950-0001</u>	
570A	6329T	6L		5392	TO444	<u>407950-0001</u>	
570A	6329T	6L		5392	TO4B31	<u>409930-0004</u>	AR77168
590E	4045T	4L		4500	TA3404	<u>465593-0006</u>	RE45326
595D	4045T	4L		4500	TA3401	<u>466334-0005</u>	RE26341
624	6059T	6L		5900	TA3401	<u>466334-0010</u>	RE26120
624	6068T	6L		6800	TA3401	<u>466334-0010</u>	RE26120
624E	6059T	6L		5900	TA3401	<u>466334-0010</u>	RE26120
624E	6068T	6L		6800	TA3401	<u>466334-0010</u>	RE26120
640	6414T	6L		6785	TO4B31	<u>409930-0001</u>	AR66397
640E	6059T	6L		5900	TA3404	<u>465593-0001</u>	RE29883
640E	6068T	6L		6800	TA3404	<u>465593-0001</u>	RE29883
643	6059T	6L		5900	TA3401	<u>466334-0010</u>	RE26120
643	6068T	6L		6800	TA3401	<u>466334-0010</u>	RE26120
644	6404T	6L		6621	3LD208	157441	AR58756
644	6404T	6L		6621	TO446	<u>407630-0001</u>	AR43572
644	6404T	6L		6621	TO446	<u>407630-0003</u>	AR48839
644	6404T	6L		6621	TO4B10	<u>408730-0003</u>	AR53753
644	6404T	6L		6621	TO4B15	<u>409250-0001</u>	AR58756
644	6404T	6L		6621	TO4B15	<u>409250-0002</u>	AR63779
644A	6404T	6L		6621	TO4B15	<u>409250-0002</u>	AR63779
644B	6531T	6L		8702	TO4B26	<u>409760-0001</u>	AR65349
644B	6531T	6L		8702	TO4B26	<u>409760-0002</u>	AR76749
644C	6466	6L		7636	TB4129	<u>466608-0003</u>	RE16970
644C	6466	6L		7636	TO4B23	<u>409710-0002</u>	AR74819
646B	6531T	6L		8702	TO4B26	<u>409760-0001</u>	AR65349
646B	6531T	6L		8702	TO4B26	<u>409760-0002</u>	AR76749
648E	6068T	6L	157	6800	T350-01	<u>466007-0011</u>	RE63078
65	6359T	6L		5883	TO4B33	<u>465040-0003</u>	AR64567
650G	4045T	4L		4500	TA3401	<u>466334-0005</u>	RE26341
670	6059T	6L		5900	TA3401	<u>466334-0010</u>	RE26120

670	6068T	6L		6800	TA3401	<u>466334-0010</u>	RE26120
670	6414T	6L		6875	TO4B31	<u>409930-0001</u>	AR66397
690					3LD	<b>155652</b>	AR53753
690	6404T	6L		6621	3LD	<b>157441</b>	AR58756
690	6404T	6L		6621	3LD208	<b>157253</b>	AR53752
690	6404T	6L		6621	TO446	<u>407630-0001</u>	AR43572
690	6404T	6L		6621	TO4B10	<b>408730-0002</b>	AR53752
690	6404T	6L		6621	TO4B15	<u>409250-0001</u>	AR58756
690	6404T	6L		6621	TO4B15	<u>409250-0002</u>	AR63779
690A	6404T	6L		6621	TO4B10	<b>408730-0003</b>	AR53753
690A	6404T	6L		6621	TO4B15	<u>409250-0002</u>	AR63779
690B	6404A	6L		6621	TB4129	<u>466608-0001</u>	RE16964
690B	6404T	6L		6621	TO4B11	<b>408970-0001</b>	
690B	6404T	6L		6621	TO4B11	<u>408970-0002</u>	AR54575
690B	6404T	6L		6621	TO4B15	<u>409250-0001</u>	AR58756
690E	6068T	6L		6800	TA3404	<u>465593-0007</u>	RE45327
693D	6059T	6L		5900	TA3401	<u>466334-0010</u>	RE26120
693D	6068T	6L		6800	TA3401	<u>466334-0010</u>	RE26120
712	6619T	6L		10144	TV6125	<u>465356-0003</u>	RE15800
740	6404A	6L		6621	TB4129	<u>466608-0001</u>	RE16964
740	6404A	6L		6621	TO4B11	<b>408970-0002</b>	AR54575
740	6404A	6L		6621	TO4B11	<u>408970-0002</u>	AR54575
740A	6466A	6L		7636	TO4B23	<u>409710-0004</u>	AR91131
744E	6101				S3A	<b>166414</b>	RE53397
744E	6619T	6L		10144	TA4537	<u>466037-0001</u>	RE39146
750	6059T	6L		5900	TA3401	<u>466334-0010</u>	RE26120
750	6068T	6L		6800	TA3401	<u>466334-0010</u>	RE26120
750	6414T	6L		6875	TO4B31	<u>409930-0001</u>	AR66397
750	6414T	6L		6875	TO4B31	<u>409930-0002</u>	AR72166
755	6059T	6L		5900	TA3401	<u>466334-0010</u>	RE26120
755	6068T	6L		6800	TA3401	<u>466334-0010</u>	RE26120
755	6414T	6L		6785	TO4B31	<u>409930-0002</u>	AR72166
755	6414T	6L		6875	TO4B31	<u>409930-0001</u>	AR66397
762	6619	6L		10144	4LE302	<b>180460</b>	AR69049
762	6619T	6L		10144	TV6102	<u>465320-0002</u>	AR73469
762B					TO4E45	<b>465355-0003</b>	RE33786
762S	6619T	6L		10144	TV6102	<u>465320-0002</u>	AR73469
790D					TO4E45	<b>465355-0003</b>	RE33786
790E	6068T	6L		6800	TA3404	<u>465593-0007</u>	RE45327

793D					TO4E45	<b>465355-0003</b>	RE33786
846A					T350-02	<b>466629-0001</b>	RE56736
850	6619	6L		10144	4LE302	<b>180460</b>	AR69049
850	6619A	6L		10144	TV6102	<b>465320-0003</b>	AR78444
850	6619T	6L		10144	TV6102	<b>465320-0003</b>	AR78444
850B					TO4E45	<b>465355-0003</b>	RE33786
855	6619	6L		10144	4LE302	<b>180460</b>	AR69049
855	6619T	6L		10144	TV6102	<b>465320-0003</b>	AR78444
860A	6619A	6L		10144	TV6102	<b>465320-0004</b>	AR77772
860B	6619A	6L		10144	TV6102	<b>465320-0004</b>	AR77772
860B	6619A	6L		10144	TV6125	<b>465356-0001</b>	AR97634
860B	6619A	6L		10144	TV6125	<b>465356-0002</b>	AR97630
890	6619A	6L		10144	TV6102	<b>465320-0005</b>	AR76693
890	6619A	6L		10144	TV6125	<b>465356-0002</b>	AR97630
892	6466A	6L		7636	3LM299	<b>193728</b>	RE16967
892E					TO4E45	<b>465355-0004</b>	RE44822
892E	6076	6L		7600	S2B	<b>166360</b>	RE52831
892E	6076	6L		7600	S2B	<b>166914</b>	RE56469
982E					TO4E45	<b>465355-0004</b>	RE44822
992E	6101				S3A	<b>166429</b>	RE46120

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

**TurboMaster**

GARRETT TURBOS OFFICIAL DISTRIBUTOR FOR SPAIN

**Offway** Catalog**APPLICATIONS**

SUITABLE FOR:

**Kobelco**

Model	Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
235SR	6D34	6L	150		TEO6H	49185-01040	ME440836
SK220	6D15CT				TB4133	465269-0013	ME047765
SK220-5	6D16T				TO4E58	479008-0001	ME078070

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.



## APPLICATIONS

SUITABLE FOR:

## Komatsu

Model	Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
CD705	SA6D125	6L		11046	TV7705	<u>466152-0002</u>	6152-81-8300
D150A					KTR130	<u>6502-12-1003</u>	6502-12-1003
D150A					KTR130	<u>6502-13-2003</u>	6502-13-2003
D155A					KTR130	<u>6502-13-2003</u>	6502-13-2003
D155A-1					KTR130	<u>6502-12-1003</u>	6502-12-1003
D31	S6D95L	6L		4884	TA3103	<u>465636-0013</u>	6206-81-8120
D31	S6D95L	6L		4884	TA3103	<u>465636-0113</u>	6206-81-8120
D31-18	S6D95L	6L		4884	TA3103	<u>465636-0213</u>	6206-81-8120
D355A-1	S6D155-4	6L		15240	KTR130	<u>6502-12-1000</u>	6502-12-1000
D355A-3	SA6D155-4A	6L		15240	KTR130	<u>6502-12-1001</u>	6502-12-1001
D355A-3	SA6D155-4A	6L		15240	KTR130	<u>6502-12-1002</u>	6502-12-1002
D355A-3	SA6D155-4A	6L		15240	KTR130	<u>6502-12-1003</u>	6502-12-1003
D355A-3	SA6D155-4A	6L		15240	KTR130	<u>6502-12-2002</u>	6502-12-2002
D355A-3	SA6D155-4A	6L		15240	KTR130	<u>6502-12-2003</u>	6502-12-2003
D355A-3	SA6D155-4A	6L		15240	KTR130	<u>6502-12-9003</u>	6502-12-9003
D355A-3	SA6D155-4A	6L		15240	KTR130	<u>6502-12-9004</u>	6502-12-9004
D355A-3	SA6D155-4A	6L		15240	KTR130	<u>6502-12-9005</u>	6502-12-9005
D355A-3	SA6D155-4A	6L		15240	KTR130	<u>6502-13-1000</u>	6502-13-1000
D355A-3	SA6D155-4A	6L		15240	KTR130	<u>6502-13-2001</u>	6502-13-2001
D355A-3	SA6D155-4A	6L		15240	KTR130	<u>6502-13-2002</u>	6502-13-2002
D37-2	S6D95L	6L		4884	TA3103	<u>465636-0213</u>	6206-81-8120
D40	S6D105	6L		6490	TO4B59	<u>465044-0059</u>	6137-82-8800
D40	S6D105	6L		6490	TO4B59	<u>465044-0159</u>	6137-82-8800
D40	S6D105	6L		6490	TO4B59	<u>465044-0235</u>	6137-81-8500
D40	S6D105	6L		6490	TO4B59	<u>465044-0259</u>	6137-82-8800
D40	S6D105-3	6L		6490	TO4B59	<u>465044-0227</u>	6131-82-8102
D45	S6D105-3	6L		6490	TO4B59	<u>465044-0227</u>	6131-82-8102
D455	KTA3067-C				T18A98	<u>465436-0009</u>	3031440
D455	VTA1710-P800			28022	T18A15	<u>408060-0001</u>	201833
D455	VTA1710-P800			28022	T18A15	<u>408060-0002</u>	201834
D455	VTA1710-P800			28022	T18A15	<u>408060-0003</u>	207420
D455	VTA1710-P800			28022	T18A15	<u>408060-0004</u>	207421

D53A					KTR100	6501-11-3002	6501-11-3002
D53S					KTR100	6501-11-3002	6501-11-3002
D55S	S4D120-11	4L		7864	KTR100	6501-11-1005	6501-11-1005
D55S	S4D120-11	4L		7864	KTR100	6501-11-3002	6501-11-3002
D57S-1	S4D130-1A	4L		8520	KTR100	6501-11-6000	6501-11-6000
D60F	SA6D125	6L		11046	TV7705	<u>466152-0002</u>	6152-81-8300
D60S	SA6D125	6L		11046	TV7705	<u>466152-0002</u>	6152-81-8300
D65EX-12E	S6D125	6L		11046	TO4E08	<u>466704-0213</u>	6151-81-8500
D66S-1	SA6D110-1	6L		7128	TO4B59	465044-0225	6138-81-8101
D75S	S6D125	6L		11046	TA4532	<u>465105-0002</u>	6152-81-8310
D75S-5	SA6D125	6L		11046	TV7705	<u>466152-0002</u>	6152-81-8300
D85					TO4E08	<u>466704-0213</u>	6151-82-8500
D90	S6D125	6L		11046	TV7705	<u>466152-0004</u>	6150-81-8300
EG110-2	S6D105	6L		6490	TO4B59	<u>465044-0233</u>	6137-81-8301
EG125S	SA6D105-1	6L		6490	TO4B59	<u>465044-0236</u>	6137-82-8100
EG150-3	SA6D110-1	6L		7128	TO4B59	<u>465044-0255</u>	6138-82-8200
EG200	SA6D125	6L		11046	TV7705	<u>466152-0001</u>	6152-81-8200
EG275	SA6D125	6L		11046	TA4532	<u>465105-0009</u>	6152-81-8610
EG300					KTR130	6502-13-2003	6502-13-2003
EG550					KTR150	6503-20-1000	6503-20-1000
EG65-2	S4D105-5	4L		6884	TO4B59	<u>465044-0238</u>	6135-82-8200
EG85CDBC	S6D95L	6L		4884	TA3103	<u>465636-0212</u>	6207-81-8230
EG85CDBS	S6D95L	6L		4884	TA3103	<u>465636-0012</u>	6207-81-8230
EG85CDBS	S6D95L	6L		4884	TA3103	<u>465636-0112</u>	6207-81-8230
FD200	SA6D108	6L		7150	TO4E08	<u>466704-0006</u>	6222-81-8130
FD200	SA6D108	6L		7150	TO4E08	<u>466704-0106</u>	6222-81-8130
FD200	SA6D108	6L		7150	TO4E08	<u>466704-0206</u>	6222-81-8130
FD400	SA6D125	6L		11046	TV7705	<u>466152-0002</u>	6152-81-8300
FD400	SA6D125	6L		11046	TV7705	<u>466152-0003</u>	6152-81-8400
FD70	S6D95L	6L		4884	TA3103	<u>465636-0211</u>	6207-81-8150
FD80H	S6D95	6L		4884	TA3103	<u>465636-0011</u>	6207-81-8150
FD80H	S6D95	6L		4884	TA3103	<u>465636-0111</u>	6207-81-8150
FD80H	S6D95	6L		4884	TA3103	<u>465636-0211</u>	6207-81-8150
GD31					KTR100	6501-11-1005	6501-11-1005
GD31					KTR100	6501-11-3002	6501-11-3002
GD37					KTR100	6501-11-1005	6501-11-1005
GD37					KTR100	6501-11-3002	6501-11-3002
GD500	S6D105-1	6L		6490	TO4B59	<u>465044-0261</u>	6137-82-8200
GD505R	S6D105-1	6L		6490	TO4B59	<u>465044-0261</u>	6137-82-8200
GD705	S6D125	6L		11046	TA4532	<u>465105-0002</u>	6152-81-8310

<b>GD705</b>	SA6D125	6L		11046	TV7705	<b><u>466152-0002</u></b>	6152-81-8300
<b>HD200-3</b>	S6D125	6L		11046	TV7705	<b><u>466152-0001</u></b>	6152-81-8200
<b>HD205</b>	S6D125	6L		11046	TA4532	<b><u>465105-0005</u></b>	6152-81-8410
<b>HD205-3</b>	S6D125	6L		11046	TA4532	<b><u>465105-0005</u></b>	6152-81-8410
<b>HD205-3</b>	S6D125	6L		11046	TV7705	<b><u>466152-0001</u></b>	6152-81-8200
<b>HD250</b>	S6D125	6L		11046	TV7705	<b><u>466152-0001</u></b>	6152-81-8200
<b>HD320</b>					KTR130	<b><u>6502-12-4007</u></b>	6502-12-4007
<b>HD320</b>					KTR130	<b><u>6502-12-4008</u></b>	6502-12-4008
<b>HD320-2</b>	VTA855-C420				KTR130	<b><u>6502-12-4005</u></b>	6502-12-4005
<b>HD325-5</b>					KTR110	<b><u>6505-11-8420</u></b>	6505-11-8420
<b>HD465</b>					KTR130C	<b><u>6502-30-1000</u></b>	6502-30-1000
<b>HD465</b>					S500	<b><u>319217</u></b>	6240-81-8600
<b>HD465</b>					TL7701	<b><u>466293-0001</u></b>	
<b>HD465</b>					TL7701	<b><u>466293-0002</u></b>	
<b>HD465</b>					TL7701	<b><u>466293-0005</u></b>	6162-84-8400
<b>HD465</b>					TL7701	<b><u>466293-0006</u></b>	6162-84-8500
<b>HD465</b>	SA6D170	6L		23155	TV7701	<b><u>465498-0023</u></b>	
<b>HD465</b>	SA6D170	6L		23155	TV7701	<b><u>465498-0024</u></b>	
<b>HD465</b>	SA6D170	6L		23155	TV7701	<b><u>465498-0027</u></b>	6162-83-8202
<b>HD465</b>	SA6D170	6L		23155	TV7701	<b><u>465498-0028</u></b>	6162-83-8302
<b>HD465-5</b>					S500	<b><u>318098</u></b>	6240-81-8400
<b>HD465-5</b>	SAA6D170E	6L	715	23156	TV7701	<b><u>465498-0035</u></b>	6162-85-8200
<b>HD465-5</b>	SAA6D170E	6L	715	23156	TV7701	<b><u>465498-0036</u></b>	6162-85-8300
<b>HD680-2</b>	VTA1710 C800				T18A15	<b><u>408060-0001</u></b>	201833
<b>HD680-2</b>	VTA1710 C800				T18A15	<b><u>408060-0002</u></b>	201834
<b>LW150</b>	S6D105	6L		6490	TO4B59	<b><u>465044-0036</u></b>	6137-82-8100
<b>LW150</b>	S6D105	6L		6490	TO4B59	<b><u>465044-0136</u></b>	6137-82-8100
<b>LW160</b>	S6D105	6L		6490	TO4B59	<b><u>465044-0236</u></b>	6137-82-8100
<b>LW200</b>	S6D105-1	6L		6490	TO4B59	<b><u>465044-0261</u></b>	6137-82-8200
<b>LW250</b>	S6D125	6L		11046	TO4E08	<b><u>466704-0201</u></b>	6152-81-8700
<b>LW250-5</b>	S6D125E	6L	250	11046	S3A	<b><u>315340</u></b>	6152-82-8110
<b>LW70</b>	S6D95L	6L		4884	TB3106	<b><u>466441-0004</u></b>	6207-81-8260
<b>LW80</b>					TB3106	<b><u>466441-0002</u></b>	
<b>LW80</b>					TB3106	<b><u>466441-0003</u></b>	
<b>LW80</b>	SA6D95L	6L		4884	TB3106	<b><u>466441-0004</u></b>	6207-81-8260
<b>P107</b>					TA3103	<b><u>465636-0003</u></b>	
<b>P107</b>					TA3103	<b><u>465636-0103</u></b>	
<b>PC100</b>	S4D105	4L		6884	TO4B59	<b><u>465044-0231</u></b>	6135-81-8201
<b>PC100</b>	S4D105	4L		6884	TO4B59	<b><u>465044-0238</u></b>	6235-82-8200
<b>PC100</b>	S4D95L	4L		2934	TA3103	<b><u>465636-0016</u></b>	6205-81-8150

PC100	S4D95L	4L		2934	TA3103	<b>465636-0116</b>	6205-81-8150
PC100	S4D95L	4L		2934	TA3103	<b>465636-0216</b>	6205-82-8100
PC100-5	S4D95L	4L		2934	TA3103	<b>465636-0206</b>	6205-81-8110
PC1100	SAA6D170E	6L		23156	KTR110G	<b>6505-52-5570</b>	6505-52-5570
PC120	S4D95L	4L		2934	TA3103	<b>465636-0016</b>	6205-81-8150
PC120	S4D95L	4L		2934	TA3103	<b>465636-0116</b>	6205-81-8150
PC120	S4D95L	4L		2934	TA3103	<b>465636-0216</b>	6205-81-8150
PC120-1	S4D105	4L		6884	TO4B59	<b>465044-0231</b>	6135-81-8201
PC120-1	S4D105	4L		6884	TO4B59	<b>465044-0238</b>	6235-82-8200
PC150	S4D95L	4L		2934	TA3103	<b>465636-0014</b>	6207-81-8240
PC150	S4D95L	4L		2934	TA3103	<b>465636-0114</b>	6207-81-8240
PC150-5	S4D95L	4L		2934	TA3103	<b>465636-0214</b>	6207-81-8240
PC200	S6D95	6L		4884	TO4B59	<b>465044-0051</b>	6207-81-8210
PC200-3	S6D105	6L		6490	TO4B59	<b>465044-0261</b>	6137-82-8200
PC200-3	S6D105B1-A	6L		6490	TO4B59	<b>465044-0262</b>	6137-82-8600
PC200-5	S6D95L	6L		4884	TO4B59	<b>465044-0251</b>	6207-81-8210
PC200-6	S6D95L	6L		4884	T300	<b>700836-0001</b>	6207-81-8331
PC220	SA6D95	6L		4884	TO4B59	<b>465044-0052</b>	6207-81-8220
PC220	SA6D95	6L		4884	TO4B59	<b>465044-0152</b>	6207-81-8220
PC220	SA6D95	6L	166	4884	S2D	<b>314474</b>	6209-81-8311
PC220	SA6D95L	6L	168	4884	S2D	<b>313579</b>	6209-81-8310
PC220-3	S6D105B1-A	6L		6490	TO4B59	<b>465044-0262</b>	6137-82-8600
PC220-5	S6D95L	6L		4884	TO4B59	<b>465044-0252</b>	6207-81-8220
PC220-5	SA6D95L	6L		4884	TO4B59	<b>465044-0252</b>	6207-81-8220
PC280	EM280				TO4B59	<b>465044-0054</b>	6138-82-8100
PC300					TO4E08	<b>466704-0003</b>	6222-81-8210
PC300					TO4E08	<b>466704-0103</b>	6222-81-8210
PC300	S6D125B	6L		11046	TB4130	<b>466702-0001</b>	6151-81-8400
PC300-3	S6D125	6L		11046	TA4532	<b>465105-0001</b>	6152-81-8110
PC300-5	S6D95L	6L		4884	TO4E08	<b>466704-0203</b>	6222-81-8210
PC300-6					TO4E15	<b>466670-0013</b>	6222-83-8171
PC400	S6D125	6L		11046	TA4532	<b>465105-0010</b>	
PC400	SA6D108	6L	242	7150	S2B	<b>314478</b>	6222-83-8170
PC400	SA6D108	6L	242	7150	S2B	<b>315122</b>	6222-83-8171
PC400	SA6D125	6L	324	11046	S3A	<b>314195</b>	6152-82-8210
PC400	SAA6D108E	6L		7150	S1B	<b>318473</b>	6222-83-8220
PC400	SAA6D125E	6L	326	11046	S3A	<b>318110</b>	6152-82-8220
PC400-3	S6D125	6L		11046	TA4532	<b>465105-0003</b>	6152-81-8210
PC400-5C	S6D125	6L		11046	TA4532	<b>465105-0010</b>	
PC400-L3C					TV7705	<b>466152-0005</b>	6152-81-8500

WA100	S6D95	6L		4884	TA3103	<u>465636-0204</u>	6206-81-8110
WA100	S6D95L	6L		4884	TA3103	<u>465636-0008</u>	6206-81-8110
WA100	S6D95L	6L		4884	TA3103	<u>465636-0108</u>	6206-81-8110
WA100	S6D95L	6L		4884	TA3103	<u>465636-0208</u>	6206-81-8110
WA150	S6D95L	6L		4884	TA3103	<u>465636-0117</u>	6205-81-8280
WA150	S6D95L	6L		4884	TA3103	<u>465636-0207</u>	6207-81-8130
WA150	S6D95L	6L		4884	TA3103	<u>465636-0217</u>	6205-81-8280
WA250	S6D105	6L		6490	TO4B59	<u>465044-0061</u>	6137-82-8200
WA250	S6D105	6L		6490	TO4B59	<u>465044-0261</u>	6137-82-8200
WA250	S6D105	6L		6490	TO4B59	<u>465044-0262</u>	6137-82-8600
WA300	S6D105	6L		6490	TO4B59	<u>465044-0061</u>	6137-82-8200
WA300	S6D105	6L		6490	TO4B59	<u>465044-0262</u>	6137-82-8600
WA300	SA6D108	6L	272	7150	S2B	<b>314766</b>	6222-83-8120
WA300-1	S6D105	6L		6490	TO4B59	<u>465044-0061</u>	6137-82-8200
WA320	SA6D108		272	7150	S2B	<b>314766</b>	6222-83-8120
WA350	S6D108	6L	217	7150	S2B	<b>314743</b>	6222-81-8181
WA350-1	S6D110-1A	6L		7128	TO4B59	<u>465044-0255</u>	6138-82-8200
WA350-3	SA6D108	6L	270	7150	TO4E08	<u>466704-0112</u>	6222-81-8170
WA350-3	SA6D108	6L	270	7150	TO4E08	<u>466704-0212</u>	6222-81-8170
WA350-3	SA6D108	6L	272	7150	S2B	<b>314766</b>	6222-83-8120
WA400	SA6D108	6L	230	7150	TBP417	<u>466535-0001</u>	
WA400	SA6D110	6L		7128	TO4B59	<u>465044-0055</u>	6138-82-8200
WA400	SA6D110	6L		7128	TO4B59	<u>465044-0155</u>	6138-82-8200
WA400	SA6D110-1A	6L		7128	TO4B59	<u>465044-0255</u>	6138-82-8200
WA400-3	SA6D108	6L	230	7150	TBP417	<u>466535-0002</u>	6222-81-8310
WA430-5					S400	<b>319143</b>	6156-81-8130
WA450	P139				S400	<u>318362</u>	6156-81-8110
WA450	S6D125	6L	369	11046	S3A	<b>314694</b>	6152-82-8310
WA480	SAA6D125E-3		296	11000	S400	<b>319448</b>	3156-81-8150
WA700					S500	<b>319167</b>	6340-81-8500
WA700					TL7701	<u>466293-0003</u>	
WA700					TL7701	<u>466293-0004</u>	
WA700					TL7701	<u>466293-0007</u>	
WA700					TL7701	<u>466293-0008</u>	
WA700					TL7701	<u>466293-0009</u>	
WA700					TL7701	<u>466293-0010</u>	
WA700					TV7701	<u>465498-0021</u>	6162-84-8200
WA700					TV7701	<u>465498-0022</u>	6162-84-8300
WA700	SA6D170	6L		23155	TV7701	<u>465498-0025</u>	6162-84-8201
WA700	SA6D170	6L		23155	TV7701	<u>465498-0026</u>	6162-84-8301

WT250

S6D125

6L

11046

TV7705

466152-0001

6152-81-8200

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: [turbomaster@turbomaster.info](mailto:turbomaster@turbomaster.info).

**TurboMaster**

GARRETT TURBOS OFFICIAL DISTRIBUTOR FOR SPAIN

**Offway** Catalog**APPLICATIONS**

SUITABLE FOR:

**Liebherr**

Model	Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
L541	D906T	6L	160	8410	K27	<b>5327-988-6426</b>	5700010
R984C	QSK-19	6L	685	18900	HX82	<b><u>3537426</u></b>	
T252	12V4000	12V	2025		BTV7506	<b><u>471084-0006</u></b>	5260200205

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

**TurboMaster**

GARRETT TURBOS OFFICIAL DISTRIBUTOR FOR SPAIN

**Offway** Catalog**APPLICATIONS**

SUITABLE FOR:

**Perlini**

Model	Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
131.33	6L60	6L	380	12700	TMF5502	466713-0001	23515635

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.



**TurboMaster**

GARRETT TURBOS OFFICIAL DISTRIBUTOR FOR SPAIN

**Offway** Catalog**APPLICATIONS**

SUITABLE FOR:

**Samsung**

Model	Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
LX18	6CT8.3	6L		8275	TO4E74	<u>706058-0001</u>	3528778
MX10W	6CT8.3	6L		8275	TO4E74	<u>706058-0001</u>	3802303

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
 Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: turbomaster@turbomaster.info.

## APPLICATIONS

SUITABLE FOR:

## Volvo

Model	Engine	Nº of cylinders	HP	CC	Model	Part Number	O.E.M Part Number
145	DH10A	6L	285	9600	HX40W	<b>3595118</b>	8194705
145	TD60	6L	139	5480	TO4B46	<b>465600-0007</b>	4880771
145	TD60	6L	139	5480	TO4B46	<b>465600-0008</b>	4880772
4400	TD71G	6L		6720	TO4E10	<b>466742-0006</b>	4881601
4500	TD71	6L		6720	TO4E10	<b>466742-0004</b>	4881599
5350	TD71G	6L		6720	TO4E10	<b>466742-0004</b>	4881599
A25C	TD73	6L		7000	TO4E10	<b>466742-0011</b>	11033542
A25C	TD73K	6L		7000	TO4E10	<b>466742-0012</b>	11033834
A25C	TD73K	6L		7000	TO4E10	<b>466742-0013</b>	11033835
A30C	TD103	6L		9600	GT4288N	<b>452174-0004</b>	11033938
A40	D12C	6L		12140	GT4594	<b>452164-0004</b>	11030483
A40	D12C	6L		12140	GT4594	<b>452164-0010</b>	11030482
A40	D12C	6L		12140	GT4594	<b>452164-0011</b>	11030483
A40	TD120	6L		11950	TA5132	<b>452154-0001</b>	11033744
A40	TD120	6L		11950	TA5132	<b>452154-0002</b>	3825106
A40	TD123	6L		11950	TA5132	<b>452154-0004</b>	11033744
L120B	TD73K	6L		7000	TO4E10	<b>466742-0010</b>	11033543
L120B	TD73KCE	6L		7000	TO4E10	<b>466742-0012</b>	11033834
L120B	TD73KCE	6L		7000	TO4E10	<b>466742-0013</b>	11033835
L120C	TD73K	6L		7000	TO4E10	<b>466742-0013</b>	11033835
L150C	TD103	6L	250	9600	GT4288N	<b>452174-0003</b>	11033937
L150C	TD103	6L	250	9600	TA4513	<b>466818-0008</b>	11033332
L180C	TD122KLE	6L		11950	TA5102	<b>466076-0021</b>	11031711
L220D	TD12KLE	6L		11950	TA5102	<b>466076-0021</b>	11031711
L320	TD164				TBP7501	<b>466749-0001</b>	11033755
L330	D16		490	16000	GTA4702	<b>723516-0001</b>	11032237
L330	D16		490	16000	GTA4702	<b>723516-0002</b>	11032389
L330	TD161		490	16000	GTA4702	<b>723516-0001</b>	11032237
L70B	TD61	6L		6720	TA3106	<b>465776-0011</b>	11033708
L70B	TD63	6L		5480	TA3106	<b>465776-0011</b>	11033708
L90B	TD61B	6L		6720	TO4E10	<b>466742-0009</b>	1103390
L90B	TD61GB	6L		6720	TO4E10	<b>466742-0014</b>	1103390

<b>L90B</b>	TD63	6L		5480	TO4E10	<b><u>466742-0013</u></b>	11033835
<b>L90B</b>	TD63	6L		5480	TO4E10	<b><u>466742-0015</u></b>	11032959
<b>L90B</b>	TD63KBE	6L		5480	TO4E10	<b><u>466742-0014</u></b>	1103390
<b>L90C</b>	TD63	6L		5480	TO4E10	<b><u>466742-0013</u></b>	11033835
<b>L90C</b>	TD63	6L		5480	TO4E10	<b><u>466742-0015</u></b>	11032959
<b>L90C</b>	TD63KBE	6L		5480	TO4E10	<b><u>466742-0014</u></b>	1103390

TurboMaster s.l. Mar Mediterráneo, 1 – Nave 7 28830 SAN FERNANDO DE HENARES ( Madrid ) Spain  
Telf: + 34 916.569.273 – 916.569.288 Fax: + 34 916569.397 e-mail: [turbomaster@turbomaster.info](mailto:turbomaster@turbomaster.info).